

ASS. REC. BY:

REF: CS/CTI18013628/T1sd3

n2

Special Instruction:

Surveyor
Munnen

Tautrich

ASSIGNMENT (Office)

From (Person): Junyn Tay of CTI Date/Time: 26/7/18 @ 10:16am

Estimated Cost: Bill to:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLU 69234 Insured: EE 3893J

at Workshop m/s Performance Motor Tel: 63190174

of 303 Alexandra Road

Policy No: DMPCS N3013021803 Claim No: SNM18D03575C02

Sum Insured: Excess:

Make of Veh: D.O.A. 18/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS up?

H.O.D. Endorsement:

Date/Time: 10:21am @ 26/7/18 Person Contacted: Caroline Vehicle: IN OPT

Date/Time	Action/Instruction (✓) Estimate
	SLU 69234-X
	EE 3893J-X

Carroll

Paytm

REF:

CT1

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SL469234

Yr Regn: 2017 Dec

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW X1

CC 1499

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

4373

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAJG12000EE61799

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45R18

R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / ☐ SUMI /

TOYO / YOKO or

Front

R/Bal:

6

mm

Rear

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

26/7/18 @ 1350

Survey held at

PML

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

01/11/18 Confirmed P/P \$ 11,910.10 @ 8 days with Taut. Lch.
(\$ 7,887.20 Red - 40%)

RECEIVED 05 NOV 2018

[Signature]
2/11/2018

Date/Time, File Pass to?

05/11/18

1)

Typist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS (\$)

Photos

Other

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 11,910.10 p/p)

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013628/T1sd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EE 3893J	Veh. Inspected	SLU 6923U
Policy No.	DMPCSN3013021803	Coverage (\$)	0.00
Claim No.	SNM18D03575C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	26/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/07/2018	Inspection Date	26/07/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2018		26 Jul 2018 10:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WONG SIU KEI MIKE, ID: S2607311A			
Main Claimant:	TAY MONG KIEW, ID: S0084184F			
Vehicle Reg. No.:	SLU6923U	Date of Loss:	18/07/2018 18:00 - :59	
Claim Type:	TP / SNM18D03575C02	Policy/Cover Note No.:	DMPCSN3013021803 (Comprehensive)	
Vehicle Reg. No. (Insured):	EE3893J	Policy No. (Claimant):	SD17V13746/VPC2/R00	
		Excess:	S\$0.00	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/08/2018]			
Driver/Custodian (Insured):	WONG SIU KEI MIKE (52 / Male), NRIC: S2607311A			
Adj Asg. Remarks:	EST \$18,867.04, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 5 November 2018 11:16 AM
To: 'PBSP'
Cc: Taufikh (LKKAuto); SUR
Subject: RE: FINAL REPORT / SLU6923U

Dear Caroline,

Confirmed final fig of \$ 11,910.10 (part by part) @ 8 days of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]
Sent: Wednesday, 24 October 2018 5:20 PM
To: taufikh@lkkauto.com; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SLU6923U

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 8,513.00

Total Parts : 3,397.10

Total Labour & Parts : 11,910.10

Repair days: 8

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete

all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2018 12:50
Date Of Accident	18/07/2018 18:20
Exact Location Of Accident	CTE CHIN SWEE TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU6923U
Insured/Policyholder	
Name Of Registered Owner	TAY MONG KIEW
NRIC No	S0084184F
Email Address	TAY.MONG.KIEW@SGH.COM.SG
Mobile Phone No	(LOCAL) +65-97589011
Alternative Phone No	OTHERS-97589011

Vehicle Particulars

Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V13746/VPC2/R00
Cover Note Number	

Driver

Name of Driver	TAY MONG KIEW
NRIC No	S0084184F
Date Of Birth	19/02/1945
Occupation	INDOOR
Date Of Driving Pass	13/01/1978
Driving Experience	40 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97589011
Fax Number	
Contact Number	OTHERS-97589011
EEmail Address	TAY.MONG.KIEW@SGH.COM.SG

Address	67 HAPPY AVENUE EAST
Postcode	369862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EE3893J
Vehicle Make/Model/Colour	MERCEDEZ WHITE COLOUR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG SIU KEI MIKE
NRIC/Passport Number	S2607311A
Contact Number	96362660
Address	BLK 9 BOON KENG ROAD #20-156
Postcode	330003
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Officer's Signature
Name: **Perumal Raju**
303 Alexandra Road
Singapore 150034

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened on 18 July 2018 at 1818 hrs. I was driving along CTE towards from Outram towards Ang Mo Kio. I was driving at about 50 kph and traffic was slow. Suddenly, a vehicle EE38937 collided into the rear of my vehicle. No one was injured. Attached a copy of video for reference.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

18/7/2018
11:50 am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No:

Inthiran A/L Thirumangalakudi
Performance Motors Limited
303 Alexandra Road
Seri Derby Performance
Singapore 159941

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



21 JUL 2018

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47770
Date Estimated : 21/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tay Mong Kiew
67 Happy Avenue East

Singapore 369862

- ACCOUNT -

135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU6923U	EE61799	11/12/2017	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper, tailgate, tail panel, repair rear right fender and attachments including knock out dent area cause by accident.

Painting rear bumper, tailgate, tail panel, rear right fender and trunk floor.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

Sundries.

To tow accident vehicle to PML workshop.

VALUE

2400 3360 5,950.00

2474 2547 4,602.00

150 177.00

150 177.00

230 271.00

100 118.00

451 531.00

150.00

195.00

Total Labour 1: 12,171.00

DESCRIPTION

BLIND RIVET NUT M6
BOOTLID
BOOTLID LH HINGE
BOOTLID RH HINGE
TAIL PANEL

QTY	PRIC
4	2.90
1	1,200.50
1	75.90
1	75.90
1	401.75

VALUE

11.60

1,200.50

75.90

75.90

401.75

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449173

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 JUL 2018

Page No. : 2 of 5

Estimate No. : b1 47770
Date Estimated : 21/07/2018
Prepared By : Inthiran A/L Thurasamy

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU6923U	EE61799	11/12/2017	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
REAR LH BUMPER MOUNT	1	142.55	142.55
REAR RH BUMPER MOUNT	1	142.55	142.55
RR BUMPER CARRIER	1	456.90	456.90
MOUNTING SMART OPENER	1	36.60	36.60
REAR TRIM UNDERRIDE PROTECTION (X L	1	99.85	99.85
RR BUMPER LH CORNER MOUNTING	1	142.55	142.55
RR BUMPER LH CORNER MOUNTING	1	142.55	142.55
REAR BUMPER PANEL PRIMED	1	723.45	723.45
REAR BUMPER MIDDLE TRIM PANEL (PDC)	1	227.90	227.90
REAR BUMPER TRIM BOTTOM (LINES)	1	217.05	217.05
EMBLEM GROMMET	2	0.80	1.60
BMW PLAQUE WITH ADHESIVE FILM	1	69.50	69.50
LETTERING X1	1	62.55	62.55
STRIKER BOOT LID	1	55.75	55.75
LOCK TRUNK LID	1	222.45	222.45
REAR BUMPER TOWING EYE COVER	1	35.55	35.55
REAR BUMPER HEAT INSULATION	1	67.85	67.85
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	40.50
ULTRASONIC SENSOR BLACK	3	248.70	746.10
DECOUPLING RING PDC TORQUE CONVERTER	4	5.05	20.20

Total Parts : 5,461.75

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 26/7/18 1330 Excess S\$

Surveyor's Name Tahir Sign

Surveyor's Tel 97495494 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tahir@khantham.com

No. of Working Days Recommend 7-8 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	12,171.00
Parts	:	5,461.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,234.29
Grand Total	:	18,867.04

19,797.30

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47770
Date Estimated : 21/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tay Mong Kiew
67 Happy Avenue East

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 369862

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLU6923U	EE61799	11/12/2017	X1 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	✓ A
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00	✓ A
# To conduct water leak tests	75.00		75.00	✓ A
# To mount vehicle on speed bench to facilitate the re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00	✓ A

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# EXPANDING NUT *	1.00	2.00		2.00	✓ A
# WASHER GASKET *	4.35	2.00		8.70	✓ A
# RR BUMPER RH CORNER MOUNTING *	142.55	1.00		142.55	✓ A
# BUMP STOP *	3.25	10.00		32.50	✓ A
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85	✓ A
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10	✓ A
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85	✓ A

Total Labour : 1,664.00
Total Parts : 500.55
Total Labour & Parts : 2,164.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47770
Date Estimated : 21/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tay Mong Kiew
67 Happy Avenue East

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 369862

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SLU6923U	EE61799	11/12/2017	X1 sDrive18i	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear bumper and attachments, boot lid, heat insulation include making good the tail end panel, to pull and straighten on accident areas and knocking out dents caused by the accident	3400.00		3,400.00			
To spray paint rear bumper, boot lid and tail end panel	2474.00		2,474.00			
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00			
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00			
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
To tow accident vehicle to PML workshop.	195.00		195.00			
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function.	451.00		451.00			
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00			
# To conduct water leak tests	75.00		75.00			
# To mount vehicle on speed bench to facilitate the re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00			
Sundries	150.00		150.00			
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT		

Performance Motors Limited

A member of the Simu Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

BLIND RIVET NUT M6	2.90	4.00	11.60
BOOTLID	1,200.50	1.00	1,200.50
# EXPANDING NUT *	1.00	2.00	2.00
# WASHER GASKET *	4.35	2.00	8.70
MOUNTING SMART OPENER	36.60	1.00	36.60
REAR TRIM UNDERRIDE PROTECTION (X L	99.85	1.00	99.85
RR BUMPER LH CORNER MOUNTING	142.55	1.00	142.55
# RR BUMPER RH CORNER MOUNTING *	142.55	1.00	142.55
REAR BUMPER PANEL PRIMED	723.45	1.00	723.45
REAR BUMPER MIDDLE TRIM PANEL (PDC)	227.90	1.00	227.90
REAR BUMPER TRIM BOTTOM (LINES)	217.05	1.00	217.05
EMBLEM GROMMET	0.80	2.00	1.60
BMW PLAQUE WITH ADHESIVE FILM	69.50	1.00	69.50
LETTERING X1	62.55	1.00	62.55
# BUMP STOP *	3.25	10.00	32.50
REAR BUMPER TOWING EYE COVER	35.55	1.00	35.55
REAR BUMPER HEAT INSULATION	67.85	1.00	67.85
# (DG) CLEANER R1 (100ML) *	23.85	1.00	23.85
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	263.10
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	27.85

SUPPLEMENTARY ITEMS

Total Labour :	8,513.00
Total Parts :	3,397.10
Total Labour & Parts :	11,910.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,910.10
GST @7%:	833.71
Grand Total :	12,743.81

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18013628/T1SD3N2

Date: 05/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3013021803
Claimant Vehicle No :	SLU6923U	Insured Vehicle No :	EE3893J
Date of Loss:	18/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03575C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6923U	Engine No:	G291H596B38B15A
Make & Model:	BMW X1, 2.0 sDrive20i (E84) (A)	Chassis No:	WBAJG12000EE61799
Reg. Date:	11/12/2017 (Man. Year: 2017)	Odometer:	4373 km
Colour:	Grey		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/70R18	Rear Tyre Size:	225/70R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,112.30	3,547.10	2,565.20	41.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,685.00	8,363.00	5,322.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,797.30	11,910.10	7,887.20	39.84
+ GST 7.00/7.00% (S\$)	1,385.81	833.71	552.10	39.84
Nett Amount (S\$)	21,183.11	12,743.81	8,439.30	39.84

INSPECTION

Date of Assignment: 26/07/2018

Date Inspected: 26/07/2018 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2018)
Parts:	M1-SUV	BMW X1 2.0 sDrive20i (E84) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6923U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	4	*BLIND RIVET NUT M6	Necessary	11.60 FS	*11.60 FS
2	1	*BOOTLID	Bent	1,200.50 FS	*1,200.50 FS
3	1	*BOOTLID LH HINGE	Repair	75.90 FS	*- FS
4	1	*BOOTLID RH HINGE	Repair	75.90 FS	*- FS
5	1	*TAIL PANEL	Not Necessary	401.75 FS	*- FS
6	1	*REAR LH BUMPER MOUNT	Not Necessary	142.55 FS	*- FS
7	1	*REAR RH BUMPER MOUNT	Not Necessary	456.90 FS	*- FS
8	1	*RR BUMPER CARRIER	Deformed	36.60 FS	*36.60 FS
9	1	*MOUNTING SMART OPENING	Deformed	99.85 FS	*99.85 FS
10	1	*REAR TRIM UNDERRIDE PROTECTION (X L)	Deformed	142.55 FS	*142.55 FS
11	1	*RR BUMPER LH CORNER MOUNTING	Not Necessary	142.55 FS	*- FS
12	1	*RR BUMPER LH CORNER MOUNTING	Deformed	723.45 FS	*723.45 FS
13	1	*REAR BUMPER PANEL PRIMED	Deformed	227.90 FS	*227.90 FS
14	1	*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	217.05 FS	*217.05 FS
15	1	*REAR BUMPER TRIM BOTTOM (LINES)	Necessary	1.60 FS	*1.60 FS
16	2	*EMBLEM GROMMET	Necessary	69.50 FS	*69.50 FS
17	1	*BMW PLAQUE WITH ADHESIVE FILM	Necessary	62.55 FS	*62.55 FS
18	1	*LETTERING X1	Not Necessary	55.75 FS	*- FS
19	1	*STRIKER BOOT LID	Not Necessary	222.45 FS	*- FS
20	1	*LOCK TRUNK LID	Necessary	35.55 FS	*35.55 FS
21	1	*REAR BUMPER TOWING EYE COVER	Bent	67.85 FS	*67.85 FS
22	1	*REAR BUMPER HEAT INSULATION	Not Necessary	42.10 FS	*- FS
23	1	*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	40.50 FS	*- FS
24	1	*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	746.10 FS	*- FS
25	3	*ULTRASONIC SENSOR BLACK	Not Necessary	20.20 FS	*- FS
26	4	*DECOUPING RING PDC TORQUE CONVERTER	Necessary	2.00 FS	*2.00 FS
27	2	*EXPANDING NUT	Necessary	8.70 FS	*8.70 FS
28	2	*WASHER GASKET	Deformed	142.55 FS	*142.55 FS
29	1	*RR BUMPER RH CORNER MOUNTING	Necessary	32.50 FS	*32.50 FS
30	10	*BUMP STOP	Necessary	23.85 FS	*23.85 FS
31	1	*(DG) CLEANER R1 (100ML)	Necessary	263.10 FS	*263.10 FS
32	2	*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	27.85 FS	*27.85 FS
33	1	*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	150.00 FS	*150.00 FS
34	1	*SUNDRIES			

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 6,112.30 3,547.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, TAILGATE, TAIL PANEL, REPAIR REAR RIGHT FENDER AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSED BY ACCIDENT	New	5,950.00	3,400.00
2	PAINTING REAR BUMPER, TAILGATE, TAIL PANEL, REAR RIGHT FENDER AND TRUNK FLOOR	New	4,602.00	2,474.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	-
8	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP	New	195.00	195.00
9	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	451.00	451.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS	New	574.00	574.00
11	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
12	TO MOUNT VEHICLE ON SPEED BENCH TO FACILITATE THE RE-ALIGNMENT OF BODYCHASSIS IN ACCORDANCE WITH BMW SPECIFICATION	New	564.00	564.00
Gross Labour Cost (S\$)			13,685.00	8,363.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >