

Performance Motors Limited

A member of the Sime Darby Group
Co, Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47770
Date Estimated : 21/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Tay Mong Kiew
67 Happy Avenue East

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 369862

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLU6923U	EE61799	11/12/2017	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00 ✓ A
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00 ✓ A
# To conduct water leak tests	75.00		75.00 ✓ A
# To mount vehicle on speed bench to facilitate the re-alignment of body/chassis in accordance with BMW specifications	564.00		564.00 ✓ A

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00 ne ✓ A
# WASHER GASKET *	4.35	2.00		8.70 ne ✓ A
# RR BUMPER RH CORNER MOUNTING *	142.55	1.00		142.55 dl ✓ A
# BUMP STOP *	3.25	10.00		32.50 ne ✓ A
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85 ne ✓ A
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00		263.10 ne ✓ A
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85 ne ✓ A

Total Labour :	1,664.00
Total Parts :	500.55
Total Labour & Parts :	2,164.55