

**K.KIM HIN AUTO PTE LTD**  
**160 Sin Ming Drive**  
**#02-20 Sin Ming AutoCity**  
**Singapore 575722**

**Claim Reference:**  
**Assessment Number: KKHA0013**  
**Version: K.KIMHIN/1**  
**Date Calculated: 25/07/2018 10:41**

**Full Report - V1**  
**Registration: SLE6877D**  
**Printed: 25/07/2018 17:42**

## Summary Information

### Claim

|                       |                              |                            |            |
|-----------------------|------------------------------|----------------------------|------------|
| Location:             | Singapore (SG)               | Currency:                  | SGD        |
| Printed by:           | SANDRA KHONG                 | Date of Incident:          | 23/07/2018 |
| Authorisation Status: | Interim                      | Able to Authorise Repairs: | TBA        |
| Work Provider:        | AXA Insurance S'pore Pte Ltd | Repairs Authorised:        | TBA        |

|                   |                        |
|-------------------|------------------------|
| Claim Reference:  | Estimated Repair Time: |
| Policy Number:    | Quote Due Date:        |
| Other Reference:  | Actual Repair Days:    |
| Third Party:      | Parts Ordered Date:    |
| Insured Amount:   | Hire Car Start:        |
| Under Warranty:   | Hire Car End:          |
| Warranty Expired: | Vehicle Collected:     |

### Vehicle Details

| Vehicle                       | Model Specs           |
|-------------------------------|-----------------------|
| Manufacturer: MITSUBISHI      | FROM 09/2016          |
| Model: Lancer                 | XENON HEADLAMPS       |
| Sub Model: EX                 | DAYTIME RUNNING LIGHT |
| Model Sheet Number: G39 57    | RADIATOR GRILLE SPORT |
| Registration: SLE6877D        | HEAD AIRBAG           |
| Registration Month: July      | 6-SPEED GEARBOX       |
| Registration Year: 2016       | HEIGHT CONTROL        |
| VIN Number: JMYSRCY1AGU005619 | PASSENGER AIRBAG      |
| Manufacture Year: 2016        | DRIVER AIRBAG         |
| Odometer: Not Known           | SIDE AIRBAGS          |
| Colour:                       | FRONT SKIRT           |
| Engine Number: 4A92CJ4834     | THREE COAT PEARL      |
| Fuel Level: %                 |                       |

### Vehicle Condition

#### Vehicle Status

|                         |                                |
|-------------------------|--------------------------------|
| Pre-Accident Condition: | Severity of Impact:            |
| Steering:               | Vehicle Status on Inspection:  |
| Brakes Pedal Travel:    | Date of Inspection: 24/07/2018 |
| Place of Inspection:    |                                |
| Pre-Accident Damage:    |                                |

#### Tyres Condition:



|                  |                      |
|------------------|----------------------|
| Tread Depth LHF: | Tread Depth RHF:     |
| Tread Depth LHR: | Tread Depth RHR:     |
| Damage Areas:    | Direction of Impact: |

**LKK Auto Consultants** henceforth the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No "legal modification(s)" is allowed
- Supplementary item(s) must be obtained and subject to final approval by the Company

Accepted by Repairer  
 Signature:  
 Date:

*Not Authorised*  
*1.3.1*  
*Runway B4 peim*  
*4 days*

**K.KIM HIN AUTO PTE LTD****Claim Reference:****Assessment Number: KKHA0013****Version: K.KIMHIN/1****Date Calculated: 25/07/2018 10:41****Full Report - V1****Registration: SLE6877D****Printed: 25/07/2018 17:42****Addresses****Repairer**

Name : K.KIM HIN AUTO PTE LTD

Address :

160 SIN MING DRIVE

#02-20

SIN MING AUTOCITY

Post Code : 575722

Email Address : service@kkimhin.com.sg

**Cost Summary**

|                           |            |
|---------------------------|------------|
| Total Labour              | \$1,417.50 |
| Total Paint/Material      | \$341.97   |
| Total Parts               | \$3,616.18 |
| Total of Additional Costs | \$230.00   |
| Excess:                   | TBA        |
| Grand Total Exc GST:      | \$5,605.65 |
| 7 % GST:                  | \$392.40   |
| Grand Total Inc GST:      | \$5,998.05 |

**Repair Information****LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR****Price/Dent = \$0.00/HR****Repair /****Guide Number Repair Details**

|            |                                                                                | WU   | Cost Price (\$) |
|------------|--------------------------------------------------------------------------------|------|-----------------|
| GROUP42B   | PREPARATION TIME PER JOB                                                       | 2.0  | 9.00            |
| 514121 10) | R + R ATTACHED PARTS OF THE BUMPER<br>(BUMPER WITH FRONT FOG LAMPS)            | 14.0 | 63.00           |
| NO NUMBER  | R + R FRONT BUMPER REINFORCEMENT<br>(BUMPER REMOVED)                           | 3.0  | 13.50           |
| 425111 10) | RENEW BONNET<br>(REMOVED)                                                      | 2.0  | 9.00            |
|            | INCLUDES: R + R ATTACHED PARTS,<br>ALIGN BONNET                                |      |                 |
| 425141 10  | R + R BONNET LOCK                                                              | 3.0  | 13.50           |
| NO NUMBER  | R + R BONNET STAY                                                              | 1.0  | 4.50            |
| 425113 10) | R + R LEFT BONNET HINGE<br>(BONNET REMOVED)                                    | 1.0  | 4.50            |
| 425113 10) | R + R RIGHT BONNET HINGE<br>(BONNET REMOVED)                                   | 1.0  | 4.50            |
| 422025 10) | R + R R/WING SPLASH SHIELD                                                     | 4.0  | 18.00           |
| NO NUMBER  | ADJUST HEADLAMPS                                                               | 2.0  | 9.00            |
| 421020 YC  | RENEW L/FRONT PANEL                                                            | 73.0 | 328.50          |
|            | INCLUDES: R + R BUMPER, SPLASH SHIELD,<br>WING, BONNET, HEADLAMP, RADIATOR AND |      |                 |



# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0013

Version: K.KIMHIN/1

Date Calculated: 25/07/2018 10:41

Full Report - V1

Registration: SLE6877D

Printed: 25/07/2018 17:42

|                    |                                             |         |            |
|--------------------|---------------------------------------------|---------|------------|
| 421020 ZAX         | ALL PARTS IN THE REPAIR SECTION             | 6.0     | 27.00      |
| 9852               | RENEW L/WHEELHOUSE CONNECTION PANEL         | 30.0*   | 135.00     |
|                    | READ OUT FAULT MEM AFTER REP                |         |            |
| <b>LABOUR COST</b> |                                             |         |            |
|                    | <b>Total Work Units</b>                     | 142.0   |            |
|                    | <b>Corrosion Protection External Labour</b> | 0.0HRS  | 0.00       |
|                    | <b>Corrosion Protection Internal Labour</b> | 0.0HRS  | 0.00       |
|                    | <b>Sub Total</b>                            | 14.2HRS | \$639.00   |
|                    | <b>Paint Labour</b>                         | 17.3HRS | \$778.50   |
|                    | <b>Total Labour</b>                         | 31.5HRS | \$1,417.50 |

| <b>PAINT WORK</b>            |                                           | <b>Time Basis 10 WU = 1 HR. Price = \$45.00/HR</b> |                        |
|------------------------------|-------------------------------------------|----------------------------------------------------|------------------------|
| <b>Guide Number</b>          | <b>Description</b>                        | <b>WU</b>                                          | <b>Cost Price (\$)</b> |
|                              | - PREPARE OFF VEHICLE                     |                                                    |                        |
|                              | - THREE COAT PEARL                        |                                                    |                        |
| 340                          | FRT BUMPER REINF SURFACE PAINT            | 4.0                                                |                        |
| 341                          | FRT BUMPER SUPPORT SURFACE PAINT          | 4.0                                                |                        |
| 471                          | BONNET NEW PART PAINTING                  | 24.0                                               |                        |
| 741                          | L/F WING NEW PART PAINTING                | 10.0                                               |                        |
| 1019                         | L/F PANEL SURFACE PAINT                   | 4.0                                                |                        |
| 1175                         | L/F W-HOUSE CONN PNLSURFACE PAINT         | 4.0                                                |                        |
| 283                          | FRONT BUMPER COVER NEW PART PAINT K1R     | 13.0                                               |                        |
| 284                          | FRONT BUMPER COVER SURFACE PAINT          | 9.0                                                |                        |
|                              | ADD/WORK FOR 3-COAT PAINTING              |                                                    |                        |
| 345                          | CTR BUMPER BRACKET SURFACE PAINT          | 4.0                                                |                        |
| 472                          | BONNET SURFACE PAINT                      | 10.0                                               |                        |
|                              | ADD/WORK FOR 3-COAT PAINTING              |                                                    |                        |
| 742                          | R/F WING SURFACE PAINT                    | 6.0                                                |                        |
| 743                          | L/F WING SURFACE PAINT                    | 5.0                                                |                        |
|                              | ADD/WORK FOR 3-COAT PAINTING              |                                                    |                        |
| 744                          | R/F WING SURFACE PAINT                    | 5.0                                                |                        |
|                              | ADD/WORK FOR 3-COAT PAINTING              |                                                    |                        |
| 1010                         | FRT LWR CROSSMEMBER SURFACE PAINT         | 5.0                                                |                        |
| 1017                         | FRT UPP LOCK CARRIERSURFACE PAINT         | 4.0                                                |                        |
| 1020                         | R/F PANEL SURFACE PAINT                   | 4.0                                                |                        |
| 1187                         | L/F OUT S-MEMBER PNLSURFACE PAINT         | 4.0                                                |                        |
| 1188                         | R/F OUT S-MEMBER PNLSURFACE PAINT         | 4.0                                                |                        |
| 1481                         | LEFT FRONT DOOR SURFACE PAINT             | 8.0                                                |                        |
| 1497                         | LEFT FRONT DOOR SURFACE PAINT             | 7.0                                                |                        |
|                              | ADD/WORK FOR 3-COAT PAINTING              |                                                    |                        |
| <b>LABOUR COST - PAINT</b>   |                                           |                                                    |                        |
|                              | <b>TIME(PAINT)</b>                        | 138.0                                              |                        |
|                              | <b>Preparation Main Work Plastic</b>      | 5.0                                                |                        |
|                              | <b>Preparation Main Work Metal</b>        | 25.0                                               |                        |
|                              | <b>Preparation Work Multi Layer Paint</b> | 5.0                                                |                        |
|                              | <b>Total Work Units (10WU/HR)</b>         | 173.0                                              |                        |
|                              | <b>Total Paintwork Labour</b>             | 17.3HRS                                            | \$778.50               |
| <b>MATERIAL COST - PAINT</b> |                                           |                                                    |                        |
|                              | <b>New Part Painting</b>                  |                                                    | \$98.04                |
|                              | <b>New Part Painting - Plastic K1R</b>    |                                                    | \$64.94                |
|                              | <b>Material-Constant Main Work Metal</b>  |                                                    | \$28.60                |



# K.KIM HIN AUTO PTE LTD

Claim Reference:

Assessment Number: KKHA0013

Version: K.KIMHIN/1

Date Calculated: 25/07/2018 10:41

Full Report - V1

Registration: SLE6877D

Printed: 25/07/2018 17:42

|                                    |          |
|------------------------------------|----------|
| Surface-/Blend Paint               | \$132.09 |
| Material-Const Main Work Plastic   | \$9.00   |
| Total Excluding Pearlescent Uplift | \$341.97 |
| Pearlescent Uplift @ 0.0%          | \$0.00   |
| Total Paint Material Cost          | \$341.97 |

## PARTS

Price Valid: 01/06/2015

| Guide No. | Qty | Description          | Part Number    | Supplier | Bet. | Price (\$) |
|-----------|-----|----------------------|----------------|----------|------|------------|
| 283       | 1   | FRONT BUMPER COVER   | 6400C075       |          | 0%   | 430.00*    |
| 295       | 1   | L/DAYTIME HEADLAMP   | 8312A045       |          | 0%   | 330.00*    |
| 313       | 1   | LWR RADIATOR GRILLE  | 6402A399       |          | 0%   | 55.00*     |
| 340       | 1   | FRT BUMPER REINF     | 6400A832       |          | 0%   | 60.00*     |
| 341       | 1   | FRT BUMPER SUPPORT   | 6400C639       |          | 0%   | 300.00*    |
| 350       | 6   | FRT BUMPER CLAMP KIT | MS100224       |          | 0%   | 10.00*     |
| 351       | 1   | L/LOWER AIR GRILLE   | 8321A089       |          | 0%   | 30.00*     |
| 354       | 1   | CTR PROTECT MOULDING | 6400C043       |          | 0%   | 130.00*    |
| 355       | 1   | L/F BUMPER BRACKET   | 6400F549       |          | 0%   | 13.00*     |
| 356       | 1   | R/F BUMPER BRACKET   | 6400F550       |          | 0%   | 13.00*     |
| 410       | 1   | GRILLE               | 7450A780       |          | 0%   | 150.00*    |
| 471       | 1   | BONNET               | 5900A209       |          | 0%   | 370.00*    |
| 475       | 1   | LEFT BONNET HINGE    | 5905A089       |          | 0%   | 40.00*     |
| 476       | 1   | RIGHT BONNET HINGE   | 5905A090       |          | 0%   | 40.00*     |
| 493       | 1   | BONNET LOCK          | 5908A009       |          | 0%   | 40.00*     |
| 495       | 1   | BONNET SUPPORT       | 5906A005       |          | 0%   | 20.00*     |
| 528       | 1   | REAR BONNET SEAL     | 5902A078       |          | 0%   | 20.00*     |
| 561       | 1   | L/F HEADLAMP CPL     | 8301C345       |          | 0%   | 400.00*    |
| 637       | 1   | L/F FOG LAMP CPL     | 8321A668       |          | 0%   | 170.00*    |
| 741       | 1   | L/F WING             | 5220G043       |          | 0%   | 270.00*    |
| 789       | 18  | L/F WING CLAMP KIT   | MS100222       |          | 0%   | 8.00*      |
| 841       | 1   | L/WHEELHOUSE SHELL   | 5370B837       |          | 0%   | 75.00*     |
| 1019      | 1   | L/F PANEL            | 5256A599       |          | 0%   | 55.00*     |
| 1175      | 1   | L/F W-HOUSE CONN PNL | 5220C499       |          | 0%   | 13.00*     |
| 1000      | 1   | FRT BUMPER RIVET     | \$1.50 @ 15PCS |          | 0%   | 22.50*     |
| 1000      | 1   | LH FRT BUMPER BRK    | Renew          |          | 0%   | 12.00*     |
| 1000      | 1   | RH FRT BUMPER BRK    | Renew          |          | 0%   | 12.00*     |
| 1000      | 1   | FRT LWR GRILLE CLIP  | \$2.00 @ 8PCS  |          | 0%   | 16.00*     |
| 1000      | 1   | BONNET INSULATO CLIP | Renew          |          | 0%   | 15.00*     |
| 1000      | 1   | L/F WING T I/4 GARNI | Renew          |          | 0%   | 25.00*     |

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Sub Total

Mark Up From Cost

Sundry Parts

Total Parts

(15 %)

(Fixed)

\$3,144.50

\$471.68

\$0.00

\$3,616.18

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

## Extras

| Description       | Specialist |
|-------------------|------------|
| AUDATEX FEE       | SPECIALIST |
| ANTIFREEZE 4 LTR  | SPECIALIST |
| TOP UP AIRCON GAS | SPECIALIST |
| FRT NUMBER PLATE  | SPECIALIST |

Betterment

0%

0%

Total Extras

NEC

Price

\$42.00

\$48.00

\$100.00

\$40.00

\$230.00

## Final Calculation

**K.KIM HIN AUTO PTE LTD****Claim Reference:****Assessment Number: KKHA0013****Version: K.KIMHIN/1****Date Calculated: 25/07/2018 10:41****Full Report - V1****Registration: SLE6877D****Printed: 25/07/2018 17:42**

|                                   |                              |          |                   |
|-----------------------------------|------------------------------|----------|-------------------|
| <b>Total Parts</b>                |                              |          | <b>\$3,616.18</b> |
| <b>Labour</b>                     |                              |          |                   |
|                                   | Total Panel/Mechanical       | \$639.00 | \$513.00          |
|                                   | Total Paintwork              | \$778.50 | \$855.00          |
| <b>Total Labour</b>               |                              |          | <b>\$1,417.50</b> |
| <b>Additional Costs</b>           |                              |          |                   |
|                                   | Corr Prot Materials External | \$0.00   |                   |
|                                   | Corr Prot Materials Internal | \$0.00   |                   |
|                                   | Cost of Specialist           | \$230.00 |                   |
| <b>Total of Additional Costs</b>  |                              |          | <b>\$230.00</b>   |
| <b>Total Paint/Material Costs</b> |                              |          | <b>\$354.97</b>   |
| <b>Grand Total Excludes GST</b>   |                              |          | <b>\$5,605.65</b> |
|                                   | GST @ 7 %                    |          | <b>\$392.40</b>   |
| <b>Grand Total Includes GST</b>   |                              |          | <b>\$5,998.05</b> |

**Assessment Notes**

Supplies  
Repair Left Front Door 10 30 min ✓ \$45