

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0414/18

DATE : 18-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
MOTOR CLAIM MANGER VALENCIA

OWNER'S NAME : LIM LEE (LIN LI)@NURISSA LIM
ADDRESS : BLK 133 EDGEDALE PLAINS
#02-48
S(820133)
TELEPHONE NO : 97836305

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SGY1113L
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2426300A
CHASSIS NO : SJNFEAJ11U1959270
MILEAGE : 12394 KM
DATE IN : 18/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER — 67038691
ACCIDENT DATE : 17/07/2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9668 FAX: 6846 7482

Not Allowed
Mark Marcus
to be before party,
27/7/18
2 dy.
HP: 90096608

EMAIL: elmer@tauchong.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGY1113L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR REAR END PANEL,RENEW FRT BUMPER	800.00	.375
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	600.00	400
3	ZZ/003	RENEW REVERSE SENSOR	110.00	✓
TOTAL LABOUR CHARGES			1510.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGY1113L

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	SENSOR-REVERSE	SENSOR	250.00	sturd ✓
2	SUNDRIES	NPN	50.00	?
3	STAY ASSY-REAR RH	H5210-4EAMA	126.00	11 X
4	STAY ASSY-REAR LH	H5211-4EAMA	126.00	11 X
5	REINFORCEMENT REAR BUMPER	H5030-4EAMA	619.20	?
6	REAR BUMPER SIDE BRACKET RH	85220-4EA0A	35.90	ner ✓
7	REAR BUMPER SIDE BRACKET LH	85221-4EA0A	35.90	ner ✓
8	ENERGY ABSORBER REAR BUMPER	85090-4EA0B	126.40	?
9	CLIP REAR BUMPER @ \$1.20 EACH	01553-05933	7.20	ner ✓
10	REAR BUMPER FASCIA	85022-4EA0H	717.00	de ✓
SUB TOTAL			1793.60	0.00 300.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			358.72	0.00 0.00
GRAND TOTAL			1434.88	0.00 300.00
OVERALL TOTAL			1734.88	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SGY1113L

TOTAL LABOUR CHARGES	1510.00
TOTAL SPARE PARTS CHARGES	1734.88

GRAND TOTAL	3244.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.