

SMRT Accident Vehicle Repair Estimates

CgM

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4755T
Ref. No : TAX/07/18/2120
Reg. Date : 01/04/2016
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TAN SOON CHIEW
Type of Accident : SIDE SWIPE
Date / Time of Accident : 24/07/2018 09:10:00 PM
Accident Reported Date / Time : 25/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 24/07/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097223
Special Instruction to ARC, if any :
TOWED \$60 / SDH9928A
Prepared Date : 25/07/2018 02:41:54 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805767765

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,872.00	0.00
Total Material Charges :	5,299.03	5,299.03
Other Charges :	1,269.00	0.00
TOTAL :	9,454.03	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	26/07/2018 09:07:28 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/07/2018 09:06:33 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 800
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	1,872.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 50
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 20
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X 111
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X 111
TO TRANSFER DOOR MECHANISM	240.00	0.00 100
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 50
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 20
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X 111
TO REPLACE SUNDRY PARTS	100.00	0.00 X 111
Total Other Costs	1,269.00	0.00

NA2 LKX
 26/7/18 1540
 P/P
 3 DAY
 AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No <i>X R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>mc</i>
69040-47070			DOOR LOCK FRT/LH	1	575.80	25.00	431.85	Replace	Replace	No <i>X Svc</i>
69410-33010			DOOR LOCK STRIKER	1	40.50	25.00	30.37	Replace	Replace	No <i>X Svc</i>
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace	No <i>X R</i>
65632-47041			SILL MEMBER PLATE RR/LH	1	57.50	25.00	43.12	Replace	Replace	No <i>?</i>
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace	No <i>X R</i>
68760-20122			HINGE UPPER LHR, DOOR	1	81.70	25.00	61.27	Replace	Replace	No <i>X Svc</i>
68780-52031			HINGE LOWER LHR, DOOR	1	72.20	25.00	54.15	Replace	Replace	No <i>X Svc</i>
68630-47031			CHECK ASSY, RR DOOR,	1	150.30	25.00	112.72	Replace	Replace	No <i>?</i>
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace	No <i>X R</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>mc</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>mc</i>
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace	No <i>X Svc</i>
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace	No <i>X Svc</i>
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>X R</i>
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No <i>?</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>?</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>mc</i>
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace	No <i>X Svc</i>
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No <i>X R</i>
TOTAL MATERIALS								5,299.07	5,299.03	
TOTAL MATERIALS(Discounted)							5,299.03	5,299.03		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									