

23/03/2009

ASS. REC. BY:

REF:

CS/FCI 18013638 / Und3 n2

Special Instruction:

Surveyor:

CWS

Marcus

ASSIGNMENT (Office)

From (Person):

Eugene Ler

of

FCI

Date/Time:

26/7/18 @ 2:33pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKF 30991

Insured:

SHC 3279H

at Workshop n/s

8ME Motor

Tel:

67476106

of

1 Kaki Bkt Ave 6 Blk D #02-15 Autobay

Policy No:

Claim No:

D18005668MF8H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

27/07/18

H.O.D. Endorsement:

Date/Time:

3:57pm @ 26/7/18

Person Contacted:

Jenny

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKF 30991-X

SHC 3279H - CS/MSG/18000637/K1vd3n2 DOA: 9/1/18

30/7/18

Email preli revised to FCI

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: Date: 27/07/18

Estimated Cost:

On ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKF 3099

at Workshop m/s SME Motor

of Ikaki Bkt Ave 6, Bld #02-15

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs: 11 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS DS) 67A 71194

Date: Person Contacted:

N/S	O/S

Veh No: SKF 3099 Yr Regn: 5112

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or ☒ Car

Make: BMW 335i C.C. 2979

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 95995 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W3A3A92050F0957ff

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Good / Jammed / Leaked / Burnt orBrake: ☒ Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 22R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 23/7/18 D.O.I. 27/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 3 yrs. 10 mths. 7-8

Dep 16 with 20806 wheel bearing damage.

No second hand parts.

13/8/18 Continued final by 9503.68 with AM yay.

(Red 3921.01, 2910) (No LS)

RECEIVED 17 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 14/9- typist

Days Of Repair: 11

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format: CWS

Lump Sum / I.B.I. (\$) 9503.68

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

3x15=45

170+45

50

50+50

112

477



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013638/Uvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3279H	Veh. Inspected	SKF 3099J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005668MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	26/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/07/2018	Inspection Date	27/07/2018	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005668MFSH

Our ref: CS/FCI18013638/Uvd3

DATE: 30/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SKE 3099J


We thank for your instruction on 26/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 27/7/2018 at the premises of M/s SME MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,635.82
Revised Estimate Amount	: S\$7,103.33
"Check" Items Amount	: S\$2,657.74
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	25-07-2018	Our Ref No.	D18005668MFSH
Accident Date	23-07-2018	Claim Type.	Third Party
Insured Vehicle	SHC3279H	Third Party Vehicle.	SKF3099J
Survey Location	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY @ KAKI BUKIT		
Contact Person.	PEIYING		
Contact No.	67476106/ 0	Fax No.	67442368
Survey Type	DIRECT SETTLEMENT: EST. COR - \$12,450.33		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SERENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242701)



PRI Documents



Close



PRI Header Details

Claim No	D18005668MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SME MOTOR PTE LTD
Workshop Name	SME MOTOR PTE LTD (Contact Person : PEIYING)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 BLK D #02-15/16/17/18AUTOBAY (Mobile: 0 , Phone: 67476106 , Fax: 67442368 EmailId: PEIYING@SMEMOTOR.COM.SG)		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$12,450.33		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3279H	TP Vehicle No	SKF3099J
PRI Recieved Date	25-07-2018 07:22:21 PM	Surveyor Appointed Date	26-07-2018 02:32:48 PM	Surveyor Accept Date	26-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 30 July 2018 8:14 AM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005668MFSH/1, SKF 3099J
Attachments: SKF 3099J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKF 3099J
Date of survey: 27/7/2018
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 26 July 2018 4:01 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005668MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 26 July 2018 2:33 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005668MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**2008 Toyota Vios 1.5A E Sports, Renewed C.O.E**

\$0 Down Payment, Low Interest
 Rate From 3.18%! Well
 Maintained With Low Mileage
 StarAd.



Browse by Category ▼

Sort by

1 vehicles

bmw 335

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mil
Search Selection	bmw 335		Any	Any	2012	Any	
	BMW 3 Series 335i		\$98,800	\$17,480 /yr	25-Sep-2012	2,979 cc	
\$0 Down Payment! Monthly \$2122! Flexible Loan With Low Installment Options! Owner Consignment! Includes Lucky Nu Beauty. Maintained At Reputable Workshop By Fussy Lady Owner. Imm...							
Don Motoring							
Posted: 24-Jul-2018 Tags: 2012 BMW 335i, BMW 335i, BMW, 335i, Used BMW							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
------	-------	-------	--------------	----------	---------	------

For old advertisements, view [Expired ads](#)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [For](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, buy used bmw 335, bmw 335 Singapore, used bmw 335 Singapore, used bmw 335, used vehicles Singapore or even buy used bmw 335 Singapore importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle le

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart. that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or wa

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9943A
Vehicle Details	
Vehicle No.:	SKF3099J
Vehicle to be Exported:	No
Intended De-registration Date:	27 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	335I AT 4DR SR ABS HID DSC NAV HUD
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	08798095N55B30A
Chassis No.:	WBA3A92050F095788
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$55,697.00
Original Registration Date:	17 May 2012
First Registration Date:	17 May 2012
Transfer Count:	0
Actual ARF Paid:	\$55,697.00 27 Jul 18
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2022
PARF Rebate Amount:	\$36,203.00
Intended COE Rebate Details	
COE Expiry Date:	16 May 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$92,050.00
COE Rebate Amount:	\$34,991.00
Total Rebate Amount:	\$71,194.00

The information contained herein is correct as at 27 Jul 2018

OK

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

Not Allowed
 hku
 try h/s
 Tok-pho-Att-hu-nyu
 27/7/18
 1/8/18

M/S : FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITY HOUSE
 Singapore 068877
 TEL: 65073848 FAX: 65073849
 ATTN: Motor Claim Department
 Your Ref No: 18/FC/TP-148 (07)
 Claim Type: Third Party
 Accident Date: 23/07/2018
 TP Veh Reg No: SHC3279H

Estimate No: EST0004300
 Date: 25 Jul 2018
 Policy No: 2100338758-05
 Veh Reg No: SKF3099J
 Make/Model: BMW 335I
 Chasis No: WBA3A92050F095788
 Engine No: 08798095N55B30A
 Reg. Date: 17/05/2012

Estimate Repair Cost to Vehicle No :SKF3099J

Description	Quantity	List Price	Amount
		SS	SS
List Price			
1 REAR BOOT <i>306500</i>	1 PC	1,204.80	—
2 REAR BOOT LOGO <i>neu</i>	1 PC	69.50	—
3 REAR BOOT EMBLEM '335I' <i>neu</i>	1 PC	72.55	—
4 REAR BOOT LAMP RH <i>500</i>	1 PC	249.80	—
5 REAR BOOT INNER RUBBER <i>neu</i>	1 PC	82.25	—
6 REAR BUMPER <i>2.5</i>	1 PC	1,100.25	—
7 REAR BUMPER TOW COVER RH <i>neu</i>	1 PC	42.20	—
8 REAR BUMPER REFLECTOR RH <i>500</i>	1 PC	35.20	—
9 REAR BUMPER RETAINER <i>2/5 neu</i>	2 PC	108.60	<i>180.30</i>
10 REVERSE SENSOR RH <i>shid</i>	1 PC	236.85	—
11 REAR UNDER COVER RH <i>11</i>	1 PC	47.25	X
12 REAR LAMP RH <i>300</i>	1 PC	356.90	—
13 REAR REINFORCEMENT <i>neu</i>	1 PC	713.85	—
14 REAR FENDER RH <i>3.500/2uc</i>	1 PC	1,524.65	—
15 REAR DOOR LOCK RH <i>11</i>	1 PC	241.85	X
16 REAR BUMPER CLIP <i>neu</i>	10 PC	30.00	—
17 REAR ABSORBER RH <i>11</i>	1 PC	844.55	X
18 REAR RH STAY ARM <i>11</i>	1 PC	127.90	X
19 REAR LOWER ARM RH <i>11</i>	1 PC	290.60	X
20 REAR KNUCKLE ARM RH <i>11</i>	1 PC	1,066.20	X
21 REAR WHEEL BEARING HUB RH <i>11</i>	1 PC	163.75	X
22 REAR RH TRAILING ARM <i>11</i>	1 PC	104.65	X
23 REAR END PANEL <i>306500</i>	1 PC	592.25	—
		9,306.40	<i>6366.35</i>
	Less 10%	930.64	8,375.82
			<i>76</i>
Special Net			
24 WINDSCREEN GUM <i>neu</i>	1 PC	60.00	<i>40</i>
		60.00	60.00
Labour			
25 WIRE CHECKING	1 UNIT	30.00	✓
26 REMOVE & REFIX REAR WINDSCREEN	1 UNIT	120.00	✓
27 REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	1 UNIT	150.00	<i>180</i>
28 REMOVE & REFIX CUSHION AND SEATS	1 UNIT	180.00	—
29 CAVITY PROTECTION ON ALL AFFECTED AREA	1 UNIT	120.00	<i>80</i>
30 LABOUR CHARGE	1 UNIT	1,500.00	<i>1400</i>
31 SPRAY PAINTING	1 UNIT	1,100.00	<i>1000</i>

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay @ Kaki Bukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-148 (07)

Claim Type: Third Party

Accident Date: 23/07/2018

TP Veh Reg No: SHC3279H

Estimate No: EST0004300

Date: 25 Jul 2018

Policy No: 2100338758-05

Veh Reg No: SKF3099J

Make/Model: BMW 335i

Chasis No: WBA3A92050F095788

Engine No: 08798095N55B30A

Reg. Date: 17/05/2012

Estimate Repair Cost to Vehicle No :SKF3099J

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
		3,200.00	3,200.00
	13,424.63	Total	SS 11,635.82
		Add GST @ 7%	814.51
		Total Amount Payable	SS 12,450.33

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FOUR HUNDRED FIFTY AND CENTS THIRTY THREE ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6830.75
102
6,476.67

3060
5.2296
950368

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay @ Kaki Bukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST: 201119451E RCB NO: 201119451E

M/S : HOW KIEN ANN
 BLK 12 UPPER SERANGOON CRESCENT #08-34
 SINGAPORE 534030

ATTN:
 Your Ref No: 18/FC/TP-148 (07)
 Claim Type: Third Party
 Accident Date: 23/07/2018
 TP Veh Reg No: SHC3279H

Estimate No: **EST0004300**
 Date: 10 Sep 2018
 Policy No: 2100338758-05
 Veh Reg No: **SKF3099J**
 Make/Model: BMW 335i
 Chasis No: WBA3A92050F095788
 Engine No: 08798095N55B30A
 Reg. Date: 17/05/2012

Estimate Repair Cost to Vehicle No :SKF3099J

Description	Quantity	List Price S\$	Amount S\$
<u>Supplementary Parts to Repair</u>			
List Price			
1 REAR BATTERY TERMINAL <i>Daye</i>	1 PC	325.50	✓
2 REAR BUMPER INNER GARNISH CENTRE <i>cm</i>	1 PC	35.75	✓
3 REAR BUMPER UNDER COVER RH <i>cm</i>	1 PC	54.30	✓
4 REAR RH TAIL LAMP SIDE TRIM <i>to in</i>	1 PC	49.85	✓
		465.40	
	Less 10%	46.54	418.87
Special Net			
5 BATTERY (AGM) <i>100</i>	1 PC	320.00	<i>x 80% 256</i>
		<i>256</i> 320.00	320.00
Labour			
6 REMOVE & REFIX REAR RH WIRE HARNESS	1 UNIT	250.00	<i>150</i>
7 REPAIR REAR RH WHEEL HOUSING PANEL AND REAR RH CHASIS	1 UNIT	500.00	<i>11</i> 500.00 <i>x</i>
8 SPRAY REAR RH WHEEL HOUSING PANEL AND REAR RH CHASIS	1 UNIT	300.00	<i>200</i>
		1,050.00	1,050.00
Total			S\$ 1,788.87
GST Amount			S\$ 125.22
Total Amount Payable			S\$ 1,914.09

For SME Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013638/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3279H	Veh. Inspected	SKF 3099J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005668MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	26/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 335i (A)	c.c	2979	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WBA3A92050F095788	Colour	GREY	
Odometer	95995	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 ZR18	MICHELIN	7 mm	
L/H Front Tyre	225/45 ZR18	MICHELIN	7 mm	
R/H Rear Tyre	225/45 ZR18	MICHELIN	7 mm	
L/H Rear Tyre	225/45 ZR18	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/07/2018	Inspection Date	27/07/2018	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 3099J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT	BADLY DENTED	1,204.80	1,204.80
1	REAR BOOT LOGO	NECESSARY	69.50	69.50
1	REAR BOOT EMBLEM "335I"	NECESSARY	72.55	72.55
1	REAR BOOT LAMP RH	BROKEN	249.80	249.80
1	REAR BOOT INNER RUBBER	TWISTED	82.25	82.25
1	REAR BUMPER	DISTORTED	1,100.25	1,100.25
1	REAR BUMPER TOW COVER RH	TWISTED	42.20	42.20
1	REAR BUMPER REFLECTOR RH	BROKEN	35.20	35.20
2	REAR BUMPER RETAINER	O/S CRACKED	108.60	54.30
1	REVERSE SENSOR RH	SHORTED	236.85	236.85
1	REAR UNDER COVER RH	NOT NECESSARY	47.25	-
1	REAR LAMP RH	BROKEN	356.90	356.90
1	REAR REINFORCEMENT	BENT	713.85	713.85
1	REAR FENDER RH	BADLY DENTED / BUCKLED	1,524.65	1,524.65
1	REAR DOOR LOCK RH	NOT NECESSARY	241.85	-
10	REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR ABSORBER RH	NOT NECESSARY	844.55	-
1	REAR RH STAY ARM	NOT NECESSARY	127.90	-
1	REAR LOWER ARM RH	NOT NECESSARY	290.60	-
1	REAR KNUCKLE ARM RH	NOT NECESSARY	1,066.20	-
1	REAR WHEEL BEARING HUB RH	NOT NECESSARY	163.75	-
1	REAR RH TRAILING ARM	NOT NECESSARY	104.65	-
1	REAR END PANEL	BADLY DENTED	592.25	592.25
1	REAR BATTERY TERMINAL (ADDITIONAL)	DAMAGED	325.50	325.50
1	REAR BUMPER INNER GARNISH CENTRE (ADDITIONAL)	CRACKED	35.75	35.75
1	REAR BUMPER UNDER COVER RH (ADDITIONAL)	CRACKED	54.30	54.30
1	REAR RH TAIL LAMP SIDE TRIM (ADDITIONAL)	TORN	49.85	49.85
	LESS 10% DISCOUNT		-977.17	-683.07
			8,794.63	6,147.68



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	WINDSCREEN GUM (SN)	NECESSARY	60.00	40.00
1	BATTERY (AGM)(80%)(SN)(ADDITIONAL)	DENTED	320.00	256.00
			380.00	296.00
	LABOUR			
	WIRE CHECKING.		30.00	30.00
	REMOVE & REFIX REAR WINDSCREEN.		120.00	120.00
	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR. }		150.00	80.00
	REMOVE & REFIX CUSHION AND SEATS. }		180.00	-
	CAVITY PROTECTION ON ALL AFFECTED AREA.		120.00	80.00
	LABOUR CHARGE.		1,500.00	1,400.00
	SPRAY PAINTING.		1,100.00	1,000.00
	REMOVE & REFIX REAR RH WIRE HARNESS (ADDITIONAL).		250.00	150.00
	REPAIR REAR RH WHEEL HOUSING PANEL AND REAR RH CHASIS (ADDITIONAL).	NOT NECESSARY	500.00	-
	SPRAY REAR RH WHEEL HOUSING PANEL AND REAR RH CHASIS (ADDITIONAL).		300.00	200.00
			4,250.00	3,060.00
	GRAND TOTAL		13,424.63	9,503.68
	RECOMMENDED COST OF REPAIRS			9,503.68

Report Ref No. CS/FCI18013638/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.