

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : HOW KIEN ANN
 BLK 12 UPPER SERANGOON CRESCENT #08-34
 SINGAPORE 534030

ATTN:

Your Ref No: 18/FC/TP-148 (07)
 Claim Type: Third Party
 Accident Date: 23/07/2018
 TP Veh Reg No: SHC3279H

Estimate No: EST0004300
Date: 10 Sep 2018
Policy No: 2100338758-05
Veh Reg No: SKF3099J
Make/Model: BMW 335I
Chasis No: WBA3A92050F095788
Engine No: 08798095N55B30A
Reg. Date: 17/05/2012

Estimate Repair Cost to Vehicle No :SKF3099J

Description	Quantity	List Price S\$	Amount S\$
<u>Supplementary Parts to Repair</u>			
List Price			
1 REAR BATTERY TERMINAL <i>Daye</i>	1 PC	325.50	✓
2 REAR BUMPER INNER GARNISH CENTRE <i>one</i>	1 PC	35.75	✓
3 REAR BUMPER UNDER COVER RH <i>one</i>	1 PC	54.30	✓
4 REAR RH TAIL LAMP SIDE TRIM <i>one</i>	1 PC	49.85	✓
		465.40	
	Less 10%	46.54	418.87
Special Net			
5 BATTERY (AGM) <i>100</i>	1 PC	320.00	<i>X 80% 256</i>
		<i>256</i> 320.00	320.00
Labour			
6 REMOVE & REFIX REAR RH WIRE HARNESS	1 UNIT	250.00	<i>150</i>
7 REPAIR REAR RH WHEEL HOUSING PANEL AND REAR RH CHASIS	1 UNIT	500.00	<i>11</i>
8 SPRAY REAR RH WHEEL HOUSING PANEL AND REAR RH CHASIS	1 UNIT	300.00	<i>200</i>
		1,050.00	1,050.00
		Total	S\$ 1,788.87
		GST Amount	S\$ 125.22
		Total Amount Payable	S\$ 1,914.09

For SME Motor Pte Ltd

AUTHORISED SIGNATURE