

2003/2001

ASS. REC. BY:

REF: CS/FCI18013639/Ksd30r

Survivor

CWS

Kenneth

Mary Chua

ASSIGNMENT (Office)

FCI

Date/Time: 25/7/18 @ 5:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 99255

Insured:

SH 8860P

at Workshop m/s

Trans-Carb

Tel:

6287 6666

of

No. 2 AMK 8F-63

Policy No:

Claim No:

D18005629MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A.

22/07/2018

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

9am @ 26/7/18

Person Contacted:

Candy

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 99255-CC3/ASM17015613/Kpb3 DOA: 5/8/17
	SH 8860P-NS/INC11012292/H/y/n DOA: 24/6/2011
27/7/18 @ 17:20 p.m.	revised PA to Mary Chua via email

(08/11/13) wef

ASS. REC. BY:

REF: FCI

## ASSIGNMENT

From: \_\_\_\_\_ Date: 26/7/18

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 99255

at Workshop m/s Trans-cob

of No. 2 AMK St. 63

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S14B 99 255 Yr Regn: 09 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Chevrolet A. Latitude c.c. 1995

Colour: White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 914727 T/Radio: Insured / Std / NI / NA

Eng/No: V11 AB2 15 AUC 273375

C/No: KLLA 69R JBB 109922

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: 7.15/60R16 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 22/7/18

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 26/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17 File pass to Customer  
11 Lp 82450h

(\$ 55,070.14 Red - 96% )

RECEIVED 30 JUL 2018

Date/Time, File Pass to?

30/07/18

1) Typst

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

S + RS, SI

Photos 580

Others

TOTAL

47x15 = 705

170 + 705

50

12

937

Report Format :

Lump Sum / I.B.I. (\$ 2,450.00 L/S )

### MOTOR SURVEY ASSIGNMENT

Date	24-07-2018	Our Ref No. D18005629MFSH
Accident Date	23-07-2018	Claim Type. Third Party
Insured Vehicle	SH8860P	Third Party Vehicle. SHB9925S
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242659)



PRI Documents



Close



PRI Header Details

Claim No	D18005629MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62877764 EmailId: CANDY.KONG@TRASCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8860P	TP Vehicle No	SHB9925S
PRI Recieved Date	24-07-2018 09:20:00 PM	Surveyor Appointed Date	25-07-2018 05:16:42 PM	Surveyor Accept Date	26-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-07-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013639/Ksd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-07-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 8860P		Veh. Inspected	SHB 9925S
Policy No.			Coverage (\$)	0.00
Claim No.	D18005629MFSH		Excess (\$)	0.00
Assign From	CWS (MAY CHUA)		Assign Date	26/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	23/07/2018		Inspection Date	26/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHB9925S
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000385
Chassis No.:	VF1ABL15AUC273375
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	16 Sep 2013
First Registration Date:	16 Sep 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2021
PARF Rebate Amount:	\$9,373.00

**Intended COE Rebate Details**

COE Expiry Date:	15 Sep 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$58,144.00
COE Rebate Amount:	\$22,810.00
<b>Total Rebate Amount:</b>	<b>\$32,183.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Jul 2018

OK

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Friday, 27 July 2018 5:20 PM  
**To:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'  
**Cc:** sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: SURVEY ASSESSMENT - D18005629MFSH/1  
**Attachments:** SHB 9925S - Preli Advise.pdf

Dear May Chua,

Enclosed herewith preliminary advice of SHB 9925S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Thursday, 26 July 2018 9:59 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com  
**Subject:** RE: SURVEY ASSESSMENT - D18005629MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]  
**Sent:** Wednesday, 25 July 2018 5:17 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18005629MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.


Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005629MFSH

Date: 27 July 2018

Our Ref: CS/FCI18013639/Ksd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9925S .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/07/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>57,520.14</u> .
Revised Estimate Amount	: S\$ <u>3,034.34</u> .
"Check" Items Amount	: S\$ <u>                    </u> .
Market Value	: S\$ <u>                    </u> .
LTA Reimbursement Value	: S\$ <u>                    </u> .
Nett Value	: S\$ <u>                    </u> .

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 2 Days

Yours faithfully,  
Kenneth Kong  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/07/2018 10:13
Date Of Accident	22/07/2018 23:55
Exact Location Of Accident	AIRPORT BOULEVARD TOWARDS T1 TAXI STAND
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB9925S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	PHUA KIAM KOK
NRIC No	S1181878A
Date Of Birth	30/07/1955
Occupation	OUTDOOR
Date Of Driving Pass	27/09/1979
Driving Experience	38 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91096251
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 279 TAMPINES STREET 22 #05-224
Postcode	520279
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 22.07.2018 at about 2359hours, I was travelling straight along Airport Boulevard towards T1 taxi stand when vehicle in front of me made a stop so I follow suit. Suddenly I felt an impact. Vehicle B (SH8860P) hit onto my taxi's rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH8860P
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

Airport Boulevard  
 towards TI  
 Taxi Stand

A = SHB 99255  
 B = SH 8860P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach G/A Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9925S****AAD1807-198***Not Notified*  
*1/1 Pnp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHB 9925S**

VF1ABL15AUC273375

RENAULT

LATITUDE

22.7.2018

**FCIL****PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bulind</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Nalwa</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Ry</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95	} X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	
13	1 BOOT REAR	\$	<i>N</i> 2,872.68	
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>na</i> 225.36	
19	1 BOOT BADGE	\$	<i>na</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>N</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>N</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>N</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>N</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

**Trans-cab Auto Services Pte Ltd****AAD1807-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9925S**

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
37	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
39	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21	
45	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	}
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49	
47	1 FUEL FLAP L70Y	\$	<i>Sn</i> 343.57	
48	1 CHASSIS PANEL REAR LH	\$	<i>R</i> 3,766.43	
49	1 WHEEL HOUSING PANEL REAR LH	\$	<i>R</i> 4,682.09	
<b>TOTAL</b>		<b>\$</b>	<b>47,505.69</b>	
<b>10%</b>		<b>\$</b>	<b>4,750.57</b>	
		<b>\$</b>	<b>42,755.12</b>	

**Special Nett**

1	1SET PARKING AID	\$	<i>Sn</i> 700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	<i>—</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	<i>—</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	<i>X</i>
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00	<i>X</i>
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	<i>X</i>
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00	<i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	<i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	<i>—</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	<i>X</i>
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20	<i>X</i>
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd****AAD1807-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 99255**

13	1 BOOT STICKER "6555-3333"	\$	<i>nn</i> 30.00	} X
14	1 BOOT INNER TRIM CLIP	\$	<i>nn</i> 45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i> 35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sh</i> 385.00	
25	1 SPARE TYRE	\$	<i>Sh</i> 330.00	

**TOTAL \$ 2,225.02****TOTAL PARTS \$ 44,980.14****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X



**Trans-cab Auto Services Pte Ltd****AAD1807-198**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9925S**

To transfer of rear end panel fittings, attachment and perform water seepage test. \$ *12* 170.00 X

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. \$ *1* 170.00 X

To supply and re-do rear luggage floor panel insulation padding. \$ *1* 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test. \$ *1* 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test. \$ *1* 170.00 X

To check steering geometry and computer wheel alignment \$ *1* 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test. \$ *1* 380.00 X

**TOTAL \$ 12,540.00***12910***Over All Total \$ 57,520.142****(LUMP SUM)****Repair Days*****20* DAYS***2 days**57900.12*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013639/Ksd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 10-08-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SH 8860P	Veh. Inspected	SHB 9925S	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005629MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	25/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273375	Colour	WHITE / RED	
Odometer	914727	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/07/2018	Inspection Date	26/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9925S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER REAR	BUCKLED / DENTED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	NOT NECESSARY	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/FC118013639/Ksd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
	LESS 10% DISCOUNT		-4,750.57	-265.48
			42,755.10	2,389.34

Report Ref No. CS/FCI18013639/Ksd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	165.00
	<b><u>LABOUR</u></b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00

Report Ref No. CS/FCI18013639/Ksd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, DOOR PANEL REAR LH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, } TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR, EXHAUST CAP REAR, CHASSIS PANEL REAR LH AND WHEEL HOUSING PANEL REAR LH. }		4,200.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			-	-
			-	-
			-	-
			12,920.00	480.00
<b>GRAND TOTAL</b>			<b>57,900.12</b>	<b>3,034.34</b>

Report Ref No. CS/FCI18013639/Ksd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,450.00
---	--	--	----------

Report Ref No. CS/FCI18013639/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.