

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

25-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8029 K

1 pc	Rear o/s door	\$	791.00	DT
2 pcs	Rear o/s door hinges @ \$34.00	\$	68.00	X SVL
		\$	859.00	
		Less 10%	\$	85.90
			\$	773.10
S/NETT				
1 set	o/s door stickers	\$	100.00	acc
1 pc	Rear o/s fender sticker	\$	60.00	acc
	Sundry	\$	50.00	20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50 X
	To dismantle and refit the inner component of rear o/s door into new shell door	\$	150.00	50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door, rear o/s fender, etc.	\$	850.00	360
	To putty and spray painting on front o/s door, rear o/s door, rear o/s fender	\$	600.00	540
	To apply rustproofing on the repaired and replaced panels.	\$	150.00	50
		\$	2,913.10	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

N/AZ LKK
25/7/18 1345
LIS
3 DAYS
AFTER REPAIR PHOTO