

22/03/2002

ASS REC BY:

REF: CS/FCL18013644 / T1sbm Special Instruction:

Surveyor: Tauwhich

ASSIGNMENT (Office)

From (Person): Ms Serene Lee of FCL

Date/Time: 25/07/2018 12:42pm

Estimated Cost: _____ Bill to: _____

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 84133

Insured: SHD 3309A

at Workshop m/s Wearnes

Tel: 6378 9336 / 9818 7517

of 249 Alexandra Rd

Policy No: _____

Claim No: D1800 5503MFSH

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 16/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: 25/07/2018 1:50pm

Person Contacted: Derek

Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SLT 84133 - X
	SHD 3309A - 023 / A174 / 2019351 / H1426521
21/8/18	Revert the email

DCA: 0411012

Tauflich

REF: FC 1

ASSIGNMENT

SLT8413S Yr Regn: 2017 Nov

Front: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Truck / Trailer or _____

Make: Volvo S60 c.c. 1969

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 11429 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 30V1FS40LDJ2455641

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____


Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

Front: 6 mm Rear: 6 mm

R/Bal: _____ mm L/Bal: 6 mm

D.O.A. _____ D.O.I. 6/8/18 @ 130

Survey held at: Weener 249 Mercedes

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

GA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

29/08/18 Confirmed P/P \$10,599.31 @ 4 days with Tauflich.
 (\$7,655.79 Red - 31%)

RECEIVED 29 AUG 2018

Date/Time: File Pass to? : Preli. Report
 29/08/18 : Final Report
 Typist

Date/Time: File Return to? _____

Report Format: _____

Lump Sum / I.B.I. (\$) 10,599.31 P/P

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Weekend (\$)

Survey Fee: _____
 Transportation: _____
 1. Photo: _____
 2. Copy: _____
 Total: _____

5x15: 75
170+ 75
50
50
26
371



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013644/T1sb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3309A	Veh. Inspected	SLT 8413S
Policy No.		Coverage (\$)	0.00
Claim No.	D18005503MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	25/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/07/2018	Inspection Date	06/08/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005503MFSH

Our Ref: CS/FC118013644/T1sb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 8413S .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.08.2018 at the premises of M/s WEARNES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,255.10</u> .
Revised Estimate Amount	: S\$ <u>10,232.70</u> .
"Check" Items Amount	: S\$ <u>2,088.50</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-07-2018	Our Ref No. D18005503MFSH
Accident Date	16-07-2018	Claim Type. Third Party
Insured Vehicle	SHD3309A	Third Party Vehicle. SLT8413S
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	DEREK OH	
Contact No.	63789336/ 98187217	Fax No. 0
Survey Type	DIRECT SETTLEMENT: EST. COR - \$16,322.96	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

✓ leasing

SERVICE ESTIMATE

90218 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte. Ltd. (BILL CUSTOMER) GST Reg.No:M28920628X
 28 Leng Kee Road Inv.No. . : B&P 0 Page 1
 Singapore 159105 Inv.date. : 24/07/2018
 WIP No. . : 17667
 Veh.In/Out: 19/07/2018
 *Tel.No. . : Mobile: 85110235 PEGG
 Reg.No. . : SLT8413S
 Reg.date . : 14/11/2017
 Mileage . : 0
 Chassis No: YV1FS40LDJ2455661

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, ETC	0	3200.00	0		3,200.00	S ¹²⁰⁰ 1600
800	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC	0	1000.00	0		1,000.00	S 700
R06	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00	S X nn
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S ✓
	BUMPER COVER REAR S6	1.0 EA	1428.70			1,428.70	S de ✓ 1285.33
	BUMPER REAR SPOILER	1.0 EA	5614.50			5,614.50	S cut ✓ 5053.05
	BUMPER BRACKET LHR S	1.0 EA	54.30			54.30	S nei ✓ 48.87
	BUMPER BRACKET RHR S	1.0 EA	54.30			54.30	S nei ✓ 48.87
	BUMPER BRACKET CTR R	1.0 EA	88.70			88.70	S nei ✓ 79.83
	BUMPER BRACKET LHR S	1.0 EA	54.30			54.30	S nei ✓ 48.87
	BUMPER BRACKET RHR S	1.0 EA	54.30			54.30	S nei ✓ 48.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party liability is on a "without prejudice" basis
- No alteration of cat. no(s) is allowed
- Supplementary terms must be resurveyed and is subject to final approval of insurance company

Acknowledged by Repairer
 Signature:
 Date:

Taujilah
97495744
wp
6/8/18 @ 1130
Ready before print
4 days
29/7/18
sw @ lkkata.com

SERVICE ESTIMATE

90218 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte. Ltd. (BILL CUSTOMER) GST Reg.No:M28920628X
 28 Leng Kee Road Inv.No. . : B&P 0 Page 2
 Singapore 159105 Inv.date. : 24/07/2018
 WIP No. . : 17667
 Veh.In/Out: 19/07/2018
 *Tel.No. . : Mobile: 85110235 PEGG
 Reg.No. . : SLT8413S
 Closed by : Derek Oh Siong Wee Reg.date. : 14/11/2017
 Svc Consultant : Mileage : 0
 Remarks : Wearnes Automotive P Chassis No: YV1FS40LDJ2455661

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TOW COVER REAR S60 1	1.0 EA	73.90			73.90	S Xnn
	BUMPER RAIL (BEAM) R	1.0 EA	1277.20			1,277.20	S Z 1149.48 BT
	PARK ASSIST REAR SV6	1.0 EA	811.30			811.30	S ? Xnn
	BLIND RIVET 4.0*21MM	10.0 EA	3.00			30.00	S net / 27
	BUMPER CLIP	10.0 EA	4.80	5.40		48.00	S net / 45.72
	PLASTIC RIVET P/W RA	10.0 EA	6.90			69.00	S net / 64.71
	BUMPER INSTALLING MT	1.0 EA	83.40			83.40	S net / 77.82
	NOISE DEADENING PAD	1.0 EA	500.00			500.00	S Xnn
	ADHESIVE TUBE CHEMIC	4.0 EA	75.80			303.20	S net / 271.88

15255.70

		Gross Total.	15,255.10
Labour Total	4,710.00	Net.....	15,255.10
Parts Total	10,545.10	GST @ 7.0%	1,067.86
Package Total	0.00	Total.....	16,322.95
		Paid.....	0.00
		Please Pay..	16,322.95

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1
 Inv.date : 20/08/2018
 WIP No. : 17667
 Veh.In/Out: 06/08/2018 13/08/2018
 *Tel.No. :
 Reg.No. : SLT8413S
 Reg.date : 14/11/2017
 Mileage : 0
 Chassis No: YV1FS40LDJ2455661

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
802	TO REPLACE REAR BUMPER,REAR BRACKET,REAR LOWER SPOILER,REAR SENSOR,ETC	0	1200.00	0		1,200.00 S
800	TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC	0	700.00	0		700.00 S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00 S
	BUMPER COVER REAR S6 ①	1.0 EA	1428.70	10		1,285.83 S
	BUMPER BRACKET LHR S ②	1.0 EA	54.30	10		48.87 S
	BUMPER BRACKET RHR S ③	1.0 EA	54.30	10		48.87 S
	BUMPER BRACKET CTR R ④	1.0 EA	88.70	10		79.83 S
	BUMPER BRACKET LHR S ⑤	1.0 EA	54.30	10		48.87 S
	BUMPER BRACKET RHR S ⑥	1.0 EA	54.30	10		48.87 S
	BLIND RIVET ⑦ *21MM	10.0 EA	3.00	10		27.00 S
	BUMPER CLIP ⑧	10.0 EA	5.40	10		48.60 S
	PLASTIC RIVET P/W RA ⑨	10.0 EA	6.90	10		62.10 S

SERVICE ESTIMATE

0 - F00003
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

SL: FIRST CAPITAL INSURANCE LTD

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2
 Inv.date. : 20/08/2018
 WIP No. . : 17667
 Veh.In/Out: 06/08/2018 13/08/2018
 *Tel.No. . :
 Reg.No. . : SLT8413S
 Reg.date. : 14/11/2017
 Mileage . : 0
 Chassis No: YV1FS40LDJ2455661

Closed by : Richmond Ho
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	ADHESIVE TUBE CHEMI (16)	4.0 EA	75.80	10		272.88	S
	BUMPER RAIL (BEAM) R (9)	1.0 EA	1277.20	10		1,149.48	S
	BUMPER SPOILER REAR (2)	1.0 EA	5614.50	10		5,053.05	S
	BUMPER INSTALLING M (14)	1.0 EA	83.40	10		75.06	S

			Gross Total.	10,599.31
Labour Total	2,350.00		Net.....	10,599.31
Parts Total	8,249.31		GST @ 7.0%	741.95
Package Total	0.00		Total.....	11,341.26
			Paid.....	0.00
			Please Pay..	11,341.26

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Ref : CS/FCI18013644/T1sbn2 Date : 03-09-2018 Code : FCI2
---	---



1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3309A	Veh. Inspected	SLT 8413S
Policy No.		Coverage (\$)	0.00
Claim No.	D18005503MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	25/07/2018

2. Vehicle Particulars & Condition			
Make & Model	VOLVO S60	c.c	1969
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	YV1FS40LDJ2455661	Colour	BLUE
Odometer	11424	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/50 R17	MICHELIN	6 mm
L/H Front Tyre	215/50 R17	MICHELIN	6 mm
R/H Rear Tyre	215/50 R17	MICHELIN	6 mm
L/H Rear Tyre	215/50 R17	MICHELIN	6 mm

4.	Description of Damages
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information	
Accident Date	16/07/2018
Inspection Date	06/08/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935

5a.	Remarks
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8413S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR S6 (SN)	DEFORMED	1,428.70	1,285.83
1	BUMPER REAR SPOILER (SN)	CUT	5,614.50	5,053.05
1	BUMPER BRACKET LHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET RHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET CTR R (SN)	NECESSARY	88.70	79.83
1	BUMPER BRACKET LHR S (SN)	NECESSARY	54.30	48.87
1	BUMPER BRACKET RHR S (SN)	NECESSARY	54.30	48.87
1	TOW COVER REAR S60 1 (SN)	NOT NECESSARY	73.90	-
1	BUMPER RAIL (BEAM) R (SN)	BENT	1,277.20	1,149.48
1	PARK ASSIST REAR SV6 (SN)	NOT NECESSARY	811.30	-
10	BLIND RIVET 4.0*21MM (SN)	NECESSARY	30.00	27.00
10	BUMPER CLIP (SN)	NECESSARY	48.60	48.60
10	PLASTIC RIVET P/W RA (SN)	NECESSARY	69.00	62.10
1	BUMPER INSTALLING MT (SN)	NECESSARY	83.40	75.06
1	NOISE DEADENING PAD (SN)	NOT NECESSARY	500.00	-
4	ADHESIVE TUBE CHEMIC (SN)	NECESSARY	303.20	272.88
			10,545.70	8,249.31
LABOUR				
	TO REPLACE REAR BUMPER, REAR BRACKET, REAR LOWER SPOILER, REAR SENSOR, ETC.		3,200.00	1,200.00
	TO PUTTY SPRAY PAINT ON REAR BUMPER, ETC.		1,000.00	700.00
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.	NOT NECESSARY	60.00	-
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		450.00	450.00
	-		-	-
	-		-	-
	-		-	-
			4,710.00	2,350.00
GRAND TOTAL			15,255.70	10,599.31
RECOMMENDED COST OF REPAIRS				10,599.31

Report Ref No. CS/FCI18013644/T1sbn2



Report Ref No. CS/FCI18013644/T1sbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.