

ASS. REC. BY:

REF: CS/FCI18013645/Klrds n2

Special Instruction:

Surveyor

Khalvin

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

25/7/18 @ 5.05pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 1877P

Insured:

SHA 3937C

at Workshop m/s:

Premier Automotive

Tel:

65446689

of

23 Chungi South Ave 2 #03-02

Policy No:

Claim No:

D18005661MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/07/2018

CA / REV / REP. / REV 24 HRS

'PS'

H.O.D. Endorsement:

Date/Time:

9:15am @ 26/7/18

Person Contacted:

Vincent

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 1877P-CS/MSG17017233/K/bq2

DOA: 4/9/2017

SHA 3937C-C03/FCI14009015/K/bq2

DOA: 13/12/13

27/8/18

Revert the email.

(08/11/13) wef

ASS. REC. BY:

Kahk

REF:

FCI

ASSIGNMENT

From:

Date:

26/7/18

Veh No:

SHD 1877P

Yr Regn:

23 Dec 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 1877P

at Workshop m/s

Premier Automotive

of

23 Changi South Ave 2# 03-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS DS

Vehicle: IN / OUT

Date: Person Contacted:

Truck / Trailer or

Make:

KIA optima

c.c

1685

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

395188

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNA 6M414MF55 6/651

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size:

F:

205/65 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

24/7/18

D.O.I.

26/7/18

Survey held at

Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/9/18

Confirm 1/45 \$2400 / 3 Bp.

Red: \$1962.90, 45%

c/s

RECEIVED 07 SEP 2018

Date/Time, File Pass to?

☐

Preli. Report

1) typist

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / L.B. (\$ 2400)

135

50

50

37

272



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013645/K1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3937C	Veh. Inspected	SHD 1877P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005661MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	26/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/07/2018	Inspection Date	26/07/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Your Ref: D18005661MFSH

Our Ref: CS/FCI18013645/K1rd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1877P .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.07.2018 at the premises of M/s PREMIER AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 4,362.90 .
Revised Estimate Amount	: S\$ 2,231.60 .
"Check" Items Amount	: S\$ 861.30 .
Market Value	: S\$.
LTA Reimbursement Value	: S\$.
Nett Value	: S\$.

Description of Damage:

The vehicle sustained damages
at rear n/s portion.



Yours faithfully
KALVIN ANG
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	25-07-2018	Our Ref No. D18005661MFSH
Accident Date	24-07-2018	Claim Type. Third Party
Insured Vehicle	SHA3937C	Third Party Vehicle. SHD1877P
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242694)



PRI Documents



Close



PRI Header Details

Claim No	D18005661MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : VINCENT CHUA)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446689 , Phone: 62148880 , Fax: 62141511 EmailId: VINCENT.CHUA@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA3937C	TP Vehicle No	SHD1877P
PRI Recieved Date	25-07-2018 04:15:59 PM	Surveyor Appointed Date	25-07-2018 05:04:04 PM	Surveyor Accept Date	26-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	23 Dec 2014 / 09:46:58	Receipt No.:	AACCK001-AX239-141223-000010
Asset Type:	Vehicle	Transaction Amount:	\$64,642.00
Asset ID:	SHD1877P	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20141223094658095320		
Vehicle No.:	SHD1877P		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	23 Dec 2014		
Original Registration Date:	23 Dec 2014		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5561651		
Engine No.:	D4FDEH311930		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$20,238.00		
Minimum PARF Benefit:	\$7,700.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	23 Dec 2014 09:46:58		
COE No.:	2014122301001647W		
COE Expiry Date:	22 Dec 2022		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$51,668.00		
Lifespan Expiry Date:	22 Dec 2022		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

26-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1877 P

<i>Bootlid x repair</i>		
1 pc	Bootlid emblem	\$ 27.00
1 pc	Bootlid CRDi	\$ 29.00
1 pc	Rear bumper	\$ 696.00
1 pc	Rear bumper lower cover	\$ 206.00
2 pcs	Rear bumper side bracket n/s & o/s @ \$29.00	\$ 58.00
1 pc	Rear bumper inner sponge	\$ 114.00
1 pc	Rear bumper reinforcement	\$ 607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$ 36.00
1 pc	Rear bumper o/s reflector @ \$46.00	\$ 46.00
		\$ 1,961.00
Less 10%		\$ 196.10
		\$ 1,764.90

S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ 280.00 <i>200</i>
1 set	Bootlid stickers	\$ 100.00
Sundry		\$ 50.00 <i>20 nec</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ 120.00 <i>20</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ 180.00 <i>X 1</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bootlid, end panel, etc.		\$ 700.00 <i>400</i>
To putty and spray painting on rear bumper, rear bumper lower cover, bootlid, bootlid lower garnish, end panel		\$ 1000.00 <i>500</i>
To apply rustproofing on the repaired and replaced panels.		\$ 120.00 <i>X 1</i>
		\$ 4,362.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are not to be on a "no-haggle" basis
- Third party claims are to be on a "no-haggle" basis
- No illegal practices to be followed
- Supplementary work must be surveyed and is subject to prior approval from insurance company

Acknowledged by Repairer

Date:

Kalini 10/16
26/7/18 100 hrs.
3 Days
4/5
After Repair photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18013645/K1rd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-09-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3937C	Veh. Inspected	SHD 1877P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005661MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	25/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414MF5561651	Colour	SILVER	
Odometer	395188	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/07/2018	Inspection Date	26/07/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1877P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET N/S & O/S @\$29.00	N/S CRACKED / O/S SERVICEABLE	58.00	29.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER N/S & O/S STAY @\$53.00	N/S BENT / O/S SERVICEABLE	106.00	53.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
1	REAR BUMPER O/S REFLECTOR	CUT	46.00	46.00
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-196.10	-187.90
			1,764.90	1,691.10
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			478.00	368.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE BOOTLID,END PANEL,ETC.		700.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER,REAR BUMPER LOWER COVER,BOOTLID,BOOTLID LOWER GARNISH,END PANEL.		1,000.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			2,120.00	960.00
GRAND TOTAL			4,362.90	3,019.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CS/FCI18013645/K1rd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.