

INS210

INS. CASE OWNER:

CC 3/CTI1801 7651, K#6352

LKK:
IDAC:

Surveyor: Fenneth DOI: 27/7/18 Date / Time: 20/7/18
Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No.: S7P 7229J
Name of Insured: KALIMATHAN GANAPATHAN
Insured Tel No.: _____ HP: _____
Excess Sec II :SS _____ D.O.A: 27/7/18
Is driver the owner? (YES / NO) Nature of Accident: _____
If NO, Driver Name / Age: RAVINDRAN KUNJANATHAN
Driver Tel No.: _____ (VL: YES / NO)

Claim No.: SNM180076440R
Policy No.: DMKESN7187361600
Make / Model: 767URE
Place of Accident: YISMAN ST " BIK 778 UP
OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Insured Liability: % Final ? Yes / No



INSRS: _____
WSP: Trans Cab
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
<u>27/7/18</u>	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI: <u>ASHLE 18.5.19</u>	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

No evidence from TP

18.05.1926 CALLED CYDID NO RESPONSE.

10.10.19 FILE PASS TO TYPST TO PREPARE REPORT.

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with: <u>WSP</u> Confirm by: <u>WSP</u>
Repair Cost:	<u>PP SS8,071.61</u> (<u>5</u> days) Reduction: <u>81</u> %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>10.12.19</u> Confirm with: <u>WSP YIM</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u> (Agreed / Assessed) BOLA S/N No.: <u>24</u>	If NO or B 28, Ass. Lia :
Repair Cost:	<u>WSP SS8,636.62</u> <u>OLD EXIT FROM PARKING LOT.</u>	
Loss of Rental (LOR):	SS <u>125.20</u> (<u>7</u> days) x <u>103.60</u>	
Loss of Use (LOU):	SS - (S x days)	
Loss of Income (LOI):	SS <u>350.00</u> (S <u>50</u> x <u>7</u> days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input checked="" type="checkbox"/>	[Tick only one]	
GIA/LTA Search	SS <u>1.49</u>	
Medical:	SS -	1) Claim status: <u>Normal/Reject/Private Settle</u>
Disbursement:	SS - (e.g. Tow/ Independent)	2) Report Format: <u>TP</u>
Legal Cost	SS -	3) Survey fee: <u>400</u>
Total:	SS <u>9,719.31</u> Global Sum SS:	
FINAL PAYMENT	Date/Time: <u>10.12.19</u> Confirm with: <u>WSP YIM</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>9,719.31</u> Name 1: <u>TRANS-CAB AUTO SERVICES PTE LTD</u>	
Payee 2: (Strike if N.A.)	SS Name 2:	
Payee 3: (Strike if N.A.)	SS Name 3:	

Copy sent

ASS. REC. BY:

REF: CT2 /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14D 283J Yr Regn: 02 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude C.C. 1995

Colour: M. White / Blue A/C: Insured / Std / NI / NA

Sp. Reading 303 645 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIAB215AUC 282324

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Grati 215/60R16

Long R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>8</u>	mm	R/Bal. <u>3</u>	mm
L/Bal. <u>8</u>	mm	L/Bal. <u>3</u>	mm
D.O.A. <u>23/7/18</u>		D.O.I. <u>25/7/18</u>	

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>26/7</u>	<u>File pass to Catherine</u>

PP: +8,071.61 (RED: +34,759.89 81%)

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trlp: _____

Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Fuel	
Others	
TOTAL	

Report Format :
Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18013651/Kpb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 26-07-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJP 7229J	Veh. Inspected	SHD 283J
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/07/2018	Inspection Date	25/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 LUBI AVE, L 002-25 PAYA LUBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18013651/Kpb3

Date: 26.07.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD283J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25.07.2018 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>42,831.50</u>
Revised Estimate Amount	: S\$	<u>7,180.39</u>
"Check" Items Amount	: S\$	<u>-</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the
N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 283J

AAD1807-221

Not Authored
Resurvey B4 paint

Vehicle No.:	SHD 283J
Chassis No.:	VF1ABL15AUC282324
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	23.7.2018
Third Party Insurer :	CHINA TAIPING

	PART		LIST	
1	FENDER PANEL FRT LH	\$	R 783.83	X
1	WHEELARCH FRT LH	\$	SL 278.84	X
1	FENDER BRACKET LOWER LH	\$	SL 15.79	X
1	FENDER INSULATOR LH	\$	SL 130.84	X
1	DOOR PANEL FRT LH	\$	R 2,844.66	✓
1	DOOR HINGE UPPER LH	\$	R 261.28	} X
1	DOOR HINGE LOWER LH	\$	R 300.55	
1	DOOR CHECK FRT LH	\$	SL 194.77	
1	DOOR LOCK FRT LH	\$	R 908.75	
1	DOOR CATCH FRT LH	\$	SL 131.23	
1	DOOR HANDLE OUTER FRT LH	\$	SL 477.76	
1	DOOR HANDLE COVER FRT LH	\$	SL 13.22	
1	DOOR HANDLE MODULE FRT LH	\$	SL 133.60	
1	DOOR REGULATOR FRT LH	\$	505.19	X } UN
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46	X } UN
1	DOOR REGULATOR GUIDE FRT LH	\$	SL 120.97	X
1	DOOR PANEL REAR LH	\$	R 2,844.66	✓
1	DOOR GUIDE REAR LH	\$	SL 176.82	X
1	DOOR HINGE UPPER LH	\$	R 274.50	X
1	DOOR HINGE LOWER LH	\$	R 300.55	X
1	DOOR CHECK REAR LH	\$	SL 203.06	X
1	DOOR LOCK REAR LH	\$	R 908.75	X
1	DOOR HANDLE OUTER REAR LH	\$	SL 126.49	X
1	DOOR HANDLE CAP REAR LH	\$	SL 35.52	X
1	DOOR HANDLE SEAL REAR LH	\$	SL 7.89	X
1	DOOR HANDLE COVER REAR LH	\$	SL 13.22	X
1	DOOR HANDLE MODULE REAR LH	\$	SL 133.60	X
1	DOOR REGULATOR REAR LH	\$	1,135.10	X } UN
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75	X
1	DOOR REGULATOR NUT REAR LH	\$	SL 12.43	X

Trans-cab Auto Services Pte Ltd

AAD1807-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 283J

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	Sm 6.31	}
1	DOOR FINISHER REAR LH	\$	Sm 423.10	
1	DOOR MOULDING REAR LH	\$	Sm 176.82	
1	DOOR MOULDING CLIP L70Y	\$	na 5.92	
1	DOOR MOULDING SCREW L70Y	\$	Sm 6.91	
1	DOOR CASING REAR LH	\$	Sm 1,509.06	
1	DOOR WATER SHIELD REAR LH	\$	Sm 30.39	
1	DOOR CASING CLIP	\$	na 12.63	
1	DOOR CASING LIGHT L70Y	\$	Sm 48.74	
1	DOOR FINISHER INNER REAR LH	\$	Sm 323.44	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 46.97	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33	
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33	
1	DOOR GRAB HANDLE REAR LH	\$	Sm 210.96	
1	DOOR BLIND REAR LH	\$	Sm 741.80	
1	DOOR WHEATHESTRIP REAR LH	\$	Sm 410.66	
1	DOOR SEAL REAR LH	\$	Sm 162.02	
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sm 229.31	
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sm 334.69	
1	DOOR WAIST SEAL INNER REAR LH	\$	Sm 115.64	
1	FENDER PANEL REAR LH	\$	n 3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	Sm 671.45	
1	WHEELARCH REAR LH	\$	Sm 543.47	
1	DOOR MIRROR ASSY LH	\$	Sm 1,483.40	
1	ROCKER PANEL INNER GARNISH LH	\$	Sm 466.51	
1	ROCKER PANEL INNER LH	\$	n 1,024.79	
1	ROCKER PANEL INNER LH	\$	na 990.25 ✓	
1	DOOR HARNESS WIRE LH	\$	Sm 2,670.00 ✓	

\$	30,969.44
10% \$	3,096.94
\$	27,872.50

Specical Nett

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00 X

Trans-cab Auto Services Pte Ltd

AAD1807-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 283J

2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60na
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	30na
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60na
1	DOOR CHECK BOLT	\$	na	22.69	} X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
1SET	BUMPER CLIP FRT	\$	na	66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1	TOW COVER FRT	\$	na	14.50	
1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1	FRONT LEFT TYRE	\$	sm	330.00	
1	FRONT LEFT TYRE RIM	\$	sm	380.00	

TOTAL \$ 1,434.63/

TOTAL PARTS \$ 27,941.50

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	7000
Putty and spray painting of the affected portion.	\$	5,000.00	8800
To rust-proofing of the affected areas.	\$	170.00	900

Trans-cab Auto Services Pte Ltd

AAD1807-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 283J

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100%
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20%
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60%
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60%
Towing Fees.	\$	120.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X

TOTAL \$ 14,890.00

Over All Total \$ 42,831.50

PART-BY-PART(REPAIR DAY)

20-DAYS
5 days

44197.11*

...the Repairer... notify the Repairer...

- To resurvey before...
- To display damaged...
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary...

is subject to the... of the insurance company

Acknowledged by Repairer
Signature:
Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD283J
Vehicle to be Exported: Yes
Intended De-registration Date: 24 Jul 2018
Vehicle Make: RENAULT
Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour: Red
Manufacturing Year: 2015
Engine No.: M9R8839C002916
Chassis No.: VF1ABL15AUC282324
Maximum Power Output: 127.0 kW (170 bhp)
Open Market Value: \$19,998.00
Original Registration Date: 04 Feb 2016
First Registration Date: 04 Feb 2016
Transfer Count: 0
Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Feb 2024
PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 03 Feb 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 8
PQP Paid: \$43,040.00
COE Rebate Amount: \$29,737.00
Total Rebate Amount: \$44,735.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Jul 2018.

OK

Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 27 July 2018 9:05 AM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SJP7229J (OI : CTI - SNM18D03644C02) AND SHD283J (TP : LKK REF - CC3/CTI18013651/Kpb3) on 23.07.2018
Attachments: leeSZ_SNM18D03644C01-SJP7229J-LKKDirectSettlementAccidentLtr_CLCR95.886.pdf; MSNH18095623-SJP7229J.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 26 July, 2018 8:16 PM
To: Claims Dept of CTI
Cc: Lucas Lee; Sharon Han; Hsiao Tong (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving SJP7229J (OI : CTI - TBA) AND SHD283J (TP : LKK REF - CC3/CTI18013651/Kpb3) on 23.07.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHD 283J M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D03644/C01/9**

Date : **27 JULY 2018**

via Ordinary & Registered Mail

**KALIMUTHU GHOPINATH
19 SPRINGSIDE CRESCENT**

SINGAPORE 786171

Dear Sir / Madam

**ACCIDENT INVOLVING SJP7229J AND SHD283J ON 23 JULY 2018
ALONG BLK 738 YISHUN ST 11 CARPARK**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHD283J**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : HSHAO TONG
Ref : CC3/CTI18013651/KPB3
Contact No : 67423197
via Email : HSHAO TONG@LKKAUTO.COM

CC : Agent - (AN0582A) - COSMO INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

Hsiao Tong (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 12 November 2018 3:34 PM
To: Hsiao Tong (LKKAuto)
Cc: 'Jasmine Tan'; zhewei.kek@transcab.com.sg; claims@transcab.com.sg
Subject: FW: <Request for Evidence> Your ref: AAD1807-221 (SHD 283J) Our Ref: CC3/CTI18013651/Kpb3 [ACCIDENT INVOLVING SJP 7229J(CHINA TAIPING) & SHD 283J ON 23/07/2018]
Attachments: STATEMENT OF SJP 7229J.pdf

WITHOUT PREJUDICE


Dear Hsiao Tong

At the moment we do not have any video/ photo or PIR for this case.

However we enclosed our driver statement for your investigation.

Circumstances of Accident

ON 23/07/18 AT ABOUT 1355HRS, I WAS TRAVELLING STRAIGHT AT THE CARPARK OF BLK 745, YISHUN ST 72. SUDDENLY VEHICLE B(SJP7229J) CAME OUT OF THE PARKING LOT WITHOUT CHECKING FOR CLEARANCE AND ONTO THE LEFT SIDE PORTION OF MY TAXI.



Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Monday, 12 November, 2018 12:24 PM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (<zhewei.kek@transcab.com.sg>); <zhewei.kek@transcab.com.sg>; <claims@transcab.com.sg>

Subject: <Request for Evidence> Your ref: AAD1807-221 (SHD 283J) Our Ref: CC3/CTI18013651/Kpb3 [ACCIDENT INVOLVING SJP 7229J(CHINA TAIPING) & SHD 283J ON 23/07/2018]

Your ref: **AAD1807-221 (SHD 283J)**
Our Ref: CC3/CTI18013651/Kpb3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SJP 7229J(CHINA TAIPING) & SHD 283J ON 23/07/2018

We refer to the above matter.

Please be informed that our driver strongly disputed liability. He reported that your client hit onto his car while he was parking. Attached here with a copy of our insured driver accident report for your easy reference.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18013651/Keb3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 31-12-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJP 7229J	Veh. Inspected	SHD 283J
Policy No.	DMPCSN3081361600	Coverage (\$)	0.00
Claim No.	SNM18D03644C02	Excess (\$)	0.00
Assign From		Assign Date	25/07/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC282324	Colour	METALLIC WHITE / RED
Odometer	303645	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	LING LONG	3 mm
L/H Rear Tyre	215/60 R16	LING LONG	3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/07/2018	Inspection Date	25/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 283J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT LH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT LH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT LH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT LH	NOT NECESSARY	505.19	-
1	DOOR REGULATOR MOTOR FRT LH	NOT NECESSARY	796.46	-
1	DOOR REGULATOR GUIDE FRT LH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR LH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR LH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH	SERVICEABLE	203.06	-
1	DOOR LOCK REAR LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-

Report Ref No. CC3/CT118013651/Keb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH	NOT NECESSARY	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH	NOT NECESSARY	893.75	-
1	DOOR REGULATOR NUT REAR LH	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	SERVICEABLE	6.91	-
1	DOOR CASING REAR LH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-

Report Ref No. CC3/CTI18013651/Keb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL INNER LH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER LH	BENT	990.25	990.25
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
	LESS 10% DISCOUNT		-3,096.94	-667.96
			27,872.50	6,011.61
	SPECIAL NETT ITEMS			
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CHASSIS' (SN)	NECESSARY	50.00	30.00
1	REAR DOOR STICKER '6555 3333' (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	NOT NECESSARY	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	330.00	-

Report Ref No. CC3/CTI18013651/Keb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
			1,434.61	150.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT LH, DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR LOCK FRT LH, DOOR LOCK REAR LH, DOOR FINISHER BRACKET INNER REAR LH, FENDER PANEL REAR LH AND ROCKER PANEL INNER LH.		6,000.00	700.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,000.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REAR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			14,890.00	1,910.00
GRAND TOTAL			44,197.11	8,071.61

Report Ref No. CC3/CTI18013651/Keb3s2



RECOMMENDED COST OF REPAIRS			8,071.61
-----------------------------	--	--	----------

Report Ref No. CC3/CT118013651/Keb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.