

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHD 283J**

**AAD1807-221**

*Not Notified*  
*Preserving B&Paint*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD 283J**  
 VF1ABL15AUC282324  
 RENAULT  
 LATITUDE  
 23.7.2018  
**CHINA TAIPING**

PART			LIST	
1	FENDER PANEL FRT LH	\$	R 783.83	X
1	WHEELARCH FRT LH	\$	Sm 278.84	X
1	FENDER BRACKET LOWER LH	\$	Sm 15.79	X
1	FENDER INSULATOR LH	\$	Sm 130.84	X
1	DOOR PANEL FRT LH	\$	R 2,844.66	✓
1	DOOR HINGE UPPER LH	\$	R 261.28	} X
1	DOOR HINGE LOWER LH	\$	R 300.55	
1	DOOR CHECK FRT LH	\$	Sm 194.77	
1	DOOR LOCK FRT LH	\$	R 908.75	
1	DOOR CATCH FRT LH	\$	Sm 131.23	
1	DOOR HANDLE OUTER FRT LH	\$	Sm 477.76	
1	DOOR HANDLE COVER FRT LH	\$	Sm 13.22	
1	DOOR HANDLE MODULE FRT LH	\$	Sm 133.60	
1	DOOR REGULATOR FRT LH	\$	505.19	?
1	DOOR REGULATOR MOTOR FRT LH	\$	796.46	?
1	DOOR REGULATOR GUIDE FRT LH	\$	Sm 120.97	X
1	DOOR PANEL REAR LH	\$	R 2,844.66	✓
1	DOOR GUIDE REAR LH	\$	Sm 176.82	X
1	DOOR HINGE UPPER LH	\$	R 274.50	X
1	DOOR HINGE LOWER LH	\$	R 300.55	X
1	DOOR CHECK REAR LH	\$	Sm 203.06	X
1	DOOR LOCK REAR LH	\$	R 908.75	X
1	DOOR HANDLE OUTER REAR LH	\$	Sm 126.49	X
1	DOOR HANDLE CAP REAR LH	\$	Sm 35.52	X
1	DOOR HANDLE SEAL REAR LH	\$	Sm 7.89	X
1	DOOR HANDLE COVER REAR LH	\$	Sm 13.22	X
1	DOOR HANDLE MODULE REAR LH	\$	Sm 133.60	X
1	DOOR REGULATOR REAR LH	\$	1,135.10	?
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75	?
1	DOOR REGULATOR NUT REAR LH	\$	Sm 12.43	X

**Trans-cab Auto Services Pte Ltd**

**AAD1807-221**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 283J**

1	DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$	Su 6.31
1	DOOR FINISHER REAR LH	\$	Su 423.10
1	DOOR MOULDING REAR LH	\$	Su 176.82
1	DOOR MOULDING CLIP L70Y	\$	na 5.92
1	DOOR MOULDING SCREW L70Y	\$	Su 6.91
1	DOOR CASING REAR LH	\$	Su 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	Su 30.39
1	DOOR CASING CLIP	\$	na 12.63
1	DOOR CASING LIGHT L70Y	\$	Su 48.74
1	DOOR FINISHER INNER REAR LH	\$	Su 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33
1	DOOR GRAB HANDLE REAR LH	\$	Su 210.96
1	DOOR BLIND REAR LH	\$	Su 741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	Su 410.66
1	DOOR SEAL REAR LH	\$	Su 162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Su 229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	Su 334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	Su 115.64
1	FENDER PANEL REAR LH	\$	n 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	Su 671.45
1	WHEELARCH REAR LH	\$	Su 543.47
1	DOOR MIRROR ASSY LH	\$	Su 1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	Su 466.51
1	ROCKER PANEL INNER LH	\$	n 1,024.79
1	ROCKER PANEL CENTER LH	\$	n 990.25
1	DOOR HARNESS WIRE LH	\$	Su 2,670.00

X

*Rack panel outer LH ✓*

\$	<b>30,969.44</b>
10% \$	<b>3,096.94</b>
\$	<b>27,872.50</b>

**Specical Nett**

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00 X

**Trans-cab Auto Services Pte Ltd**

AAD1807-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 283J**

2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	80.00
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	30.00
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	80.00
1	DOOR CHECK BOLT	\$	na	22.69	} X
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
1SET	BUMPER CLIP FRT	\$	na	66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1	TOW COVER FRT	\$	na	14.50	
1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1	FRONT LEFT TYRE	\$	sm	330.00	
1	FRONT LEFT TYRE RIM	\$	sm	380.00	

**TOTAL \$ 1,434.63**

**TOTAL PARTS \$ 27,941.50**

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	7000
Putty and spray painting of the affected portion.	\$	5,000.00	8000
To rust-proofing of the affected areas.	\$	170.00	900

**Trans-cab Auto Services Pte Ltd**

**AAD1807-221**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 283J**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100%
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	↳ X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	↳ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	↳ X
To Check Electrical Lighting Concerned.	\$	170.00	20%
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60%
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60%
Towing Fees.	\$	120.00	nn X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	nn X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X

**TOTAL \$ 14,890.00**

**Over All Total \$ 42,831.50**

**PART-BY-PART (REPAIR DAY)**

**20-DAYS**  
*5 days*

the Repairer must be notified in writing  
 • To resurvey before painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary fees must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: