

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

| | | | |
|---------------------------------|---------------------|----------|--------------------------|
| TO | : CHINA TAIPING | DATE | : 24/07/2018 |
| ATTENTION | : MOTOR CLAIMS DEPT | JOB TYPE | : T/P CLAIM |
| ESTIMATE REPORT | : | | |
| <u>VEHICLE DETAILS</u> | | | |
| VEHICLE NO | : SGG9981P | | |
| MODEL | : HONDA ACCORD 2.0A | | <i>Thin Thin</i> |
| CHASSIS NO | | | <i>MRHCR1630EP000072</i> |
| <u>ACCIDENT DETAILS</u> | | DATE | : 21-Jul-18 |
| | | TIME | : 14:45HRS |
| THIRD PARTY REQUESTOR / CONTACT | : JACK LI | | |

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---|-----|-----------------|----------------------------------|
| 1 | REAR BUMPER <i>torn</i> | 1 | \$ 1,050.00 | \$ <u>1,050.00</u> <i>680.50</i> |
| 2 | REAR BUMPER SIDE RETAINER <i>new RH</i> | 2 | \$ 55.00 | \$ 110.00 <i>55.</i> |
| 3 | REAR FENDER <i>Distorted.</i> | 1 | \$ 1,711.60 | \$ <u>1,711.60</u> <i>1119.</i> |
| 4 | REAR FENDER MUDFLAP <i>torn</i> | 1 | \$ 113.70 | \$ 113.70 <i>-</i> |
| 5 | REAR FENDER AIR VENT <i>new</i> | 2 | \$ 62.00 | \$ 124.00 <i>+</i> |
| 6 | REAR WINDSCREEN MOULDING <i>new</i> | 1 | \$ 211.40 | \$ 211.40 <i>-</i> |
| 7 | REAR LOWER ARM (FRONT) <i>new</i> | 1 | \$ 456.50 | \$ 456.50 <i>+</i> |
| 8 | REAR LOWER ARM (REAR) <i>new</i> | 1 | \$ 362.50 | \$ 362.50 <i>+</i> |
| 9 | REAR UPPER ARM | 1 | \$ 382.50 | \$ 382.50 <i>+</i> |
| 10 | REAR KNUCKLE ARM <i>new</i> | 1 | \$ 388.90 | \$ 388.90 <i>+</i> |
| 11 | REAR KNUCKLE ARM BEARING <i>new</i> | 1 | \$ 215.60 | \$ 215.60 <i>+</i> |
| 12 | REAR WHEEL HUP <i>new</i> | 1 | \$ 224.50 | \$ 224.50 <i>+</i> |
| 13 | REAR SHOCK ABSORBER <i>new</i> | 1 | \$ 374.50 | \$ 374.50 <i>+</i> |

3008.60

TOTAL PRICE \$ 5,725.70

2406.88

LESS 20% \$ 1,145.14

SUB TOTAL PRICE \$ 4,580.56

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|------------------------------------|-----|-------------|---------------------|
| 1 | REAR BUMPER CLIP(SET) <i>new</i> | 1 | \$ 25.00 | \$ 25.00 <i>-</i> |
| 2 | REAR WINDSCREEN SEALANT <i>new</i> | 1 | \$ 80.00 | \$ 80.00 <i>60.</i> |

535

| | | | | | |
|---|-----------------------------|---|--------------|--------------------|------|
| 3 | REAR WHEEL TYRE <i>Alca</i> | 1 | \$ 650.00 | \$ 650.00 | X |
| 4 | REAR WHEEL RIM <i>Lit</i> | 1 | \$ 1,200.00 | \$ 1,200.00 | 450. |
| | | | TOTAL | \$ 1,955.00 | |

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

| | | | | |
|---|--|------------------------|------|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$1,400.00 | 500 | |
| 2 | TO SPRAY PAINT AFFECTED AREA | \$ 1,000.00 | 400. | |
| 3 | TUFF COAT | \$ 250.00 | 40 | |
| 4 | WIRING CHECK | \$ 60.00 | 30 | |
| 5 | CONDUCT WATER LEAKAGE TEST | \$ 80.00 | X | |
| 6 | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | \$ 120.00 | 50 | |
| 7 | REMOVE AND REFIX REAR UNDERCARRIAGE | \$ 350.00 | 150 | |
| 8 | FOUR WHEEL ALIGNMENT | \$ 100.00 | 80 | |
| 9 | REMOVE AND REFIX REAR WINNSCREEN | \$ 100.00 | ✓ | |

TOTAL

\$3,460.00

1350

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,535.56
 TOTAL LABOUR COST : \$ 3,460.00
 TOTAL REPAIR COST : \$ 9,995.56

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

*Adrian King,
 r/s 24/07/18.*

total: 4291.88

r/s: 31/11

05 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: