

INSURANCE

INS. CASE OWNER:

CC 6/CTI.1801 7654, A 66302 | LKK IDAC:

Surveyor:

Adnan

DOI:

ASSIGNMENT

21/7/18

Date / Time:

21/7/18

Registered in Meritmen:

Pre-assign / CCU / FTE

WC 6539K



Insured Vehicle No.:

Claim No.:

SWM18D1768400 ✓

Name of Insured:

GARY ENGINEERING P/L

Policy No.:

DMCHEN1759801700

Insured Tel No.:

HP:

Make / Model:

Subaru

Excess Sec II :SS

D.O.A.:

21/7/18

Place of Accident:

SHEPPARS AVE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

THANIKRASAN VJAYALAKSHMI

LOI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

* Final ? Yes / No

599 9981P



INSRS: WSP: Tel: Liability: RMKS:

MG Solution



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
21/8/18	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call Of	
	After call Itr to OE	22/08/19-VIC
22/08/19	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OE	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA/GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

PRELIMINARY ADVICE Date/Time: 01/07/19 Sent By: JOY

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: 45 \$5 3,400.00 (5 days) Reduction: 66 % Email Call

FINAL SETTLEMENT Date/Time: 10/11/19 Confirm with: SU WONG Email Call

Final Liability: % 100 (Assessed) BOLA S/N No.: NIL

Repair Cost: (w/loss) \$5 3,638.00

Loss of Rental (LOR): \$5 - (days) TP VIDEO IN. OLD BUCKETHEAD

Loss of Use (LOU): \$5 400.00 (5 days) CHAIR

Loss of Income (LOI): \$5 - (x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$5 7.45

Medical: \$5 -

Disbursement: \$5 - (e.g. Trav/Independent)

Legal Cost: \$5 -

Total: \$5 4,045.45 Global Sum \$5: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$5 4,045.45 Name 1: MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.) \$5 - Name 2: -

Payee 3: (Strike if N.A.) \$5 - Name 3: -

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SG69981P Yr Regn: 2015 August
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Honda Accord cc 1997
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 90195 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: MRHCR1630EPO00072
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50R17

R: 225/50R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

/	
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

Front Rear
 R/Bal: 06 mm R/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A. _____ D.O.I. 24/07/18

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Survey held at: MG Solution
 Des. of Damages: Frt / Rear O/S / N/S / UIC / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP done</u>
	<u>LIG \$3,400.00</u>
	<u>CRSD: \$6,595.56 (66%)</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Insp (\$) _____
 Weekend (\$) _____

Survey Fee:	<input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/>
Transportation:	
S + RD: \$	
Folio:	
Other:	
TOTAL	<input type="text"/>

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 24/07/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGG9981P		
MODEL	: HONDA ACCORD 2.0A		<i>Thin Thin</i>
CHASSIS NO			<i>MRHCR1630EP000J2</i>
<u>ACCIDENT DETAILS</u>		DATE	: 21-Jul-18
		TIME	: 14:45HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>tozn</i>	1	\$ 1,050.00	\$ 1,050.00 <i>630.50</i>
2	REAR BUMPER SIDE RETAINER <i>new RH</i>	2	\$ 55.00	\$ 110.00 <i>55.</i>
3	REAR FENDER <i>Distorted</i>	1	\$ 1,711.60	\$ 1,711.60 <i>1119.</i>
4	REAR FENDER MUDFLAP <i>tozn</i>	1	\$ 113.70	\$ 113.70
5	REAR FENDER AIR VENT <i>new</i>	2	\$ 62.00	\$ 124.00
6	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 211.40	\$ 211.40
7	REAR LOWER ARM (FRONT) <i>new</i>	1	\$ 456.50	\$ 456.50
8	REAR LOWER ARM (REAR) <i>new</i>	1	\$ 362.50	\$ 362.50
9	REAR UPPER ARM	1	\$ 382.50	\$ 382.50
10	REAR KNUCKLE ARM <i>new</i>	1	\$ 388.90	\$ 388.90
11	REAR KNUCKLE ARM BEARING <i>new</i>	1	\$ 215.60	\$ 215.60
12	REAR WHEEL HUP <i>new</i>	1	\$ 224.50	\$ 224.50
13	REAR SHOCK ABSORBER <i>new</i>	1	\$ 374.50	\$ 374.50

3008.60 TOTAL PRICE \$ 5,725.70
2406.88 LESS 20% \$ 1,145.14
SUB TOTAL PRICE \$ 4,580.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 25.00	\$ 25.00
2	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>60.</i>

535

3	REAR WHEEL TYRE <i>162 or</i>	1	\$ 650.00	\$ 650.00	*
4	REAR WHEEL RIM <i>162</i>	1	\$ 1,200.00	\$ 1,200.00	450.
TOTAL				\$ 1,955.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,400.00	500	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 60.00	30	
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	
7	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 350.00	150	
8	FOUR WHEEL ALIGNMENT	\$ 100.00	80	
9	REMOVE AND REFIX REAR WINNSCREEN	\$ 100.00	✓	

TOTAL

\$3,460.00

1350

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,535.56
 TOTAL LABOUR COST : \$ 3,460.00
 TOTAL REPAIR COST : \$ 9,995.56

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

*Adrian King,
 L/S 24/07/18.*

total: 4291.88

*L/S: 314K
 05 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TEO HIN TYRES

11 KAKI BUKIT ROAD 1
 #01-01 EUNOS TECHNOLINK
 SINGAPORE 415939
 TEL:67455711

Work Order: R002964
 Company: MG SOLUTION
 License: SGG 9981 P
 Date: 24.7.18 10:39

Honda : Accord/Vigor : 2008-16 : Rest of World : with 17" Wheel

Front : Left

Actual	Before	Specified Range
-0°28'		-0°30' 0°30'
4°07'		2°54' 3°57'
0°29'		-0°05' 0°05'
11°28'		
11°00'		

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°47'		-0°30' 0°30'
4°08'		2°54' 3°57'
-0°25'		-0°05' 0°05'
8°45'		
7°58'		

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°18'		-0°30' 0°30'
-0°01'		-0°30' 0°30'
2°43'		
0°04'		-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-1°07'		-1°30' -0°30'
0°09'		0°00' 0°09'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-3°05'		-1°30' -0°30'
1°49'		0°00' 0°09'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
1°58'		-0°30' 0°30'
1°58'		0°00' 0°19'
-0°50'		

Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Tuesday, 21 August 2018 4:16 PM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving WC6539K (OI : CTI - SNM18D03684C02) and SGG9981P (TP : LKK REF - CC6/CTI18013654/Aub3) on 21.07.2018
Attachments: MJAS18103729-WC6539K.pdf

Dear Shu Pei,

As per requested, kindly refer to the attachment.

Lucas Lee

Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]
Sent: Tuesday, 21 August, 2018 11:53 AM
To: Lucas Lee
Subject: RE: Direct Settlement - Accident Involving WC6539K (OI : CTI - SNM18D03684C02) and SGG9981P (TP : LKK REF - CC6/CTI18013654/Aub3) on 21.07.2018

WITHOUT PREJUDICE

Dear Lucas,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>

Sent: Friday, 27 July 2018 11:32 AM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving WC6539K (OI : CTI - SNM18D03684C02) and SGG9981P (TP : LKK REF - CC6/CTI18013654/Aub3) on 21.07.2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Thursday, 26 July, 2018 8:10 PM

To: Claims Dept of CTI

Cc: Sharon Han; Angie Foo; Admin A; Thin Thin (LKKAuto)

Subject: Direct Settlement - Accident Involving WC6539K (OI : CTI - TBA) and SGG9981P (TP : LKK REF - CC6/CTI18013654/Aub3) on 21.07.2018

WITHOUT PREJUDICE

Dear Sharon,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SGG 9981P at M/s MG Solution Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Our Reference: **SNM18D03684/C01/9**

Date : **27 JULY 2018**

via Ordinary & Registered Mail

**SAAY ENGINEERING PTE LTD
570 CHOA CHU KANG STREET 52
#09-236 LIMBANG GREEN
SINGAPORE 680570**

Dear Sir / Madam

**ACCIDENT INVOLVING WC6539K AND SGG9981P ON 21 JULY 2018
ALONG SHEARER AVE TOWARDS ECP**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SGG9981P**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us **IMMEDIATELY** through **LKK Auto Consultants Pte Ltd** or any of **our authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your **NO CLAIM DISCOUNT** will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : THIN THIN
Ref : CC6/CT118013654/AUB3
Contact No : 68412360
via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0420A) - INXPRESS INSURANCE AGENCY PTE LTD

MG SOLUTION PTE LTD
23 Kaki Bukit Ave 4 (South Wing) #02-03B
Vicom Inspection Centre, Singapore 415933
Tel: 6243 1373 Fax: 6243 1376
GST Reg. No. : 201427944N

MOTOR CLAIM DISCHARGE

INSURED: FOON SAH MUN
CAR/ LORRY/CYCLE: REG NO: SGG 9981P POLICY NO:
ACCIDENT CLAIM NO:

I / We confirm that I / we have taken delivery of Car / Lorry / Motor Cycle

Registered No. SGG 9981Pfrom the repairers,
Messrs MG SOLUTION PTE LTD

And that all repairs necessary as a result of an accident in which the said vehicle was involved on or
about the 21 day of 07 2018 have been completed to my / our satisfaction, and that

I / we have no further claim on the above company in Respect thereof.

Date: Signature: [Signature]

Co's Stamp: NRIC No:

24/7/2018 - PR1

vehicle In - 24/7/2018

vehicle out - 28/7/2018

LOU - 5 days x \$ 250

= \$ 1,250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CT118013654/Ahb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 03-12-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	WC 6539K	Veh. Inspected	SGG 9981P
Policy No.	DMCVSN1759801700	Coverage (\$)	0.00
Claim No.	SNM18D03684C02/9	Excess (\$)	0.00
Assign From		Assign Date	24/07/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA ACCORD	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHCR1630EP000072	Colour	GREY
Odometer	90195	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/07/2018	Inspection Date	24/07/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 9981P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TORN	1,050.00	680.50
2	REAR BUMPER SIDE RETAINER @\$55.00	O/S NECESSARY	110.00	55.00
1	REAR FENDER	DISTORTED	1,711.60	1,119.00
1	REAR FENDER MUDFLAP	TORN	113.70	113.70
2	REAR FENDER AIR VENT @\$62.00	NOT NECESSARY	124.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	211.40	211.40
1	REAR LOWER ARM (FRONT)	NOT NECESSARY	456.50	-
1	REAR LOWER ARM (REAR)	NOT NECESSARY	362.50	-
1	REAR UPPER ARM	NOT NECESSARY	382.50	-
1	REAR KNUCKLE ARM	DAMAGED	388.90	388.90
1	REAR KNUCKLE ARM BEARING	NECESSARY	215.60	215.60
1	REAR WHEEL HUP	DAMAGED	224.50	224.50
1	REAR SHOCK ABSORBER	NOT NECESSARY	374.50	-
	LESS 20% DISCOUNT		-1,145.14	-601.72
			4,580.56	2,406.88
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR WHEEL TYRE (SN)	NOT NECESSARY	650.00	-
1	REAR WHEEL RIM (SN)	CUT	1,200.00	450.00
			1,955.00	535.00
LABOUR				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.		1,400.00	500.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	400.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		60.00	30.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	80.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISMANTLE SETTING.		120.00	50.00
	REMOVE AND REFIX REAR UNDERCARRIAGE.		350.00	150.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	FOUR WHEEL ALIGNMENT.		100.00	80.00
	REMOVE AND REFIX REAR WINDSCREEN.		100.00	100.00
			3,460.00	1,350.00
GRAND TOTAL			9,995.56	4,291.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC6/CTI18013654/Ahb3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.