

15/2/11

INS. CASE OWNER:

CC 3 / CTI1801

7657, G 46302

LKK:

IDAC:

Surveyor:

XGR

DOI:

ASSIGNMENT

24/7/18

Date / Time:

24/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

G6F 5865H

Name of Insured:

T &amp; Q Terdim

Insured Tel No.:

HP:

Excess Sec II:SS

D.O.A:

24/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

VEE YEW LAM

Driver Tel No.:

9164777

(V/L: YES / NO)

Claim No.:

SNM1801161210 ✓

Policy No.:

DMLVSN 3027361802

Make / Model:

TUYOCH

Place of Accident:

MUK KAW K.

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO:

Insured Liability:

Final? Yes / No

SHA 4013B

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:code  
mINSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

21/7/18  
TH

SHA 4013B - X

G6F 5865H - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

24/7/18 - WLC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

☐☐☒☐☒☐☒☐☒☐☒☐☐☐☒☐☐☐☐☐☒☐☒☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐

PRELIMINARY ADVICE

Date/Time: 24/7/18

Sent By: TLL

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

46

S\$ 5,900.00 (6 days) Reduction:

15

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time: 26/12/18

Confirm with:

WILLIAM

Email ☐Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

(w/46)

S\$ 6,313.00

Loss of Rental (LOR):

S\$

996.88 (8.5 days) x \$117.28

Loss of Use (LOU):

S\$

415.00 x 8.5 days

Loss of Income (LOI):

S\$

— (5 x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$

7.19

Medical:

S\$

—

Disbursement:

S\$

—

(e.g. Tow/ Independent)

Legal Cost

S\$

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4400.00

Total:

S\$

7,742.57

Global Sum S\$:

7,740.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

7,740.00

Name 1:

COMPTON ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

—

Name 2:

—

Payee 3: (Strike if N.A.)

S\$

—

Name 3:

—

OLD CHANGING TIME  
COPY SENT  
21/1/19

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHA 4017B

Yr Regn:

18 Feb 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai i40

G.G.

1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

565869

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMR/LB41UMC-4047605

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Air / S/Rim / STD Air / Rim or

Tyre Size:

F:

205/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24-07-18

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

46

\$5,900.00

Chgs: \$4,833.16 (45%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                          |  |                            |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|--|----------------------------|-------------------------------------------------------------------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                          |  | Ref : CC3/CTI18013657/Gub3 |                                                                                     |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                          |  | Date : 26-07-2018          |  |
|                                                                                                                                           |                                                                          |  | Code : CTI                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                          |  |                            |                                                                                     |
| Insured Veh.                                                                                                                              | GBF 5865H                                                                |  | Veh. Inspected             | SHA 4017B                                                                           |
| Policy No.                                                                                                                                |                                                                          |  | Coverage (\$)              | 0.00                                                                                |
| Claim No.                                                                                                                                 |                                                                          |  | Excess (\$)                | 0.00                                                                                |
| Assign From                                                                                                                               |                                                                          |  | Assign Date                | 26/07/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                          |  |                            |                                                                                     |
| Make & Model                                                                                                                              |                                                                          |  | c.c                        | 0                                                                                   |
| Engine No.                                                                                                                                | HIDDEN                                                                   |  | Year of Reg.               |                                                                                     |
| Chassis No.                                                                                                                               |                                                                          |  | Colour                     |                                                                                     |
| Odometer                                                                                                                                  | -                                                                        |  | Steering                   |                                                                                     |
| Brakes                                                                                                                                    |                                                                          |  | Modification               |                                                                                     |
| General                                                                                                                                   |                                                                          |  |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                          |  |                            |                                                                                     |
|                                                                                                                                           | Size                                                                     |  | Make                       | Balance                                                                             |
| R/H Front Tyre                                                                                                                            |                                                                          |  |                            | mm                                                                                  |
| L/H Front Tyre                                                                                                                            |                                                                          |  |                            | mm                                                                                  |
| R/H Rear Tyre                                                                                                                             |                                                                          |  |                            | mm                                                                                  |
| L/H Rear Tyre                                                                                                                             |                                                                          |  |                            | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                          |  |                            |                                                                                     |
|                                                                                                                                           |                                                                          |  |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                          |  |                            |                                                                                     |
| Accident Date                                                                                                                             | 22/07/2018                                                               |  | Inspection Date            | 24/07/2018                                                                          |
| Survey held at                                                                                                                            | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |  |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                          |  |                            |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |  |                            |                                                                                     |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/CTI18013657/Gub3

Date: 26.07.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHA4017B**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.07.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

|                          |       |           |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 10,733.16 |
| Revised Estimate Amount  | : S\$ | 7,444.92  |
| "Check" Items Amount     | : S\$ | -         |
| Market Value             | : S\$ | -         |
| LTA Reimbursement Value  | : S\$ | -         |
| Nett Value               | : S\$ | -         |

**Description of Damage:**

The vehicle sustained damages at the  
N/S Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

XING GUO QIANG  
Licensed Appraiser

## COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHA 4017B

MAKE :

MODEL : HYUNDAI SONATA

DATE 24/7/2018 10:33

the Repairer of the following:

- To resurvey the car after spray painting
- To display damaged part(s) during resurvey

| Qty | Parts Description/ Labour              | Type | Unit Price | Amount              |
|-----|----------------------------------------|------|------------|---------------------|
|     | Rear Bumper                            |      |            | \$ 578.40           |
|     | Rear Bumper Clip                       |      |            | \$ 22.00            |
|     | Rear Fender (LH)                       |      |            | \$ 1,935.90         |
|     | Rear Fender Inner Lining (LH)          |      |            | \$ 74.10            |
|     | Rear Windscreen Moulding               |      |            | \$ 60.00            |
|     | Rear Door (LH)                         |      |            | \$ 1,294.70         |
|     | Front Door (LH)                        |      |            | \$ 1,344.50         |
|     | Front Door Mirror (LH)                 |      |            | \$ 545.50           |
|     | Frt & Rear Tyre Rim (LH)               | \$   | 284.70     | \$ 569.40           |
|     | Frt & Rear Wheel Hup-Cap (LH)          | \$   | 145.00     | \$ 290.00           |
|     | Front Fender (LH)                      |      |            | \$ 593.10           |
|     | Front Fender Shield (LH)               |      |            | \$ 86.00            |
|     | Front Bumper Cover                     |      |            | \$ 538.80           |
|     | Front Bumper Bracket Top (LH)          |      |            | \$ 22.40            |
|     | Headlamp (LH)                          |      |            | \$ 797.90           |
|     | <b>SUB TOTAL</b>                       |      |            | <b>\$ 8,752.70</b>  |
|     | <b>LESS 20%</b>                        |      |            | <b>\$ 1,750.54</b>  |
|     | <b>DISCOUNTED TOTAL</b>                |      |            | <b>\$ 7,002.16</b>  |
|     | Rear Bumper Rubber Mat                 |      |            | \$ 50.00            |
|     | Rear Fender Advertisement Logo (LH)    |      |            | \$ 100.00           |
|     | Rear Windscreen Sealant                |      |            | \$ 46.00            |
|     | Rear Door Tel No. Sticker (LH)         |      |            | \$ 10.00            |
|     | Front Door Coloured Comfort Logo (LH)  |      |            | \$ 75.00            |
|     | Front Door Advertisement Logo (LH)     |      |            | \$ 100.00           |
|     | Front Fender Advertisement Logo (LH)   |      |            | \$ 100.00           |
|     |                                        |      |            | <b>\$ 481.00</b>    |
|     | <b>Labour Charge</b>                   |      |            |                     |
|     | Panel Beating                          |      |            | \$ 1,200.00         |
|     | Spray Painting Charge                  |      |            | \$ 1,200.00         |
|     | Wiring Charge                          |      |            | \$ 50.00            |
|     | Tuff Kote                              |      |            | \$ 50.00            |
|     | Remove/Refix Cushion & Upholstery Rear |      |            | \$ 150.00           |
|     | Remove/Refix Rear Windscreen Glass     |      |            | \$ 120.00           |
|     | Remove/Refix Reverse Sensor            |      |            | \$ 120.00           |
|     | Transfer of Door                       | \$   | 120.00     | \$ 240.00           |
|     | Four Wheel Alignment                   |      |            | \$ 120.00           |
|     | <b>TOTAL LABOUR</b>                    |      |            | <b>\$ 3,250.00</b>  |
|     | <b>ESTIMATE TOTAL</b>                  |      |            | <b>\$ 10,733.16</b> |


This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Team: IN ARC Repair TP(CLSO)1  
STOMER  
COMFORT TRANSPORTATION PTE LTD  
7010045  
383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755  
(R)  
(P)  
COUNT CARD NO.

JOB CARD  
Sales Order:  
JC NO.: 305191358  
REGN NO.: SHC3716M  
MAKE: HYUNDAI  
MODEL: SONATA  
YR OF MANU: 30.07.2011  
CHASSIS CODE: KMHET41VMBA815127  
MILEAGE  
FUEL: E.....1/2.....F  
DATE/TIME IN: 23.07.2018 12:55  
TARGET DATE  
COMPLETION DATE/TIME:

Accident Date: 23.07.2018  
NATURE: 3P 23.07.2018

S/NO LABOR CODE  
AIG - Right Front  
LKK/



CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Acknowledgement Slip  
Vehicle No.: SHC3716M  
LARRY  
Signature/Date  
Name of Service Advisor  
Date  
To be kept by Security Guard



# COMFORTDELGRO ENGINEERING

Our Job Ref No . 305191233

Date : 2. Aug. 2018

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHA4017B

Date of Accident: 22. Jul. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA GBF5865H

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$5,900.00

3. Estimated normal period for repairs: 6 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Guo Qiang

Name : Guo Qiang

Date : 10/9/18

## For Official Use Only

| Item                                                 | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|--------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |        | YES                         |                        |         |
| 2. Loss of Income Paid                               |        |                             |                        |         |
| 3. Survey Fees                                       |        |                             |                        |         |
| 4. LTA Search Fee                                    |        |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |        |                             |                        |         |
| 6. Overrun                                           |        |                             |                        |         |

Remarks:

## Shu Pei (LKKAUTO)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Friday, 27 July 2018 11:52 AM  
**To:** Shu Pei (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving GBF5865H (OI : CTI - SNM18D03622C02) and SHA4017B (TP : LKK REF - CC3/CTI18013657/Gub3) on 22.07.2018  
**Attachments:** leeSZ\_SNM18D03622C01-GBF5865H-LKKDirectSettlementAccidentLtr\_CLCR95.788.pdf; MLHM18094618-GBF5865H.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

**Lucas Lee**  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175/6224 7478  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Thursday, 26 July, 2018 8:01 PM  
**To:** Claims Dept of CTI  
**Cc:** Angie Foo; Elaine Cheong; Admin A; Thin Thin (LKKAUTO)  
**Subject:** Direct Settlement - Accident Involving GBF5865H (OI : CTI - TBA) and SHA4017B (TP : LKK REF - CC3/CTI18013657/Gub3) on 22.07.2018

**WITHOUT PREJUDICE**

Dear Elaine,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHA 4017B at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Co. Reg. No. 200208384E

Our Reference: **SNM18D03622/C01/5**

Date : **27 JULY 2018**

via Ordinary & Registered Mail

**T & Q TRADING  
BLK 313A SUMANG LINK  
#16-103 PUNGGOL PARCVISTA  
SINGAPORE 821313**

Dear Sir / Madam

**ACCIDENT INVOLVING GBF5865H AND SHA4017B ON 22 JULY 2018  
ALONG MACKARROW ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHA4017B**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC3/CTI18013657/GUB3

Contact No : 68412360

via Email : THINTHIN@LKKAUTO.COM

CC : Agent - (AN0397A) - INDEX AGENCY PTE LTD

F01/LKKDS-2013



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18013657/Ghb3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-01-2019



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | GBF 5865H        | Veh. Inspected | SHA 4017B  |
| Policy No.   | DMCVSN3039361800 | Coverage (\$)  | 0.00       |
| Claim No.    | SNM18D03622C02/5 | Excess (\$)    | 0.00       |
| Assign From  |                  | Assign Date    | 24/07/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | HYUNDAI I40       | c.c          | 1685     |
| Engine No.   | HIDDEN            | Year of Reg. | 2014     |
| Chassis No.  | KMHLB41UMEU047605 | Colour       | BLUE     |
| Odometer     | 565869            | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

## 3. Conditions of Tyres

|                | Size       | Make      | Balance |
|----------------|------------|-----------|---------|
| R/H Front Tyre | 205/60 R16 | WEST LAKE | 6 mm    |
| L/H Front Tyre | 205/60 R16 | WEST LAKE | 6 mm    |
| R/H Rear Tyre  | 205/60 R16 | WEST LAKE | 6 mm    |
| L/H Rear Tyre  | 205/60 R16 | WEST LAKE | 6 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |                                                                          |                 |            |
|----------------|--------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 22/07/2018                                                               | Inspection Date | 24/07/2018 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                 |            |

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 6 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4017B

| Qty                                | Description of Parts                                        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                             |                      |                           |                   |
| 1                                  | REAR BUMPER                                                 | TORN                 | 578.40                    | 578.40            |
| 10                                 | REAR BUMPER CLIP                                            | NECESSARY            | 22.00                     | 22.00             |
| 1                                  | REAR FENDER (LH)                                            | TO REPAIR SEE LABOUR | 1,935.90                  | -                 |
| 1                                  | REAR FENDER (INNER LINING LH)                               | CUT                  | 74.10                     | 74.10             |
| 1                                  | REAR WINDSCREEN MOULDING                                    | NOT NECESSARY        | 60.00                     | -                 |
| 1                                  | REAR DOOR (LH)                                              | BENT                 | 1,294.70                  | 1,294.70          |
| 1                                  | FRONT DOOR (LH)                                             | BENT                 | 1,344.50                  | 1,344.50          |
| 1                                  | FRONT DOOR MIRROR (LH)                                      | DISTORTED            | 545.50                    | 545.50            |
| 2                                  | FRT & REAR TYRE RIM (LH) @\$284.70                          | NOT NECESSARY        | 569.40                    | -                 |
| 2                                  | FRT & REAR WHEEL HUP-CAP (LH) @\$145.00                     | NECESSARY            | 290.00                    | 290.00            |
| 1                                  | FRONT FENDER (LH)                                           | BUCKLED              | 593.10                    | 593.10            |
| 1                                  | FRONT FENDER SHIELD (LH)                                    | DEFORMED             | 86.00                     | 86.00             |
| 1                                  | FRONT BUMPER COVER                                          | DEFORMED             | 538.80                    | 538.80            |
| 1                                  | FRONT BUMPER BRACKET TOP (LH)                               | NECESSARY            | 22.40                     | 22.40             |
| 1                                  | HEADLAMP (LH)                                               | SCRATCHED            | 797.90                    | 797.90            |
|                                    | LESS 20% DISCOUNT                                           |                      | -1,750.54                 | -1,237.48         |
|                                    |                                                             |                      | 7,002.16                  | 4,949.92          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                             |                      |                           |                   |
| 1                                  | REAR BUMPER RUBBER MAT (SN)                                 | NECESSARY            | 50.00                     | 50.00             |
| 1                                  | REAR FENDER ADVERTISEMENT LOGO (LH) (SN)                    | NECESSARY            | 100.00                    | 100.00            |
| 1                                  | REAR WINDSCREEN SEALANT (SN)                                | NOT NECESSARY        | 46.00                     | -                 |
| 1                                  | REAR DOOR TEL NO. STICKER (LH) (SN)                         | NECESSARY            | 10.00                     | 10.00             |
| 1                                  | FRONT DOOR COLOURED COMFORT LOGO (LH) (SN)                  | NECESSARY            | 75.00                     | 75.00             |
| 1                                  | FRONT DOOR ADVERTISEMENT LOGO (LH) (SN)                     | NECESSARY            | 100.00                    | 100.00            |
| 1                                  | FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)                   | NECESSARY            | 100.00                    | 100.00            |
|                                    |                                                             |                      | 481.00                    | 435.00            |
| <b><u>LABOUR</u></b>               |                                                             |                      |                           |                   |
|                                    | PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER (LH). |                      | 1,200.00                  | 600.00            |
|                                    | SPRAY PAINTING CHARGE.                                      |                      | 1,200.00                  | 1,100.00          |

Report Ref No. CC3/CTI18013657/Ghb3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

| Qty                                                                     | Description of Parts                    | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|-----------------------------------------|---------------|---------------------------|-------------------|
|                                                                         | WIRING CHARGE.                          | NOT NECESSARY | 50.00                     | 30.00             |
|                                                                         | TUFF KOTE.                              |               | 50.00                     | 50.00             |
|                                                                         | REMOVE/REFIX CUSHION & UPHOLSTERY REAR. |               | 150.00                    | 60.00             |
|                                                                         | REMOVE/REFIX REAR WINDSCREEN GLASS.     |               | 120.00                    | -                 |
|                                                                         | REMOVE/REFIX REVERSE SENSOR .           |               | 120.00                    | 40.00             |
|                                                                         | TRANSFER OF DOOR.                       |               | 240.00                    | 120.00            |
|                                                                         | FOUR WHEEL ALIGNMENT.                   |               | 120.00                    | 60.00             |
|                                                                         |                                         |               | 3,250.00                  | 2,060.00          |
|                                                                         | GRAND TOTAL                             |               | 10,733.16                 | 7,444.92          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                                         |               |                           | 5,900.00          |

Report Ref No. CC3/CT118013657/Ghb3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.