

Surveyor:

REF: CS/INC17000515 / 6215-1

Special Instruction:

48: \$ 8800.00

From (Person): Linda Pua of Linda Pua Law Date/Time: 23/07/2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: PPR Automotive

Workshop: Twincar Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SGL 7588D Insured: YL 5580A

at Workshop m/s Twincar Automotive Tel: 6342 0051

of 2 Kaki Bukit Ave 2 #01-17

Policy No: MT/0896104-001 Claim No: 4/ATUC/2017-0414

Sum Insured: Excess:

Make of Veh: D.O.A. 30-03-2016

(Client's Record)

03/08/2018 (Friday) @ 11am

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 9 days)

Date/Time: 18/9/18 Submit Final Fig 4350 5 days (Red \$ 4450 / 51 %; Original days)

Date/Time	Action/Instruction
	SGL 7588D - CC3 / ATG16006118 / G40302
	YL 5580A
10-01-17 244pm	Text letter to Twincar Automotive & Vision Law
14-02-17 3-59pm	Call Elum ask for RL appt. need arrange.
17-03-17 12-10pm	Still pending appt with owner.
18-03-17 1231pm	Email to Rajeswary close this file temporary

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 19 SEP 2018

Para(3) : Nett Value

Market Value :
Salvage Value :
Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

150

- 1) Date/Time 19/9- typist File Pass to 2) Date/Time File Return to
3) Date/Time File Pass to 4) Date/Time File Return to
5) Date/Time File Pass to 6) Date/Time File Return to

REF:

ASSIGNMENT

C-2021

27 Sep 2006

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL7588D

Yr Regn:

27 Sep 2006

Type: M / Car / M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

cc 1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp Reading:

- 205200

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0532EC 107/28730

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F:

185 / 70 R14

R:

H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

PALKEN

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

03-08-18

Survey held at

w/s

11Am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/9/2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) \$ + P.S. \$

2) Photos

3) Others

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp. (\$)

☐

Interview (\$)

☐

Tech. Insp. (\$)

☐

Workshop (\$)

TOTAL

Nivitha (LKK Auto)

From: Linda Phua <linda@lindaphualaw.com>
Sent: Monday, 23 July 2018 2:59 PM
To: Catherine Chong (LKK Auto)
Subject: INSTRUCTIONS TO CARRY OUT A REINSPECTION - REF: LP/NTUC/2017-0414 - NTUC's Ref: MT/0896104-001
Attachments: consent for reinspection.pdf

Dear Sirs

1. WE act for NTUC Income Insurance Co-Op Ltd.
2. Our client has appointed your company to carry out a post repair inspection for this vehicle SGL 7588D.
3. Attached is a copy of the letter dated 19 Jul 2018 from Vision Law LLC.
4. Our firm was closed last week and we would like you to attend to this reinspection on an urgent basis.

Regards

Linda Phua



LINDA PHUA LAW PRACTICE
COMMISSIONER FOR OATHS

E: linda@lindaphualaw.com

T: +65 6534 7388 F: +65 6534 8911 M: 9777 2781

20 Havelock Road, Central Square #02-45 Singapore 059765

Website: www.lindaphualaw.com

LINDA PHUA LAW PRACTICE (UEN 53313522B) DO NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FAX OR EMAIL.

This document is confidential and privileged. If you have received this transmission in error, please notify the sender immediately by reply e-mail and then delete this message. You should not copy or use it for any purpose or disclose its contents to any other person.

VISION LAW LLCAdvocates & Solicitors - Notary Public - Commissioners for Oaths
(Incorporated with limited liability)

ERIC NG CHING HOON
WONG KENG LEONG RAYNEV
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D-O MUNANDY
SEGA PARAM
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN



Unique Entity Number: 20072114811

Head Office: 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Lorong 6 Toa Payoh
#03-11 HDB Hub (Biz 3 Lobby 1)
Singapore 310490

Main
TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802
E-MAIL : annatan@visionlawllc.com

Branch
TEL : (65) 63580703

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

Our Ref : AKN-atv-INS-T140-100468-16
Your Ref : LP/NTUC/2017-0414

without prejudice

19 July 2018

LINDA PHUA LAW PRACTICE
20 Havelock Road
Central Square #02-45
Singapore 059765

BY FAX 6534-8911 ONLY

Dear Sir,

M C SUIT NO. 19255 / 2017

We refer to the above matter.

We have made an arrangement for our client's vehicle **SGL 7588 D** to be available for re-inspection on the following date, time and venue.

- (a) Date : 3rd August 2018 [Friday]
- (b) Time : 11.00 a.m. [Sharp]
- (c) Place : TWINCAR AUTOMOTIVE PTE LTD
Block 1059 Eunos Avenue 3
#01-152
- (d) Tel : 6842-0051 [Contact: Emily]

Kindly ensure that your appointed surveyor attends to the above without fail.

Please also let us have your written confirmation on the above arrangement urgently within 5 days.

Yours faithfully

(Head Office)

c.c. client (By fax 6741-0510 only - SGL 7588 D)

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL, AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Saturday, 18 March, 2017 12:31 PM
To: 'NTUC Rajeswary'
Cc: 'assignments'
Subject: RE: YOUR REF: MT/CA/TP/009/0896104-001/RD/CK ; VEHICLE NO: SGL 7588D ; DOA: 30.03.2016

Dear Rajeswary,

We refer to the above-mentioned and your letter dated on 30/11/2016.

We regret to inform you that we are unable to arrange an appointment to conduct a physical re-inspection on this vehicle SGL 7588D.

This case has been pending for a long time due to the unavailability of the owner, therefore we decided to temporarily close this case.

Kindly advise us if there is any arrangement made and will be glad to re-open the case accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Your Ref: AKN-atv-Ins-T140-100468-16
Our Ref: MT/CA/TP/009/0896104-001/RD/CK

30.11.16

28 Nov 2016

VISION LAW LLC
133 NEW BRIDGE ROAD
#18-01/02 CHINATOWN POINT
SINGAPORE 059413

Dear Sir/Madam

CLAIM NUMBER: MT/0896104-001
ACCIDENT INVOLVING YL5580A / SGL7588D ON 30 Mar 2016


We refer to your claim.

In order for us to assess the cost of repair, we will require a physical inspection of your vehicle.

We would appreciate it if you could contact LKK Auto Consultants Pte Ltd at 62563561 or email at assignments@lkkauto.com to arrange for an appointment.

If you have any queries, please contact Rajeswary Doraisamy at 6430 7934 or email us at rajeswary.doraisamy@income.com.sg.

Yours sincerely



Jenny Pe
Senior Claims Manager
Motor Insurance

cc LKK Auto Consultants Pte Ltd

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

PLUS CAR RENTAL & TRADING
4 PETAIN ROAD PETAIN COURT
SINGAPORE 208086

Contact : 98209527

TAX INVOICE

Date : 27/09/2016
Date in : 30/03/2016
Vehicle Num. : SGL7588D
Make/Model : TOYOTA COROLLA ALTIS 1.6 AUTO-2006
Chassis/Eng# : MR053ZEC107129730/3ZZ4597677
Accident Date : 30/03/2016
Claim No : CLM13250
Reference : MAR-41/2016
Policy No. : 999995501/100778513 (19/06/2016)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0375-16-TCA DATED 05/09/2016
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$
8,800.00

E. & O.E.	Sub S\$:	8,800.00
Add GST (7 %) S\$:		616.00
Total Amount S\$:		9,416.00



for TWINCAR AUTOMOTIVE PTE LTD

PAR Automotive Consultancy

Regn. No. S29869741

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0375-16-TCA

05 September 2016

Plus Car Rental & Trading
4 Petain Road Petain Court
Singapore 208086

INVOICE No. 0375-16-TCA


Vehicle No. SGL7588D

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$662.00
Total amount payable		<u>\$662.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0375-16-TCA

05 September 2016

ACCIDENT VEHICLE SURVEY REPORT

Plus Car Rental & Trading
4 Petain Road Petain Court
Singapore 208086

VEHICLE INFORMATION:

Vehicle Reg No.:	SGL7588D	Odometer:	177692km
Make & Model:	Toyota Corolla Altis 1.6A	Colour:	Silver
Chassis number:	MR053ZEC107129730	Date of accident:	30/03/2016
Year of Regn.:	27/09/2006	Date inspected:	31/03/2016
Repairer at:	Twincar Automotive Pte Ltd Blk 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Falken	6mm/Falken	185/70R14
Rear:	6mm/Falken	6mm/Falken	185/70R14

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the RH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
FRONT RH DOOR	1	buckled	1,242.80	1,242.80 ✓
FRONT RH DOOR CHECKER	1	reuse	128.60	0.00 NN
FRONT RH DOOR HINGES (TOP & LOWER)	2	repair	178.40	0.00 R
FRT RH DOOR INNER BLACK FRAME STICKER 'HORIZONTAL'	1	necessary	55.10	55.10 ✓
FRONT RH DOOR INNER LOCK HANDLE	1	distorted	91.20	X 91.20 NN
FRONT RH DOOR INNER TRIM BOARD	1	fractured	399.45	399.45 ✓
FRONT RH DOOR LOCK STRIKER	1	bent	36.10	X 36.10 NN
FRONT RH DOOR MECHANISM LOCK	1	bent	503.10	503.10 ✓
FRONT RH DOOR OUTER CHROME LOCK HANDLE	1	distorted	69.80	69.80 ✓
FRONT RH DOOR PILLAR WEATHERSTRIP	1	deformed	85.70	85.70 ✓
FRONT RH DOOR POWER WINDOW CHANNEL	1	bent	55.70	55.70 ✓
FRT RH DOOR POWER WINDOW CHANNEL WEATHERSTRIP	1	necessary	87.70	87.70 ✓
FRONT RH DOOR POWER WINDOW MAIN CONTROL SWITCH	1	reuse	294.01	0.00 NN
FRONT RH DOOR POWER WINDOW MOTOR	1	shorted	237.69	237.69 ✓
FRONT RH DOOR POWER WINDOW REGULATOR	1	bent	68.60	68.60 ✓
FRONT RH DOOR PROTECTOR	1	necessary	131.35	131.35 ✓
FRONT RH DOOR PROTECTOR CHROME MOULDING	1	necessary	15.70	15.70 ✓
FRONT RH DOOR RUBBER GUIDE STOPPER	2	deformed	244.20	X 244.20 NN
FRONT RH DOOR SIDE MIRROR	1	fractured	380.80	380.80 ✓
FRONT RH DOOR SIDE MIRROR COVER	1	abraded	66.00	66.00 ✓
FRONT RH DOOR SIDE MIRROR INNER GARNISH	1	reuse	122.35	0.00 NN
FRONT RH DOOR SIDE MIRROR INNER GARNISH CLIPS	2	necessary	13.00	13.00 ✓
FRONT RH DOOR SWITCH	1	reuse	36.10	0.00 NN
FRONT RH DOOR WEATHERSTRIP	1	deformed	181.10	181.10 ✓
FRONT RH DOOR WIRE HARNESS - SET	1	reuse	325.70	0.00 NN
FRONT RH FENDER	1	buckled	179.00	X 179.00 repair
FRONT RH FENDER INNER SHIELD	1	reuse	85.00	0.00 NN
FRONT RH FENDER QUARTER GARNISH	1	warped	61.75	61.75 ✓
FRONT RH FENDER QUARTER GARNISH CLIPS	2	necessary	13.00	13.00 ✓
FRONT RH FENDER SIGNAL LAMP	1	reuse	30.80	0.00 NN
FRONT SUSPENSION RH ABS SENSOR	1	reuse	381.72	0.00 NN
FRONT SUSPENSION RH KNUCKLE ARM	1	distorted	172.55	X 172.55
FRONT SUSPENSION RH KNUCKLE ARM BEARING	1	dislodged	132.50	X 132.50 NN
FRONT SUSPENSION RH LOWER ARM	1	bent	170.95	X 170.95
FRONT SUSPENSION RH LOWER BALL JOINT	1	reuse	245.10	0.00 NN
FRONT SUSPENSION RH SHOCK ABSORBER	1	bent	311.40	X 311.40
FRONT SUSPENSION RH SHOCK ABSORBER TOP MOUNTING	1	necessary	149.80	X 149.80 NN
FRONT SUSPENSION RH STABILIZER BAR LINK	1	bent	171.25	X 171.25
REAR RH DOOR	1	buckled	981.20	981.20 ✓
REAR RH DOOR CHECKER	1	reuse	131.35	0.00 NN
REAR RH DOOR GLASS OUTER CHROME MOULDING	1	necessary	171.80	171.80 ✓
REAR RH DOOR HINGES (TOP & LOWER)	2	repair	178.40	0.00 R

PAR Automotive Consultancy

Annex A Page 2
Report No: 0375-16-TCA-SGL7588D

RR RH DOOR INNER BLACK FRAME STICKER 'HORIZONTAL'	1	necessary	125.10	125.10	
REAR RH DOOR INNER LOCK HANDLE	1	distorted	91.20	X 91.20	
REAR RH DOOR INNER TRIM BOARD	1	fractured	561.40	X 561.40	
REAR RH DOOR LOCK STRIKER	1	bent	121.35	X 121.35	NN
REAR RH DOOR MECHANISM LOCK	1	bent	71.30	X 71.30	
REAR RH DOOR OUTER CHROME LOCK HANDLE	1	distorted	68.10	X 68.10	
REAR RH DOOR OUTER CHROME LOCK HANDLE COVER	1	distorted	28.20	X 28.20	
REAR RH DOOR PILLAR WEATHERSTRIP	1	reuse	281.80	0.00	NN
REAR RH DOOR POWER WINDOW CHANNEL	1	bent	55.70	X 55.70	
RR RH DOOR POWER WINDOW CHANNEL WEATHERSTRIP	1	necessary	47.10	X 47.10	
REAR RH DOOR POWER WINDOW MOTOR	1	shorted	223.70	X 223.70	NN
REAR RH DOOR POWER WINDOW REGULATOR	1	bent	65.30	X 65.30	
REAR RH DOOR PROTECTOR	1	necessary	77.30	77.30	
REAR RH DOOR PROTECTOR CHROME MOULDING	1	necessary	15.10	15.10	
REAR RH DOOR RUBBER GUIDE STOPPER	2	deformed	87.40	X 87.40	NN
REAR RH DOOR WEATHERSTRIP	1	deformed	161.25	X 161.25	NN
REAR RH FENDER	1	repair	981.80	0.00	R
REAR RH FENDER INNER AIR VENT	1	reuse	83.20	0.00	
REAR RH FENDER INNER UPHOLSTERY TRIM	1	reuse	181.85	0.00	NN
REAR WINDSCREEN INNER GARNISH CLIPS L/R	10	reuse	65.00	0.00	
REAR WINDSCREEN MOULDING	1	reuse	373.80	0.00	
Subtotal before discount			S\$ 12,384.77	S\$ 8,279.79	5038.84
Percentage discount 25% and 25%			S\$ 3,096.19	S\$ 2,069.95	
Sub-total 1			S\$ 9,288.58	S\$ 6,209.84	3779.13
REAR RH DOOR POWER WINDOW CONTROL SWITCH	1	reuse	380.00	0.00	NN
REAR RH DOOR SWITCH	1	reuse	380.00	0.00	NN
Subtotal before discount			S\$ 760.00	S\$ 0.00	
Percentage discount 10% and 10%			S\$ 76.00	S\$ 0.00	
Sub-total 2			S\$ 684.00	S\$ 0.00	
FRONT RH 14" SPORT RIM	1	abraded	350.00	X 350.00	NN
FRONT RH 185/70R14 88T TYRE	1	abraded	380.00	X 380.00	NN
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	30.00	30.00	
FRONT RH DOOR SPEAKER	1	distortion	180.00	180.00	120
FRONT RH FENDER INNER SHIELD CLIPS - SET	1	necessary	30.00	30.00	NN
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	1	necessary	30.00	30.00	
REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET	1	reuse	30.00	0.00	NN
REAR WINDSCREEN SEALANT	1	reuse	100.00	0.00	NN
Subtotal before discount			S\$ 1,130.00	S\$ 1,000.00	180
Sub-total 3			S\$ 1,130.00	S\$ 1,000.00	
Parts-total			S\$ 11,102.58	S\$ 7,209.84	

PAR Automotive Consultancy

LABOUR

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

180.00

~~60.00~~ X NN

To remove, reinstall window glass. (to FR)

150.00

~~120.00~~ 80

To remove and refit rear windscreen(to FR)

150.00

0.00

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

550.00

~~400.00~~ X NN

To road test driving, check and resetting wheel alignments system.

180.00

~~180.00~~ X

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

140.00

60.00 /

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,750.00

1,200.00

800

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1,750.00

1,100.00

500

To apply anti-rust chemical on repaired and replaced panel.

120.00

60.00

Labour Total SS 4,970.00 SS 3,180.00

Parts & Labour Total SS 16,072.58 SS 10,389.84

1500

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 8,800.00 and the recommended number of working days for the repairs is within 9 day(s).

B J Loi (I Eng., MIM, AIRTE)

Automotive Appraiser

8459.13

20% : 4350

5 Days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC17000575/Gvbs2-1

C/O: LINDA PHUA LAW PRACTICE
20 HAVELOCK ROAD
#02-45 CENTRAL SQUARESINGAPORE 059765

Date : 19-09-2018



Code : INC3

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	YL 5580A	Veh. Inspected	SGL 7588D
Policy No.	MT/0896104-001	Coverage (\$)	0.00
Claim No.	LP/NTUC/2017-0414	Excess (\$)	0.00
Assign From	LINDA PHUA	Assign Date	23/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107129730	Colour	SILVER
Odometer	205200	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70R14	FALKEN	6 mm
L/H Front Tyre	185/70R14	FALKEN	6 mm
R/H Rear Tyre	185/70R14	FALKEN	6 mm
L/H Rear Tyre	185/70R14	FALKEN	6 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

5. General Information

Accident Date	30/03/2016	Inspection Date	03/08/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 7588D

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH DOOR	REPLACED	1,242.80	1,242.80
1	FRONT RH DOOR CHECKER	NOT NECESSARY	-	-
2	FRONT RH DOOR HINGES (TOP & LOWER)	REPAIRED SEE LABOUR	-	-
1	FRT RH DOOR INNER FRAME STICKER 'HORIZONTAL'	REPLACED	55.10	55.10
1	FRONT RH DOOR INNER LOCK HANDLE	NOT NECESSARY	91.20	-
1	FRONT RH DOOR INNER TRIM BOARD	REPLACED	399.45	399.45
1	FRONT RH DOOR LOCK STRIKER	NOT NECESSARY	36.10	-
1	FRONT RH DOOR MECHANISM LOCK	REPLACED	503.10	503.10
1	FRONT RH DOOR OUTER CHROME LOCK HANDLE	REPLACED	69.80	69.80
1	FRONT RH DOOR PILLAR WEATHERSTRIP	REPLACED	85.70	85.70
1	FRONT RH DOOR POWER WINDOW CHANNEL	REPLACED	55.70	55.70
1	FRT RH DOOR POWER WINDOW CHANNEL WEATHERSTRIP	REPLACED	87.70	87.70
1	FRONT RH DOOR POWER WINDOW MAIN CONTROL SWITCH	NOT NECESSARY	-	-
1	FRONT RH DOOR POWER WINDOW MOTOR	REPLACED	237.69	237.69
1	FRONT RH DOOR POWER WINDOW REGULATOR	REPLACED	68.60	68.60
1	FRONT RH DOOR PROTECTOR	REPLACED	131.35	131.35
1	FRONT RH DOOR PROTECTOR CHROME MOULDING	REPLACED	15.70	15.70
2	FRONT RH DOOR RUBBER GUIDE STOPPER	NOT NECESSARY	244.20	-
1	FRONT RH DOOR SIDE MIRROR	REPLACED	380.80	380.80
1	FRONT RH DOOR SIDE MIRROR COVER	REPLACED	66.00	66.00
1	FRONT RH DOOR SIDE MIRROR INNER GARNISH	NOT NECESSARY	-	-
2	FRONT RH DOOR SIDE MIRROR INNER GARNISH CLIPS	REPLACED	13.00	13.00
1	FRONT RH DOOR SWITCH	NOT NECESSARY	-	-
1	FRONT RH DOOR WEATHERSTRIP	REPLACED	181.10	181.10
1	SET FRONT RH DOOR WIRE HARNESS	NOT NECESSARY	-	-
1	FRONT RH FENDER	REPAIRED SEE LABOUR	179.00	-
1	FRONT RH FENDER INNER SHIELD	NOT NECESSARY	-	-
1	FRONT RH FENDER QUARTER GARNISH	REPLACED	61.75	61.75

Report Ref No. CS/INC17000575/Gvbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
2	FRONT RH FENDER QUARTER GARNISH CLIPS	REPLACED	13.00	13.00
1	FRONT RH FENDER SIGNAL LAMP	NOT NECESSARY	-	-
1	FRONT SUSPENSION RH ABS SENSOR	NOT NECESSARY	-	-
1	FRONT SUSPENSION RH KNUCKLE ARM	NOT NECESSARY	172.55	-
1	FRONT SUSPENSION RH KNUCKLE ARM BEARING	NOT NECESSARY	132.50	-
1	FRONT SUSPENSION RH LOWER ARM	NOT NECESSARY	170.95	-
1	FRONT SUSPENSION RH LOWER BALL JOINT	NOT NECESSARY	-	-
1	FRONT SUSPENSION RH SHOCK ABSORBER	NOT NECESSARY	311.40	-
1	FRONT SUSPENSION RH SHOCK ABSORBER TOP MOUNTING	NOT NECESSARY	149.80	-
1	FRONT SUSPENSION RH STABILIZER BAR LINK	NOT NECESSARY	171.25	-
1	REAR RH DOOR	REPLACED	981.20	981.20
1	REAR RH DOOR CHECKER	NOT NECESSARY	-	-
1	REAR RH DOOR GLASS OUTER CHROME MOULDING	REPLACED	171.80	171.80
2	REAR RH DOOR HINGES (TOP & LOWER)	REPAIRED SEE LABOUR	-	-
1	RR RH DOOR INNER BLACK FRAME STICKER 'HORIZONTAL'	REPLACED	125.10	125.10
1	REAR RH DOOR INNER LOCK HANDLE	NOT NECESSARY	91.20	-
1	REAR RH DOOR INNER TRIM BOARD	NOT NECESSARY	561.40	-
1	REAR RH DOOR LOCK STRIKER	NOT NECESSARY	121.35	-
1	REAR RH DOOR MECHANISM LOCK	NOT NECESSARY	71.30	-
1	REAR RH DOOR OUTER CHROME LOCK HANDLE	NOT NECESSARY	68.10	-
1	REAR RH DOOR OUTER CHROME LOCK HANDLE COVER	NOT NECESSARY	28.20	-
1	REAR RH DOOR PILLAR WEATHERSTRIP	NOT NECESSARY	-	-
1	REAR RH DOOR POWER WINDOW CHANNEL	NOT NECESSARY	55.70	-
1	RR RH DOOR POWER WINDOW CHANNEL WEATHERSTRIP	NOT NECESSARY	47.10	-
1	REAR RH DOOR POWER WINDOW MOTOR	NOT NECESSARY	223.70	-
1	REAR RH DOOR POWER WINDOW REGULATOR	NOT NECESSARY	65.30	-
1	REAR RH DOOR PROTECTOR	REPLACED	77.30	77.30
1	REAR RH DOOR PROTECTOR CHROME MOULDING	REPLACED	15.10	15.10
2	REAR RH DOOR RUBBER GUIDE STOPPER	NOT NECESSARY	87.40	-
1	REAR RH DOOR WEATHERSTRIP	NOT NECESSARY	161.25	-

Report Ref No. CS/INC17000575/Gvbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
1	REAR RH FENDER	REPAIRED SEE LABOUR	-	-
1	REAR RH FENDER INNER AIR VENT	NOT NECESSARY	-	-
1	REAR RH FENDER INNER UPHOLSTERY TRIM	NOT NECESSARY	-	-
10	REAR WINDSCREEN INNER GARNISH CLIPS L/R	NOT NECESSARY	-	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	-	-
	LESS 25% DISCOUNT		-2,069.95	-1,259.71
			6,209.84	3,779.13
	NETT ITEMS			
1	REAR RH DOOR POWER WINDOW CONTROL SWITCH (N)	NOT NECESSARY	-	-
1	REAR RH DOOR SWITCH (N)	NOT NECESSARY	-	-
			-	-
	SPECIAL NETT ITEMS			
1	LESS 10% DISCOUNT		-	-
1	FRONT RH 14" SPORT RIM (SN)	NOT NECESSARY	350.00	-
1	FRONT RH 185/70R14 88T TYRE (SN)	NOT NECESSARY	380.00	-
1	SET FRONT RH DOOR INNER TRIM BOARD CLIPS (SN)	REPLACED	30.00	30.00
1	FRONT RH DOOR SPEAKER (SN)	REPLACED	180.00	120.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR RH DOOR INNER TRIM BOARD CLIPS (SN)	REPLACED	30.00	30.00
1	SET REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS (SN)	NOT NECESSARY	-	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	-	-
			1,000.00	180.00
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS. CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.	NOT NECESSARY	60.00	-
	TO REMOVE, REINSTALL WINDOW GLASS. (TO FR)		120.00	80.00
	TO REMOVE AND REFIT REAR WINDOW (TO FR)	NOT NECESSARY	-	-
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER. LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.	NOT NECESSARY	400.00	-

Report Ref No. CS/INC17000575/Gvbs2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Initial Surveyor (\$)	Our Adjusted (\$)
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENT SYSTEM.	NOT NECESSARY	180.00	-
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		60.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,200.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT RH DOOR HINGES (TOP & LOWER), FRONT RH FENDER, REAR RH DOOR HINGES (TOP & LOWER) AND REAR RH FENDER.		1,100.00	500.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		60.00	60.00
			3,180.00	1,500.00
GRAND TOTAL			10,389.84	5,459.13
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,800.00	4,350.00

Report Ref No. CS/INC17000575/Gvbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.