

ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:			
Type of Claim :	TP	Vehicle No.	SKZ9544X
.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Make & Model	HYUNDAI ELANTRA 1.6 A
		Year of Manufacture	2015
		Chassis No.	KMHDH41CMGU656631
Ins Company :AIG V	S LONPAC	Engine No.	G4FGFU068069
Excess :		Policy No.	81 -
Date of Accident : 21	.07.2018	Time of Accident	: 10:50
Suggested Days of Repair :		In-house Vehicle Asse	ssor
Repair Estimate		Case Owner	WILLIAM
Parts (a) Cost / List Price Items	\$ 5,848.40	Signature Contact No	÷
Plus/Less 20%	\$ 1,169.68	Frt Counter Operatio	n
Total of Cost / List	\$ 4,678.72	63837466 - Rohani	KK Auto Consultants hence notify e Repairer of the following:
(b) Nett Price Items	-	braddell_cr@sparkcarca	re.com/vey before/after spray painting o display damaged part(s) during resurvey
Less		Workshop Operation	arts prices are subject to confirmation
Total of Nett Item		63837362 - N	bird party survey is on a "Without Prejudice" basis lo illegal modification(s) is allowed
(c) Special Nett Items	\$ -	63838115 - Andrew G	upplementary item(s) must be resurveyed and subject to final approval from Insurance Company
Total Parts Cost (Appendix A)	\$ 4,678.72	braddell operation@spa	rkcarcare.com nature:
Labour (Appendix B)	\$ 2,670.00	Date	
Total Repair Cost	\$ 7,348.72		
The above total will be subjected t	o 7% G.S.T.		
Name of Surveyor	: Quo	2; ang - 8.	2880282

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair

(c) Resurvey

(d) Excess

(e) Signature of surveyor

Surveyor

Authorized until further notice.

Authorized part of part o

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No	:	SKZ9544X	Case Owner	WILLIAM
Make & Model	:	HYUNDAI ELANTRA 1.6 A	Year Manufacture	2015
Chassis No	:	KMHDH41CMGU656631	Engine No	G4FGFU068069
Sales Order	;		Supplier	:
Order By	:	<u></u>	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Front bumper / 1//	1	11100	\$ 448.30	11100	3/14	Surveyor
2	Front bumper lower lip	1		\$ 48.60			
3	Front bumper lower lip clips ?	1		\$ 52.50			
4	Front bumper fog lamp RH / UA	1		\$ 233.50			
5	Front bumper center grille X	1		\$ 255.70			
6	Front bumper sponge / CHA	1		\$ 110.70			
7	Front bumper reinforcement 💢 🕹	1		\$ 515.10			
8	Front bumper lower stiffener	1		\$ 138.40			
	Front bumper upper side bracket RH / C	1/21		\$ 28.00			
	Front bumper side bracket RH / 61	1		\$ 28.00			
	Front bumper side support LH 2 / 160	_1		\$ 28.00			
	Front bumper side support RH / 02 ·	1		\$ 28.00			
_	Front bumper side support rivets / M C	6		\$ 20.40			
14	Front grille assy	1		\$ 126.00			
	RH headlamp / CA/A	1		\$ 1,756.00			
	RH headlamp lower bracket	1		\$ 65.00			
-	RH front fender Buc.	1		\$ 460.60			
18	RH front fender inner shield / h/5	1		\$ 56.50			
19	RH front fender inner shield clips /m/	8		\$ 28.00			
20	Washer tank / R	1		\$ 43.00			
21	Bonnet / 131	1		\$ 1,184.30			
22	Bonnet seal front	1		\$ 18.00			
23	Bonnet insulator clips / N/4C	8		\$ 28.00			
24	Bonnet hinge LH / / M	1		\$ 52.00			
25	Bonnet hinge RH	1		\$ 52.00			
26	Bonnet lock X MM.	1		\$ 43.80			
27	0	0					
28	0	0					
29	0	0					
	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

 Vehicle No. :
 SKZ9544X
 Case Owner
 :
 WILLIAM

 Make & Model :
 HYUNDAI ELANTRA 1.6 A
 Year of Manufacture
 :
 2015

S/No	Labour Description	Esimated Price	Adjusted Price
1	To remove/refit aircond parts, vacuum & recharge gas.	\$120.00	7
2	Labour charges to repair and panel beat the frt support panel, RH front pillar panel, LH front fender and replace damaged parts. (per day \$240.00)	\$720.00	480
3	To check wiring functions and focus headlamps.	\$60.00	30
4	To putty, apply primer & spray-paint the front bumper, bonnet, LH front fender, RH front fender, RH front pillar panel, front support panel and affected areas.	\$1,500.00	1250
5	To apply rust-proofing on repaired/replaced panels.	\$150.00	50
6	To check/re-set steering geometry and wheel alignment.	\$120.00	\$0 S.0

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.