

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SH 6194S

DATE 24/7/2018 14:41

MAKE :

MODEL : HYUNDAI i40

*AIG/LKK*  
*RIGHT REAR*

*F*  
*12*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>/ RE</i>			\$ 603.60
	Rear Bumper Clips <i>- MC</i>			\$ 22.00
	<b>SUB TOTAL</b>			<b>\$ 625.60</b>
	<b>LESS 20%</b>			<b>\$ 125.12</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 500.48</b>
	Rear Bumper Advertisement Logo <i>/ YMC</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>/ YMC</i>		\$ 100.00	\$ 200.00
				<b>\$ 250.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 770.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,520.48</b>

Nett  
Nett

*200*  
*200*  
*A YMC*  
*X YMC*

*2 Days.*  
*lumpsum repair*  
*After repair photos.*  
*Good QIP.*  
*24/7/18 4:30 pm*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.