INS. CASE OWNER		CC 7/AIG1801	n680, E	Lebb LIXE	
Surveyor.	talvin	DOI: ASSIGN		Date / Time:	relyliv
Pre-assign/CCU	(t6 95)	9 16		Registered in Merimen 79 70 V84	W/7/18
Insured Vehicle No Name of Insured	ité illem	T MEI WAN	Claim No. Policy No.	*	htt4-06.
Excess Sec II :SS Is driver the owner		D.O.A : 10 PT	Make / Model Place of Accide	4.000 (10.1.1)	-
If NO, Driver Nan Driver Tel	The second second	(VIL (VI)	OI GIA REPOR Insunst Liability	YEY/NO : TP GIA F	REPORT YE / NO
CHO 667	99 —		INSRS:		INSRS:
	MY WSP: Tel: Liability RMKS		WSP: Tel: Laubility: RMKS:		WSP: Tet: Liability: RMKS:
my 18	100000000000000000000000000000000000000	महत्त्व म् । पर्वास्त्रक	v 004.0[4[19	STAGE Nos-Reporting ltr (1st)	DATE/PIC
Asher	ekousist - 2			Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Nonfication ltr (if non-picku	Attended to the second
39.8.18 + 3.44	CHURD OF NO BRENDA	L.		After call lir to Ol: Documentation Check List	Handler Typist
				Notification by (if non-picks After call by to Of:	
				Authorisation To Act: Release Voucher.	2
				Fluid Repair Bill: Car Rental Invoice:	
				LTA / GIA : Medical Bill:	
				PIR: Mandate/Reject Instruction LOD	. = =
PRELIMINARY ADVICE	Date/Time: -	Sent By:		Payment Breakdown For: Post-Repair Photos: Others:	
FINALIZATION Repair Cost: 100	Date/Time: 3-7-15 555-085-20 (Confirm with: (Horse)	5 6	Confirm by: 40%	- Cat I
FINAL SETTLEMENT Final Liability:	Date/Time to find (Agreed /	Confirm with (South	1	Email Cal If NO or B 28. Ass. Lia	
Repair Cost: wifee; Less of Rental (LOR); Less of Use (LOU); Less of Income (LOI); LOR only LOU only			SAS ENDED TP	G 18 (0	
GIA/LTA Saurch Medical: Disbursement: Legal Coss	\$\$1.44 \$\$ \$\$ \$\$ \$\$	(e.g. Tow/ Independen	C).	Claim status: Normal/9 Report Format; Survey fee:	teject/Private Settle
Total: FINAL PAYMENT		Confirm with Confirm		Email Cal	
Payee 1: Payee 2: (Strike if N.A.)		Name 1: Energoer Distance & Name 2:	Santacry, 2st.	(fp)	

(08/11/13)	
Bineya: Kalvin REF:	
19.5	ASSIGNMENT
From: Date:	Veh No: SHO 66757 Yr Regn: Mar , 216
EstimatedCost	Type: M.Car / M.Cycle / Bus / Van / Lorry / 10/ Prime Mover /
OD ITP WS ITP RESIGN RESIEVA / INV / MV	Truck / Trailer or
To imped Vehicle No:	Make: _ Merates But E22 0.0 2143 1.
at Workstep m/s	Colour Lite AIC: Instead / Std / NI / NA
of .	Sp.Reading 4 7 1269 T/Radio: Ins Ged / Std / NI / NA
Insured;	Eng/No:
Policy No.	CANO: WPO2120012B308246
Claims No.	Gen. Cond: Good / F 1 Poor / Burnt
Sum In swed: Excess:	Steering: Inor a / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inofert Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STBA/Rim of
repair at the time of Inspection. Bal. or Market Value: IDAC Accident Rport: Consistent? : Yes or Sold / PR Seen: Consistent? : Yes or Set. Repairs: 48 days Res.: Yes or Lum Sum: % 3 Val.: Yes or CA / REV / REP. / 24 HRS	No D.O.A. 19/2/-8 mm L/Bal. 7 mm
Date / Time Action / Instruction	AZ4
PJP: +5.085.30 (RED: +3.41-	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	17
4	:
	-,
	1, , , , , , , , , , , , , , , , , , ,
	8 9
Date(Time, File Pass to? : Prell, Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:

		-1., · · · ·			
Date(Time, File Page to?	: Prell. Report	Day	s Of Repair:		
1)	: Final Report	Res	survey No. of Trip:	Survey Fee:	
Date/Time, File Return to?		-	_	Transportation:	
2)		Add Fee:	:Site Insp (\$)8+RSSI	
81			:Interview (\$) Photos	
Report Format:		Ī	: Tech: Invs (\$) Others	
Lump Sum / 1.B.I: (\$. =	:Weekend (\$		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHAR SING	IENTON WAY #0 RTIS BUILDING APORE 079120	8-16	Date: 27-07-2018	
_			Code: AIG	
_		Policy Particu	lars :- THIRD PARTY CLA	M
	Insured Veh.	SKG 9818G	Veh. Inspected	SHD 6675Y
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	27/07/2018
2.		Vehicle F	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	*	Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Desc	ription of Damages	
5.		Ge	neral Information	
	Accident Date	19/07/2018	Inspection Date	26/07/2018
	Survey held at	COMFORTDELGRO ENGI 59 LOYANG DRIVE SINGAPORE 508969	NEERING PTE LTD	
5a.			Remarks	

COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

VEHICLE NO : SHA 6675Y :

DATE 26/7/2018 10:22

Qty	: MERCEDES BENZ Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper / libral			\$ 1,510.00
	Rear Bumper Reinforcement			\$ 1,150.00
	Rear Bumper Bracket Lower (LH/RH)		\$ 135.00	\$ 270.00
	Rear Bumper Bracket Top (LH/RH)		\$ 125.00	\$ 250,00
	Rear Bumper Retainer Mounting (LH/RH)	m-	\$ 115.00	\$ 230,00
	Rear Bumper Covering			\$ 55.00
	Rear Panel End			\$ 1,380.00
	Rear Panel Inner Garnish			\$ 115.00
	Rear Panel Inner Garnish Clip (10pcs) メー			\$ 40.00
		15.00		in in its
	Her Bund live ((-)	OTAL		\$ 5,125.00
		S 20%		\$ 1,025.00
	DISCOUNTED T			\$ 4,100.00
		20		
	1 41			
	Rear Bumper Sensor			\$ 388.00
	Rear Bumper Sensor Rear Bumper Rubber Mat			\$ 50.00
				\$ 438.00
	Labour Charge			300
	Panel Beating		a notify	\$ 490.00
	Spray Painting Charge	auto Consultants her	Sac	5 340.00
	Wiring Charge has R	epase 4	mrond.	S == > 50.00
	Remove/Refix Reverse Sensor	Reliable page of the page of	Ace basis	\$ 120.00
	* FI		Sect Days	٠,٢
	TOTAL LA	BOUR	most company	\$ 820.00
		-		
	K. La I CICLE ESTIMATE T	FOTAL	\	\$ 5,358.00
	107	A		
	1/ 26/7/18 1/35/17			-
	7 Pm			
	010			
	Kohn I Clar ESTIMATE TO 1/26/7/-8 1135hr. 3 Byz PIP Beton Paint plat.			
			The state of the s	
	This is an initial estimate based on a visual inspect	ion of the above vi	ehicle. The final repair	

COMFORTDELGRO ENGINEERING

VEHICLE !	SHD6675Y	TYPE OF C:	TP
	LKK	SURVEY B':	KALVIN
2	305192470	DATE :	19/07/2018

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION	QTY	ESTIMATE \$	REMARKS
BLUE TEC EMBLEM	/ M.	60.00	*
MERC STAR EMBLEM	M.	43.00	14
E220L EMBLEM	Me 1	52, 00	0
FASTENER NUT	- ME 1	14.00	
COMPRESSOR COVER I	H WA	35.00	*
BOOTLID	IBM 1	2470.00	20
			_
			+

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305192470 ComfortDelGro Engineering Pte Ltd 30/07/18 Date 59 Loyang Drive Singapore 508969 Fax: 6546 8156 **FINALIZATION FORM** LKK Fax: KALVIN Attn:: Vehicle Reg No. : SHD6675Y 19/07/2018 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-AIG SKG9818G The repair job shall bill to: The finalized amount shall be: Spare Parts after List discount \$4,353.20 (b) Labour Charges \$730.00 \$5,083.20 Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost 3 working days. 3. Estimated normal period for repairs: We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 4. working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature : Signature: Kaha : CHIANG Name Name 62148314 Tel Date 65468156 Fax For Official Use Only Document Confirm By Attached Remarks Item Amount (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid N 3. Survey Fees LTA Search Fee 7.49 5. Medical Fees (on behalf of driver, if applicable) Overrun Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 30.07.2018 Time: 16:24:35

Page: 1

COMPA_NY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRE SS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE MAKE : 305192470 : SHD6675Y : 0000000000

KE : MERCEDES BENZ

MODEL : E220CDI(E6)

DATE OF REGN : 23.03.2016

DATE/TIME IN : 26.07.2018 09:45

ACCIDENT DATE : 19.07.2018

JOB PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2282-G 212VB REAR BUMPER ASSY 1 1,510.00 20.00 1,208.00 0002 04-01-0202-0809-G 212VC REARLID 1 2,470.00 20.00 1,976.00 0003 04-01-0202-2252-G 212VA/211B BOOTLID E220 L 1 52.00 20.00 41.60 0004 09-01-0299-2005-A (212/211B)REVERSE SENSOR 1 388.00 2.00- 388.00 0005 04-01-0103-1150-A I40VC PROTECTOR MAT 1 50.00 0.20 50.00 0006 04-01-0202-2152-G 212VB BLUETEC EMBLEM AT T 1 60.00 20.00 48.00 0007 04-01-0202-2105-G (212)TRUNK LID MERCEDES S 1 43.00 20.00 34.40 0008 23-01-0202-2001-G (212)TRUNK LID MERCEDES S 1 41.00 20.00 11.20 0 04-01-0202-2124-G (212)PANELLING LOADING ED 1 115.00 20.00 92.00 0010 04-01-0202-2283-G 212VB REAR BUMPER LOWER C 1 325.00 20.00 260.00 0011 01-01-0202-2013-G (212)COMPRESSOR COVER 1 35.00 20.00 28.00 0012 04-01-0202-3886-G 212VB BUMPER BRACKET RR/L 1 135.00 20.00 108.00 0013 04-01-0202-3986-G 212VB BUMPER BRACKET RR/L 1 135.00 20.00 108.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.07.2018 Time: 16:24:35

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTO MER: 7010045

ADDRE SS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

: 305192470

REGN NO

SHD6675Y

MILEAGE MAKE

: 0000000000

: MERCEDES BEN. : E220CDI(E6)

MODEL DATE OF REGN

: 23.03.2016

DATE/TIME IN

: 26.07.2018 09:45

ACCIDENT DATE : 19.07.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL: 4,353.20

NA TURE

1.0000

PANEL BEATING

300.00

0001 23-502

SPRAYPAINT ON AFFECTED AREA

400.00

0002.20-22

REMOVE/REFIX REVERSE SENSOR

30.00

SUB-TOTAL: 730.00

TOTAL : 5,083.20

AUTHORISED: YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE:

DATE:

OMFORTDELGRO ENGINEERING

member of COMFORTDELCRO

ComfortDelGro Engineering Pte Ltd

The second section of the Control of

Date/Time: 26.07.2018 10:13

Page : 1

JOB CARD JCND: 305192470 ARC Repair TP(CLSO)1 Sales Order: Team: MILEAGE REGN NO. TOMER SHD6675Y COMPORT TRANSPORTATION PTE LTD FUEL vi8 7010045 MERCEDES BENZ TOMER NO. 383 SIN MING DRIVE 26.07.2018 09:45 MOOREL FIESS Singapore SINGAPORE 575717 E220CDI(E6) 65508755 YR OF MANU. 23.03.2016 TARGET DATE (R) (P) CHASSIS CODE WDD2120012B308245 COMPLETION DATE/TIME SOUNT CARD NO.


JOB DESCRIPTION

Accident Date: 19.07.2018

NATURE: 3P 19.07.2018

S/NO

LABOR CODE



ECKED & PASSED OUT BY:			
SERVICE ADVISOR			CUSTOMER'S SIGNATURE
reledgement Sto		Exit Pass	
SHD6675Y CH	IANG	Venicia No. SHD6675Y	
of Service Advisor returned to Service Reception upon collection	Signature/Date	Name of Service Advisor To be kept by Secority Guaro	Contra

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 6675Y

DATE 26/7/2018 10:22

DEL	: MERCEDES BENZ			MGL			
Qty	Parts Description/ La	bour	Type	Unit P	rice	-	Amount
	Rear Bumper					S	1,510.00
	Rear Bumper Reinforcement ?	2011			125.00	S	1,150.00
	Rear Bumper Bracket Lower (LH/			S	135.00	S	270.00
	Rear Bumper Bracket Top (LH/RH	_		S	125.00	S	250.00
	Rear Bumper Retainer Mounting (Rear Bumper Covering	LH/KH) -		S	115.00	S	230.00
	ACCOUNT OF THE PARTY OF THE PAR					S	55.00
	Rear Panel End X Rear Panel Inner Garnish X					S	1,380.00
	Rear Panel Inner Garnish Clip (10)	naa) L				S	40.00
	Batkil	pes) /				3	40.00
	Batho	SUB TOTAL				s	5,125.00
		LESS 20%				5	1,025.00
	DISC	OUNTED TOTAL				S	4,100.00
							111111111
	Rear Bumper Sensor					s	388.00
	Rear Bumper Rubber Mat					s	50.00
	Enter the 25 Transaction (60 € 1 or 0 or					-	
						S	438.00
	Labour Charge	LIOCADII Covi the Repairs	en five	lasty	1		300
	Panel Beating	• To meaning		T		\$	490.00
	Spray Painting Charge	To display (iii) Pam (iiii)		- Lines	200	8	340.00
	Wiring Charge	. 7		stoe"basis		S	× 50.00
	Remove/Refix Reverse Sensor	• Ni		ed and		\$	120.00
		8100000000			1		٠,٠
		TOTAL LABOUR				S	820.00
	1 11/4 FS	STIMATE TOTAL				S	5,358.00
	Kahn 1 Cick	Torrat					2,000,00
	Kohn 1 Clle ES 1/ 26/7/18 1135 3 Pys PIP Betoe Paint	thr.					
	prv= 1 · q	,	1/4/	7010 102 123	V 0		
	This is an initial estimate based on a v						
	quantum will be prepared after the veh	ticle is surveyed by a	motor Sur	vevor appoint	ed		

OMFORTDELGRO ENGINEERING

Our Ref :

T 0718 / SHD6675Y /CL(st)

Your Ref. Date

16-Aug-18

AIG ASIA PACIFIC INSURANCE PTE LTD

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

CDGE Taxi Claims Dept

Singapore 508969

59 Loyang Drive 4th Floor

Facsimilie +65 6280 9755

CHARTIS Buliding

78 Shenton Way

#07-16

Workshops

Singapore 079120 Attn: Motor Claims Department

WITHOUT PREJUDICE

Braddell Singapore 579701

www.cdge.com.sq.

Dear Sir

59 Loying Driv Singapore 5089617

ACCIDENT INVOLVING OUR TAXI AND OTHER

SHD6675Y YOUR INSURED SKG9818G ON 19.07.18

Sin Ming 383 Sin Miro Drive Singapore \$75717

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : SHD6675Y which was involved in the captioned accident with your insured vehicle to support the captioned accident The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

Singapore 408649 Senako 24 Semoko Loop Singilijore 758158

As the accident was caused by the negligent act of your insured driving SKG9818G we are submitting these claim for your consideration on behalf of the claimants.

Sungel Kadut 7 Sunger Kadut Way

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 5,439.02
2	3 days Loss of Rental @ \$ 179.57 per day	\$ 538.71
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation	\$ -
	Sub Total :	\$ 5,985.22

501 Yehrun Industrial Park A Singapore 768732

HIRER'S CLAIM

3 days Loss of Income @ \$ 80.00 per days

S 240.00

6,225.22

F 400 00

Total Claims: \$

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs: a)

8 pcs.

b) LTA search slip/s of : SKG9818G

c) GIA / Police report/s of : SHD6675Y

d) Letter of authority from owner / hirer / operator

(X) Photograph/s of Accident Scene

() Certificate of Insurance

() Witness statement/s

(x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Cecilia Lee Executive

CDGE Claims Department

Tel: 6214 8354 Fax: 6214 1843 Email: cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

A member of









Asher Sng (LKKAuto)

From:

Asher Sng (LKKAuto)

Sent:

Wednesday, 12 September 2018 3:03 PM

To:

CLWH0466@YAHOO.COM

Subject:

ACCIDENT INVOLVING SKG 9818G AND SHD 6675Y ON 19/07/2018

Our Ref: CC3/AIG18013680/K1eb3

12 SEPT 2018

LEE CHENG, MEI-MAN

Dear Sir/Madam.

ACCIDENT INVOLVING SKG 9818G AND SHD 6675Y ON 19/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher

Case Handler DID: 6841 6051 FAX: 6741 4108

Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd

(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

ALONG

MERCEDES E220 SHD6675Y , SKG9818G

VICTORIA ST X BRAS BASAH RD

ON 19-Jul-18 12:05

I/We

CHU TECK MIN

(Hirer) NRIC No.: \$1591773C

and/or

TOH LAM YONG

(Relief) NRIC No.: 56823511A

Taxi Number

SHD6675Y

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque. shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of

"ComfortDelGro Engineering Pte Ltd".

Date

19-Jul-2018

Name of Hirer

CHU TECK MIN

Hirer NRIC

S1591773C

Signature :

Address

532 SERANGOON NORTH AVENUE 4 ...

550532

Contact No.

96900299

Name of Relief

TOH LAM YONG

Relief NRIC

S6823511A

Signature :

Address

701 HOUGANG AVENUE 2 04-33

530701

Contact No.

92307701

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS 6020.00 (Global Sum) for vehicle no. SHD 6675Y that was damaged pursuant to the accident which occurred on 19/07/2018 (date) along VICTORIA ST X BRAS BASAH ROAD (location) involving vehicle no/s SKG 9818G.

This is pursuant to the inspection conducted on 26/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>COMFORT TRANSPORTATION</u>

<u>PTE LTD</u> ("the third party claimant") of vehicle no. <u>SHD 6675Y</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHD 6675Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this (day) of ((month) 20 (year)
Naz (LKK)	CLAIMS DEPARTMENT COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD SINGAPORE 579701
Signed by appointed surveyor	Signed by "the workshop" (with chop)

Please forward your cheque made payable to COMFORTPELGRO ENGINEERING PTE LTD

COMFORTDELGRO ENGINEERING

A member of COMFORDELCRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Brandell Flood Singapore 579701 Malmino + 65 8363 6200 Faccionie + 65 6290 9755

Workshops

88 Louing Drive Singapore \$56999 . 383 Sin Ming Crive Singapore 575717 45 Pandan Road Singapore 639288 24 Senoto Luco Surgepore 758156 7 Surger Katha Way Surgepore 728791 501 Yelson Industria Park A Engagese 70873 370 Uhi Road 3 Singapore 408648

> COMPANY REG. NO.: 199506048W Page: 1

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, CHARTIS BUILDING #08 SINGAPORE SG 079120

CONTACT NO: 64193000

Description : 3P 19.07.2018

3225094

VEHCLE NO SH06675Y

INV. NO/DATE 91387269 31.07.2018

MAKE MERCHERS BENZ

JOB NO. 305192470

MODRI. E220CDI(86)

ODOMETER READING

DATE OF REG 23.03.2016

DATE/TIME IN 26.07.2018 09:45

CHASSIS CODE

WDD2120012B308246

Oty Unit Price %Disc

Net

PART	REOUT	SITI	ON

S/No Part No.

PART	REQUISITION					
0001	04-01-0202-2282	212VB RRAR HUMPRR ASSSY	3.	1,510.00	20.00	1,208.00
0002	04-01-0202-0809	212VC REARLID	1	2,470.00	20.00	1,976.00
0003	04-01-0202-2252	212VA/211B BOOTLID R220 L	1.	52.00	20.00	41.60
0004	09-01-0299-2005	(212/211B)REVERSE SENSOR		388.00	0.00	388.00
0005	04-01-0103-1150	140VC PROTECTOR MAT	3.	50.00	0.00	50.00
0006	04-01-0202-2152	212VB BEURTEC EMBERM AT T	7.	60.00	20,00	48.00
0007	04-01-0202-2105	(212)TRUNK LID MERCEDRS S	3	43.00	20.00	34,40
8000	23-01-0202-2001	(212)TRUNKLID FASTENER NU	4	3.50	20.00	11.20
0009	04-01-0202-2283	212VH REAR HUMPER LOWER C	1	325.00	20.00	260.00
0010	01-01-0202-2013	(212)COMPRESSOR COVER	1.	35.00	20.00	28.00
0011	04-01-0202-2124	(212)PANELLING LOADING ED	1	115.00	20.00	92.00

ComfortDelGro Engineering Pte Ltd

A member of COMFORTCELCING

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91.387269	5,439.02	

Kindly note that no receipt shall be issued unless requested.



A member of COMFORDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

Montine - 85 6363 6260. Faccinité + 65 6260 9755.

Workshoos

330 Utr Road 3 Singapore 408849

188 Leyang Drive Bingapore 586969 54 Sandkir Libb Bingapore 758156 55 Ser Ming Drive Singapore 575717 7 Bungoi Kadul Way Singapore 758797 45 Paretan Road Singapore 505200 501 Vision totality Park A Singapore 75879

COMPANY REG. NO.: 199506048W

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, CHARTIS BUILDING #08 SINGAPORE SG 079120

CONTACT NO: 64193000

3225094

VEHCLE NO SHD6675Y

INV. NO/DATE 91387269 31.07.2018

MAKR MKRCEDKS BENZ JOB NO. 305192470

MODEL E220CDI(R6) ODOMRTER READING

DATE OF REG 23.03.2016

SUB-TOTAL

DATE/TIME IN 26,07,2018 09:45

730.00

CHASSIS CODE WDD2120012B308246

S/No	Part. No.					Qty	Unit Price	%Disc	Net:
0012	04-01-0202-3886	21.2VB	BUMPER	BRACKET	RR/L	1	135.00	20.00	108.00
0013	04-01-0202-3986	212VB	BUMPER	BRACKET	RR/R	1	135.00	20.00	108.00
						SUB-TOTAL		4,35	53, 20

JOB NATURE

0001	L	PANKI, HKATING	300.00	300.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	400.00	400.00
0003	20-22	REMOVE/REFIX REVERSE SENSOR	30.00	30.00

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELCAGE

Head Office:

205 Braddell Road Singapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT** 5,439,02 8010004 91387269

Kindly note that no receipt shall be issued unless requested.

COMFORTDELGRO ENGINEERING

A member of COMFORDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Sreddell Road Singapore 579701 Mardina + 85 6363 6260 Facerolle + 65 6260 9750

Workshops

59 Loyeng Drive Singapore 505059 053 Sin Ming Drive Singapore 57571* 45 Pandan Read Singapore 625266 200 Utr Road 5 Singapore 408649

24 Senote Lone Bingspore /18136 7 Songer Hattef Way Singspore 728791 501 Yester Hillattis Park A Singspore 75875

COMPANY REG. NO.: 199506048W

Page: 3

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY.CHARTIS BUILDING #08 SINGAPORE SG 079120

CONTACT NO: 64193000

3225094

VEHCLE NO SHD6675Y

INV. NO/DATK 91387269 31.07.2018

MAKE MERCEDES BENZ

JOB NO. 305192470

MODEL. K220CDT (E6)

CHAMETER READING

DATE OF REG 23.03.2016

DATE/TIME IN 26.07.2018 09:45

CHASSIS CODE WDD2120012B308246

Items total

5,083.20

Add GST @

7,000 %

355.82

Invoice amount

5,439.02

Issued by

KATHERINETAN 01.08.2018 11:07:23

Payment Type/Term: /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELCRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. AMOUNT 8010004 91387269 5,439.02

Kindly note that no receipt shall be issued unless requested.

Our Ref: CT18070556

Date: 01 August 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

19/07/2018 @ 12:05 hrs

ALONG

VICTORIA ST X BRAS BASAH RD

INVOLVING

SKG9818G

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHD6675Y (the "Taxi"). The Taxi was hired to CHU TECK MIN IC NO S1591773C a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$179.57 per day (inclusive of GST).

Please be advised that the Taxi was insured with India International Insurance Pte Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

The second second	(
		100 15	MILEAGE	HOURS OPERATED (TIME	ATED (TIME	DATE	NAME OF DRIVER
Date	NAME OF DRIVER		TRAVELLED	FROM	10		
1100	N		370	547	DOUTS		
BANGE.	Chilar	2000	202	4.100m 3.5541	3. Clar		
23718	KIGNES	0 - 2 + + 3	000	4	15.13		
S. Complete	Second.	4 6 8 7 7	293	04.35	2.3		
S (1) C	D. Charl	ヒトダナダー	t27	4000	10 MCN		
4 1 1	, , ,	478787	345	18.25			
550010	Mr. M.	0 7 0 5 0	(16)	4.100m	5 50 m		
25118	KI Grewy	+	1	SOW S	\		
7007	Acciding		M	1	(W)		
100	Nepan	3	(10)	\	3		
20							

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SKG9818G 19 Jul 2018 / 12:05:00 Successful A04 AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING									
Case:	Notified	Est Submitted	Adj Assigned	Adj Rpt		Ad) S	Submitted	Ins Auth'ed	1	Status	
Main	23 Jul 2018 Edit Reg		26 Jul 2018 00:00 Edit Adj Rpt	S\$5,083 Edit Est			083.20 w Rpt			Pending for Report Cancel Case	
	Main		Reference		laim Det	alls		Docume	nts	\neg	Show All
CLAIM SU	BFOLDER D	ETAILS					[Created	by adjuster]		_==-	
Insured:	Lee Chen	g, Mei-Man, II): F1287521P								
Main Claimant:	COMFOR	TRANSPORTA	TION PTE LTD. Co	Reg. No.:	1993038	21R					
Vehicle Rep No.:	SHD667	5Y			Date of	Loss:		8 12:00 - :59 s and 26 Days	From L	TA Reg Date	(Man Yr)]
Claim Type	TP / 797	0285506SG			Policy/C Note No						
Vehicle Rep No. (Insured):	SKG9818	G			Policy N (Claima		MCOM0015				
					Excess:						
Repairer:	ComfortD	elGro Engineer	ing Pte Ltd (Loyans	 59 Loyar 	ng Drive,	50896	9 Loyang -	Tel: 6214 8300			
Handling Insurer:	AIG Asia	Pacific Insuran	ce Pte. Ltd. (Expres	s) - Tel: 6	5-6419-3	000	. [Handled t	y Wul, Shawn	-KJ) 5	hawnkaijye.\	Vui@aig.co
Claimant's Insurer:	India Int	ernational Insu	rance Pte Ltd (HQ)	- Tel: 634	76100						
Adjuster:	07/08/2		e Ltd (HQ) - Tel: 62	56-3561	[Handled	by K	ALVIN AND	WEI KUN]	. [Fina	al Rpt due	
ASSOCIA	TED MAIL RE	CEIVED						A	View All	Compo	se Case Mail
There are r	o mail for this	case.									
ALL ASSO	CIATED TAS	ks⊟				v	lew All 5	Search Tasks	Create	New Task	Complete
Due Dat No results.	51 07700000	Type Tas	k Group Subjec	t Hand	ler A	ssign	ed By	Completed O	in	Created O	

Claim Documents

*SHD6675Y (7970285506SG)

[SKG9818G]

TP

COMFORT TRANSPORTATION PTE LTD

Jul 19 2018 12:00PM

[Lee Cheng, Mei-Man]

ComfortDelGro Engineering Pte Ltd

Let	ters/Corresponder	nces	1 per	page 🔻	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page V	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1 per	Thumbnail	-
1	30/07/18 12:00	Accident Statement	0	Load HTM	7.1111
		From: OD - Reg. No: SKG9818G, Claimant: LEE CHENG, MEI-MAN		100011111	_
Pho	otos/Images		3 per i	page [v]	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
1	27/07/18 17:39	General View	0	Load JPG	V
2	27/07/18 17:39	General View	0	Load JPG	1
3	27/07/18 17:39	General View	0	Load JPG	V
4	27/07/18 17:39	General View	0	Load JPG	V
5	27/07/18 17:39	General View	0	Load JPG	V
6	27/07/18 17:39	General View	0	Load JPG	V
7:	27/07/18 17:39	General View	0	Load JPG	V
B.	27/07/18 17:39	General View	0	Load JPG	V
9	27/07/18 17:39	General View	0	Load JPG	1
10	27/07/18 17:39	General View	0	Load JPG	₹
11	27/07/18 17:39	General View	0	Load JPG	12
12	27/07/18 17:39	General View	0	Load JPG	V
13	27/07/18 17:39	General View	0	Load JPG	V
14	27/07/18 17:39	General View	0	Load JPG	V
15	27/07/18 17:39	General View	0	Load JPG	V
16	27/07/18 17:39	General View	0	Load JPG	52
17	27/07/18 17:39	General View	0	Load JPG	V
18	27/07/18 17:39	General View	0	Load JPG	V
19	27/07/18 17:39	General View	0	Load JPG	3
20	27/07/18 17:39	General View	0	Load JPG	V
21	27/07/18 17:39	General View	0	Load JPG	V
22	27/07/18 17:39	General View	0	Load JPG	Z
23	27/07/18 17:39	General View	0	Load JPG	1
24	27/07/18 17:39	General View	0	Load JPG	V
25	27/07/18 17:39	General View	0	Load JPG	V
26	27/07/18 17:39	General View	0	Load JPG	V
27	27/07/18 17:39	General View	0	Load JPG	V
28	27/07/18 17:39	General View	0	Load JPG	V
29	30/07/18 16:57	Reinspection Photo	0	Load JPG	[2]
30	30/07/18 16:57	Reinspection Photo	0	Load JPG	V

Merimen e-Claims

Let	ters/Corresponder	nces	1 per p	age 🗸	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
31	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
32	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
33	30/07/18 16:57	Reinspection Photo	0	Load JPG	7
34	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
35	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
36	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
37	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
38	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
39	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
40	30/07/18 16:57	Reinspection Photo	0	Load JPG	\mathbf{Z}
41	30/07/18 16:57	Reinspection Photo	0	Load JPG	1
42	30/07/18 16:57	Reinspection Photo	0	Load JPG	V
43	30/07/18 16:57	Reinspection Photo	0	Load 3PG	V
Doc	umentation		[1 per p	age 🔽	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
1	30/07/18 10:06	TP ESTIMATE- MARKED	0	Load PDF	
2	30/07/18 10:06	TP GIA REPORT	0	Load PDF	
3	12/09/18 15:18	LETTER TO OI	0	Load PDF	
4	22/10/18 09:38	WORKSHOP INVOICE	0	Load PDF	
5	22/10/18 09:38	AUTHORISATION TO ACT FORM	0	Load PDF	
6	22/10/18 09:38	Release Voucher	0	Load PDF	
7	22/10/18 09:38	RENTAL RECEIPT	0	Load PDF	
В	22/10/18 09:38	RENTAL MILEAGE	0	Load PDF	
9	22/10/18 09:38	LTA SEARCH	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Nota: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

T			
I = A M			

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Veh	icle No:	SKG9818G (Insd vel	h)	Model:	MERCEDES-BENZ E220 2.0
		SHD6675Y (TP veh)			(A)
Dat	e of Accident:	19/07/2018			1000
01-1	bal Sum Settlem				1
	to a section of the s	ent : [X] Yes	Lal	[] No	1
	pair Estimate		: \$	8,460.70	
	al Repair Cost		: \$	6,020.00	
	s of Use		: \$		2.50 days at \$50.00 per day
_	ntal (if any)		: \$		2.50 days
LTA	/ GIA Search Fe	ee	: \$		
Oth	ers:		: \$		
			: \$		
Fina	al Settlement Sur	m (Global Sum)	: \$	6,020.00	
ls T		kshop GIA Registered	3 [X] YES	[] NO (Kindly indicate
A)	For Non GIA R	egistered Workshop:		Agreed Liability	(%)
B)	For GIA Regist	ered Workshop:		BOLA Applicabl	e: Yes/-NoBOLA Scenario No:
		100(%) bility to be filled only for	chain c		ity (*):(%) ases where BOLA does not apply.
Ren	narks				
Pay	ment Instructio	n: Payee's Breakdow	n		
1)	ComfortDelGro	Engineering Pte Ltd		: \$	6,020.00
2)				: \$	
3)				: \$	
4)				: \$	

JOANNE LEE KHANG MIN 22 Oct 2018

LKK Auto Consultants Pte Ltd Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG18013680/K1EB3Q2

Date:

22/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100303754

Claimant Vehicle SHD6675Y No:

Insured Vehicle No:

SKG9818G

Date of Loss:

19/07/2018

Nature of Claim:

TP

Claim No: 7970285506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHD6675Y

Make & Model:

MERCEDES-BENZ E220, 2.0 (A)

Engine No:

65192433098644

Reg. Date: Colour:

23/03/2016 (Man. Year: 2015) White

Chassis No:

WDD2120012B308246

Odometer:

479269 km

Engine Capacity:

2143 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/55 R16

Rear Tyre Size:

225/55 R16

Front Left Side: Front Right Side: West Lake 7 mm West Lake 7 mm Rear Left Side: Rear Right Side:

West Lake 7 mm West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,837.20	4,353.20	2,484.00	36.33
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,070.00	730.00	340.00	31.78
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Towing	Gross Total (S\$)	7,907.20	5,083.20	2,824.00	35.71
	+ GST 7.00/7.00% (S\$)	553.50	355.82	197.68	35.71
	Nett Amount (S\$)	8,460.70	5,439.02	3,021.68	35.71
	+ Loss of Use (2.5 x 5	\$\$50.00/day) (\$\$)	125.00		
	+ Car Rental (2.5 x S	\$179.57/day) (S\$)	448.93		

+ Doc/Search Fee (S\$) 7.49 Nett Liability (S\$) 6,020,44 6,020.00 Global Sum Settlement (S\$)

INSPECTION

Date of Assignment:

26/07/2018

Date Inspected:

26/07/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

Adjuster Report

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

3.0 days

Adjuster: KALVIN ANG WEI KUN Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,510.00 FL	*1,510.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	1,150.00 FL	*-FL
3	2		*REAR BUMPER BRACKET LOWER (LH/RH)	Cracked	270.00 FL	*270.00 FL
4	2		*REAR BUMPER BRACKET TOP (LH/RH)	Serviceable	250.00 FL	*-FL
5	2		*REAR BUMPER RETAINER MOUNTING (LH/RH)	Serviceable	230.00 FL	*-FL
6	1		*REAR BUMPER COVERING	Serviceable	55.00 FL	*-FL
7	1		*REAR PANEL END	Serviceable	1,380.00 FL	*-FL
8	1		*REAR PANEL INNER GARNISH	Cracked	115.00 FL	*115.00 FL
9	10		*REAR PANEL INNER GARNISH CLIP	Not Necessary	40.00 FL	*-FL
10	1		*REAR BUMPER LOWER	Cut	325.00 FL	*325.00 FL
11	1		*REAR BUMPER SENSOR	Shorted	388.00 FS	*388.00 FS
12	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
13	1		*BLUE TEC EMBLEM	Necessary	60.00 FL	*60.00 FL
14	1		*MERC STAR EMBLEM	Necessary	43.00 FL	*43.00 FL
15	1		*E220L EMBLEM	Necessary	52.00 FL	*52.00 FL
16	1		*FASTENER NUT	Necessary	14.00 FL	*14.00 FL
17	1		*COMPRESSOR COVER LH	Cracked	35.00 FL	*35.00 FL
18	1		*BOOTLID	Dented	2,470.00 FL	*2,470.00 FL
F=Fm	inchise	part. S=Spcl	Nett. L=ListItemDisc.			
	Sub Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)					5,332.00
						978.80
				Total Parts (S\$)	6,837.20	4,353.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	300.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
		Gross Labour Cost (S\$)	1,070.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >