



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

27 July 2018

HHTPClaims18-78

India International Insurance Pte Ltd
64 Cecil Street, IOB Building
#04-00 / #05-00
Singapore 049711

Attn: Motor Claims Department

ACCIDENT INVOLVING SLU 9383 H & SHD 3372 R ON 15/7/2018 ALONG HOLLAND DR AT ABOUT 1835 HOURS

Insured : HUA HONG PTE. LTD.
Vehicle Registration No : SLU 9383 H
Vehicle Make : TOYOTA
Vehicle Model : SIENTA 1.5X HYBRID AT ABS D/AIRBAG 2WD
Vehicle Chassis No : NHP1707075625
Policy No : 5087272209-01
Date of Accident : 15/7/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Side Mirror (RH)		\$ 695.00 <i>see</i>
2	1	Front Side Mirror Cover (RH)		\$ 75.00 X
3	1	Front Side Mirror Signal Lamp (RH)		\$ 95.00 <i>see</i>
				\$ 865.00
			Less 20%	\$ (173.00)
				\$ 692.00
		To dismantle & refit front RH door trim to change front RH side mirror rear panel and all area affected by accident.		\$ 150.00 <i>100</i>
		To perform wire checking.		\$ 20.00
		To spray front RH side mirror cover		\$ 100.00 X
				\$ 962.00
			7% GST	\$ 67.34
			Total	\$ 1,029.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
1 day 7/8
30/07/18 @ 1040
Reg by paint



Authorised by Claims Dept
Mrs Tan @ 9639 9195