



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	21/07/2018
Vehicle Reg. No.:	SFS131J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHEN KIEN PIN(CHEN JIANBIN)		
Make/Model:	TOYOTA LEXUS, 3.5 RX350 STD (A)	Vehicle Reg. Date:	04/02/2015
Vehicle Colour:	BLUE	Chassis No:	JTHHE5BC705002354
Engine No:	2GR8887117		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	9		
Description of Accident/Loss	PLEASE REFER TO THE SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	48,273.39
Miscellaneous Items	10.00
Labour	4,130.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	52,413.39
+ GST 7.00% (\$\$)	3,668.94
Nett Amount (\$\$)	56,082.33

This claim is handled by: AH WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2018)
Parts: 143	TOYOTA LEXUS 3.5 RX350 STD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFS131J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*REAR BOOT LAMP L+R	10.00	0.00	*2,217.20 FL
2	1		*REAR BOOT	10.00	0.00	*2,158.70 FL
3	1		*REAR BOOT WEATHERSTRIP	10.00	0.00	*451.30 FL
4	1		*REAR END PANEL TOP GARNISH	10.00	0.00	*641.30 FL
5	10		*REAR END PANEL TOP GARNISH CLIPS	10.00	0.00	*50.00 FL
6	1		*REAR BOOT LOGO (RC350)	10.00	0.00	*82.50 FL
7	1		*REAR BOOT LOGO (LEXUS)	10.00	0.00	*89.10 FL
8	1		*REAR END PANEL	10.00	0.00	*956.10 FL
9	2		*REAR FENDER LAMP L+R	10.00	0.00	*1,797.80 FL
10	2		*REAR FENDER LAMP LOWER BRACKET L+R	10.00	0.00	*250.40 FL
11	2		*REAR BUMPER RETAINER L+R	10.00	0.00	*484.62 FL
12	2		*REAR BUMPER SCREW COVER L+R	10.00	0.00	*185.20 FL
13	3	IPC	*REAR PARKING SENSOR	10.00	0.00	*2,067.30 FL
14	1		*REAR BUMPER LOWER GARNISH	10.00	0.00	*590.30 FL
15	1		*REAR BUMPER REFLECTOR LH	10.00	0.00	*78.20 FL
16	1		*REAR EXHAUST CHROME LH	10.00	0.00	*778.20 FL
17	1		*REAR EXHAUST LH	10.00	0.00	*1,250.20 FL
18	1		*REAR BUMPER TOW COVER	10.00	0.00	*25.80 FL
19	1		*REAR REINFORCEMENT	10.00	0.00	*1,190.70 FL
20	1		*REAR REINFORCEMENT SPONGE	10.00	0.00	*195.60 FL
21	1		*REAR KEYLESS SENSOR	10.00	0.00	*364.60 FL
22	1		*REAR BOOT LOCK	10.00	0.00	*705.83 FL
23	1		*FRONT BUMPER	10.00	0.00	*1,250.40 FL
24	1		*FRONT GRILLE	10.00	0.00	*2,972.20 FL
25	1		*FRONT GRILLE LOWER	10.00	0.00	*770.60 FL
26	1		*FRONT EMBLEM	10.00	0.00	*789.40 FL
27	1		*FRONT NUMBER PLATE GARNISH	10.00	0.00	*185.90 FL
28	1		*NUMBER PLATE	0	0.00	*45.00 FS
29	1		*FRONT BUMPER LOWER GARNISH	10.00	0.00	*698.00 FL
30	2		*FRONT BUMPER RETAINER L+R	10.00	0.00	*282.60 FL
31	2		*FRONT HEADLAMP LOWER BRACKET L+R	10.00	0.00	*157.20 FL
32	2		*FRONT HEADLAMP L+R	10.00	0.00	*15,082.40 FL
33	2		*FRONT PARKING SENSOR CENTRE	10.00	0.00	*10,982.20 FL
34	2		*FRONT PARKING SENSOR COVER	10.00	0.00	*51.60 FL
35	1		*FRONT REINFORCEMENT	10.00	0.00	*935.10 FL
36	1		*FRONT REINFORCEMENT SPONGE	10.00	0.00	*157.20 FL
37	1		*FRONT REINFORCEMENT TOP GARNISH	10.00	0.00	*168.50 FL
38	1		*FRONT RADIATOR TOP GARNISH	10.00	0.00	*385.70 FL
39	10		*FRONT RADIATOR TOP GARNISH CLIPS	10.00	0.00	*50.00 FL
40	1		*FRONT BONNET LOCK - CHECK	10.00	0.00	-
41	1		*FRONT BONNET CATCH	10.00	0.00	*275.90 FL
42	1		*REAR BUMPER	10.00	0.00	*1,781.25 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	53,632.10
- List Item Discount on L Items (\$\$)	5,358.71
Total Parts (\$\$)	48,273.39

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REPAIR FRONT SUPPORT PANEL, FRONT FENDER L+R, REAR FENDER LH, REAR SPARE TYRE HOUSE, REAR FENDER LH AND REALIGN AFFECTED AREAS	New <i>600</i>	1,400.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New <i>600</i>	1,550.00
3	TO RUST PROOF AFFECTED AREAS	New <i>XMM</i>	80.00
4	TO REMOVE & REFIX REAR CUSHION, REAR BACK REST, SIDE GARNISH AND OTHER ATTACHMENT PARTS	New <i>60</i>	100.00
5	TO APPLY SEAL ON WELDING JOINT & NEW PARTS	New <i>?</i>	80.00
6	TO CHECK CHASSIS ALIGNMENT	New <i>MMX</i>	350.00
7	TO REMOVE & REFIX AIRCON CONDENSER & TOP UP GAS	New <i>1X</i>	120.00
8	TO INSPECT FRONT LIGHTING & WATER LEAKAGE TEST	New <i>30</i>	80.00
9	TO REMOVE FRONT & REAR PARKING SENSOR AND CHECK WIRING	New <i>40</i>	120.00
10	TO RE-CONFIGURE FRONT HEADLAMP COMPUTER BOX	New <i>?</i>	250.00
Gross Labour Cost (\$\$)			4,130.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*5 Days .
part by part .
before paint photos .
Gmo Q:ay - 82880282
27/7/18 .*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: