

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

861 0830 31/7

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE	Document No.	: SQT18003121	Page	1
	64 CECIL STREET	Date	: 26. Jul 2018		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	:		
Registration No	: SLA9235H	Engine No	: L15Z12871348		
Chassis No	: MRHDD4870GP000090	Date Time	: 26. Jul 2018 9:17:29 AM		
Model	: MOBILIO YM 2016	Surveyor Name	:		
Owner's Name	: LUI HUI YONG AMY	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 25/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:LUI HUI YONG AMY						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:25/07/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH:SH7115P						
73225-TE7-K00	RUBBER A WINDSHIELD DAMPER	1	18.10	25	13.57	0.95	14.52
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.50	25	14.25	1.00	15.25
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
68100-TRD-K10ZZ	TAILGATE COMP	1	1092.30	25	819.22	57.35	876.57
74440-TE7-K01	WEATHERSTRIPTAILGATE	1	62.80	25	47.10	3.30	50.40
74801-TF0-902	LOCK ASSYTAILGATE	1	174.70	25	131.02	9.17	140.19
74813-SEY-003	STRIKER ASSYTAILGATE	1	27.20	25	20.40	1.43	21.83
74830-TE7-K00	CABLETAILGATE OPENER	1	5.10	25	3.82	0.27	4.09
75722-TE8-K00	EMBLEM SETRR.MOBILIO	1	18.30	25	13.72	0.96	14.68
75725-TRD-T00	EMBLEMRR.I VTEC	1	11.90	25	8.92	0.62	9.54
75723-TE7-K90	EMBLEMRR.RS	1	17.30	25	12.97	0.91	13.88
71501-TE7-K90ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71502-TE7-K90	MOLDINGRR.BUMPER	1	109.10	25	81.82	5.73	87.55
33555-TE7-T11	REFLECTOR ASSY (RIGHT REAR)	1	15.00	25	11.25	0.79	12.04
71570-TE7-K90	ABSORBERR.RR.BUMPER	1	60.20	25	45.15	3.16	48.31
71575-TE7-K90	ABSORBERL.RR.BUMPER	1	60.20	25	45.15	3.16	48.31
71593-TE7-K01	SPACERR.RR.BUMPER SIDE	1	27.60	25	20.70	1.45	22.15



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
 64 CECIL STREET
 #04-00 & #05-00 IOB BUILDING
 SINGAPORE 049711

Registration No : SLA9235H

Chassis No : MRHDD4870GP000090

Model : MOBILIO YM 2016

Owner's Name : LUI HUI YONG AMY

Ins Policy No. :

Date of Accident : 25/7/2018

Document No. : SQT18003121 Page 2

Date : 26. Jul 2018

Customer No. : WZI007

Svc Advisor :

Engine No : L15Z12871348

Date | Time : 26. Jul 2018 9:17:29 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71598-TE7-K01	SPACERL.RR.BUMPER SIDE	1	27.60	25	20.70	1.45	22.15
91505-TG1-T01	CLIP ABUMPER	2	6.10	25	9.15	0.64	9.79
84640-TE7-K01ZB	LINING ASSYRR.PANEL	1	60.80	25	45.60	3.19	48.79
66100-TE7-K10ZZ	PANEL COMP.RR.	1	314.70	25	236.02	16.52	252.54
Sum Item					2090.50	146.34	2,236.84
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BA01R	REMOVE & INSTALL REVERSE SENSORS-2 PCS (N)	1	150.00		150.00	10.50	160.50
BOBC	BODY UNDERSIDE COATING (N)	1	350.00	X	350.00	24.50	374.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	X	450.00	31.50	481.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	5000.00	2800	5000.00	350.00	5350.00
BP05R	SPRAY PAINTING ON TAILGATE, RR BUMPER, RR PANEL,	1	3000.00	2700	3000.00	210.00	3210.00
BOJSE	SEALANT FOR REAR END PANEL	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	80.00	X	80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BOMISC1	REMOVE AND ALIGN REAR VIEW CAMERA	1	380.00		380.00	26.60	406.60
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	X	560.00	39.20	599.20
Sum Labor					12190.00	853.30	13,043.30

Survey By

Date & Time

Excess

Status

Repair - Hp 9000000

31/07/18 @ 1145

8 days

Reay by paint

Total Amount 14,280.50 999.64 15,280.14

Total (Inclusive of GST) 15,280.14

Printed on 26/7/2018 9:36:06 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE	Document No.	: SQT18003121	Page	3
	64 CECIL STREET	Date	: 26. Jul 2018		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	:		
Registration No	: SLA9235H	Engine No	: L15Z12871348		
Chassis No	: MRHDD4870GP000090	Date Time	: 26. Jul 2018 9:17:29 AM		
Model	: MOBILIO YM 2016	Surveyor Name	:		
Owner's Name	: LUI HUI YONG AMY	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 25/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Signature	_____						

Printed on 26/7/2018 9:36:06 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)