

2/10/2018

ASS. REC. BY:

REF:

CS/CTI18013689/4-13/18

Special Instructions:

Surveyor
menmen

Marcus

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTI

Date/Time:

26/7/18 @ 3:13pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJK 88712

Insured:

SLN 7843Y

at Workshop m/s:

Rico Go Auto

Tel:

62866060 / 9069 7882

of

8/keki Bkt Ave 4 # 02-24 premier

Policy No:

DMHCSN1736121801

Claim No:

SNM18D03652C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 21/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:56am 027/7/18

Person Contacted:

Kelvin

Vehicle IN OUT

Date/Time

Action/Instruction

(✓) Estimate

SJK 88712 - X

SLN 7843Y - NBA/CTI18010912/K4

DOA: 13/6/2018

(05/1/13) wel

ASS REC BY: Marcus

REF:

C74/
ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

31/8/2018

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

car used 6-11-2018 but renew to yr 31/8/2018
 renew car MV - GOK - LTA 3382 = 26438
 no renew car bal 3 months MV 10k?

10/8/18 Confirmed a/s @ 13500 m/s helven. (red: 24128: 64%)

RECEIVED 13 AUG 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 10/8 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

14

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I: (\$ 13,500/-)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Name	Est. Subm.	Est. Recd.	Ad. Subm.	Ad. Recd.	Ad. Auth'd	Status
Main	25 Jul 2018	26 Jul 2018 15:13					New Assignment Cancel Case

Mail

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

KIRALY AUTOMOBILE PRIVATE LIMITED, Co. Reg. No.: -

Main Claimant:

WEE POON HOE, ID: S1131419H

Vehicle Reg. No.:

SJK8871Z

Date of Loss:

24/07/2018 11:00 - :59

Claim Type:

TP / SNM18D03652C02

Policy/Cover Note No.:

DMHCSN1736121801 (Comprehensive)

Vehicle Reg. No. (Insured):

SLN7843Y

Policy No. (Claimant):

S097955644

Excess:

S\$0.00

Repairer:

RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]

Claimant's Insurer:

NTUC Income Insurance Co-operative Ltd (HQ) - Tel:

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/08/2018]

Driver/Customer (Insured):

HAM KOW YEN (39 / Male), NRIC: S7837393H, Tel: +6588285046

Adj Asg Remarks:

NO EST, ASSIGN ADRIAN LING AS SJE.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due

Handler

Assigned By

Completed On

Created On

Done?

No results.



RICO 60 AUTO SERVICES PTE. LTD.

Co. Reg. No.: 201807623M

Kaki Bukit Avenue 4, Premier @ Kaki Bukit, #02-24

Singapore 415875 | Email: enquiry@rico60.com

Tel: +65 6286 6060 | Fax: +65 6286 7060

PRI ARRANGEMENT

Date: 25/07/2018

To: Lim Jia Pin

ATTN: Motor Claims Department

RE: Accident involving motor vehicle nos. SJK 88712, SLN 78437 & SLK 63797
along CTE before Moulas in Hyoval on 24/07/2018 @ 11:50hrs

We refer to the above matter.

We are instructed by Wol Poin Hoe
to notify you of a road traffic accident on 24/07/2018 at about 11:50hrs
along CTE before Moulas in Hyoval
involving our client's vehicle no. SJK 88712 and vehicle no. SLN 78437
driven by you at the stated time.

Due to the above-mentioned accident, our client's vehicle has been damaged. Before our client/we proceed with the repair(s) of the damaged vehicle, please kindly let us know within 2 working days of your receipt of this notice, whether you or your insurer would like to conduct pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to the repair work(s) of the vehicle without further reference to you.

Thank you.


Signature

Name: Kelvin Wo

Mobile No.: 9069 7882



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013689/Utd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 7843Y	Veh. Inspected	SJK 8871Z
Policy No.	DMHCSN1736121801	Coverage (\$)	0.00
Claim No.	SNM18D03652C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	27/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/07/2018	Inspection Date	27/07/2018
Survey held at	RICO AUTO(8 KAKI BUKIT AVE 4# 02-24 PREMIER)		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/07/2018 12:54
Date Of Accident	24/07/2018 11:50
Exact Location Of Accident	CTE BEFORE MOULMEIN FLYOVER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK8871Z
Insured/Policyholder	
Name Of Registered Owner	WEE POON HOE
NRIC No	S1131419H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90991900
Alternative Phone No	OTHERS-90991900

Vehicle Particulars

Manufacturer	TOYOTA
Model	PREMIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097955644
Cover Note Number	

Driver

Name of Driver	WEE POON HOE
NRIC No	S1131419H
Date Of Birth	29/01/1955
Occupation	INDOOR
Date Of Driving Pass	09/09/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90991900
Fax Number	
Contact Number	OTHERS-90991900
Email Address	NOEMAIL

Address	BLK 474 #14-185 CHOA CHU KANG AVENUE 3
Postcode	680474
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK6379T
Vehicle Make/Model/Colour	TOYOTA SIENTA 1.5G CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NEO XIONG ZHU
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLN7843Y
Vehicle Make/Model/Colour	HONDA VEZEL HYBRID 1.5X AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HAM KOW YEN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

25 JUL 2018

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
Reporting Centre
Name: 23 KAKI BUKIT AVE 3
Singapore 415933
Tel: 67416697
NRIC/FIN No. Fax: 67492305
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1

Modulena Flyover

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle B was travelling straight along the said location. Suddenly vehicle C brake and I follow suit. I then felt an impact from my rear and realise that vehicle B has collided into my vehicle, my vehicle surged forward and collided into vehicle C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Weepr...

Policyholder's Signature
Date & Time:

Weepr...

Driver's Signature
(If driver is not the policyholder)
Date & Time:

25 JUL 2018

IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4

Reporting Centre
Name: *Singapore 119*
Tel: 67416697
Fax: 67492305
Email: *vackb@singnet.com.sg*



SELL YOUR CAR BY BIDDING

HIGHEST SELLING PRICE GUARANTEED!

OR GET \$100 CASH!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

BMW 523i PML Unit/Lowest Mileage/Showroom Condition



Genuine 5.2L 2300i Crown Platinum
Drive Away With \$1,250 Monthly
Installment
Direct Owner - [View Ad](#)

PRIME MOTOR & LEASING

(JOHNS YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

Sort by Date Posted 20 results/page

8 vehicles

Toyota Premio

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Premio	Any	Any	2008	Any	Any	Any	Available
	Toyota Premio 1.5A F (New 5-yr COE)	\$34,800	\$6,960 /yr	19-Aug-2008	1,496 cc	88,331 km	Sedan	Available
Only 1 Owner Low Mileage Super Reliable Premio For Sale! Fuel Efficiency Of 15km/L. Interior In Pristine Condition. Engine And Gearbox Healthy And Smooth. Interior Clean And Never Abused. Ideal For Co...								
Posted: 22-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota								
	Toyota Premio 1.5A (New 5-yr COE)	\$35,500	\$7,100 /yr	15-Sep-2008	1,496 cc	-	Sedan	Available
Lucky Win Pricedown Cars! Confirmed Selling Price! In House Finance Of \$30K With A Monthly Of \$555. Higher Grade Than A Toyota Altis But With A Cheaper Price Tag! Luxurious Interior. Please Call Our Pr...								
Posted: 22-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota								
	Toyota Premio 1.5A F (New 5-yr COE)	\$35,988	\$7,190 /yr	26-Nov-2008	1,496 cc	-	Sedan	Available
Value For Money, Responsive, Well Maintained, Good Condition. High Loan And Trade In Available. Call Us Now For Test Drive.								
Posted: 21-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota								
	Toyota Premio 1.5A F (New 5-yr COE)	\$36,800	\$7,360 /yr	26-Nov-2008	1,496 cc	-	Sedan	Available
10% Down Payment! Monthly \$686! Known As The Mini Toyota Crown. Luxurious, Reliable, Roomy Cabin And Elegant Look At Very Low Depreciation! Car Regularly Maintained. Only Minor Touch Up Required. Trad...								
Don Motoring								
Posted: 19-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota								

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

\$2233E

Bidder Carplates For Sale!

	Toyota Premio 1.5A F (New 5-yr COE)	\$36,000	\$7,200 /yr	09-Sep-2008	1,496 cc	105,000 km	Sedan	Available
A Reliable & Spacious Sedan Packed With Smart Key For Keyless Entry/start. Loan 90%, Driveway \$4700, can Loan \$31300 At 4% Monthly \$584 Only. Premio Is TOP If The Range Toyota 1.5a. Its Have The Funct...								
Allmotoring.sg								
Posted: 19-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota								
	Toyota Premio 1.5A F (New 5-yr COE)	\$33,800	\$6,760 /yr	14-Jul-2008	1,496 cc	151,220 km	Sedan	Available
Accident Free! Genuine Low Mileage, Very Well Maintain! Luxurious Interior Pristine Condition, No Obligation To Call Our Friendly Staff To View And Test Drive, All Trade In Welcome, Major Bank And In ...								
Posted: 13-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota								
	Toyota Premio 1.5A F (New 5-yr COE)	\$34,800	\$6,960 /yr	02-Sep-2008	1,496 cc	-	Sedan	Available
0% Down Payment With Flexible Loan C Only Put Up The Good Condition Units F								
Price With Lowest Depreciation At \$6K Per Year! Priced To Go, No Gimmicks! We								

Compare

Posted: 11-Jul-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota



Toyota Premio 1.8A X (New 5-yr COE) **\$35,800** **\$7,160 /yr** **15-Oct-2008** **1,797 cc** **103,000 km** **Sedan** **Available**

Bank Loan At 3.18% Or 100% Loan Also Available, Ex-Bankruptcy And Bad Credit Welcome, High Trade In, 1 Year Engine & Gearbox Warranty From Our In-house Workshop, 10 Years Coe Also Available.

PREMIUM AD

Posted: 21-Jun-2018 Tags: 2008 Toyota Premio, Toyota Premio, Toyota, Premio, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make: Filtered Price: Filtered Depreciation: Filtered Avg Cost: Filtered Eng Cap: Filtered Mileage: Filtered Veh Type: Filtered Status: Filtered

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota, Toyota Singapore, used Toyota Singapore, used Toyota, used vehicles Singapore or even buy used Toyota Singapore. We have new car dealers, comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1419H
Vehicle Details	
Vehicle No.:	SJK8871Z
Vehicle to be Exported:	No
Intended De-registration Date:	07 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREMIO 1.5F A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZD170587
Chassis No.:	NZT2603031788
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,918.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$14,918.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2018
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$33,562.00
Total Rebate Amount:	\$33,562.00

The information contained herein is correct as at 30 Jul 2018

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1419H
Vehicle Details	
Vehicle No.:	SJK8871Z
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREMIO 1.5F A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1Nzd170587
Chassis No.:	NZT2603031788
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,918.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$14,918.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2018
PARF Rebate Amount:	\$7,459.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$281.00
Total Rebate Amount:	\$7,740.00

The information contained herein is correct as at 30 Jul 2018

OK


> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1419H
Vehicle Details	
Vehicle No.:	SJK8871Z
Vehicle to be Exported:	No
Intended De-registration Date:	06 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PREMIO 1.5F A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1NZD170587
Chassis No.:	NZT2603031788
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,918.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$14,918.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2018
PARF Rebate Amount:	\$7,459.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$33,571.00
Total Rebate Amount:	\$41,030.00

The information contained herein is correct as at 30 Jul 2018

OK



Not Adhered
by 27/7/18
1/4 #1350

ATTN			QTY	PRICE	
NO	DESCRIPTION - PARTS				
1	REAR WINDSCREEN MOULDING	17	1	\$ 158.20	X
2	REAR BOOTLID	50/500	1	\$ 951.60	/
3	REAR BOOTLID LOGO - TOYOTA	48-50	1	\$ 78.00	/
4	REAR BOOTLID EMBLEM - PREMIO	121	1	\$ 88.00	/
5	REAR BOOTLID EMBLEM - X	60.00	1	\$ 85.00	/
6	REAR BOOTLID CHROME	121	1	\$ 361.90	?
7	REAR BOOTLID HINGE L+R	12	2	\$ 250.00	X
8	REAR BOOTLID INSULATOR	12	1	\$ 429.80	X
9	REAR BOOTLID WEATHERSTRIP	121	1	\$ 181.50	/
10	REAR BOOTLID LAMP L+R	CR2	2	\$ 483.60	/
11	TAILLAMP L+R	CM	2	\$ 763.80	/
12	TAILLAMP LOWER BRACKET L=R	17	2	\$ 99.80	X
13	TAILLAMP PANEL L+R	30/40	2	\$ 291.60	?
14	REAR BUMPER	121	1	\$ 1,431.80	/
15	REAR BUMPER RETAINER L+R	30/40	2	\$ 190.00	/
16	REAR BUMPER BRACKET L+R	121	2	\$ 196.20	/
17	REAR BUMPER REFLECTOR L+R	NF	2	\$ 196.00	X
18	REAR FENDER L+R	12	2	\$ 2,550.00	X
19	REAR FENDER COWLING L+R	17	2	\$ 258.20	X
20	REAR FENDER INNER TRIM L+R	681-30	2	\$ 1,302.60	IP
21	END PANEL	50/500	1	\$ 655.00	/
22	END PANEL TOP GARNISH	121	1	\$ 199.80	/
23	SPARE TYRE PANEL	30/40/121	1	\$ 995.00	?
24	SPRAE TYRE PANEL TOP BOARD	121	1	\$ 389.50	/
25	REAR EXHAUST	12	1	\$ 940.10	X
26	REAR EXHAUST MOUNTING	17	4	\$ 180.00	X
27	REAR EXHAUST GASKET	12	1	\$ 125.00	1
28	REAR EXHAUST HEAT SEAL	17	1	\$ 245.00	2
29	REAR CHASSIS EXTENSION RH	12	1	\$ 1,125.00	X
30	REAR CHASSIS MEMBER RH	12	1	\$ 1,750.00	X
31	FRONT BONNET	12	1	\$ 984.00	1
32	FRONT BONNET CHROME	CM	1	\$ 250.00	/
33	FRONT BONNET RUBBER	17	1	\$ 72.00	X
34	FRONT BONNET INSULATOR	17	1	\$ 450.00	X
35	FRONT BONNET LOCK	121	1	\$ 115.00	/
36	FRONT BONNET HINGE L+R	12	2	\$ 140.00	X
37	FRONT GRILLE	CM	1	\$ 480.00	/
38	FRONT GRILLE LOGO	121	1	\$ 60.00	/
39	HEADLAMP L+R	CM	2	\$ 1,840.00	?

[illegible]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2018		26 Jul 2018 15:13 Edit Adj Rpt	\$13,500.00 Edit Estimates	\$13,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS
[Created by Insurer]

Insured:	KIRALY AUTOMOBILE PRIVATE LIMITED , Co. Reg. No.: *		
Main Claimant:	WEE POON HOE , ID: S1131419H		
Vehicle Reg. No.:	SJK8871Z	Date of Loss:	24/07/2018 11:00 - :59 [116 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03652C02	Policy/Cover Note No.:	DMHCSN1736121801 (Comprehensive)
Vehicle Reg. No. (Insured):	SLN7843Y	Policy No. (Claimant):	5097955644
		Excess:	S\$0.00
Repairer:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 06/08/2018]		
Driver/Custodian (Insured):	HAM KOW YEN (39 / Male), NRIC: S7837393H, Tel: +6588285046		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJK8871Z (SNM18D03652C02)

[SLN7843Y]

TP

WEE POON HOE

Jul 24 2018 11:00AM

[KIRALY AUTOMOBILE PRIVATE LIMITED]

RICO 60 AUTO SERVICES PTE LTD

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print					
1	25/07/18 15:00	Accident Statement		 Load HTM						
2	25/07/18 15:07	Addendum Sheet		 Load TIF						
3	25/07/18 15:08	Accident Statement Addm. #1		 Load HTM						
Photos/Images							3 per page		☒	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print					
1	25/07/18 14:10	Driving License [Linked Accident Report Documents]		 Load JPG	☒					
2	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
3	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
4	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
5	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
6	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
7	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
8	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
9	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
10	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
11	25/07/18 14:10	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	10/08/18 17:33	General View		 Load JPG	☒					
2	10/08/18 17:33	General View		 Load JPG	☒					
3	10/08/18 17:33	General View		 Load JPG	☒					
4	10/08/18 17:33	General View		 Load JPG	☒					
5	10/08/18 17:33	General View		 Load JPG	☒					
6	10/08/18 17:33	General View		 Load JPG	☒					
7	10/08/18 17:33	General View		 Load JPG	☒					
8	10/08/18 17:33	General View		 Load JPG	☒					
9	10/08/18 17:33	General View		 Load JPG	☒					
10	10/08/18 17:33	General View		 Load JPG	☒					
11	10/08/18 17:33	General View		 Load JPG	☒					
12	10/08/18 17:33	General View		 Load JPG	☒					
13	10/08/18 17:33	General View		 Load JPG	☒					
14	10/08/18 17:33	General View		 Load JPG	☒					
15	10/08/18 17:33	General View		 Load JPG	☒					
16	10/08/18 17:33	General View		 Load JPG	☒					

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
17	10/08/18 17:33	General View	 Load JPG	☒
18	10/08/18 17:33	General View	 Load JPG	☒
19	10/08/18 17:33	General View	 Load JPG	☒
20	10/08/18 17:33	General View	 Load JPG	☒
21	10/08/18 17:33	General View	 Load JPG	☒
22	10/08/18 17:33	General View	 Load JPG	☒
23	10/08/18 17:33	General View	 Load JPG	☒
24	10/08/18 17:33	General View	 Load JPG	☒
25	10/08/18 17:33	General View	 Load JPG	☒
26	10/08/18 17:33	General View	 Load JPG	☒
27	10/08/18 17:33	General View	 Load JPG	☒
28	10/08/18 17:33	General View	 Load JPG	☒
29	10/08/18 17:33	General View	 Load JPG	☒
30	10/08/18 17:33	General View	 Load JPG	☒
31	10/08/18 17:33	General View	 Load JPG	☒
32	10/08/18 17:33	General View	 Load JPG	☒
33	10/08/18 17:33	General View	 Load JPG	☒
34	10/08/18 17:33	General View	 Load JPG	☒
35	10/08/18 17:33	General View	 Load JPG	☒
36	10/08/18 17:33	General View	 Load JPG	☒
37	10/08/18 17:33	General View	 Load JPG	☒
38	10/08/18 17:33	General View	 Load JPG	☒
39	10/08/18 17:33	General View	 Load JPG	☒
40	10/08/18 17:33	General View	 Load JPG	☒
41	10/08/18 17:33	General View	 Load JPG	☒
42	10/08/18 17:33	General View	 Load JPG	☒
43	10/08/18 17:33	General View	 Load JPG	☒
44	10/08/18 17:33	General View	 Load JPG	☒
45	10/08/18 17:33	General View	 Load JPG	☒
46	10/08/18 17:33	General View	 Load JPG	☒
47	10/08/18 17:33	General View	 Load JPG	☒
48	10/08/18 17:33	General View	 Load JPG	☒
49	10/08/18 17:33	General View	 Load JPG	☒
50	10/08/18 17:33	General View	 Load JPG	☒
51	10/08/18 17:33	General View	 Load JPG	☒
52	10/08/18 17:33	General View	 Load JPG	☒
53	10/08/18 17:33	General View	 Load JPG	☒
54	10/08/18 17:33	General View	 Load JPG	☒
55	10/08/18 17:33	General View	 Load JPG	☒
56	10/08/18 17:33	General View	 Load JPG	☒
57	10/08/18 17:33	General View	 Load JPG	☒
58	10/08/18 17:33	General View	 Load JPG	☒
59	10/08/18 17:33	General View	 Load JPG	☒
60	10/08/18 17:33	General View	 Load JPG	☒
61	10/08/18 17:33	General View	 Load JPG	☒
62	10/08/18 17:33	General View	 Load JPG	☒
63	10/08/18 17:33	General View	 Load JPG	☒
64	10/08/18 17:33	General View	 Load JPG	☒
65	10/08/18 17:33	General View	 Load JPG	☒
66	10/08/18 17:33	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
67	10/08/18 17:33	General View	 Load JPG	☒
68	10/08/18 17:33	General View	 Load JPG	☒
69	10/08/18 17:33	General View	 Load JPG	☒
70	10/08/18 17:33	General View	 Load JPG	☒
71	10/08/18 17:33	General View	 Load JPG	☒
72	10/08/18 17:33	General View	 Load JPG	☒
73	10/08/18 17:33	General View	 Load JPG	☒
74	10/08/18 17:33	General View	 Load JPG	☒
75	10/08/18 17:33	General View	 Load JPG	☒
76	10/08/18 17:33	General View	 Load JPG	☒
77	10/08/18 17:33	General View	 Load JPG	☒
78	10/08/18 17:33	General View	 Load JPG	☒
79	10/08/18 17:33	General View	 Load JPG	☒
80	10/08/18 17:33	General View	 Load JPG	☒
81	10/08/18 17:33	General View	 Load JPG	☒
82	10/08/18 17:33	General View	 Load JPG	☒
83	10/08/18 17:33	General View	 Load JPG	☒
84	10/08/18 17:33	General View	 Load JPG	☒
85	10/08/18 17:33	General View	 Load JPG	☒
86	10/08/18 17:33	General View	 Load JPG	☒
87	10/08/18 17:33	General View	 Load JPG	☒
88	10/08/18 17:33	General View	 Load JPG	☒
89	10/08/18 17:33	General View	 Load JPG	☒
90	10/08/18 17:33	General View	 Load JPG	☒
91	10/08/18 17:33	General View	 Load JPG	☒
92	10/08/18 17:33	General View	 Load JPG	☒
93	10/08/18 17:33	General View	 Load JPG	☒
94	10/08/18 17:33	General View	 Load JPG	☒
95	10/08/18 17:33	General View	 Load JPG	☒
96	10/08/18 17:33	General View	 Load JPG	☒
97	10/08/18 17:33	General View	 Load JPG	☒
98	10/08/18 17:33	General View	 Load JPG	☒
99	10/08/18 17:33	General View	 Load JPG	☒
100	10/08/18 17:33	General View	 Load JPG	☒
101	10/08/18 17:33	General View	 Load JPG	☒
102	10/08/18 17:33	General View	 Load JPG	☒
103	10/08/18 17:33	General View	 Load JPG	☒
104	10/08/18 17:33	General View	 Load JPG	☒
105	10/08/18 17:33	General View	 Load JPG	☒
106	10/08/18 17:33	General View	 Load JPG	☒
107	10/08/18 17:33	General View	 Load JPG	☒
108	10/08/18 17:33	General View	 Load JPG	☒
109	10/08/18 17:33	General View	 Load JPG	☒
110	10/08/18 17:33	General View	 Load JPG	☒
111	10/08/18 17:33	General View	 Load JPG	☒
112	10/08/18 17:33	General View	 Load JPG	☒
113	10/08/18 17:33	General View	 Load JPG	☒
114	10/08/18 17:33	General View	 Load JPG	☒
115	10/08/18 17:33	General View	 Load JPG	☒
116	10/08/18 17:33	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
117	10/08/18 17:33	General View	 Load JPG	☒
118	10/08/18 17:33	General View	 Load JPG	☒
119	10/08/18 17:33	General View	 Load JPG	☒
120	10/08/18 17:33	General View	 Load JPG	☒
121	10/08/18 17:33	General View	 Load JPG	☒
122	10/08/18 17:33	General View	 Load JPG	☒
123	10/08/18 17:33	General View	 Load JPG	☒
124	10/08/18 17:33	General View	 Load JPG	☒
125	10/08/18 17:33	General View	 Load JPG	☒
126	10/08/18 17:33	General View	 Load JPG	☒
127	10/08/18 17:33	General View	 Load JPG	☒
128	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
129	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
130	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
131	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
132	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
133	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
134	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
135	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
136	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
137	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
138	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
139	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
140	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
141	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
142	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
143	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
144	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
145	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
146	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
147	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
148	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
149	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
150	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
151	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
152	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
153	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
154	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
155	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
156	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
157	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
158	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
159	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
160	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
161	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
162	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
163	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
164	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
165	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
166	10/08/18 17:34	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
167	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
168	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
169	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
170	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
171	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
172	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
173	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
174	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
175	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
176	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
177	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
178	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
179	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
180	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
181	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
182	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
183	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
184	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
185	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
186	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
187	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
188	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
189	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
190	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
191	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
192	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
193	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
194	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
195	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
196	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
197	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
198	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
199	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
200	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
201	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
202	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
203	10/08/18 17:34	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/18 15:12	PRS	 Load PDF	
2	26/07/18 15:12	OI GIA	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	25/07/18 14:55	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	25/07/18 14:55	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	25/07/18 15:00	Accident Statement	 Load HTM	☐
2	25/07/18 15:07	Addendum Sheet	 Load TIF	☐
3	25/07/18 15:08	Accident Statement Addm. #1	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	25/07/18 14:10	Driving License	 Load JPG	☒
2	25/07/18 14:10	Accident Photo	 Load JPG	☒
3	25/07/18 14:10	Accident Photo	 Load JPG	☒
4	25/07/18 14:10	Accident Photo	 Load JPG	☒
5	25/07/18 14:10	Accident Photo	 Load JPG	☒
6	25/07/18 14:10	Accident Photo	 Load JPG	☒
7	25/07/18 14:10	Accident Photo	 Load JPG	☒
8	25/07/18 14:10	Accident Photo	 Load JPG	☒
9	25/07/18 14:10	Accident Photo	 Load JPG	☒
10	25/07/18 14:10	Accident Photo	 Load JPG	☒
11	25/07/18 14:10	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	25/07/18 14:55	Sketch Plan	 Load TIF	☐
2	25/07/18 14:55	Sketch Plan #2	 Load TIF	☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013689/UTD3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1736121801

Claimant Vehicle
No: SJK8871Z

Insured Vehicle
No: SLN7843Y

Date of Loss: 24/07/2018

Nature of Claim: TP

Claim
No: SNM18D03652C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK8871Z**

Make & Model: TOYOTA PREMIO, 1.5 (A)

Engine No: 1NZD170587

Reg. Date: 07/11/2008 (Man. Year: 2008)

Chassis No: NZT2603031788

Colour: Silver

Odometer: 203466 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size:

185/70 R14

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,278.00	12,568.82	13,709.18	52.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,350.00	4,340.00	7,010.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,628.00	16,908.82	20,719.18	55.06
Approved Total (Overridden) (S\$)		13,500.00		
Nett Amount (S\$)	37,628.00	13,500.00	24,128.00	64.12

INSPECTION

Date of Assignment: 26/07/2018

Date Inspected: 27/07/2018 Inspected At:

RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24,
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2018)
Parts:	143	TOYOTA PREMIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK8871Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	158.20 FL	*- FL
2	1		*REAR BOOTLID	Badly Dented	951.60 FL	*951.60 FL
3	1		*REAR BOOTLID LOGO -TOYOTA	Necessary	78.00 FL	*48.50 FL
4	1		*REAR BOOTLID EMBLEM -PREMIO	Necessary	88.00 FL	*88.00 FL
5	1		*REAR BOOTLID EMBLEM -X	Necessary	85.00 FL	*60.00 FL
6	1		*REAR BOOTLID CHROME	Cracked	361.90 FL	*361.90 FL
7	2		*REAR BOOTLID HINGE L+R	Repair	250.00 FL	*- FL
8	1		*REAR BOOTLID INSULATOR	Not Necessary	429.80 FL	*- FL
9	1		*REAR BOOTLID WEATHERSTRIP	Twisted	181.50 FL	*181.50 FL
10	2		*REAR BOOTLID LAMP L+R	Cracked	483.60 FL	*483.60 FL
11	2		*TAILLAMP L+R	Cracked	763.80 FL	*763.80 FL
12	2		*TAILLAMP LOWER BRACKET L+R	Not Necessary	99.80 FL	*- FL
13	2		*TAILLAMP PANEL L+R	Bent	291.60 FL	*291.60 FL
14	1		*REAR BUMPER	Distorted	1,431.80 FL	*1,431.80 FL
15	2		*REAR BUMPER RETAINER L+R	Bent	190.00 FL	*190.00 FL
16	2		*REAR BUMPER BRACKET L+R	Bent	196.20 FL	*196.20 FL
17	2		*REAR BUMPER REFLECTOR L+R	Not fitted	196.00 FL	*- FL
18	2		*REAR FENDER L+R	Repair	2,550.00 FL	*- FL
19	2		*REAR FENDER COWLING L+R	Not Necessary	258.20 FL	*- FL
20	1		*REAR FENDER INNER TRIM L+R	O/S Torn	1,302.60 FL	*651.30 FL
21	1		*END PANEL	Badly Dented	655.00 FL	*655.00 FL
22	1		*END PANEL TOP GARNISH	Twisted	199.80 FL	*199.80 FL
23	1		*SPARE TYRE PANEL	Badly Dented / Buckled	995.00 FL	*995.00 FL
24	1		*SPARE TYRE PANEL TOP BOARD	Torn	389.50 FL	*389.50 FL
25	1		*REAR EXHAUST	Repair	940.10 FL	*- FL
26	4		*REAR EXHAUST MOUNTING	Not Necessary	180.00 FL	*- FL
27	1		*REAR EXHAUST GASKET	Not Necessary	125.00 FL	*- FL
28	1		*REAR CHASSIS EXTENSION RH	Repair	1,125.00 FL	*- FL
29	1		*REAR EXHAUST HEAT SEAL	Not Necessary	245.00 FL	*- FL
30	1		*REAR CHASSIS MEMBER RH	Repair	1,750.00 FL	*- FL
31	1		*FRONT BONNET	Repair	984.00 FL	*- FL
32	1		*FRONT BONNET CHROME	Cracked	250.00 FL	*250.00 FL
33	1		*FRONT BONNET RUBBER	Not Necessary	72.00 FL	*- FL
34	1		*FRONT BONNET INSULATOR	Not Necessary	450.00 FL	*- FL
35	1		*FRONT BONNET LOCK	Twisted	115.00 FL	*115.00 FL
36	2		*FRONT BONNET HINGE L+R	Repair	140.00 FL	*- FL
37	1		*FRONT GRILE	Cracked	480.00 FL	*480.00 FL
38	1		*FRONT GRILE LOGO	Necessary	60.00 FL	*60.00 FL
39	2		*HEADLAMP L+R	Cracked	1,840.00 FL	*1,840.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT BUMPER	Dented / Deformed	682.00 FL	*682.00 FL
41	1		*FRONT BUMPER GRILLE	Torn	185.00 FL	*185.00 FL
42	2		*FRONT BUMPER RETAINER L+R	Bent	154.00 FL	*154.00 FL
43	2		*FRONT BUMPER BRACKET L+R	Bent	196.00 FL	*196.00 FL
44	2		*FRONT BUMPER REINFORCEMENT BAR	Bent	376.00 FL	*376.00 FL
45	1		*FRONT BUMPER SPONGE	Torn	85.00 FL	*85.00 FL
46	2		*FRONT BUMPER FOG LAMP COVER L+R	Not Necessary	180.00 FL	*- FL
47	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,305.00 FL	*1,305.00 FL
48	1		*BRACE PANEL	Twisted	98.00 FL	*98.00 FL
49	2		*HORN L+R	Not Necessary	155.00 FL	*- FL
50	1		*AIR CON CONDENSER	Bent / Punctured	1,820.00 FL	*1,820.00 FL
51	1		*AIR CON CONDENSER LIQUID PIPE	Not Necessary	850.00 FL	*- FL
52	1		*AIR CON CONDENSER DISCHARGE PIPE	Not Necessary	498.00 FL	*- FL
53	1		*AIR CON CONDENSER SUCTION PIPE	Not Necessary	475.00 FL	*- FL
54	1		*RADIATOR	Not Necessary	2,450.00 FL	*- FL
55	1		*RADIATOR TOP HOSE	Not Necessary	60.00 FL	*- FL
56	1		*RADIATOR TOP HOSE CONNECTOR	Not Necessary	110.00 FL	*- FL
57	1		*RADIATOR BOTTOM HOSE	Not Necessary	65.00 FL	*- FL
58	1		*ELECTRIC FAN COWLING ASSY	Not Necessary	782.00 FL	*- FL
59	1		*RADIATOR SPARE TANK	Not Necessary	195.00 FL	*- FL
60	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*40.00 FS
61	1		*REAR NUMBER PLATE	Cracked	80.00 FS	*40.00 FS
62	1		*REAR WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
63	10		*REAR BOOTLID INNER TRIM CLIPS	Necessary	100.00 FS	*50.00 FS
64	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
65	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
66	2		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
67	1		*REVERSE CAM	Damaged	450.00 FS	*300.00 FS
68	2		*REAR FENDER SEALANT	Not Necessary	240.00 FS	*- FS
69	10		*REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
70	10		*REAR FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
71	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
72	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*100.00 FS
73	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	120.00 FS	*- FS
74	1		*RADIATOR COOLANT	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	34,294.00	16,465.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,016.00	3,896.28
Total Parts (\$\$)	26,278.00	12,568.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT DAMAGED PARTS ,CUT /WELD ,KNOCK & REALIGN	New	4,500.00	2,100.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	3,500.00	1,800.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	120.00
4	TO RNR REAR WINDSCREEN	New	450.00	0.00
5	TO RNR REAR BOOT MECHANISM	New	120.00	60.00
6	TO RNR REAR LUGGAGE COMPARTMENT }	New	400.00	80.00
7	TO RNR UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS }	New	400.00	0.00
8	TO RNR REVERSE SENSOR & CHECK FUNCTION }	New	120.00	50.00
9	TO RNR REVERSE CAMERA & CHECK FUNCTION }	New	120.00	0.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
11	TO RNR REAR FUEL TANK	New	250.00	0.00
12	TO RNR A/C CONDENSOR ASSY AND REFILL GAS	New	120.00	100.00
13	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS }	New	120.00	30.00
14	TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION }	New	120.00	0.00
15	TO CHECK WIRING LAYOUT AND BOOTLID LAMP FUNCTION	New	120.00	0.00
16	TO DO WATER LEAK TEST	New	120.00	0.00
17	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	New	120.00	0.00
18	TO DO CHASSIS ALIGNMENT	New	400.00	0.00
Gross Labour Cost (\$\$)			11,350.00	4,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >