



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : SKP5050H
Date of Accident : 24 July 2018

Mr Yang Choon Siong

Date : 31 July 2018

Estimate To Repair SFL36M - VOLVO V60 T4 1.6 AUTO ABS D/AB 2WD 5
Chassis No : YV1FW485BC1051622

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	rear bumper	\$ 1,563.80
02	1 pc	rear bumper lower garnish	\$ 1,516.50
03	1 pc	rear bumper reinforcement	\$ 1,395.70
04	1 pc	rear bumper absorber foam	\$ 125.00
05	2 pc	rear bumper side retainer @ \$98.80	\$ 197.60
06	1 pc	rear bumper lower centre diffuser	\$ 451.70
07	1 pc	rear bumper parking sensor harness	\$ 248.80
08	2 pc	rear bumper stay @ \$155.00	\$ 310.00
09	2 pc	rear exhaust chrome culter @ \$278.10	\$ 556.20
10	1 pc	rear exhaust heat shield	\$ 298.80
			\$ 6,664.10
Less 10 %			\$ 666.41
			\$ 5,997.69
SPECIAL NETT ITEMS			
11	2 pc	rear bumper parking sensor @ \$201.00	\$ 402.00
12	2 pc	parking sensor @ \$201.00	\$ 402.00
			\$ 804.00
LABOUR & MISC. CHARGES			
01		To reinstall of rear bumper parking sensor and simulator test.	\$ 180.00
02		To check electrical lighting concerned.	\$ 60.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
04		Putty and spray painting of the affected portion.	\$ 550.00
05		To redo paint protection system	\$ 300.00
			\$ 1,590.00
Total			\$ 8,391.69

LKK Auto Consultants henceforth the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature

at