

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 30 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKR9189E	Accident Date	: 13/07/2018
TP Vehicle No	: SDT898Z	Assignment Date	: 26/07/2018
Make	: PORSCHE MACAN S	Est. Duration of Repair	: 12.00
Date of Inspection	: 27/07/2018		
Inspection At	: STUTTGART AUTO PTE LTD (HQ) 12 SUNGEI KADUT AVE SINGAPORE 729648		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,249.62
Revised Amount	:S\$	27,388.92
Check Items (Estimated)	:S\$	2,262.81
Total	:S\$	29,651.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.