

ASS. REC. BY:

REF:

CS/MSG/18013700/T1vd312

Special Instructions:

Surveyor
menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Muhammad Ashik

of

MSG

Date/Time:

26/7/18 @ 4:32pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDT 898Z

Insured:

SKR 9189E

at Workshop m/s

Stuttgart Auto

Tel:

6360 2845

of

12 Sungai Kerdui Ave

Policy No:

A29040105AT2

Claim No:

564510

Sum Insured:

Excess:

Make of Veh.

(Client's Record)

D.O.A.

13/07/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

9:33am @ 27/7/18

Person Contacted:

Eva

Vehicle In / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDT 898Z - NBA / DAI 18012863 / Y

D.O.A: 13/07/2018

SKR 9189E - X

30/7/18

Send preli revised via menmen

11/10/18

@ 12:19pm Jessica will check & call back

REF: msig

Director: Taylor

REF:

msig

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Log

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Eva

Veh No: SDT 898 Z Yr Regn: 20/4/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Macan c.c. 2997

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 47036 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP 122295ZF-LB 50887

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55 R17

R: 255/50 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 27/7/18 10am

Survey held at Spottgnt 12/7/18

Des. of Damages: Frt Rear O/S N/S U/C Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
14/11/18	Final fig \$28,948.17 (Red 5308.25, 15%) confirmed by email
	RECEIVED 14 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 14/11 - typist

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format : merimen
Lump Sum / I.B.I. (\$) 28,948.17

250
10
260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013700/T1vd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 27-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 9189E	Veh. Inspected	SDT 898Z
Policy No.	A29040105AT2	Coverage (\$)	0.00
Claim No.	564510	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	27/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/07/2018	Inspection Date	27/07/2018
Survey held at	STUTT GART AUTO PTE LTD 12 SUNGEI KADUT AVE. SINGAPORE 729648		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Ref	Est	Ref	Ref	AD Submitted	Ins Auth'd	Status
Main	14 Jul 2018		26 Jul 2018 16:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All			
CLAIM SUBFOLDER DETAILS [Created by insurer]							
Insured:	TAN SWEE SENG , ID: S8835169Z, Tel: +6598393901						
Main Claimant:	KOH WAH CHUANG , ID: S1213489D						
Vehicle Reg. No.:	SDT898Z	Date of Loss:	13/07/2018 21:00 - :59 [48 Months and 11 Days From LTA Reg Date (Man Yr)]				
Claim Type:	TP / 564510	Policy/Cover Note No.:	A29040105AT2 (Comprehensive) Coverage: 28/11/2017 - 27/11/2018				
Vehicle Reg. No. (Insured):	SKR9189E	Policy No. (Claimant):					
		Excess:	S\$3,500.00				
Repairer:	Stuttgart Auto Pte Ltd (HQ) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845						
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/07/2018]						
Driver/Custodian (Insured):	TAN SWEE SIANG (), NRIC: S9113579E, Tel: +6596616647						
Adj Asg. Remarks:	ON WP. Survey appt 27/07/18(Fri), 10am. Owner waiting. Liability 100%, Contact : Eva Kok at 6360 2846 Kindly avoid lunch time 12pm-1pm						
ASSOCIATED MAIL RECEIVED View All Compose Case Mail							
There are no mail for this case.							
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete							
Due Date	Priority	Task	Handler	Assigned By	Completed On	Created On	Done?
No results.							

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 30 Jul 2018

Preliminary Advice

Insured Vehicle : SKR9189E
No

TP Vehicle No : SDT898Z

Accident Date : 13/07/2018

Make : PORSCHE MACAN S

Assignment Date : 26/07/2018

Date of Inspection : 27/07/2018

Est. Duration of Repair : 12.00

Inspection At : STUTTGART AUTO PTE LTD (HQ)
12 SUNGEI KADUT AVE
SINGAPORE 729648

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,249.62
Revised Amount	:S\$	27,388.92
Check Items (Estimated)	:S\$	2,262.81
Total	:S\$	29,651.73

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3489D
Vehicle Details	
Vehicle No.:	SDT898Z
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	PORSCHE
Vehicle Model:	MACAN S 3.0 A/T ABS D/AIRBAG 4WD
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	001920
Chassis No.:	WP1ZZZ95ZFLB50887
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$80,077.00
Original Registration Date:	02 Jul 2014
First Registration Date:	02 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$116,139.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jul 2024
PARF Rebate Amount:	\$87,104.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,010.00
COE Rebate Amount:	\$44,401.00
Total Rebate Amount:	\$131,505.00

The information contained herein is correct as at 30 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2018 13:29
Date Of Accident	13/07/2018 21:30
Exact Location Of Accident	ALONG PIE TOWARDS CHANGI BEFORE EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT898Z
Insured/Policyholder	
Name Of Registered Owner	KOH WAH CHUANG
NRIC No	S1213489D
Email Address	WAHCHUANG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98362991
Alternative Phone No	OFFICE-98362991

Vehicle Particulars

Manufacturer	PORSCHE
Model	MACAN S-3.0 PDK (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2018-V0101496-VDP-R001
Cover Note Number	

Driver

Name of Driver	KOH WAH CHUANG
NRIC No	S1213489D
Date Of Birth	13/01/1956
Occupation	INDOOR
Date Of Driving Pass	23/08/1976
Driving Experience	41 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98362991
Fax Number	
Contact Number	OFFICE-98362991
Email Address	WAHCHUANG@HOTMAIL.COM

Address 87 TOH YI DRIVE
 Postcode 596547
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 5
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : KOH PEI BEI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] BUKIT TIMAH NPP - PLEASE REFER TO THE ATTACHED POLICE REPORT
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Please refer to the attached Police Report and the Sketch Plan for the accident details

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR9189E
 Vehicle Make/Model/Colour VEHICLE (B)
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAN SWEE SIANG
 NRIC/Passport Number S9113579E
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJH3123Z
Vehicle Make/Model/Colour VEHICLE (C)
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver ARSHVEEN KAUR D/O BILWANDER SINGH
NRIC/Passport Number S8331370F
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJZ8274T
Vehicle Make/Model/Colour VEHICLE (D)
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver FENG LU
NRIC/Passport Number S7683049E
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SKP5914R
Vehicle Make/Model/Colour VEHICLE (E)
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LIM JUN JIE
NRIC/Passport Number S9315089I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 17/7/18 12:38 PM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the Police report

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PRN No.:



**SINGAPORE
POLICE FORCE**



T/20180714/2176

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

1 of 5
Report No. T/20180714/2176

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2018 21:19		Vide Report No.:		Station Diary No.: 72	
Informant's Particulars					
Name of Informant: KOH WAH CHUANG			Address: 87 TOH YI DRIVE SINGAPORE 596547		
ID Type / ID No.: NRIC NO / S1213489D			Contact No.: Home/Office: Mobile: 98362991		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 62	Date of Birth: 13/01/1956	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Company director			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 13/07/2018 21:30	Type of Location:
Location: Along Road 1 PAN ISLAND EXPRESSWAY TOWARDS CHANGI AIRPORT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDT898Z	Car	PORSCHE	MACAN S 3.0 A/T ABS D/AIRBAG 4WD	Blue	Slightly Damaged	1
SJH3123Z	Car				Slightly Damaged	0
SJZ8274T	Car				Slightly Damaged	0
SKP5914R	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180714/2178

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

2 of 5

Report No. T/20180714/2178

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKR9189E	Car				Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SDT898Z	OVERSEAS ASSURANCE CORPORATION LIMITED	V0101496	02/07/2017	01/07/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Koh Wah Chuang		ID No.	S1213489D
Related Vehicle	SDT898Z (Car)		Contact No.	98362991
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	Arshveen Kaur D/O Bilwander Singh		ID No.	S8331370F
Related Vehicle	SJH3123Z (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20180714/2176

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 5

Report No. T/20180714/2176

CONTINUATION OF REPORT

Driver			
Name	Feng Lu	ID No.	S7883049E
Related Vehicle	SJZ8274T (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Lim Jun Jie	ID No.	S9315089I
Related Vehicle	SKP5914R (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	Tan Swee Siang	ID No.	S9113579E
Related Vehicle	SKR9189E (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 13/07/2018 at about 2130hrs, I was driving my vehicle (registration number SDT898Z) along PIE towards Changi Airport.

While I was travelling along the extreme right lane on the expressway, I noticed that the front vehicles on my lane were stepping on their brake pedals.

As I was approaching nearer, I noticed that the front vehicles were stationary as they had a chain collision involving 3 vehicles. Thus, I stepped onto my brake pedal and was able to stop in time.

However, the vehicle behind me was unable to stop in time and collided to the rear of my vehicle. Due to that, my vehicle surged forward and collided to the rear of the front vehicle (which was involved in the



**SINGAPORE
POLICE FORCE**



T/20180714/2176

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

4 of 5

Report No. T/20180714/2176

CONTINUATION OF REPORT

chain collision).

Vehicle registration numbers as follow:-

SKP5914R (1st vehicle) - Lim Jun Jie S9315089I

SJZ8274T (2nd vehicle) - Feng Lu S7683049E

SJH3123Z (3rd vehicle) - Arshveen Kaur D/O Bilwander Singh S8331370F

SDT898Z (4th vehicle, myself) - Koh Wah Chuang S1213489D

SKR9189E (5th vehicle) - Tan Swee Slang S9113579E

I wish to state that my vehicle does not have in-car camera. No ambulance or police was at scene and no government property was damaged. No one was injured as well.



**SINGAPORE
POLICE FORCE**



T/20180714/2176

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

5 of 5

Report No. T/20180714/2176

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report
D /
Sgt 3 CAMERON TOH CHUN HAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Signature Of Informant:

Date/Time:
14/07/2018 21:19

Classification Of Case:

Authentication Stamp

NP189

311 32

SIGNATURE



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

MSIG INSURANCE (SINGAPORE) PTE LTD		NAME :	Mr Koh Wah Chuang	WIP :	35894
4 SHENTON WAY #21-01		ADDRESS :	87 Toh Yi Drive	EXCESS :	
SGX CENTRE 2 S 068807			Singapore 596547	DATE :	20.07.2018
ATTN. :	MOTOR CLAIMS	TEL :			
FAX :					
VEH NO :	SDT898Z	DATE IN :		CONTACT PERSON :	EVA 63602846
CHASSIS NO :	WP1ZZZ95ZFLB50887	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SKR9189E
MODEL :	Macan S	DATE REG.:	02.07.2014	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
		QTY			
1	FRONT BUMPER	1	P95B-807-221-A -G2X	de ✓	\$ 929.20 ✓
2	FRONT BUMPER CENTER GRILLE	1	P95B-807-683-H -1E0	de ✓	\$ 304.60 ✓
3	LICENSE PLATE BRACKET	1	P95B-807-287- -1E0	de ✓	\$ 79.90 ✓
4	FRONT BUMPER SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	X nn	\$ 455.20 X
5	FRONT SENSOR GASKET	2	P5Q0-919-133- -9B9	X nn	\$ 5.00 X
6	FRONT BUMPER REINFORCEMENT	1	P8RD-807-113-D -	? bt ✓	\$ 350.20 ✓
7	REINFORCEMENT FOAM STRIP	1	P95B-807-550-G -	? de ✓	\$ 61.00 ✓
8	RADIATOR VANES	1	P95B-121-257-BY-	? de ✓	\$ 355.20 ✓
9	FRONT CENTER AIR DUCT	1	P95B-121-710- -1E0	? de ✓	\$ 142.50 ✓
10	AIR DUCT LH	1	P95B-121-673- -1E0	? de ✓	\$ 42.60 ✓
11	AIR DUCT RH	1	P95B-121-674- -1E0	? de ✓	\$ 42.60 ✓
12	RADIATOR AIR DUCT	1	P95B-121-707-F -	? de ✓	\$ 166.00 ✓
13	BONNET	1	P95B-823-031-HY-GRV	bt ✓	\$ 3,138.00 ✓
14	CAVITY PRESERVATION	1	P000-043-305-51-	X nn	\$ 80.30 X
15	NUT	2	PWHT-004-974- -	X nn	\$ 3.00 X
16	BONNET INNER SEAL	2	P95B-823-739- -	ae ✓	\$ 14.60 ✓
17	FRONT PANEL TOP COVER	1	P95B-805-806-N -1E0	de ✓	\$ 68.00 ✓
18	BONNET INSULATION	1	P95B-863-831-A -	ae ✓	\$ 225.00 ✓
19	NOZZLE COVER (RH)	1	P95B-955-100-A -	ae ✓	\$ 122.50 ✓
20	NOZZLE COVER (LH)	1	P95B-955-099-A -	X nn	\$ 122.50 X
21	HEADLAMP GASKET LH	1	P95B-941-323-E -	ae ✓	\$ 90.30 ✓
22	HEADLAMP GASKET RH	1	P95B-941-323-D -	X nn	\$ 90.30 X
23	WARNING SIGN STICKER	1	P7PP-010-006-A -	ae ✓	\$ 6.10 ✓
24	MOBIL 1 STICKER	1	P7PP-010-786-T -	ae ✓	\$ 6.40 ✓
25	P95B-807-417-G -G2X/BUMPER	1	P95B-807-417-K -G2X	de ✓	\$ 864.00 ✓
26	REAR BUMPER INSULATION LH	1	P95B-805-885- -	ae ✓	\$ 33.10 ✓
27	REAR BUMPER INSULATION RH	1	P95B-805-886- -	ae ✓	\$ 33.10 ✓
28	REAR BUMPER SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	X nn	\$ 455.20 X
29	SENSOR GASKET	2	P5Q0-919-133- -9B9	X nn	\$ 5.00 X
30	TOW COVER	1	P95B-807-500-A -G2X	ae ✓	\$ 39.60 ✓
31	REAR BUMPER SPOILER	1	P95B-807-521-AA-1E0	de ✓	\$ 280.30 ✓
32	EXPANSION RIVET	6	PN -038-549-4 -	ae ✓	\$ 3.00 ✓
33	REAR BUMPER COVER	1	P95B-807-834-K -1E0	de ✓	\$ 186.90 ✓
34	REAR BUMPER REINFORCEMENT	1	P8RD-807-313-D -	? bt ✓	\$ 311.90 ✓
35	REINFORCEMENT SUPPORT RH	1	P8RD-807-332-E -	? bt ✓	\$ 105.00 ✓
36	COMBINATION SCREW	4	PN -907-075-02-	? ae ✓	\$ 25.60 ✓

37	COMBINATION SCREW	4	PN -907-721-02-	7 hel	\$	34.00	✓
38	NUT	4	PN -905-038-01-	? hel	\$	6.80	✓
39	REAR BUMPER REFLECTOR RH	1	P95B-945-726-L-	cut	\$	298.90	✓
40	LICENSE PLATE LIGHT	2	P95B-631-620-00-	X ny	\$	80.80	X
42	REAR MUFFLER RH	1	P95B-253-612-RY-	bt	\$	2,316.60	✓
43	TAIL PIPE RH	1	P95B-253-682-N-	cut	\$	585.00	✓
44	LENS-HEAD SCREW	2	P999-073-594-01-	na	\$	9.20	✓
45	HEXAGON-HEAD BOLT	2	PN -106-620-01-	use	\$	2.40	✓
46	(WB15) CLAMPING SLEEVE EXHAUST SYSTEM	1	P95B-111-220-10-	RM	\$	80.60	✓
47	HEAT PROTECTION RH	1	P8R0-804-172-0-	bt	\$	81.50	✓
48	BATTERY COMPARTMENT COVER	1	P95B-825-216-	? de	\$	82.30	✓
TOTAL PARTS					\$	12,821.80	
LESS 10%					\$	1,282.18	
TOTAL PARTS COST					\$	11,539.62	

Labour Description							
1	TO REMOVE / REPLACE FRONT / REAR BUMPER, BONNET, OTHER DAMAGED PARTS	1560	Front 4680 Rear 4680	9360	\$	10,920.00	
	& TO REPAIR REAR END PANEL, SPARE WELL COMPARTMENT AREAS AFFECTED BY THE ACCIDENT.		+ 2 days for end panel.				
2	TO RESPRAY FRONT / REAR BUMPER, BONNET, REAR END PANEL & SPARE WELL COMPARTMENT.	1720	Front 2400 Rear 2400		\$	6,100.00	
3	TO CARRY-OUT BODY CAVITY PRESERVATION.		✓ 150		\$	250.00	
4	TO REMOVE & REFIT CARPET, TRIMS & BATTERY ON THE SPARE WELL COMPARTMENT TO GIVE WAY TO THE REPAIR ON THE REAR END PANEL.		✓ 1560		\$	2,340.00	
5	TO REMOVE & REPLACE THE RH REAR EXHAUST ASSY.		✓ NETT ✓		\$	1,560.00	
6	TO SUPPLY 1PC BONNET STICKER.		✓ NETT ✓		\$	150.00	
7	TO SUPPLY 1 SET FRONT / REAR NUMBER PLATE WITH CASING.		✓ NETT ✓		\$	140.00	
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		✓ 200		\$	250.00	
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		✓ NETT ✓		\$	600.00	
10	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		nm X NETT ?		\$	300.00	
11	SUNDRIES.		✓ NETT 50		\$	100.00	

Taufik 97495749
- WP
27/7/18 @ 10am
* Resurvey checkers &
before paint 12 days
sure like auto.com.

TOTAL LABOUR	\$	-	\$	22,710.00	
TOTAL PARTS	\$	-	\$	11,539.62	
TOTAL	34,256.42	\$	-	\$	34,249.62
LESS EXCESS	\$	-	\$	-	
TOTAL AFTER EXCESS	\$	-			
GST 7%	\$	-	\$	-	
GRAND TOTAL	\$	-	\$	-	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE
be any more damages found during the process of repairing, you will
- Supplementary item(s) must be added and
is subject to final approval from insurance Company

Acknowledged by Repairer

BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT,

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A
QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.



PORSCHE

STUTTGART AUTO PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
FINALIZATION COST OF REPAIRS



MSIG INSURANCE (SINGAPORE) PTE LTD		NAME : Mr Koh Wah Chuang		WIP : 35894	
4 SHENTON WAY #21-01		ADDRESS : 87 Toh Yi Drive		EXCESS :	
SGX CENTRE 2 S 068807		Singapore 596547		DATE : 20.07.2018	
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SDT898Z	DATE IN :		CONTACT PERSON :	EVA 63602846
CHASSIS NO :	WP12ZZ95ZFLB50887	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SKR9189E
MODEL :	Macan S	DATE REG.:	02.07.2014	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description			REVISED	PRICES
		QTY			
1	FRONT BUMPER	1	P95B-807-221-A -G2X	\$ 929.20	\$ 929.20
2	FRONT BUMPER CENTER GRILLE	1	P95B-807-683-H -1E0	\$ 304.60	\$ 304.60
3	LICENSE PLATE BRACKET	1	P95B-807-287- -1E0	\$ 79.90	\$ 79.90
4	FRONT BUMPER SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	\$ -	\$ 455.20
5	FRONT SENSOR GASKET	2	P5Q0-919-133- -989	\$ -	\$ 5.00
6	FRONT BUMPER REINFORCEMENT	1	P8RD-807-113-D -	\$ 350.20	\$ 350.20
7	REINFORCEMENT FOAM STRIP	1	P95B-807-550-G -	\$ 61.00	\$ 61.00
8	RADIATOR VANES	1	P95B-121-257-BY-	\$ 355.20	\$ 355.20
9	FRONT CENTER AIR DUCT	1	P95B-121-710- -1E0	\$ 142.50	\$ 142.50
10	AIR DUCT LH	1	P95B-121-673- -1E0	\$ 42.60	\$ 42.60
11	AIR DUCT RH	1	P95B-121-674- -1E0	\$ 42.60	\$ 42.60
12	RADIATOR AIR DUCT	1	P95B-121-707-F -	\$ 166.00	\$ 166.00
13	BONNET	1	P95B-823-031-HY-GRV	\$ 3,138.00	\$ 3,138.00
14	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 80.30
15	NUT	2	PWHT-004-974- -	\$ -	\$ 3.00
16	BONNET INNER SEAL	2	P95B-823-739- -	\$ 14.60	\$ 14.60
17	FRONT PANEL TOP COVER	1	P95B-805-806-N -1E0	\$ 68.00	\$ 68.00
18	BONNET INSULATION	1	P95B-863-831-A -	\$ 225.00	\$ 225.00
19	NOZZLE COVER (RH)	1	P95B-955-100-A -	\$ 122.50	\$ 122.50
20	NOZZLE COVER (LH)	1	P95B-955-099-A -	\$ -	\$ 122.50
21	HEADLAMP GASKET LH	1	P95B-941-323-E -	\$ 90.30	\$ 90.30
22	HEADLAMP GASKET RH	1	P95B-941-323-D -	\$ -	\$ 90.30
23	WARNING SIGN STICKER	1	P7PP-010-006-A -	\$ 6.10	\$ 6.10
24	MOBIL 1 STICKER	1	P7PP-010-786-T -	\$ 6.40	\$ 6.40
25	P95B-807-417-G -G2X/BUMPER	1	P95B-807-417-K -G2X	\$ 864.00	\$ 864.00
26	REAR BUMPER INSULATION LH	1	P95B-805-885- -	\$ 33.10	\$ 33.10
27	REAR BUMPER INSULATION RH	1	P95B-805-886- -	\$ 33.10	\$ 33.10
28	REAR BUMPER SENSOR PARKASSIST	2	P5Q0-919-275-B -G2X	\$ -	\$ 455.20
29	SENSOR GASKET	2	P5Q0-919-133- -989	\$ -	\$ 5.00
30	TOW COVER	1	P95B-807-500-A -G2X	\$ 39.60	\$ 39.60
31	REAR BUMPER SPOILER	1	P95B-807-521-AA-1E0	\$ 280.30	\$ 280.30
32	EXPANSION RIVET	6	PN -038-549-4 -	\$ 3.00	\$ 3.00
33	REAR BUMPER COVER	1	P95B-807-834-K -1E0	\$ 186.90	\$ 186.90
34	REAR BUMPER REINFORCEMENT	1	P8RD-807-313-D -	\$ 311.90	\$ 311.90

35	REINFORCEMENT SUPPORT RH	1	P8RO-807-332-E -	\$ 105.00	\$ 105.00
36	COMBINATION SCREW	4	PN -907-075-02-	\$ 25.60	\$ 25.60
37	COMBINATION SCREW	4	PN -907-721-02-	\$ 34.00	\$ 34.00
38	NUT	6	PN -905-038-01-	\$ 13.60	\$ 6.80
39	REAR BUMPER REFLECTOR RH	1	P95B-945-726-L -	\$ 298.90	\$ 298.90
40	LICENSE PLATE LIGHT	2	P95B-631-620-00-	\$ -	\$ 80.80
42	REAR MUFFLER RH	1	P95B-253-612-RY-	\$ 2,316.60	\$ 2,316.60
43	TAIL PIPE RH	1	P95B-253-682-N -	\$ 585.00	\$ 585.00
44	LENS-HEAD SCREW	2	P999-073-594-01-	\$ 9.20	\$ 9.20
45	HEXAGON-HEAD BOLT	2	PN -106-620-01-	\$ 2.40	\$ 2.40
46	(WB15) CLAMPING SLEEVE EXHAUST SYSTEM	1	P95B-111-220-10-	\$ 80.60	\$ 80.60
47	HEAT PROTECTION RH	1	P8RO-804-172-D -	\$ 81.50	\$ 81.50
48	BATTERY COMPARTMENT COVER	1	P95B-825-216- -	\$ 82.30	\$ 82.30
TOTAL PARTS				\$ 11,531.30	\$ 12,821.80
LESS 10%				\$ 1,153.13	\$ 1,282.18
TOTAL PARTS COST				\$ 10,378.17	\$ 11,539.62
Labour Description					
1	TO REMOVE / REPLACE FRONT / REAR BUMPER, BONNET, OTHER DAMAGED PARTS & TO REPAIR REAR END PANEL, SPARE WELL COMPARTMENT AREAS AFFECTED BY THE ACCIDENT.			\$ 9,360.00	\$ 10,920.00
2	TO RESPRAY FRONT / REAR BUMPER, BONNET, REAR END PANEL & SPARE WELL COMPARTMENT.			\$ 4,800.00	\$ 6,100.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 150.00	\$ 250.00
4	TO REMOVE & REFIT CARPET, TRIMS & BATTERY ON THE SPARE WELL COMPARTMENT TO GIVE WAY TO THE REPAIR ON THE REAR END PANEL.			\$ 1,560.00	\$ 2,340.00
5	TO REMOVE & REPLACE THE RH REAR EXHAUST ASSY.			\$ 1,560.00	\$ 1,560.00
6	TO SUPPLY 1PC BONNET STICKER.			\$ 150.00	\$ 150.00
7	TO SUPPLY 1 SET FRONT / REAR NUMBER PLATE WITH CASING.			\$ 140.00	\$ 140.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 200.00	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 600.00	\$ 600.00
10	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.			\$ -	\$ 300.00
11	SUNDRIES.			\$ 50.00	\$ 100.00
TOTAL LABOUR				\$ 18,570.00	\$ 22,710.00
TOTAL PARTS				\$ 10,378.17	\$ 11,539.62
TOTAL				\$ 28,948.17	\$ 34,249.62
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ 28,948.17	
GST 7%				\$ 2,026.37	\$ -
GRAND TOTAL				\$ 30,974.54	\$ -

NUMBER OF DAYS:12 WORKING DAYS (EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SATURDAY,SUNDAY AND PUBLIC HOLIDAY)
OWNER CLAIMING LOSS OF USE : \$180.00 x15 DAYS =\$2,700
GIA SEARCH FEES: \$2.00

Line	T	Product	Description	Quant	Price	Disc%	Total
1	L	CST	TP CLAIM AGAINST MSIG	0	0	0	0
2	P	P95B-807-221-A -G2X	LINING	1	929.2	20	\$ 929.20
3	P	P95B-807-683-H -1E0	GRILLE	1	304.6	20	\$ 304.60
4	P	P95B-807-287- -1E0	LICENSE PLATE BRACKET	1	79.9	20	\$ 79.90
7	P	P8R0-807-113-D -	BRACKET	1	350.2	20	\$ 350.20
8	P	P95B-807-550-G -	PLASTIC FOAM STRIP	1	61	20	\$ 61.00
9	P	P95B-121-257-BY-	P95B-121-257- Y-/VANES	1	355.2	20	\$ 355.20
10	P	P95B-121-710- -1E0	AIR DUCT	1	142.5	20	\$ 142.50
11	P	P95B-121-673- -1E0	AIR DUCT	1	42.6	20	\$ 42.60
12	P	P95B-121-674- -1E0	AIR DUCT	1	42.6	20	\$ 42.60
13	P	P95B-121-707-F -	P95B-121-707-B -/AIR DUCT	1	166	20	\$ 166.00
14	P	P95B-823-031-HY-GRV	P95B-823-031-CY-GRV/LID	1	3138	20	\$ 3,138.00
17	P	P95B-823-739- -	GASKET	2	7.3	20	\$ 14.60
18	P	P95B-805-806-N -1E0	P95B-805-806-G -1E0/COVER	1	68	20	\$ 68.00
19	P	P95B-863-831-A -	SOUND ABSORBER	1	225	20	\$ 225.00
20	P	P95B-955-100-A -	JET CARRIER (RH)	1	122.5	20	\$ 122.50
22	P	P95B-941-323-E -	GASKET	1	90.3	20	\$ 90.30
24	P	P7PP-010-006-A -	(WB35) WARNING SIGN	1	6.1	20	\$ 6.10
25	P	P7PP-010-786-T -	(WE72) START/STOP WARNING SIGNSTICKER	1	6.4	20	\$ 6.40
26	P	P95B-807-417-K -G2X	P95B-807-417-G -G2X/BUMPER	1	864	20	\$ 864.00
27	P	P95B-805-885- -	DAMPING PART LH	1	33.1	20	\$ 33.10
28	P	P95B-805-886- -	DAMPING PART RH	1	33.1	20	\$ 33.10
31	P	P95B-807-500-A -G2X	P95B-807-500- -G2X/CAP	1	39.6	20	\$ 39.60
32	P	P95B-807-521-AA-1E0	P95B-807-521-M -1E0/SPOILER	1	280.3	20	\$ 280.30
33	P	PN -038-549-4 -	EXPANSION RIVET	6	0.5	20	\$ 3.00
34	P	P95B-807-834-K -1E0	P95B-807-834- -1E0/COVER	1	186.9	20	\$ 186.90
35	P	P8R0-807-313-D -	BRACKET	1	311.9	20	\$ 311.90
37	P	P8R0-807-332-E -	SUPPORT	1	105	20	\$ 105.00

38	P	PN -907-075-02-	COMBINATION SCREW	4	6.4	20	\$	25.60
39	P	PN -907-721-02-	COMBINATION SCREW BM10X105X45	4	8.5	20	\$	34.00
40	P	PN -905-038-01-	NUT	4	1.7	20	\$	6.80
41	P	P958-945-726-L -	REFLECTOR REAR (RH)	1	298.9	20	\$	298.90
44	P	P958-253-612-RY-	P958-253-612-FY-/REAR MUFFLER	1	2316.6	20	\$	2,316.60
46	P	P958-253-682-N -	TAIL PIPE	1	585	20	\$	585.00
47	P	P999-073-594-01-	LENS-HEAD SCREW	2	4.6	20	\$	9.20
48	P	PN -106-620-01-	HEXAGON-HEAD BOLT	2	1.2	20	\$	2.40
49	P	P958-111-220-10-	(WB15) CLAMPING SLEEVE EXHAUST SYSTEM	1	80.6	20	\$	80.60
50	P	P8R0-804-172-D -	HEAT PROTECTION	1	81.5	20	\$	81.50
51	P	P958-825-216- -	LINING	1	82.3	20	\$	82.30
52	P	PN -905-038-01-	NUT	4	1.7	20	\$	6.80

\$ 11,531.30

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 14 November 2018 12:04 PM
To: 'jessicahs@eurokars.com.sg'; rickteo@eurokars.com.sg
Cc: stanley@eurokars.com.sg; SUR
Subject: RE: Finalization TP MSIG SDT898Z

Dear Jessica,

WITHOUT PREJUDICE

Confirm COR \$28,948.17 before GST @ 12 repair days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Monday, 12 November 2018 11:01 AM
To: rickteo@eurokars.com.sg
Cc: stanley@eurokars.com.sg; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: Finalization TP MSIG SDT898Z

Dear Rick,

Please assist. Veron call me today and requesting for the photo.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Jessica Harry Shastri
Sent: 22 October 2018 5:52 PM
To: Stanley Ngu <stanley@eurokars.com.sg>
Subject: FW: Finalization TP MSIG SDT898Z

Dear Stanley,

Please assist. Thank you.

Regards,

JESSICA SHASTRI

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: 22 October 2018 11:49 AM

To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>; Samuel Ng <samuel.ng@eurokars.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>

Cc: SUR <sur@lkkauto.com>; Janice Syn <janice.syn@porsche.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Subject: RE: Finalization TP MSIG SDT898Z

Dear Samuel/ Eva,

Please assist check items and before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>

Sent: Thursday, 18 October 2018 11:19 AM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; samuel.ng@eurokars.com.sg

Cc: SUR <sur@lkkauto.com>; janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Subject: RE: Finalization TP MSIG SDT898Z

Dear Samuel/ Eva,

Please assist. Thanks.

Regards,

JESSICA SHASTRI

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: 18 October 2018 11:15 AM
To: Jessica Harry Shastri <jessicahs@eurokars.com.sg>
Cc: SUR <sur@lkkauto.com>; Janice Syn <janice.syn@porsche.com.sg>; Eva Kok <eva.kok@eurokars.com.sg>;
Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: FW: Finalization TP MSIG SDT898Z

Dear Jessica,

Kindly provides us check items and before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg <jessicahs@eurokars.com.sg>
Sent: Thursday, 18 October 2018 10:51 AM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: janice.syn@porsche.com.sg; eva.kok@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>
Subject: Finalization TP MSIG SDT898Z

Dear Taufikh,

Please find our computation attached for your agreement.

COR: \$28,948.17 before GST
12 repair days (not including preparation of estimate, wait for liability/wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirmation for this case urgently.

Thank you.

Regards,

JESSICA SHASTRI

Admin Executive – Insurance Claims

27A, Tanjong Penjuru

Singapore 609042

Dir: +65 6331 0691 | Fax: +65 6331 0690 | Email: jessicahs@eurokars.com.sg

Website: www.eurokarsgroup.com

Veron Chen (LKKAUTO)

From: eva.kok@eurokars.com.sg
Sent: Tuesday, 11 September 2018 11:49 AM
To: Veron Chen (LKKAUTO); jessicahs@eurokars.com.sg
Subject: RE: SDT 898Z-DOA: 13/7/2018 (MSIG TP)

Hi,

Vehicle just release.

Please let us have some time.

Thank you

Best Regards.



Eva Kok
Insurance Claims Officer

EUROKARS SERVICES PTE LTD
27A Tanjong Penjuru
Singapore 609042
T: (65) 6331 0683
E: eva.kok@eurokars.com.sg

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: 11 September 2018 11:24 AM
To: Eva Kok <eva.kok@eurokars.com.sg>; Jessica Harry Shastri <jessicahs@eurokars.com.sg>
Subject: RE: SDT 898Z-DOA: 13/7/2018 (MSIG TP)

Dear Eva/Jessica,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 September 2018 4:06 PM
To: eva.kok@eurokars.com.sg; 'jessicahs@eurokars.com.sg' <jessicahs@eurokars.com.sg>
Subject: SDT 898Z-DOA: 13/7/2018 (MSIG TP)

Dear Eva/Jessica,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jul 2018		26 Jul 2018 16:32 Edit Adj Rpt	S\$28,948.17 Edit Estimates	S\$28,948.17 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN SWEE SENG , ID: S8835169Z, Tel: +6598393901									
Main Claimant: KOH WAH CHUANG , ID: S1213489D									
Vehicle Reg. No.: SDT898Z		Date of Loss: 13/07/2018 21:00 - :59 [48 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 564510		Policy/Cover Note No.: A2904010SAT2 (Comprehensive) Coverage: 28/11/2017 - 27/11/2018							
Vehicle Reg. No. (Insured): SKR9189E		Policy No. (Claimant):							
		Excess: S\$3,500.00							
Repairer: Stuttgart Auto Pte Ltd (HQ) 27A Tanjong Penjuru, 609042 Sungei Kadut - Tel: 6331 0680 / 6331 0686 (DID)									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/08/2018]									
Driver/Custodian (Insured): TAN SWEE SIANG {}, NRIC: S9113579E, Tel: +6596616647									
Adj Asg. Remarks: ON WP. Survey appt 27/07/18(Fri), 10am. Owner waiting. Liability 100%, Contact : Eva Kok at 6360 2846 Kindly avoid lunch time 12pm-1pm									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDT898Z (564510)
[SKR9189E]

TP

KOH WAH CHUANG

Jul 13 2018 9:00PM

[TAN SWEE SENG]

Stuttgart Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/07/18 17:20	Accident Statement From: OD - Reg. No: SKR9189E, Claimant: TAN SWEE SENG	 Load HTML	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/18 15:09	Adjuster Immediate Advice	 Load HTML	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/18 11:58	General View	 Load JPG	☒
2	30/07/18 11:58	General View	 Load JPG	☒
3	30/07/18 11:58	General View	 Load JPG	☒
4	30/07/18 11:58	General View	 Load JPG	☒
5	30/07/18 11:58	General View	 Load JPG	☒
6	30/07/18 11:58	General View	 Load JPG	☒
7	30/07/18 11:58	General View	 Load JPG	☒
8	30/07/18 11:58	General View	 Load JPG	☒
9	30/07/18 11:58	General View	 Load JPG	☒
10	30/07/18 11:58	General View	 Load JPG	☒
11	30/07/18 11:58	General View	 Load JPG	☒
12	30/07/18 11:58	General View	 Load JPG	☒
13	30/07/18 11:58	General View	 Load JPG	☒
14	30/07/18 11:58	General View	 Load JPG	☒
15	30/07/18 11:58	General View	 Load JPG	☒
16	30/07/18 11:58	General View	 Load JPG	☒
17	30/07/18 11:58	General View	 Load JPG	☒
18	30/07/18 11:58	General View	 Load JPG	☒
19	30/07/18 11:58	General View	 Load JPG	☒
20	30/07/18 11:58	General View	 Load JPG	☒
21	30/07/18 11:58	General View	 Load JPG	☒
22	30/07/18 11:58	General View	 Load JPG	☒
23	30/07/18 11:58	General View	 Load JPG	☒
24	30/07/18 11:58	General View	 Load JPG	☒
25	30/07/18 11:58	General View	 Load JPG	☒
26	30/07/18 11:58	General View	 Load JPG	☒
27	30/07/18 11:58	General View	 Load JPG	☒
28	30/07/18 11:58	General View	 Load JPG	☒
29	30/07/18 11:58	General View	 Load JPG	☒
30	30/07/18 11:58	General View	 Load JPG	☒
31	30/07/18 11:58	General View	 Load JPG	☒
32	30/07/18 11:58	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	30/07/18 11:58	General View	 Load JPG	☒
34	30/07/18 11:58	General View	 Load JPG	☒
35	30/07/18 11:58	General View	 Load JPG	☒
36	30/07/18 11:58	General View	 Load JPG	☒
37	30/07/18 11:58	General View	 Load JPG	☒
38	30/07/18 11:58	General View	 Load JPG	☒
39	30/07/18 11:58	General View	 Load JPG	☒
40	30/07/18 11:58	General View	 Load JPG	☒
41	30/07/18 11:58	General View	 Load JPG	☒
42	30/07/18 11:58	General View	 Load JPG	☒
43	30/07/18 11:58	General View	 Load JPG	☒
44	30/07/18 11:58	General View	 Load JPG	☒
45	30/07/18 11:58	General View	 Load JPG	☒
46	30/07/18 11:58	General View	 Load JPG	☒
47	30/07/18 11:58	General View	 Load JPG	☒
48	30/07/18 11:58	General View	 Load JPG	☒
49	30/07/18 11:58	General View	 Load JPG	☒
50	30/07/18 11:58	General View	 Load JPG	☒
51	30/07/18 11:58	General View	 Load JPG	☒
52	30/07/18 11:58	General View	 Load JPG	☒
53	30/07/18 11:58	General View	 Load JPG	☒
54	30/07/18 11:58	General View	 Load JPG	☒
55	30/07/18 11:58	General View	 Load JPG	☒
56	30/07/18 11:58	General View	 Load JPG	☒
57	30/07/18 11:58	General View	 Load JPG	☒
58	30/07/18 11:58	General View	 Load JPG	☒
59	30/07/18 11:58	General View	 Load JPG	☒
60	30/07/18 11:58	General View	 Load JPG	☒
61	30/07/18 11:58	General View	 Load JPG	☒
62	30/07/18 11:58	General View	 Load JPG	☒
63	30/07/18 11:58	General View	 Load JPG	☒
64	30/07/18 11:58	General View	 Load JPG	☒
65	30/07/18 11:58	General View	 Load JPG	☒
66	30/07/18 11:58	General View	 Load JPG	☒
67	30/07/18 11:58	General View	 Load JPG	☒
68	30/07/18 11:58	General View	 Load JPG	☒
69	30/07/18 11:58	General View	 Load JPG	☒
70	30/07/18 11:58	General View	 Load JPG	☒
71	30/07/18 11:58	General View	 Load JPG	☒
72	30/07/18 11:58	General View	 Load JPG	☒
73	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
74	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
75	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
76	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
77	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
78	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
79	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
80	13/11/18 16:03	Reinspection Photo	 Load JPG	☒
81	13/11/18 16:03	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	13/11/18 16:03	Reinspection Photo		☒
83	13/11/18 16:03	Reinspection Photo		☒
84	13/11/18 16:03	Reinspection Photo		☒
85	13/11/18 16:03	Reinspection Photo		☒
86	13/11/18 16:03	Reinspection Photo		☒
87	13/11/18 16:03	Reinspection Photo		☒
88	13/11/18 16:03	Reinspection Photo		☒
89	13/11/18 16:03	Reinspection Photo		☒
90	13/11/18 16:03	Reinspection Photo		☒
91	13/11/18 16:03	Reinspection Photo		☒
92	13/11/18 16:03	Reinspection Photo		☒
93	13/11/18 16:03	Reinspection Photo		☒
94	13/11/18 16:03	Reinspection Photo		☒
95	13/11/18 16:03	Reinspection Photo		☒
96	13/11/18 16:03	Reinspection Photo		☒
97	13/11/18 16:03	Reinspection Photo		☒
98	13/11/18 16:03	Reinspection Photo		☒
99	13/11/18 16:03	Reinspection Photo		☒
100	13/11/18 16:03	Reinspection Photo		☒
101	13/11/18 16:03	Reinspection Photo		☒
102	13/11/18 16:03	Reinspection Photo		☒
103	13/11/18 16:03	Reinspection Photo		☒
104	13/11/18 16:03	Reinspection Photo		☒
105	13/11/18 16:03	Reinspection Photo		☒
106	13/11/18 16:03	Reinspection Photo		☒
107	13/11/18 16:03	Reinspection Photo		☒
108	13/11/18 16:03	Reinspection Photo		☒
109	13/11/18 16:03	Reinspection Photo		☒
110	13/11/18 16:03	Reinspection Photo		☒
111	13/11/18 16:03	Reinspection Photo		☒
112	13/11/18 16:03	Reinspection Photo		☒
113	13/11/18 16:03	Reinspection Photo		☒
114	13/11/18 16:03	Reinspection Photo		☒
115	13/11/18 16:03	Reinspection Photo		☒
116	13/11/18 16:03	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/07/18 17:20	TP SOT898Z GIA REPORT (4/5) From: OD - Reg. No: SKR9189E, Claimant: TAN SWEE SENG		☐
2	20/07/18 17:34	Estimate		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013700/T1VD3E2

Date: 26/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29040105AT2

Claimant Vehicle
No: SDT898Z

Insured Vehicle No: SKR9189E

Date of Loss: 13/07/2018

Nature of Claim: TP

Claim No: 564510

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDT898Z

Make & Model: PORSCHE MACAN S, 3.0 PDK (A)

Engine No: 001920

Reg. Date: 02/07/2014 (Man. Year: 2014)

Chassis No: WP1ZZZ95ZFLB50887

Colour: Blue

Odometer: 47056 km

Engine Capacity: 2997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size: 255/50 R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,935.74	10,718.17	1,217.57	10.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,320.00	18,230.00	4,090.00	18.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,255.74	28,948.17	5,307.57	15.49
+ GST 7.00/7.00% (S\$)	2,397.90	2,026.37	371.53	15.49
Nett Amount (S\$)	36,653.64	30,974.54	5,679.10	15.49

INSPECTION

Date of Assignment: 26/07/2018

Date Inspected: 27/07/2018

Inspected At:

Stuttgart Auto Pte Ltd (HQ)

12 Sungei Kadut Ave

Singapore 729648

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts:	M1-SUV	PORSCHE MACAN S 3.0 PDK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDT898Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Deformed	929.20 FL	*929.20 FL
2	1		*FRONT BUMPER CENTER GRILLE	Deformed	304.60 FL	*304.60 FL
3	1		*LICENSE PLATE BRACKET	Deformed	79.90 FL	*79.90 FL
4	2		*FRONT BUMPER SENSOR PARKASSIST	Not Necessary	455.20 FL	*- FL
5	2		*FRONT SENSOR GASKET	Not Necessary	5.00 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	350.20 FL	*350.20 FL
7	1		*REINFORCEMENT FOAM STRIP	Deformed	61.00 FL	*61.00 FL
8	1		*RADIATOR VANES	Deformed	355.20 FL	*355.20 FL
9	1		*FRONT CENTER AIR DUCT	Deformed	142.50 FL	*142.50 FL
10	1		*AIR DUCT LH	Deformed	42.60 FL	*42.60 FL
11	1		*AIR DUCT RH	Deformed	42.60 FL	*42.60 FL
12	1		*RADIATOR AIR DUCT	Deformed	166.00 FL	*166.00 FL
13	1		*BONNET	Bent	3,138.00 FL	*3,138.00 FL
14	1		*CAVITY PRESERVATION	Not Necessary	80.30 FL	*- FL
15	2		*NUT	Not Necessary	3.00 FL	*- FL
16	2		*BONNET INNER SEAL	Necessary	14.60 FL	*14.60 FL
17	1		*FRONT PANEL TOP COVER	Deformed	68.00 FL	*68.00 FL
18	1		*BONNET INSULATION	Necessary	225.00 FL	*225.00 FL
19	1		*NOZZLE COVER (RH)	Cut	122.50 FL	*122.50 FL
20	1		*NOZZLE COVER (LH)	Not Necessary	122.50 FL	*- FL
21	1		*HEADLAMP GASKET LH	Cut	90.30 FL	*90.30 FL
22	1		*HEADLAMP GASKET RH	Not Necessary	90.30 FL	*- FL
23	1		*WARNING SIGN STICKER	Necessary	6.10 FL	*6.10 FL
24	1		*MOBIL 1 STICKER	Necessary	6.40 FL	*6.40 FL
25	1		*P95B-807-417-G -G2X/BUMPER	Deformed	864.00 FL	*864.00 FL
26	1		*REAR BUMPER INSULATION LH	Necessary	33.10 FL	*33.10 FL
27	1		*REAR BUMPER INSULATION RH	Necessary	33.10 FL	*33.10 FL
28	2		*REAR BUMPER SENSOR PARKASSIST	Not Necessary	455.20 FL	*- FL
29	2		*SENSOR BRACKET	Not Necessary	5.00 FL	*- FL
30	1		*TOW COVER	Cut	39.60 FL	*39.60 FL
31	1		*REAR BUMPER SPOILER	Deformed	280.30 FL	*280.30 FL
32	6		*EXPANSION RIVET	Necessary	3.00 FL	*3.00 FL
33	1		*REAR BUMPER COVER	Deformed	186.90 FL	*186.90 FL
34	1		*REAR BUMPER REINFORCEMENT	Bent	311.90 FL	*311.90 FL
35	1		*REINFORCEMENT SUPPORT RH	Bent	105.00 FL	*105.00 FL
36	4		*COMBINATION SCREW	Necessary	25.60 FL	*25.60 FL
37	4		*COMBINATION SCREW	Necessary	34.00 FL	*34.00 FL
38	1		*NUT (6PCS)	Necessary	13.60 FL	*13.60 FL
39	1		*REAR BUMPER REFLECTOR RH	Cut	298.90 FL	*298.90 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*LICENSE PLATE LIGHT	Not Necessary	80.80 FL	*- FL
41	1		*REAR MUFFLER RH	Bent	2,316.60 FL	*2,316.60 FL
42	1		*TAIL PIPE RH	Cut	585.00 FL	*585.00 FL
43	2		*LENS-HEAD SCREW	Necessary	9.20 FL	*9.20 FL
44	2		*HEXAGON-HEAD BOLT	Necessary	2.40 FL	*2.40 FL
45	1		*(WB15) CLAMPING SLEEVE EXHAUST SYSTEM	Necessary	80.60 FL	*80.60 FL
46	1		*HEAT PROTECTION RH	Bent	81.50 FL	*81.50 FL
47	1		*BATTERY COMPARTMENT COVER	Deformed	82.30 FL	*82.30 FL
48	1		*BONNET STICKER	Necessary	150.00 FS	*150.00 FS
49	1		*SET FRONT / REAR NUMBER PLATE WITH CASING	Cracked	140.00 FS	*140.00 FS
50	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **13,218.60** **11,871.30**

- List Item Discount on L Items 10.00/10.00% (\$\$) **1,282.86** **1,153.13**

Total Parts (\$\$) **11,935.74** **10,718.17**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE FRONT / REAR BUMPER, BONNET, OTHER DAMAGED PARTS & TO REPAIR REAR END PANEL, SPARE WELL COMPARTMENT AREAS AFFECTED BY THE ACCIDENT	New	10,920.00	9,360.00
2	TO RESPRAY FRONT / REAR BUMPER, BONNET, REAR END PANEL & SPARE WELL COMPARTMENT	New	6,100.00	4,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	150.00
4	TO REMOVE & REFIT CARPET, TRIMS & BATTERY ON THE SPARE WELL COMPARTMENT TO GIVE WAY TO THE REPAIR ON THE REAR END PANEL	New	2,340.00	1,560.00
5	TO REMOVE & REPLACE THE RH REAR EXHAUST ASSY	New	1,560.00	1,560.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	200.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
8	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	300.00	0.00
Gross Labour Cost (S\$)			22,320.00	18,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >