




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18013708/T1pa3s2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 27-04-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SJU 7472X	<b>Veh. Inspected</b>	SLM 9706C
	<b>Policy No.</b>	DMCFHQ17-000185	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	DM18HO02629/JT	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	26/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	MAZDA 3	<b>c.c</b>	1496
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
	<b>Chassis No.</b>	JM6BN22A8H0149988	<b>Colour</b>	GREY
	<b>Odometer</b>	94724	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	205/60 R16	WEST LAKE	6 mm
	<b>L/H Front Tyre</b>	205/60 R16	WEST LAKE	6 mm
	<b>R/H Rear Tyre</b>	205/60 R16	WEST LAKE	6 mm
	<b>L/H Rear Tyre</b>	205/60 R16	WEST LAKE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	02/07/2018	<b>Inspection Date</b>	26/07/2018
	<b>Survey held at</b>	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	