



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR NG CHER CHOON
BLK. 406 YISHUN AVE 6
#04-1316 SINGAPORE 760406

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SJH 7104 C (AXA)
OUR REF : TP 5922
VECHICLE NO : SKG 9619 P
MAKE/MODEL : HONDA EDIX
DATE OF ACCIDENT : 24-07-18

SURVEY BY

DATE : 25-Jul-18

1 PC FRONT DOOR RH		S\$	1,050.00 <i>ht</i>
2 PCS FRONT DOOR HINGES RH	48.60		97.20 <i>Ry</i>
1 PC FRONT DOOR OUTER MOULDING RH			90.00 <i>de</i>
1 PC FRONT DOOR STICKER RH			70.00 <i>de</i>
1 PC FRONT DOOR OUTER HANDLE RH			150.00 <i>x</i>
1 PC FRONT DOOR GLASS RH			486.00 <i>x</i>
1 PC FRONT DOOR REGULATOR GEAR (WITH MOTOR) RH			450.00 <i>?</i>
1 PC FRONT DOOR CENTRE LOCK MOTOR RH			268.00 <i>?</i>
		S\$	2,661.20
	LESS 20%		532.24
		S\$	2,128.96
1 PC FRONT DOOR SUN VISOR		S\$	120.00 <i>net 60</i> S/NETT
TO CHECK WIRING FUNCTION			30.00 <i>✓</i>
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL			80.00 <i>30.</i>
LABOUR CHARGES			500.00 <i>400</i>
TO PUTTY AND SPRAY PAINTING CHARGES			700 <i>700</i> 800.00 <i>600</i>
		S\$	3,658.96

SIN DOLLARS: THREE THOUSAND SIX HUNDRED FIFTY-EIGHT AND CENTS NINTY-SIX ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
-WP'
27/7/18 P 1050
Lump sum
Resurvey after repair
4 days
sure (Meant to be m.)