



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR NG CHER CHOON
BLK. 406 YISHUN AVE 6
#04-1316 SINGAPORE 760406

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : SJH 7104 C (AXA)
OUR REF : TP 5922
VEHICLE NO : SKG 9619 P
MAKE/MODEL : HONDA EDIX
DATE OF ACCIDENT : 24-07-18

SURVEY BY

DATE : 25-Jul-18

1 PC FRONT DOOR RH		S\$	1,050.00 <i>bt</i>
2 PCS FRONT DOOR HINGES RH	48.60		97.20 <i>Ry</i>
1 PC FRONT DOOR OUTER MOULDING RH			90.00 <i>de</i>
1 PC FRONT DOOR STICKER RH			70.00 <i>de</i>
1 PC FRONT DOOR OUTER HANDLE RH			150.00 <i>x nn</i>
1 PC FRONT DOOR GLASS RH			480.00 <i>x nn</i>
1 PC FRONT DOOR REGULATOR GEAR (WITH MOTOR) RH			450.00 <i>? - bt</i>
1 PC FRONT DOOR CENTRE LOCK MOTOR RH			268.00 <i>? - bt</i>
		S\$	2,661.20
	LESS 20%		532.24
		S\$	2,128.96
1 PC FRONT DOOR SUN VISOR	60.00	S\$	120.00 <i>nei 60</i>
TO CHECK WIRING FUNCTION			30.00 ✓
TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL			80.00 <i>30</i>
LABOUR CHARGES	1160.00		500.00 <i>400</i>
TO PUTTY AND SPRAY PAINTING CHARGES			700 <i>700</i>
			800.00 <i>600</i>
	22762.40	S\$	3,658.96

SIN DOLLARS: THREE THOUSAND SIX HUNDRED FIFTY-EIGHT AND CENTS NINTY-SIX ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Tanpin 97495749
-wp'

27/7/18 P 1050

Leap sum
Recovery after repair
4 days

sure (bleant) com.