

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOM	SOMPO INSURANCE SINGAPORE PL			CS3/SMO18013713	3/Gz4d3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	20-08-2018		
			Code:	SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	SLE 2948J	Veh. Inspected		FY 7919B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD1803206	Excess (\$)		0.00	
	Assign From	MELVIN YONG	Assign Date		26/07/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	NC31055958	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size Make		Balance		
	R/H Front Tyre	120/60 R17	METZELER		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60Z R17	METZE	LER	4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS	SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
5.	5. General Information					
	Accident Date	26/07/2018	Inspec	t Date / Time	30/07/2018 (03:10 PM)	
	Survey held at	Survey held at ASIA MOTORSPORTS SOLUTION PTE LTD				
	568 GEYLANG ROAD SINGAPORE 389514					
5a.	a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/SMO18013713/Gz4d3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.