

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Withheld ESTIMATE

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Accident Claims Department

*1. B1
Paying B4 pain*

7-10 days

Date : 27/07/2018
Vehicle No : SLC1911G
Veh Make/Model : Honda Odyssey 2.4 EXV-S
YOM : 2016
Chassis No : JHMRC1890GC203028
Date of Accident : 25/07/2018

No	Qty	Description	Amount \$
		List Items:-	
1	1	Tail gate	\$ <i>Bt</i> 1,193.00 ✓
2	1	Tail gate reflector (LH)	\$ <i>cm</i> 378.60 ✓
3	1	Tail gate reflector (RH)	\$ <i>cm</i> 378.60 ✓
4	1	Tail gate "ODYSSEY" chrome	\$ - 225.90 ?
5	1	Tail gate logo	\$ <i>re</i> 25.80 ✓
6	1	Tail gate chrome	\$ <i>war</i> 195.00 ✓
7	2	Tail gate number plate lamp	\$ 110.00 ?
8	1	Tail gate windscreen glass	\$ <i>su</i> 1,211.00 X
9	1	Tail gate windscreen glass moulding	\$ <i>re</i> 220.00 ✓
10	1	Tail gate wiper motor	\$ 247.40 ?
11	2	Tail gate hinge	\$ <i>n</i> 100.00 X
12	1	Tail gate weatherstrip	\$ 115.00 ?
13	1	Tail gate lock	\$ <i>Tn</i> 189.00 ✓
14	1	Tail gate inner trim board	\$ 202.20 ?
15	10	Tail gate inner trim board clip	\$ 60.00 ?
16	1	LH tail lamp	\$ <i>pu</i> 821.80 X
17	1	RH tail lamp	\$ 821.80 ?
18	1	Rear LH corner bumper	\$ 75.30 ?
19	1	Rear RH corner bumper	\$ 75.30 ?
20	1	Rear bumper	\$ <i>pu</i> 552.70 ✓
21	1	Rear LH bumper reflector	\$ <i>ma</i> 43.80 ✓
22	1	Rear RH bumper reflector	\$ <i>cm</i> 43.80 ✓
23	1	Rear LH bumper spoiler	\$ 111.80 ?
24	1	Rear RH bumper spoiler	\$ <i>Bu</i> 111.80 ✓
25	2	Rear bumper side retainer	\$ <i>su</i> 80.00 X
26	10	Rear bumper clips	\$ <i>re</i> 38.00 ✓
27	1	Antenna assy	\$ 85.00 ?
28	1	Keyless smart entry buzze	\$ 85.00 ?
29	1	End panel	\$ <i>Bt</i> 551.80 ✓
30	1	End panel top garnish	\$ 135.00 ?
Balance b/f			\$ 8,484.40

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attn: Accident Claims Department

Date : 27/07/2018
Vehicle No : SLC1911G
Veh Make/Model : Honda Odyssey 2.4 EXV-S
YOM : 2016
Chassis No : JHMRC1890GC203028
Date of Accident : 25/07/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 8,484.40
31	6	End panel top garnish clip	\$ 18.00 ✓
32	1	Floor panel	\$ 397.56 ?
33	1	Floor panel board	\$ 465.72 ?
34	1	Exhaust silencer	\$ 636.80 X
35	2	Exhaust silencer rubber	\$ 50.00 X
36	1	Exhaust silencer heat shield	\$ 90.36 ?
		Total - List Item	\$ 10,142.84
		Less 20%	\$ 2,028.57
		Total	\$ 8,114.27
		Special Nett Items:-	
1	1	Rear number plate with holder	\$ 55.00 ?
2	1 Set	Rear reverse sensor (original)	\$ 400.00 ✓
3	1	Tail gate windscreen glass sealant/gum and clip	\$ 80.00 barn
4	1	Tail gate windscreen glass v-cool	\$ 300.00 X
		Total - SN Item	\$ 835.00
		Labour Charges:-	
1		Spray painting on all affected area.	\$ 1,200.00 9000
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,100.00 ?
3		To apply anti rust treatment.	\$ 120.00 ?
4		To check wiring system & light.	\$ 80.00 200
5		To remove and replace reverse sensor.	\$ 120.00 500
6		To remove and reinstall tail gate winscreen glass.	\$ 150.00 1200
7		To remove and reinstall rear passenger seats to assist on repair.	\$ 150.00 1200
8		To remove and replace tailgate attachments and test water leaking.	\$ 100.00 600
9		To remove and reinstall interior upholstery.	\$ 80.00 ✓
10		To remove and replace/adjust exhaust silencer, rubber and heat shield.	\$ 150.00 X
		Total - L/C	\$ 3,250.00
		Sub-Total	\$ 12,199.27
		7% GST	\$ 853.95
		Total	\$ 13,053.22

Acknowledged by Repairer

Signature:

Date: