

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0851/2018/PH
Date : 26-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Cranfield Mark
Address : Blk 765A Mountbatten Road
Singapore 437853
Telephone : HP +65 97544431
Type of Claim : Own Damage Claims
Policy No. : 2100495488-01
Vehicle No : **SDQ 8839 H**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Dec-16
Engine No : CYG015942
Chassis No : WAUZZZ4G5HN026081
Mileage : 15327 KM
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-18
Place of Accident : ECP exit at Marine Parade Still Road South

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDQ 8839 H.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00	✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and automatic rear lid closure assy.	S/N \$ 360.00	X
3	To remove and transfer lhs rear door's multi lock system and power window devices.	S/N \$ 280.00	✓
4	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain airbag and sill trims.	S/N \$ 1,400.00	✓
5	To remove and renew lhs quarter glass and rear windscreen for fender renewal.	S/N \$ 600.00	✓
6	To dislodge and reinstall rear wire harness for tail lights, fuse units, battery manager, fuse and relay trays and electrical components.	S/N \$ 1,400.00	✓
7	To dismantle lhs rear door, lhs side member trim, rear bumper and rear lid. Cut out and reweld lhs rear fender. Renew lhs rear door. Re-organise crash management components.	S/N \$ 6,650.00	3500.00
TOTAL LABOUR CHARGES		: \$ 11,050.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDQ 8839 H.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To respray lhs rear door, lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 4,200.00	2200. ✓
9	To renew lhs rear rim and carry out wheel alignment. S/N	\$ 280.00	✓ ✓
10	To carry out diagnostic check S/N	\$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 15,722.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDQ 8839 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	DOOR - LH Distorted	\$ 3,211.00	✓ 2568.80
2	ATTACHMENT PARTS FOR DOOR Not New	\$ 72.00	? X
3	OUTER DOOR SEAL New	\$ 202.00	✓ 161.60
4	BONDING AGENT Not New	\$ 43.00	? X
5	CLEANING SOLUTION New	\$ 64.00	? X
6	COVER DOOR CATCH New	\$ 15.00	X
7	DOOR CATCH Not New	\$ 105.00	X
8	SECTIONAL PART - SIDE PANEL LH Distorted	\$ 2,739.00	✓ 2191.20
9	WHEEL HOUSING LINER - LH Not New	\$ 246.00	X.
10	ATTACHMENT PARTS FOR WHEEL LINER Not New	\$ 62.00	X
11	HEATED REAR WINDOW New	\$ 1,017.00	? 813.60
12	PRIMER - 10 ML New	2 \$ 37.00	✓ 29.12
13	SIDE WINDOW - LH New	\$ 344.00	? 275.20
14	TRIM STRIPS FOR SIDE WINDOW Not New	\$ 222.00	X
15	ALUMINIUM RIM Lt	\$ 726.00	✓ 580.40
16	ATTACHMENT PARTS - CLIP New	\$ 77.00	✓ 60.88
17	ATTACHMENT PARTS - ADHESIVE TAPE New	\$ 14.00	✓ 10.96
18	ARCYLIC SEALANT	\$ 180.00	✓ 180
19	CAVITY WAX	\$ 140.00	✓ 140
20	STONE CHIP TREATMENT	\$ 180.00	✓ 180
SUB - TOTAL SPARE PARTS CHARGES :		\$ 9,696.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDQ 8839 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	METAL FILLER POWDER	\$ 280.00	✓ 280
22	REAR WINDSCREEN SEALANT	\$ 200.00	✓ 200
23	1/4 GLASS SEALANT	\$ 100.00	✓ 100
24	SUNDRIES	\$ 300.00	? 94.40
TOTAL SPARE PARTS CHARGES		\$ 10,576.00	
TOTAL LABOUR CHARGERS		\$ 15,722.00	
GRAND TOTAL		\$ 26,298.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

26,698

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 27/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant