

Premium Automobiles

Road 1, Singapore 408699
6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDQ 8839 H.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	DOOR - LH Distorted	\$	3,211.00	✓ 2568.80
2	ATTACHMENT PARTS FOR DOOR Not New	\$	72.00	? X
3	OUTER DOOR SEAL New	\$	202.00	✓ 161.60
4	BONDING AGENT Not New	\$	43.00	? X
5	CLEANING SOLUTION Not New	\$	64.00	? X
6	COVER DOOR CATCH Not New	\$	15.00	+ }
7	DOOR CATCH Not New	\$	105.00	X
8	SECTIONAL PART - SIDE PANEL LH Distorted	\$	2,739.00	✓ 2191.20
9	WHEEL HOUSING LINER - LH Not New	\$	246.00	X.
10	ATTACHMENT PARTS FOR WHEEL LINER Not New	\$	62.00	X
11	HEATED REAR WINDOW New	\$	1,017.00	? 813.60
12	PRIMER - 10 ML New	2 \$	37.00	✓ 29.12
13	SIDE WINDOW - LH New	\$	344.00	? 275.20
14	TRIM STRIPS FOR SIDE WINDOW Not New	\$	222.00	X
15	ALUMINIUM RIM Lt	\$	726.00	✓ 580.40
16	ATTACHMENT PARTS - CLIP New	\$	77.00	✓ 60.88
17	ATTACHMENT PARTS - ADHESIVE TAPE New	\$	14.00	✓ 10.96
18	ARCYLIC SEALANT	\$	180.00	✓ 180
19	CAVITY WAX	\$	140.00	✓ 140
20	STONE CHIP TREATMENT	\$	180.00	✓ 180
SUB - TOTAL SPARE PARTS CHARGES :		\$	9,696.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.