

SERVICE ESTIMATE

86164 - C00001 SL: SERVICE SALES - PC
 Mr Yeo Eng Lam @ Clement Yeo
 230 Jalan Hock Chye

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.date : 25/07/2018

WIP No. : 18408

Veh.In/Out:

*Tel.No. : Mobile: 97694447

Reg.No. : SCM6928E

Reg.date : 18/06/2016

Mileage : 0

Chassis No: SAJBB4AGXGCY20117

Singapore 538223

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Yeo Eng Lam @ Cle

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount G
-------	-------------	----------	-------	-------	-----	----------

802	TO REPLACE REAR RH DOOR, REAR RH DOOR TRIM, REAR RH DOOR SEAL, REAR RH FENDER, REAR BUMPER, ETC	0	7200.00	0		7,200.00 \$ 6300
-----	---	---	---------	---	--	-----------------------------

800	TO PUTTY SPRAY PAINT ON REAR RH DOOR, REAR RH FENDER, REAR BUMPER, REAR END PANEL, RH ROCKER PANEL, ETC	0	4800.00	0		4,800.00 \$ 4000
-----	---	---	---------	---	--	-----------------------------

802	TO REPLACE REAR WINDSCREEN	0	900.00	0		900.00 \$ 180
802	TO REMOVE & INSTALL REAR BOOT	0	2700.00	0		2,700.00 \$ 2700

COMPARTMENT PARTS

802	TO REMOVE & INSTALL INTERIOR P	0	3600.00	0		3,600.00 \$ 2700
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 \$
0031	TO REPLACE REAR RH RIM	0	50.00	0		50.00 \$
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00 \$
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00 \$

RESETTING OF ALL ELECTRICAL MODULES

SERVICE ESTIMATE

64 - C00001 SL: SERVICE SALES - PC
Yeo Eng Lam @ Clement Yeo
10 Jalan Hock Chye

Singapore 538223

Closed by : Michelle Ong Siew Be
Svc Consultant :
Remarks : Mr Yeo Eng Lam @ Cle

Inv.No. : B&P
Inv.date : 25/07/2018
WIP No. : 18408
Veh.In/Out:
*Tel.No. : Mobile: 97694447
Reg.No. : SCM6928E
Reg.date : 18/06/2016
Mileage : 0
Chassis No: SAJBB4AGXGCY20117

GST Reg.No:M28920628X

0 Page 2

Op.No Description Mech Qty Price Disc% Pkg Amount G

PANEL-QUARTER	1.0 EA	1889.30	1,889.30	SA
PANEL-DOOR	1.0 EA	1951.10	1,951.10	repair
SOUND DEADENING PAD	2.0 EA	250.00	500.00	new
JT2H1237/SEAL-DOOR	1.0 EA	220.40	220.40	X
HANDLE-DOOR	1.0 EA	395.20	395.20	scr
REAR WINDSCREEN XF Y	1.0 EA	1433.40	1,433.40	new photo
WINDSCREEN SPACER	4.0 EA	8.40	33.60	scr
JC207026/SEALANT WIN	2.0 EA	159.70	319.40	scr
D PRIMER GLASS & P	1.0 EA	37.40	37.40	scr
ALLOY 18" CHALICE TW	1.0 EA	1428.60	1,428.60	scr
LINER-WHEELARCH	1.0 EA	420.20	420.20	?
3M07333 IMPACT RESIS	1.0 EA	80.00	80.00	X
BODY PANEL SEALANT X	1.0 EA	878.80	878.80	scr
ADHESIVE SEALER FL2	1.0 EA	425.40	425.40	scr

Gross Total. 30,308.80

Labour Total 20,296.00
Parts Total 10,012.80
Package Total 0.00

Net..... 30,308.80
GST @ 7.0% 2,121.62
Total..... 32,430.40
Paid..... 0.00
Please Pay.. 32,430.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Wearnes Automotive Pte Ltd
45 Leng Kee Road Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Date: 02/08/18
Co reg no: 183501400R / GST reg no: M28920628X

Rasul

Ap 90000068

13 days

02/08/18 @ 1030

EXCESS: NIL

Revert

Reay by paint