

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4817T

DATE 26/7/2018 10:16

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid 'H' Emblem X			\$ 27.20	
	Boot Lid CRDI Plate /			\$ 41.00	
	Bootlid Moulding X 1400			\$ 85.00	
	Bootlid i40 Emblem /			\$ 41.00	
	Bootlid Lower Garnish X 1400			\$ 398.00	
	Rear Bumper /			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Clips /			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover /			\$ 225.00	
	SUB TOTAL			\$ 2,548.55	
	LESS 20%			\$ 509.71	
	DISCOUNTED TOTAL			\$ 2,038.84	
	Boot Lid Comfort Logo & Tel No. Sticker X			\$ 30.00	Nett
	Rear Bumper Reverse Sensor /			\$ 135.70	Nett
	Rear Bumper Rubber Mat /			\$ 50.00	Nett
				\$ 215.70	
	Labour Charge				
	Panel Beating			\$ 350.00 ²⁰⁰	
	Spray Painting Charge-Bootlid/Bumper			\$ 500.00 ⁴⁰⁰	
	Wiring Charge			\$ 50.00 ^X	
	Remove/Refix Reverse Sensor			\$ 120.00 ⁷⁰	
	TOTAL LABOUR			\$ 1,020.00	
	ESTIMATE TOTAL			\$ 3,274.54	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalra 10/11/18
 26/7/18 11:00 hrs
 20/7/18
 4/5
 After Repair photo