

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0857/2018/KS
Date : 26-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Eng Kim Hooi
Address : PIE Near Toa Payoh
Blk 612 Choa Chu Kang St 62
Singapore 680612
Telephone : HP +65 98303275
Type of Claim : Own Damage claims
Policy No. : 2100443117-02
Vehicle No : **SKX 5699 U**
Model Code : Audi A6 1.8 TFSI S-TRONIC
Model / Year : Dec-15
Engine No : CYG 007809
Chassis No : WAUZZZ4G0GN041408
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Jul-18
Place of Accident : PIE Near Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 5699 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, both headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,600.00	1000
3	To respray front bumper and bonnet.	\$ 1,700.00	1100
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,972.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5699 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER <i>Defunct.</i>	\$ 2,326.00	✓
2	BUMPER GRILLE <i>Not new</i>	\$ 574.00	X
3	CHROME TRIM ?	\$ 260.00	?
4	FRONT BUMPER FIXING PARTS	\$ 43.00	X
5	FRONT BUMPER CLOSING ELEMENT	\$ 188.00	X
6	FRONT BUMPER SPOILER	\$ 216.00	X
7	RADIATOR GRILLE <i>crushed</i>	\$ 1,697.00	✓
8	RADIATOR GRILLE COVER ?	\$ 32.00	?
9	AIR GUIDE GRILLE LH / RH ?	2 \$ 614.00	?
10	FOG LAMP COVER LH / RH ?	2 \$ 88.00	?
11	GUIDE PIECE LH / RH <i>Not new</i>	2 \$ 64.00	X
12	FOAM FILLER PIECE ?	\$ 203.00	?
13	REINFORCEMENT BEAM ?	\$ 702.00	?
14	BUMPER TOP COVER <i>Defunct.</i>	\$ 105.00	✓
15	BUMPER BRACE LH / RH <i>Not new</i>	2 \$ 50.00	X
16	CAUTION SIGN STICKER ?	\$ 12.00	✓
17	AIR COND SIGN STICKER	\$ 17.00	✓
18	FRONT PARKING AID SENSOR	\$ 421.00	X
19	PARKING AID SENSOR SEAL RING	4 \$ 15.00	X
20	BONNET <i>Dented</i>	\$ 4,771.00	✓
SUB- TOTAL SPARE PARTS		\$ 12,398.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5699 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET LOCK WITH MIRCO SWITCH <i>Not m</i>	\$ 188.00	*
22	ATTACHMENT PARTS FOR BONNET ?	\$ 153.00	?
22	STOP BUFFER <i>Not m</i>	\$ 50.00	*
23	LOCK BAR <i>Not m</i>	\$ 44.00	*
24	LED HEADLIGHT LH ?	\$ 10,934.00	?
25	LED HEADLIGHT RH ?	\$ 10,934.00	?
26	LIFT CYLINDER LH / RH <i>Not m</i>	2 \$ 416.00	*
27	FRONT NO PLATE <i>Not m</i>	S/N \$ 25.00	✓
28	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 35,442.00	
TOTAL LABOUR CHARGES		: \$ 4,972.00	
GRAND TOTAL		: \$ 40,414.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 27/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant