

REPAIR ESTIMATE*

VEHICLE NO : SHA 2483B

MAKE :

MODEL : HYUNDAI SONATA

EQ Ins (L/S)

DATE 25/7/2018

LKK-Naz

TS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>X repair</i>			\$ 1,151.80
	Front Bumper Cover <i>/</i>			\$ 538.80
	Front Bumper Sponge <i>?</i>			\$ 136.30
	Front Bumper Reinforcement <i>?</i>			\$ 504.10
	Front Bumper Bracket Top (LH) <i>?</i>			\$ 22.40
	Front Bumper Protector (LH) <i>X</i>			\$ 29.20
	Headlamp Support Panel Assy <i>?</i>			\$ 1,023.00
	Headlamp (LH) <i>/</i>			\$ 797.90
	Front Fender (LH) <i>/</i>			\$ 593.00
	Front Fender Shield (LH) <i>/</i>			\$ 86.00
	Front Fender Retainer <i>LH ?</i>			\$ 9.20
	SUB TOTAL			\$ 4,891.70
	LESS 20%			\$ 978.34
	DISCOUNTED TOTAL			\$ 3,913.36
	Front Fender Advertisement Logo (LH) <i>/</i>			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 850.00 <i>400</i>
	Spray Painting Charge			\$ 600.00 <i>540</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>X</i>
	TOTAL LABOUR			\$ 1,700.00
	ESTIMATE TOTAL			\$ 5,713.36
<i>Ka mi 10/11/18</i> <i>26/7/18 1040hr</i> <i>2 Days</i> <i>L/S</i> <i>After Repair p LK</i>		to Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____		
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				