DEPRIN	REF:	a happileo 1374	OLZC	Special Instruction:		ette:
Surveyor .		ASSIGNMEN	I (Office)		1.1	1
From (Person	Kanaliah Kamie.	of 299		Date/Time:_	8100/4/19	
Estimated Co.	d:	B	ill to:			
OD/TP/W	STTP RES / OD RES / EV /	LINVIMVICS				
To Inspect Ve	thicle No: SHC DIE	4-1		Insured:		
nt Workshop	m/s			Tel:		1
of						
Policy No: MHASPF DGOODOOD 1842			Claim No: TP 17 38107 2018.			
Sum Insured:			Excess:	A A A A		
				D.O.A	- 310c F	
CA / REV	REP. / REV 24 HRS			H.O.D. Ende	rsement:	
. Date/Time:	Pe	rson Contacted;		Vehicle IN/	TUC	
Date/Time	Action/Instruction () Estimate				
	SHC 2164 L -X.					2.00
			1.4			- 2
			- 0	70/10		
			1	1201	1	
))	
-	-					-
					THE RESERVE THE PARTY OF THE PA	Contract.



Warn Copy - 13 new copes record SHC2164L

Rohaizal (LKKAuto)

From:

Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sg >

Sent

Thursday, 19 July 2018 4:31 PM

To:

Rohaizal (LKKAuto)

Cc

Bryan Ang (LKKAuto); SPF-TP FAIT; Jackson MU (SPF)

Subject:

Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 13 vehicles below:

a) Case: IAFP-IB-20180706 Mechanical Inspection of Tipper Truck; XD2023R (TP/IP/36553/2018)

b) Case: IAFP-IB-20180706 Mechanical Inspection of Lorry; YN5405M (TP/IP/36553/2018)

On 20 June 2018 (Wednesday) at or about 6.52 p.m., the Accused was driving the company's motor lorry, YN 5405 M, on the left lane of the 3 lanes road along Tanah Merah Coast Road towards Aviation Park Drive. While travelling straight, the Accused collided into the rear of motor lorries, GBC 2374 T, YN 3089 E and a tipper truck, XD 2023 R, which were stationary along on the left lane. Earlier, the tipper truck broke down along the left lane due to damages to the rear left tyre axle. The driver then contacted the company who send two company's lorries to the scene for repairs. The Deceased sustained severe multiple injuries and was pronounced dead at the accident scene by the attending paramedic at 7.16 p.m.

Vehicles to be inspected: XD2023R - Driver (not at fault) - Driver claimed the left rear tyre faulty therefore stopped along the left lane

YN5405M - Driver (at fault)

IO In-Charge: DOC Shahril

c) Case IAFP-IB-20180706 - Mechanical Inspection of Motorcycle, FBE2009M (TP/IP/37553/2018)

On 26/06/2018 at about 11.07 pm, the Deceased was riding motorcycle FBE 2009 M along Bukit Batok Road towards Choa Chu Kang Road, when he collided onto a pedal cyclist that was cycling across the signalised pedestrian crossing, at the T-junction of Bukit Batok West Avenue 7, from the right to left of Deceased's view. The rider (Deceased) suffered fatal injuries and passed away at scene. He was pronounced dead by paramedic, Sangitar at 11.21 pm. As for the cyclist, he suffered injuries and was conveyed to NTFGH.

Vehicle to be inspected: FBE2009M - Rider (Deceased)

IO In-Charge: SIO Farhan

d) Case IAFP-IB-20180706 - Mechanical Inspection of Motor Car, SLG3578B (TP/IP/25945/2018)

On 01/05/2018 at about 7.10 am, the driver of motor car, SLG3578B was negotiating a right turn along Rochor Road junction of Victoria Street when the motor car skidded. Driver then claimed that there was a mechanical fault to his motor car and his steering was locked.

Vehicle to be inspected: SLG3578B - Driver (may be liable) - Driver claimed there was a mechanical fault to his motor car

IO In-Charge: SIO Jackson Mu

- e) Case IAFP-IB-20180706 Mechanical Inspection of Malaysian Lorry, JRV1328 (TP/IP/38117/2018)
- f) Case IAFP-IB-20180706 Mechanical Inspection of Malaysian Motorcycle, JRY 7606 (TP/IP/38117/2018)
- g) Case IAFP-IB-20180706 Mechanical Inspection of Malaysian Motorcycle, JSA 5371 (TP/IP/38117/2018)
- h) Case IAFP-IB-20180706 Mechanical Inspection of Malaysian Trailer, JNQ 8386 (TP/IP/38117/2018)
- Case IAFP-IB-20180706 Mechanical Inspection of Motorcycle, FBH 5117 Z (TP/IP/38117/2018)

On 30 June 2018 sometime before 1.04 a.m., the Malaysian trailer, JNQ 8386 (B1), was travelling along centre lane of the 3 lanes road at Woodlands Crossings after the Sultan Iskandar CIQ (Malaysia's Checkpoint) towards Singapore Checkpoint while the Malaysian lorry, JRV 1328 (B2), was travelling in the same direction along the 1st lane. While both were travelling side by side, B2 suddenly veered to the right towards the centre divider. B2 then drove through the opening along the centre divider and into the opposite direction; towards Malaysia Checkpoint, against the flow of traffic. B2 then continued to travel forward and collided into the two Malaysian motorcycles, JSA 5371 (D1) and JRY 7606 (A1) and a Singapore motorcycle, FBH 5117 Z (D2) that were travelling along the 3rd lane of the opposite direction. The rider of the motorcycle, JSA 5371, was pronounced dead at the scene by the attending paramedic at 1.59 a.m. The rider of motorcycle, FBH 5117 Z, was conveyed to Khoo Teck Puat Hospital (KTPH). On the same day, he succumbed to his injuries and pronounced dead in the hospital at 2.11 a.m by Dr Ebuna.

Vehicles to be inspected: JRV 1328 - Driver (Involved Party)

JRY 7606 - Rider (Involved Party)

JSA 5371 - Rider (Deceased)

JNQ 8386 - Driver (Involved Party)

FBH 5117 Z - Rider (Deceased)

10 In-Charge: 10 Clarence Lim

- Case IAFP-IB-20180706 Mechanical Inspection of Motorcycle, JSJ7950 (TP/IP/38003/2018)
- k) Case IAFP-IB-20180706 Mechanical Inspection of Motorcycle, JQS5167 (TP/IP/38003/2018)

On 30/06/2018 at about 12.19 am, the rider of motorcycle, JQS5167 (B1) was travelling straight along BKE towards Wdlands Checkpoint on lane 2 of the 4-lanes road when all of a sudden he collided into the rear of a motorcycle, JSJ7950 (A1). Due to the collision, both fall off from their respective motorcycles. A1 was conveyed to KTPH in a conscious state and was discharged from KTPH the next day. Meanwhile, B1 was reported to be unconscious due to head injuries and was conveyed to KTPH by ambulance. However on 06/07/2018 at 6.19 am, B1 was succumbed to his injuries and was pronounced dead by Dr Li Kim Selby in KTPH.

Vehicle to be inspected: JSJ7950 - Rider (not at fault)

JQSS167 - Rider (deceased)

10 In-Charge: 10 Kamaliah Kamis

Case IAFP-IB-20180712 - Mechanical Inspection of Motor Taxi, SHC2164L (TP/IP/38107/2018)

On 2.7.2018 at about 4.42 am, motor taxi was driving along Crawford Street towards Republic Avenue on the right lane of 2 lanes road when near to pedestrian crossing, Deceased (pedestrian) was crossing from taxi's left to right and taxi front portion collided onto the Deceased. Deceased was conscious but however, succumbed to his injuries and in TTSH and pronounced dead on the 8.7.2018 at 11.45 pm.

Vehicle to be inspected: SHC2164L - Driver (Accused)

10 In-Charge: SIO Vilton

m) Case IAFP-IB-20180712 - Mechanical Inspection of Motor Van, GBG2430T (TP/IP/39585/2018)

On 12.7.2018 at about 6.59 am, motor van was driving along Marsiling Road towards Riverside Road on the left lane of the 2- lanes road. Upon nearing the signalised T-junction of Marsiling Road by Marsiling Drive, traffic light ahead of him was green only thus he made a left turn into Marsiling Drive and its frontal centre portion collided into a pedestrian who was crossing along the signalised pedestrian crossing, ahead of him from unknown direction. Due to the accident, the pedestrian was conveyed to KTPH. However on the same day at 8.06 am, the pedestrian succumbed to her injuries and she was pronounced dead by Dr Yuen, Shang Ren.

Vehicle to be inspected: GBG2430T - Driver (Accused)

IO In-Charge: IO Kamaliah Kamis

- These request has been <u>approved</u> by my management.
- Thank you Sirs.
- Cc: Bryan Ang (LKK), FAIT Team & SIO Jackson Mu, fyip

Best regards.

Kamaliah Kamis (Miss) Investigation Officer | Fatal Accident Investigation Team Traffic Police | Singapore Police Force DID: (65) 6547 6435 | FAX: (65) 6547 6352



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in respect thereon. Communication of any information in this enture to any unauthorized person is an offence under the Official Secrets Air (Cap 210). Please notify the sender truncdistriby if you necesse this in error."