

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0853/2018/KS  
Date : 26-Jul-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**

Your insured vehicle no : **SLC 6370 J**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name : Mr. Pradeep Kumar Datar  
Address : 70 Bayshore Road  
#07-07  
Singapore 469987  
Telephone : HP +65 98193167  
Type of Claim : Third Party Claim  
Policy No. : GA070133/1  
Vehicle No : **SKQ 1185 Z**  
Model Code : Audi Q3 1.4 TFSI S-TRONIC  
Model / Year : Oct-14  
Engine No : CHP 172606  
Chassis No : WAUZZZ8U1ER118969  
Mileage : -  
Date In :  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 24-Jul-18  
Place of Accident : ALONG BUKIT TIMAH RD

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKQ 1185 Z.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid . Check function.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper and both rear wheel. Re-organise rear crash management components. Re-install all parts removed.	\$ <del>1,400.00</del> 600	
3	To respray rear bumper.	\$ <del>800.00</del> 600	
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>2,672.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No.SKQ 1185 Z.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>delivered</i>	\$ 1,205.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 106.00	X
3	REAR BUMPER SPOILER <i>delivered</i>	\$ 413.00	✓
4	REAR BUMPER CARRIER ?	\$ 545.00	?
5	GUIDE SECTION LH / RH <i>new</i>	\$ 76.00	X
6	REAR PARKING AID SENSOR	\$ 421.00	X
7	REAR PARKING AID SENSOR SEAL RING <i>from</i>	\$ 5.00	X
8	WHEEL ARCH COVER LH / RH <i>new</i>	2 \$ 454.00	✓
9	REAR BUMPER TAILLIGHT LH / RH <i>Not new</i>	2 \$ 454.00	X
10	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 3,979.00	
TOTAL LABOUR CHARGES		: \$ 2,672.00	
GRAND TOTAL		: \$ 6,651.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

Adrian Ling

27/07/18

Not Authorised

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant