

ASS. REC. BY:

REF

CS/MSG18013779/Urd3e2

Special Instruction:

Surveyor
merimen

Markus

ASSIGNMENT (Office)

From (Person):

Catherine Hia

of

MSG

Date/Time:

30/7/18 @ 9:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDA 8969A

Insured:

8LL 6156p

at Workshop m/z:

Kan Fook Sing

Tel:

67479560

of

No. 61 De fu June 12

Policy No:

A29069766 MCF

Claim No:

565505

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/7/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:41am @ 30/7/18

Person Contacted:

patricia

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDA 8969A - CS

SMO18013683

/ T19d3

DOA: 23/7/2018

8LL 6156p - CS

SMO18013683

/ T19d3

DOA: 23/07/2018

31/7/18

Send preli. revised via merimen

21/1/19

@ 4:44pm

Final fig

\$ 18,032.56

(Red 7605.49, 30/7)

(No LS)

CD 11/121212
ASS' REC BY Marcus

REF:

MS167

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SDA8968A
at Workshop m/s: KFS
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 110k.
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 8 days Res: Yes or No
Lump Sum: 131 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS net 339k
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SDA8968A Yr Reg: 6.14
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Mer Benz E200 ca 1991
Colour: Grey A/C: _____ Insured / Std / NI / NA
Sp. Reading: 54406 T/Radio: Insured / Std / NI / NA
Engl No: _____
C/No: WDD2120342A987860
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or ok
Brake: In order / Jammed / Leaked / Burnt or _____
Mod: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 245/45R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 23/7/18 D.O.I. 32/7/18
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.
Int 068

Date / Time _____ Action / Instruction _____
LTA 76k rep 15k 5 yrs 10m.

RECEIVED 03 JAN 2019

2/1/2019

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	<u>200</u>
Transportation:	_____
Photos	_____
Others	<u>10</u>
TOTAL	<u>210</u>

Report Format: menmen
Lump Sum / I.B.I. (\$) 18,032.56

1) 1/1 - typist



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013779/Uvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 30-07-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 6156P	Veh. Inspected	SDA 8969A
Policy No.	A29069766MKF	Coverage (\$)	0.00
Claim No.	565505	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	30/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/07/2018	Inspection Date	30/07/2018
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 31 Jul 2018

Preliminary Advice

Insured Vehicle No	: SLL6156P		
TP Vehicle No	: SDA8969A	Accident Date	: 23/07/2018
Make	: MERCEDES-BENZ E200	Assignment Date	: 30/07/2018
Date of Inspection	: 30/07/2018	Est. Duration of Repair	: 8.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and front windscreen cracked. The undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,757.94
Revised Amount	:S\$	10,412.04
Check Items (Estimated)	:S\$	11,309.10
Total	:S\$	21,721.14

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1096A

Vehicle Details

Vehicle No.: SDA8969A
Vehicle to be Exported: No
Intended De-registration Date: 30 Jul 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: E200 SEDAN (R17)
Primary Colour: Blue
Manufacturing Year: 2014
Engine No.: 27492030161115
Chassis No.: WDD2120342A987860
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$42,793.00
Original Registration Date: 02 Jun 2014
First Registration Date: 02 Jun 2014
Transfer Count: 1
Actual ARF Paid: \$46,911.00 23451

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 01 Jun 2024
PARF Rebate Amount: \$35,183.00

Intended COE Rebate Details

COE Expiry Date: 01 Jun 2024
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$70,002.00
COE Rebate Amount: \$40,872.00
Total Rebate Amount: \$76,055.00

Message

The information contained herein is correct as at 30 Jul 2018

OK



SELL YOUR CAR BY BIDDING
HIGHEST SELLING PRICE GUARANTEED!
OR GET \$100 CASH!



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Estima 2.4A



\$5800 Downpayment Monthly
From \$938 Onwards. Lowest
3.68%P.A.QOV Cars Financing
GV Credit Pte Ltd StarAd



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Sort by Date Posted 20 results/page

13 vehicles

Mercedes-Benz e200

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz e200		Any	Any	2014	Any	Any	Any	Available
	Mercedes-Benz	E-Class E200	\$109,800	\$15,260 /yr	18-Mar-2014	1,991 cc	43,000 km	Luxury	Available
1 Owner. Fully Serviced And Maintained By Agent C&C. Car In Showroom Condition. 100% Accident Free. Call Or Drop By For A No Obligation Discussion On Test Drive Or Financial Matters. Auto Zoom Enterprise Pte Ltd Posted: 30-Jul-2018 Tags: 2014 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz									
	Mercedes-Benz	E-Class E200	\$115,800	\$15,610 /yr	07-May-2014	1,991 cc	123,000 km	Luxury	Available
1 Owner! Fully Agent Serviced. Latest R18 Facelift. Beautiful Midnight Blue With Space Grey Interior. Great Cabin Space. Guaranteed Condition As Good As New, Well Taken Care By Previous Owner. Powerfu... Posted: 29-Jul-2018 Tags: 2014 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz									
	Mercedes-Benz	E-Class E200 Avantgarde	\$113,800	\$16,040 /yr	27-Jan-2014	1,991 cc	73,000 km	Luxury	Available
R18 Avantgarde! Cycle And Carriage Unit. Buy With A Peace Of Mind. STA And VICOM Evaluation Welcome. Vehicle Condition By Professional Groomer. Elegant Silver With Cinnamon Brown Interior. Lowest Inte... Shuang Hup Credit Posted: 29-Jul-2018 Tags: 2014 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz									
	Mercedes-Benz	E-Class E200 Coupe	\$138,800	\$17,920 /yr	26-Dec-2014	1,991 cc	54,000 km	Sports	Available
Only 1 Owner. Certified C&C Unit. Guaranteed \$15k Driveaway! Latest R18 Facelift. Beautiful Sleek Black Original Paintwork. Adjustable Air Pressure Seats. Extremely Well Maintained By Previous Owner, ... Posted: 29-Jul-2018 Tags: 2014 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz									
Car Buying Car Selling Car Ownership Car Aftermarket On The Move Lifestyle Buy Tires Online Latest Special Offers from Tirexpert									
	Mercedes-Benz	E-Class E200	\$133,800	\$16,410 /yr	14-Nov-2014	1,991 cc	62,000 km	Luxury	Available
New 6 Months Road Tax. Original 19" Rims. Facelift Model. High Gloss Black With Beautiful Brown Leather. Regularly Serviced And Maintained By Owner. High ARF And COE! Not To Be Miss. Call Our Professi... Eurokars Pre Owned Posted: 28-Jul-2018 Tags: 2014 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz									
	Mercedes-Benz	E-Class E200 Avantgarde	\$109,800	\$15,460 /yr	08-Jan-2014	1,991 cc	68,300 km	Luxury	Available
C&C Unit, Latest R18 Facelifted Model. Fully Agent Maintained. All In Original Stock Condition. Low Mileage, Guaranteed Accident Free. Road Tax Till 01/2019. Can Trade In / High Loan Available. Price ... Posted: 27-Jul-2018 Tags: 2014 Mercedes-Benz E200, Mercedes-Benz E200, Mercedes-Benz, E200, Used Mercedes-Benz									
Compare	Mercedes-Benz	E-Class E200	\$116,800	\$14,990 /yr	20-Oct-2014	1,991 cc	55,800 km	Luxury	Available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2018 16:01
Date Of Accident	23/07/2018 11:25
Exact Location Of Accident	JUNCTION OF CAMBRIDGE RD AND CARLISE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDA8969A
Insured/Policyholder	
Name Of Registered Owner	TAN SIANG HEE THOMSON
NRIC No	S1691096A
Email Address	THOMSONTANSH@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-93888246
Alternative Phone No	OTHERS-93888246

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 SEDAN (R17)

Exact Purpose for which vehicle was being used at time of accident	PRIVATE
--	---------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01015819
Cover Note Number	N.A

Driver

Name of Driver	TAN SIANG HEE THOMSON
NRIC No	S1691096A
Date Of Birth	02/03/1965
Occupation	INDOOR
Date Of Driving Pass	26/12/1985
Driving Experience	32 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93888246
Fax Number	
Contact Number	OTHERS-93888246
Email Address	THOMSONTANSH@YAHOO.COM.SG

Address	46 DAFNE STREET 459566
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving straight along CAMBRIDGE RD, upon reaching x-junction of CARLISLE RD. Suddenly a vehicle appeared, as a result the vehicle hit my vehicle front right side portion. Due to the impact, my vehicle mounted the kerb and ended at the pedestrian passage way. At the same time, there was pedestrian was at the passage way. As a result my vehicle bumped onto the pedestrian. The pedestrian was conveyed to the hospital.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WILL UPLOAD TO MERIMEN AFTER INSURED SEND
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL6156P
Vehicle Make/Model/Colour	MAZDA3 4-DOOR SEDAN 1.5L / DARK GREY
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	YONG LEE LIN
NRIC/Passport Number	S0125738B
Contact Number	96808873
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER 1

GENDER: : FEMALE

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

PEDESTRIAN

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

PEDESTRIAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the Insurers and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - i. I understand, acknowledge, agree and consent that:
 - (a) My Insurer, my workshop and the General Insurance Association of Singapore (GIA) Insurers permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all Insurers who have insured vehicle(s) involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident and any relevant government agency/authority (such as "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any necessary investigations relating to the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/post packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

VERIFIED BY AJAX MARS
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving straight along CAMBRIDGE RD, upon reaching x-junction of CARLISLE RD. Suddenly a vehicle appeared, as a result the vehicle hit my vehicle front right side portion. Due to the impact, my vehicle mounted the kerb and ended at the pedestrian passage way. At the same time, there was a pedestrian at the passage way. As a result my vehicle bumped onto the pedestrian. The pedestrian was conveyed to the hospital.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 July 2018 at 12:50 PM

Date/Time:

23 July 2018 at 12:50 PM

**KAN FOOK SING MOTOR
WORKSHOP
61 DEFU LANE 12
SINGAPORE
539147**

Claim Reference:
Assessment Number: KFS01510
Version: KFSMOTOR/1
Date Calculated: 24/07/2018 09:40

Full Report - V1
Registration: SDA8969A
Printed: 24/07/2018 16:40

Summary Information

Claim

Location: Singapore (SG)
Printed by: Ryan Kan
Authorisation Status: Interim
Work Provider: MSIG Insurance (Singapore) Pte

Currency: SGD
Date of Incident:
Able to Authorise Repairs: TBA
Repairs Authorised: TBA

Claim Reference:
Policy Number: D17MTPV01015819
Other Reference:
Third Party: True
Insured Amount:
Under Warranty:
Warranty Expired:

Estimated Repair Time:
Quote Due Date:
Actual Repair Days:
Parts Ordered Date:
Hire Car Start:
Hire Car End:
Vehicle Collected:

*Not Allowed
rhr
take photo before
repair.
30/7/18 @ 11
Sdy.*

Vehicle Details

Vehicle

Manufacturer: MERCEDES
Model: E Class
Sub Model: E 200
Model Sheet Number: 3EE 46
Registration: SDA8969A
Registration Month: June
Registration Year: 2014
VIN Number: WDD2120342A987860
Odometer: Not Known
Colour:
Engine Number:
Fuel Level: %

Model Specs

FR PRODUCTION START
MODIFICAT PACK 13/3
FRT COLLISION ALARM
EL DRIVE POS SELECT
LOAD COMPARTMENT BOX
MULTIMEDIA INTERFACE
HEATED WASHER UNIT
SUNBLIND TWO-PIECE
MEMORY PACKAGE
S-WDW ROLLER BLIND
REM RELEASE FUEL CAP
PELVIS BAG
ECO START/STOP
EMISSION STD EURO 6
DIRECT CONTROL SUSP
WHEELS 8J X 17 ALLOY
FUEL TANK 80 LTR
TWO COAT METALLIC
CLEAR COAT HARD
MOD PACK 13/2
MODEL 2014
RADIATOR SHROUD
PARKTRONIC
AUDIO 20 CD CHANGER
LAMINATED GLASS
LEATHER TRIM
TRIM ELEGANCE
DIPPING MIRROR
WOOD TRIM ASH TREE
KEYLESS GO
RR SCREEN SUN BLIND
STRG COLUMN SHIFT
7 SPEED AUTOMATIC
TYRES 245/45 WR 17
SPARE WHEEL
HD COOLING
COMPRESSOR VARIABLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection: Repairer
Pre-Accident Damage:

Tyres Condition:
Tread Depth LHF:

Severity of Impact:
Vehicle Status on
Inspection:
Date of Inspection:

Tread Depth RHF:



LKK Auto Consultants hence notify the Repairer of the following:
• To display damaged part(s) during resurvey
• To display prices are \$23/07/2018
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:
Assessment Number: KFS01510
Version: KFSMOTOR/1
Date Calculated: 24/07/2018 09:40

Full Report - V1
Registration: SDA8969A
Printed: 24/07/2018 16:40



Addresses

Cost Summary

Total Labour	\$2,025.00
Total Paint/Material	\$247.24
Total Parts	\$19,110.70
Total of Additional Costs	\$375.00
Excess:	TBA
Grand Total Exc GST:	\$21,757.94
7 % GST:	\$1,523.06
Grand Total Inc GST:	\$23,281.00

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	15.00
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	15.00
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	10.00
61-1069 02	R + R COMPL LWR ENGINE COMPARTMENT COVER	3.0	15.00
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	45.00
88-2534 02	REPAIR OF R/FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	170.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	10.00
88-1357 ZAX	ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	2.0	10.00
NO NUMBER	R + R R/F WHEEL COVER	1.0	5.00
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE	11.0	55.00

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/1

Date Calculated: 24/07/2018 09:40

Full Report - V1

Registration: SDA8969A

Printed: 24/07/2018 16:40

	COMPARTMENT FOR RENEWAL OF THE FRONT MODULE		
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1269 01	R + R OR RENEW FRONT CROSSMEMBER AND R/TRUSSING BETWEEN WHEELHOUSES	12.0	60.00
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
67-1700 02	RENEW WINDSCREEN	32.0	160.00
22-4350 03	R + R R/F ENGINE CARRIER	15.0	75.00
20-3865 01	R + R RADIATOR	19.0	95.00
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
20-5410 01	R + R OVERFLOW TANK	6.0	30.00
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	45.00
33-1855 ZAX	R + R FRONT AXLE CARRIER	41.0	205.00
33-1859 ZAX	RENEW FRONT AXLE SUPPORT (REMOVED)	6.0	30.00
33-3570 03)	R + R R/F STEERING KNUCKLE	20.0	100.00
33-1425 02)	DETACH + REFIT R/F TENSION ROD	2.0	10.00
33-1421 03)	R + R RIGHT FRONT TORSION BAR	9.0	45.00
32-1960 03)	R + R R/F STRUT	5.0	25.00
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	15.00
NO NUMBER	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	15.00
46-3406 02)	RENEW POWER STEERING (REMOVED)	2.0	10.00
40-1470 01	ADD TO L/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH)	1.0	5.00
40-1470 01	ADD TO R/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH)	1.0	5.00
40-2410 01	R + R RIGHT FRONT TYRE	3.0	15.00
40-2702 ZAX	ADDITION TO R + R R/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	5.00
40-2055 01	R/F FRONT WHEEL BALANCE	2.0	10.00
54-1014 01	ACTIVATE VOLTAGE OF THE HIGH VOLTAGE ELECTRIC SYSTEM AND BRING SYSTEM INTO OPERATION (AFTER SHORT TEST)	3.0	15.00
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	45.00
40-6500 01	ALIGN VEHICLE	7.0	35.00
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	5.00
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	10.00
1164	REPAIR R/UPP W-HOUSE S-MEMB	20.0*	100.00
LABOUR COST			
	Total Work Units	304.0	
	Panel / Mechanical Labour	29.4HRS	\$1,470.00
	Visual Alignment Labour	1.0HRS	\$50.00
	Corrosion Protection External Labour	0.0HRS	0.00

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/1

Date Calculated: 24/07/2018 09:40

Full Report - V1

Registration: SDA8969A

Printed: 24/07/2018 16:40

Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	30.4HRS	\$1,520.00
Paint Labour	10.1HRS	\$505.00
Total Labour	40.5HRS	\$2,025.00

PAINT WORK Time Basis 10 WU = 1 HR. Price = \$50.00/HR
Guide Number Description WU Cost Price (\$)

	- TWO COAT METALLIC		
	- COMPRESSOR VARIABLE		
471	BONNET NEW PART PAINTING	30.0	
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	13.0	
362	R/F OUTER SENSOR NEW PART PAINT K1R	3.0	
361	L/F OUTER SENSOR SURFACE PAINT PLAST.	3.0	
365	L/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
741	L/F WING SURFACE PAINT	5.0	
1164	R/UPP W-HOUSE S-MEMBSURFACE PAINT	4.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
1730	R/DOOR MIRROR HSG SURFACE PAINT PLAST.	3.0	

LABOUR COST - PAINT

TIME(PAINT)	85.0	
Preparation Main Work Metal	11.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	101.0	
Total Paintwork Labour	10.1HRS	\$505.00

MATERIAL COST - PAINT

New Part Painting		Cost Price
New Part Painting - Plastic K1R		\$120.74
Surface-/Blend Paint		\$63.47
Surface Paint Plastic		\$32.63
Material-Const Main Work Metal		\$3.30
Material-Const Comp. Work Plastic		\$18.10
Total Excluding Pearlescent Uplift		\$9.00
Pearlescent Uplift @ 0.0%		\$247.24
Total Paint Material Cost		\$0.00
		\$247.24

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER COVER	212 880 2547 9999	715	0%	790 712.00*
300	1	TOWING EYE COVER	212 885 0526 9040	11	0%	42.00*
304	1	R/F OUT BUMP GRILLE	212 885 2222	70-1	0%	33 28.00*
305	1	FRONT BUMPER GRILLE	212 885 0722	70-1	0%	54 45.00*
312	1	R/F COVER STRIPE	212 885 3021	11	0%	60.00*
340	1	FRT CTR BUMPER REINF	212 885 3965	BUM	0%	70 43.00*
344	1	R/F BUMPER CARRIER	212 885 3865	301	0%	38 31.00*
349	1	FRT/CTR IMPACT DAMP	212 880 0135	ner	0%	78 65.00*
356	1	R/F OUT SPACER RING	000 542 1251	ner	0%	4.00 6.00*
360	1	R/F INN SPACER RING	000 542 1251	ner	0%	4.00 6.00*
362	1	R/F OUTER SENSOR	000 905 5604 9999	shad	0%	120 88.00*

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/1

Date Calculated: 24/07/2018 09:40

Full Report - V1

Registration: SDA8969A

Printed: 24/07/2018 16:40

366	1	R/F INNER SENSOR	000 905 5504 9999	shad	-0%	120	88.00*	✓
405	1	GRILLE	212 880 1483	ma	-0%	560	510.00*	✓
471	1	BONNET	212 880 0357	Buc	-0%	1280	1,215.00*	✓
516	1	R/LOWER LATCH	204 880 0260	54	-0%	38	32.00	✓
562	1	RIGHT HEADLAMP ASSY	212 820 2039	370	-0%	1600	1,775.00*	✓
742	1	R/F WING	212 880 1218	7.5	-0%	580	498.00*	✓
784	1	R/F WING MOULDING	212 690 4482	nu	-0%	26	22.00*	✓
796	2	R/NUT	414 990 0051	7.5	-0%	30	40.00*	✓
840	1	R/F WHEELHOUSE COVER	212 690 6230		-0%	115	96.00*	✓
842	1	R/F W-HOUSE CVR REAR	212 690 6530		0%		83.00*	✓
930	1	CTR FRT REINF	212 620 1100	17	0%		78.00*	✓
1001	1	FRT LWR CROSSMEMBER	212 620 1500	17	0%		260.00*	✓
1180	1	R/REINFORCEMENT	212 620 0285	30	0%	295	26.00*	✓
1188	1	R/F UPP REINF head long panel	212 620 4700	30	0%	30	128.00*	✓
1192	1	R/F BUMPER ABSORBER	212 620 0895	But	0%	150	138.00*	✓
1401	1	WINDSCREEN	212 670 1200 28	70-1	0%	160	640.00*	✓
1411	1	WINDSCREEN REP KIT	000 670 0100	Cue	-0%	700	0.00F	✓
1413	4	FRT SCREEN SUPPORTS	210 671 0397	17	0%		0.00F	✓
4467	1	DRYER BOTTLE	204 835 0147	17	0%		0.00F	✓
7011	1	FRONT AXLE SUPPORT	218 628 0100	17	0%		0.00F	✓
7048	1	R/F TENSION ROD	212 330 2811	54	0%		1,180.00*	✓
7056	1	R/TENSION ROD RUBBER	212 333 0014	Self	-0%	270	242.00*	✓
7072	1	R/F LWR CONTROL ARM	212 330 3011	17	0%		70.00*	✓
7082	1	R/F STEERING KNUCKLE	212 332 0800	Self	-0%	270	304.00*	✓
7088	1	R/F SHOCK ABSORBER	212 323 5300	Self	-0%	695	648.00*	✓
7092	1	R/F STRUT BEARING	212 323 0020	Self	-0%	465	410.00*	✓
7098	1	R/LWR DAMPER RING	212 322 0084	17	0%		100.00*	✓
7102	1	R/UPPER BUFFER	212 321 0106	17	0%		33.00*	✓
7132	1	R/F WHEEL HUB	212 330 0025	17	0%		35.00*	✓
7202	1	R/F WHEEL	212 401 5402	34	-0%	385	348.00*	✓
		7X45		20/24	0%	500.5	800.00*	✓
7208	1	R/F WHEEL COVER	171 400 0125 5337	17	0%		0.00F	✓
7264	1	R/F STABILISER ARM	212 320 1289	17	0%		52.00*	✓
7302	1	STEERING GEAR EXCH	212 460 0501 80	54	0%		4,310.00*	✓
7787	1	EXPANSION TANK	204 500 0749	De/Cue	-0%	80	70.00*	✓
8622	1	R/ENGINE SUPPORT	274 223 0204	17	0%		148.00*	✓
8779	1	FRONT GRILLE PANEL	212 520 3923	Self	-0%	130	112.00*	✓
9650	1	R/H-LAMP LVL C-UNIT	218 900 7206	Cue	-0%		480.00*	✓
1000	1	FRT SENSOR WIRE	Renew	Torn	-0%	115	102.00*	✓
1000	1	RAIN SENSOR	Renew	17	0%		180.00*	✓
1000	1	R/F BONNET STOPPER	Renew	nu	-0%	18.50	6.00*	✓
1000	1	R/TIE ROD	Renew	Self	-0%	70	88.00*	✓
1000	1	R/OUTER TIE ROD BALL	Renew	Self	0%	105	145.00*	✓
f: OEM Parts			Saving				\$140.81	
g: Original			Sub Total				\$16,618.00	
h: Secondhand			Mark Up From Cost	(15 %)			\$2,492.70	
p: Parallel			Sundry Parts	(Fixed)			\$0.00	
x: Exchange			Total Parts				\$19,110.70	

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
-------------	------------	-------

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/1

Date Calculated: 24/07/2018 09:40

Full Report - V1

Registration: SDA8969A

Printed: 24/07/2018 16:40

FRT WINDSCREEN	SPECIALIST	0%	RM \$40.00 ✓
GUM			
ERP STICKER	SPECIALIST		RM \$10.00 ✓
R/F TYRE	SPECIALIST	0%	RM \$325.00 ✓
Total Extras			\$375.00

Final Calculation

Total Parts **\$19,110.70**

Labour

Total Panel/Mechanical	\$1,470.00	1195
Total Paintwork	\$505.00	520
Total Visual Alignment work	\$50.00	50
Total Labour		\$2,025.00

Additional Costs

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$375.00

Total of Additional Costs **\$375.00**

Total Paint/Material Costs **\$247.24**

Grand Total Excludes GST **\$21,757.94**

GST @ 7 % **\$1,523.06**

Grand Total Includes GST **\$23,281.00**

Assessment Notes

Claim Reference:
Assessment Number: KFS01510
Version: KFSMOTOR/2
Date Calculated: 31/07/2018 05:11

Full Report - V1
Registration: SDA8969A
Printed: 31/07/2018 12:11

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	D17MTPV01015819	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	


Vehicle Details

Vehicle		Model Specs	
Manufacturer:	MERCEDES	FR PRODUCTION START	MOD PACK 13/2
Model:	E Class	MODIFICAT PACK 13/3	MODEL 2014
Sub Model:	E 200	FRT COLLISION ALARM	RADIATOR SHROUD
Model Sheet Number:	3EE 46	EL DRIVE POS SELECT	PARKTRONIC
Registration:	SDA8969A	LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
Registration Month:	June	MULTIMEDIA INTERFACE	LAMINATED GLASS
Registration Year:	2014	HEATED WASHER UNIT	LEATHER TRIM
VIN Number:	WDD2120342A987860	SUNBLIND TWO-PIECE	TRIM ELEGANCE
Odometer:	Not Known	MEMORY PACKAGE	DIPPING MIRROR
Colour:		S-WDW ROLLER BLIND	WOOD TRIM ASH TREE
Engine Number:		REM RELEASE FUEL CAP	KEYLESS GO
Fuel Level:	%	PELVIS BAG	RR SCREEN SUN BLIND
		ECO START/STOP	STRG COLUMN SHIFT
		EMISSION STD EURO 6	7 SPEED AUTOMATIC
		DIRECT CONTROL SUSP	TYRES 245/45 WR 17
		WHEELS 8J X 17 ALLOY	SPARE WHEEL
		FUEL TANK 80 LTR	HD COOLING
		TWO COAT METALLIC	COMPRESSOR VARIABLE
		CLEAR COAT HARD	


Vehicle Condition

Vehicle Status			
Pre-Accident Condition:		Severity of Impact:	
Steering:		Vehicle Status on Inspection:	
Brakes Pedal Travel:		Date of Inspection:	23/07/2018
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:			
Tread Depth LHF:		Tread Depth RHF:	
Tread Depth LHR:		Tread Depth RHR:	

Damage Areas:



Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$2,025.00
Total Paint/Material	\$247.24
Total Parts	\$19,073.90
Total of Additional Costs	\$375.00
Excess:	TBA
Grand Total Exc GST:	\$21,721.14
7 % GST:	\$1,520.48
Grand Total Inc GST:	\$23,241.62

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	15.00
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	15.00
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	10.00
61-1069 02	R + R COMPL LWR ENGINE COMPARTMENT COVER	3.0	15.00
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	45.00
88-2534 02	REPAIR OF R/FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	170.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	10.00
88-1357 ZAX	ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	2.0	10.00
NO NUMBER	R + R R/F WHEEL COVER	1.0	5.00
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT	11.0	55.00

	MODULE		
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1269 01	R + R OR RENEW FRONT CROSSMEMBER AND R/TRUSSING BETWEEN WHEELHOUSES	12.0	60.00
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
67-1700 02	RENEW WINDSCREEN	32.0	160.00
22-4350 03	R + R R/F ENGINE CARRIER	15.0	75.00
20-3865 01	R + R RADIATOR	19.0	95.00
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
20-5410 01	R + R OVERFLOW TANK	6.0	30.00
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	45.00
33-1855 ZAX	R + R FRONT AXLE CARRIER	41.0	205.00
33-1859 ZAX	RENEW FRONT AXLE SUPPORT (REMOVED)	6.0	30.00
33-3570 03)	R + R R/F STEERING KNUCKLE	20.0	100.00
33-1425 02)	DETACH + REFIT R/F TENSION ROD	2.0	10.00
33-1421 03)	R + R RIGHT FRONT TORSION BAR	9.0	45.00
32-1960 03)	R + R R/F STRUT	5.0	25.00
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	15.00
NO NUMBER	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	15.00
46-3406 02)	RENEW POWER STEERING (REMOVED)	2.0	10.00
40-1470 01	ADD TO L/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH)	1.0	5.00
40-1470 01	ADD TO R/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH)	1.0	5.00
40-2410 01	R + R RIGHT FRONT TYRE	3.0	15.00
40-2702 ZAX	ADDITION TO R + R R/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	5.00
40-2055 01	R/F FRONT WHEEL BALANCE	2.0	10.00
54-1014 01	ACTIVATE VOLTAGE OF THE HIGH VOLTAGE ELECTRIC SYSTEM AND BRING SYSTEM INTO OPERATION (AFTER SHORT TEST)	3.0	15.00
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	45.00
40-6500 01	ALIGN VEHICLE	7.0	35.00
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	5.00
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	10.00
1164	REPAIR R/UPP W-HOUSE S-MEMB	20.0*	100.00
LABOUR COST			
	Total Work Units	304.0	
	Panel / Mechanical Labour	29.4HRS	\$1,470.00
	Visual Alignment Labour	1.0HRS	\$50.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/2

Printed: 31/07/2018 12:11

Date Calculated: 31/07/2018 05:11

Sub Total	30.4HRS	\$1,520.00
Paint Labour	10.1HRS	\$505.00
Total Labour	40.5HRS	\$2,025.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- COMPRESSOR VARIABLE		
471	BONNET NEW PART PAINTING	30.0	
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	13.0	
362	R/F OUTER SENSOR NEW PART PAINT K1R	3.0	
361	L/F OUTER SENSOR SURFACE PAINT PLAST.	3.0	
365	L/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
741	L/F WING SURFACE PAINT	5.0	
1164	R/UPP W-HOUSE S-MEMBSURFACE PAINT	4.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
1730	R/DOOR MIRROR HSG SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		85.0	
Preparation Main Work Metal		11.0	
Preparation Comp. Work Plastic		5.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		101.0	
Total Paintwork Labour		10.1HRS	\$505.00
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$120.74
New Part Painting - Plastic K1R			\$63.47
Surface-/Blend Paint			\$32.63
Surface Paint Plastic			\$3.30
Material-Const Main Work Metal			\$18.10
Material-Const Comp. Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$247.24
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$247.24

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
471	1	BONNET	212 880 0357		0% 1,215.00*
930	1	CTR FRT REINF	212 620 1100		0% 78.00*
4467	1	DRYER BOTTLE	204 835 0147		0% 0.00F
7787	1	EXPANSION TANK	204 500 0749		0% 70.00*
7011	1	FRONT AXLE SUPPORT	218 628 0100		0% 1,180.00*
283	1	FRONT BUMPER COVER	212 880 2547 9999		0% 712.00*
305	1	FRONT BUMPER GRILLE	212 885 0722		0% 45.00*
8779	1	FRONT GRILLE PANEL	212 520 3923		0% 112.00*
340	1	FRT CTR BUMPER REINF	212 885 3965		0% 43.00*
1001	1	FRT LWR CROSSMEMBER	212 620 1500		0% 260.00*
1413	4	FRT SCREEN SUPPORTS	210 671 0397		0% 0.00F
1000	1	FRT SENSOR WIRE	Renew		0% 102.00*

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/2

Printed: 31/07/2018 12:11

Date Calculated: 31/07/2018 05:11

349	1	FRT/CTR IMPACT DAMP	212 880 0135	0%	65.00*
405	1	GRILLE	212 880 1483	0%	510.00*
8622	1	R/ENGINE SUPPORT	274 223 0204	0%	148.00*
1000	1	R/F BONNET STOPPER	Renew	0%	6.00*
1192	1	R/F BUMPER ABSORBER	212 620 0895	0%	138.00*
344	1	R/F BUMPER CARRIER	212 885 3865	0%	31.00*
312	1	R/F COVER STRIPE	212 885 3021	0%	60.00*
360	1	R/F INN SPACER RING	000 542 1251	0%	6.00*
366	1	R/F INNER SENSOR	000 905 5504 9999	0%	88.00*
7072	1	R/F LWR CONTROL ARM	212 330 3011	0%	304.00*
304	1	R/F OUT BUMP GRILLE	212 885 2222	0%	28.00*
356	1	R/F OUT SPACER RING	000 542 1251	0%	6.00*
362	1	R/F OUTER SENSOR	000 905 5604 9999	0%	88.00*
7088	1	R/F SHOCK ABSORBER	212 323 5300	0%	410.00*
7264	1	R/F STABILISER ARM	212 320 1289	0%	52.00*
7082	1	R/F STEERING KNUCKLE	212 332 0800	0%	648.00*
7092	1	R/F STRUT BEARING	212 323 0020	0%	100.00*
7048	1	R/F TENSION ROD	212 330 2811	0%	242.00*
1188	1	R/F UPP REINF	212 620 4700	0%	128.00*
7202	1	R/F WHEEL	212 401 5402	0%	800.00*
			7X45		
7208	1	R/F WHEEL COVER	171 400 0125 5337	0%	0.00F
7132	1	R/F WHEEL HUB	212 330 0025	0%	348.00*
840	1	R/F WHEELHOUSE COVER	212 690 6230	0%	96.00*
842	1	R/F W-HOUSE CVR REAR	212 690 6530	0%	83.00*
742	1	R/F WING	212 880 1218	0%	498.00*
784	1	R/F WING MOULDING	212 690 4482	0%	22.00*
9650	1	R/H-LAMP LVL C-UNIT	218 900 7206	0%	480.00*
7098	1	R/LWR DAMPER RING	212 322 0084	0%	33.00*
796	2	R/NUT	414 990 0051	0%	40.00*
1000	1	R/OUTER TIE ROD BALL	Renew	0%	145.00*
1180	1	R/REINFORCEMENT	212 620 0285	0%	26.00*
7056	1	R/TENSION ROD RUBBER	212 333 0014	0%	70.00*
1000	1	R/TIE ROD	Renew	0%	88.00*
7102	1	R/UPPER BUFFER	212 321 0106	0%	35.00*
1000	1	RAIN SENSOR	Renew	0%	180.00*
562	1	RIGHT HEADLAMP ASSY	212 820 2039	0%	1,775.00*
7302	1	STEERING GEAR EXCH	212 460 0501 80	0%	4,310.00*
300	1	TOWING EYE COVER	212 885 0526 9040	0%	42.00*
1401	1	WINDSCREEN	212 670 1200 28	0%	640.00*
1411	1	WINDSCREEN REP KIT	000 670 0100	0%	0.00F
f: OEM Parts			Saving		\$140.81
g: Original			Sub Total		\$16,586.00
h: Secondhand			Mark Up From Cost	(15 %)	\$2,487.90
p: Parallel			Sundry Parts	(Fixed)	\$0.00
x: Exchange			Total Parts		\$19,073.90

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT WINDSCREEN SPECIALIST	0%	\$40.00
GUM		

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/2

Printed: 31/07/2018 12:11

Date Calculated: 31/07/2018 05:11

ERP STICKER	SPECIALIST		\$10.00
R/F TYRE	SPECIALIST	0%	\$325.00
	Total Extras		\$375.00

Final Calculation

Total Parts	\$19,073.90
--------------------	--------------------

Labour

Total Panel/Mechanical	\$1,470.00
Total Paintwork	\$505.00
Total Visual Alignment work	\$50.00

Total Labour	\$2,025.00
---------------------	-------------------

Additional Costs

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$375.00

Total of Additional Costs	\$375.00
----------------------------------	-----------------

Total Paint/Material Costs	\$247.24
-----------------------------------	-----------------

Grand Total Excludes GST	\$21,721.14
---------------------------------	--------------------

GST @ 7 %	\$1,520.48
-----------	-------------------

Grand Total Includes GST	\$23,241.62
---------------------------------	--------------------

Assessment Notes

**KAN FOOK SING MOTOR
WORKSHOP**
61 DEFU LANE 12
SINGAPORE
539147

Workshop Finalised

Claim Reference:
Assessment Number: KFS01510
Version: KFSMOTOR/7
Date Calculated: 31/08/2018 02:43

Full Report - V1
Registration: SDA8969A
Printed: 31/08/2018 09:44

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Patricia Kan	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	D17MTPV01015819	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 200
Model Sheet Number:	3EE 46
Registration:	SDA8969A
Registration Month:	June
Registration Year:	2014
VIN Number:	WDD2120342A987860
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FR PRODUCTION START	MOD PACK 13/2
MODIFICAT PACK 13/3	MODEL 2014
FRT COLLISION ALARM	RADIATOR SHROUD
EL DRIVE POS SELECT	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
MULTIMEDIA INTERFACE	LAMINATED GLASS
HEATED WASHER UNIT	LEATHER TRIM
SUNBLIND TWO-PIECE	TRIM ELEGANCE
MEMORY PACKAGE	DIPPING MIRROR
S-WDW ROLLER BLIND	WOOD TRIM ASH TREE
REM RELEASE FUEL CAP	KEYLESS GO
PELVIS BAG	RR SCREEN SUN BLIND
ECO START/STOP	STRG COLUMN SHIFT
EMISSION STD EURO 6	7 SPEED AUTOMATIC
DIRECT CONTROL SUSP	TYRES 245/45 WR 17
WHEELS 8J X 17 ALLOY	SPARE WHEEL
FUEL TANK 80 LTR	HD COOLING
TWO COAT METALLIC	COMPRESSOR VARIABLE
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status


Pre-Accident Condition:		Severity of Impact:	
Steering:		Vehicle Status on	
		Inspection:	
Brakes Pedal Travel:		Date of Inspection:	23/07/2018
Place of Inspection:	Repairer		
Pre-Accident Damage:			
Tyres Condition:			
Tread Depth LHF:		Tread Depth RHF:	

KAN FOOK SING MOTOR WORKSHOP


Claim Reference:
Assessment Number: KFS01510
Version: KFSMOTOR/7
Date Calculated: 31/08/2018 02:43

Full Report - V1
Registration: SDA8969A
Printed: 31/08/2018 09:44

Tread Depth LHR:
 Damage Areas:



Tread Depth RHR:
 Direction of Impact:



Addresses

Cost Summary

Total Labour	\$1,765.00
Total Paint/Material	\$247.61
Total Parts	\$14,849.95
Total of Additional Costs	\$1,170.00
Excess:	TBA
Grand Total Exc GST:	\$18,032.56
7 % GST:	\$1,262.28
Grand Total Inc GST:	\$19,294.84

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	15.00
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	15.00
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	10.00
61-1069 02	R + R COMPL LWR ENGINE COMPARTMENT COVER	3.0	15.00
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	45.00
88-2534 02	REPAIR OF R/FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	170.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	10.00
88-1357 ZAX	ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	2.0	10.00
91-2147 01)	R + R R/F AIRBAG SENSOR	2.0	10.00
NO NUMBER	R + R R/F WHEEL COVER	1.0	5.00

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/7

Date Calculated: 31/08/2018 02:43

Full Report - V1

Registration: SDA8969A

Printed: 31/08/2018 09:44

60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE	11.0	55.00
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1269 01	R + R OR RENEW FRONT CROSSMEMBER AND R/TRUSSING BETWEEN WHEELHOUSES	12.0	60.00
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
67-1700 02	RENEW WINDSCREEN	32.0	160.00
20-3865 01	R + R RADIATOR	19.0	95.00
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
20-5410 01	R + R OVERFLOW TANK	6.0	30.00
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	45.00
40-1580 01	R + R FRONT WHEEL	3.0	15.00
33-3570 03)	R + R R/F STEERING KNUCKLE	20.0	100.00
33-3630 03)	R + R FRONT STEERING KNUCKLE ASS WORK	3.0	15.00
33-1425 02)	DETACH + REFIT R/F TENSION ROD	2.0	10.00
33-1421 03)	R + R RIGHT FRONT TORSION BAR	9.0	45.00
32-1960 03)	R + R R/F STRUT	5.0	25.00
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	15.00
NO NUMBER	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	15.00
46-7005 01)	R + R RIGHT TIE ROD	5.0	25.00
40-1470 01	ADD TO R/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH	1.0	5.00
40-2410 01	R + R RIGHT FRONT TYRE	3.0	15.00
40-2702 ZAX	ADDITION TO R + R R/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	5.00
40-2055 01	R/F FRONT WHEEL BALANCE	2.0	10.00
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	45.00
40-6500 01	ALIGN VEHICLE	7.0	35.00
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
40-6710 01	CHECK FRONT AND REAR VEHICLE LEVEL		
	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	5.00
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	10.00
1164	REPAIR R/UPP W-HOUSE S-MEMB	20.0*	100.00
LABOUR COST			
Total Work Units			
Panel / Mechanical Labour		249.0	
Visual Alignment Labour		23.9HRS	\$1,195.00
Corrosion Protection External Labour		1.0HRS	\$50.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		0.0HRS	0.00
Paint Labour		24.9HRS	\$1,245.00
Total Labour		10.4HRS	\$520.00
		35.3HRS	\$1,765.00

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/7

Date Calculated: 31/08/2018 02:43

Full Report - V1

Registration: SDA8969A

Printed: 31/08/2018 09:44

PAINT WORK

Guide Number Description Time Basis 10 WU = 1 HR. Price = \$50.00/HR
WU Cost Price (\$)

- TWO COAT METALLIC
- COMPRESSOR VARIABLE

471	BONNET NEW PART PAINTING	30.0
742	R/F WING NEW PART PAINTING	10.0
283	FRONT BUMPER COVER NEW PART PAINT K1R	13.0
362	R/F OUTER SENSOR NEW PART PAINT K1R	3.0
361	L/F OUTER SENSOR SURFACE PAINT PLAST.	3.0
363	L/F CTR PARKING SENS SURFACE PAINT PLAST.	3.0
365	L/F INNER SENSOR SURFACE PAINT PLAST.	3.0
741	L/F WING SURFACE PAINT	5.0
1164	R/UPP W-HOUSE S-MEMBSURFACE PAINT	4.0
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0
1730	R/DOOR MIRROR HSG SURFACE PAINT PLAST.	3.0

LABOUR COST - PAINT

TIME(PAINT)

Preparation Main Work Metal

Preparation Comp. Work Plastic

Preparation Work Multi Layer Paint

Total Work Units (10WU/HR)

Total Paintwork Labour

88.0
11.0
5.0
0.0
104.0
10.4HRS

\$520.00

MATERIAL COST - PAINT

New Part Painting

New Part Painting - Plastic K1R

Surface-/Blend Paint

Surface Paint Plastic

Material-Const Main Work Metal

Material-Const Comp. Work Plastic

Total Excluding Pearlescent Uplift

Pearlescent Uplift @ 0.0%

Total Paint Material Cost

Cost Price
\$120.74
\$63.47
\$32.63
\$3.67
\$18.10
\$9.00
\$247.61
\$0.00
\$247.61

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015	Bet.	Price (\$)
7753	1	AIR GUIDE	212 505 2930	ADD	0%	25.00*	
471	1	BONNET	212 880 0357		0%	1,280.00*	
318	1	CTR LWR GRILLE MLDG	212 885 2474		0%	108.00*	
4467	1	DRYER BOTTLE	204 835 0147	ADD	0%	0.00F	
7787	1	EXPANSION TANK	204 500 0749		0%	80.00*	
283	1	FRONT BUMPER COVER	212 880 2547 9999		0%	790.00*	
305	1	FRONT BUMPER GRILLE	212 885 0722		0%	54.00*	
8779	1	FRONT GRILLE PANEL	212 520 3923		0%	130.00*	
540	1	FRONT RADAR SENSOR	000 905 5103		0%	650.00*	
340	1	FRT CTR BUMPER REINF	212 885 3965	ADD	0%	70.00*	
1001	1	FRT LWR CROSSMEMBER	212 620 1500		0%	295.00*	
1413	4	FRT SCREEN SUPPORTS	210 671 0397		0%	0.00F	
1000	1	FRT SENSOR WIRE	Renew		0%	115.00*	
349	1	FRT/CTR IMPACT DAMP	212 880 0135		0%	78.00*	
405	1	GRILLE	212 880 1483		0%	560.00*	

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/7

Date Calculated: 31/08/2018 02:43

Full Report - V1

Registration: SDA8969A

Printed: 31/08/2018 09:44

9644	1	HIGH TONE HORN	007 542 6920	ADD	0%	Daye	105.00*
8730	1	INTERCOOLER	204 500 0200	ADD	0%	Daye	680.00*
7752	1	LOWER AIR GUIDE	212 505 3230	ADD	0%	Daye	55.00*
496	1	R/F ACCELERAT SENSOR	172 905 6000	ADD	0%	Daye	65.00*
7066	1	R/F BALL JOINT	212 330 0135	ADD	0%	Daye	60.00*
1000	1	R/F BONNET STOPPER	Renew		0%		18.50*
1192	1	R/F BUMPER ABSORBER	212 620 0895		0%		160.00*
344	1	R/F BUMPER CARRIER	212 885 3865		0%		38.00*
836	1	R/F BUMPER COVER	212 885 2822	ADD	0%	Daye	19.50*
364	1	R/F CTR PARKING SENS	000 905 5504 9999	ADD	0%	Daye	120.00*
358	1	R/F CTR SPACER RING	000 542 1251	ADD	0%	Daye	4.00*
360	1	R/F INN SPACER RING	000 542 1251		0%		4.00*
366	1	R/F INNER SENSOR	000 905 5504 9999		0%		120.00*
7072	1	R/F LWR CONTROL ARM	212 330 3011		0%		270.00*
304	1	R/F OUT BUMP GRILLE	212 885 2222		0%		33.00*
356	1	R/F OUT SPACER RING	000 542 1251		0%		4.00*
362	1	R/F OUTER SENSOR	000 905 5604 9999		0%		120.00*
7088	1	R/F SHOCK ABSORBER	212 323 5300		0%		465.00*
7082	1	R/F STEERING KNUCKLE	212 332 0800		0%		695.00*
7048	1	R/F TENSION ROD	212 330 2811		0%		270.00*
1188	1	R/F UPP REINF	212 620 4700		0%		150.00*
7202	1	R/F WHEEL	212 401 5402		0%		0.00F
			7X45				
7208	1	R/F WHEEL COVER	171 400 0125 5337		0%		0.00F
7132	1	R/F WHEEL HUB	212 330 0025		0%		385.00*
840	1	R/F WHEELHOUSE COVER	212 690 6230		0%		115.00*
742	1	R/F WING	212 880 1218		0%		560.00*
784	1	R/F WING MOULDING	212 690 4482		0%		56.00*
9650	1	R/H-LAMP LVL C-UNIT	218 900 7206		0%		480.00*
516	1	R/LOWER LATCH	204 880 0260		0%		38.00*
796	2	R/NUT	414 990 0051		0%		30.00*
7312	1	R/OUTER TIE ROD BALL	212 330 8200		0%		105.00*
1180	1	R/REINFORCEMENT	212 620 0285		0%		30.00*
508	1	R/SPRING ELEMENT	204 880 0127	ADD	0%	Daye	16.00*
514	1	R/SUPPORT	212 620 0028	ADD	0%	Daye	24.00*
7056	1	R/TENSION ROD RUBBER	212 333 0014		0%		0.00F
7310	1	R/TIE ROD	212 330 2000		0%		70.00*
7761	1	RADIATOR	099 500 6203	ADD	0%	Daye	735.00*
562	1	RIGHT HEADLAMP ASSY	212 820 2039		0%		1,800.00*
7751	1	UPPER AIR GUIDE	212 500 0455	ADD	0%	Daye	78.00*
1401	1	WINDSCREEN	212 670 1200 28		0%		700.00F
1411	1	WINDSCREEN REP KIT	000 670 0100		0%		0.00F
f: OEM Parts		Saving					\$426.61
g: Original		Sub Total					\$12,913.00
h: Secondhand		Mark Up From Cost		(15 %)			\$1,936.95
p: Parallel		Sundry Parts		(Fixed)			\$0.00
x: Exchange		Total Parts					\$14,849.95

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT WINDSCREEN SPECIALIST	0%	\$40.00

KAN FOOK SING MOTOR WORKSHOP

Claim Reference:

Assessment Number: KFS01510

Version: KFSMOTOR/7

Date Calculated: 31/08/2018 02:43

Full Report - V1

Registration: SDA8969A

Printed: 31/08/2018 09:44

GUM					
ERP STICKER	SPECIALIST				\$10.00
F/W/S SOLAR FILM	SPECIALIST	0%	ADD / REC		\$250.00
FRONT RIM RH	SPECIALIST				\$500.00
CONFIGURATION	SPECIALIST	0%	ADD		\$300.00
H/LAMP					
AIR CON GAS	SPECIALIST		ADD		\$50.00
ANTI-FREEZE	SPECIALIST	0%	ADD		\$20.00
Total Extras					\$1,170.00

Final Calculation

Total Parts		\$14,849.95
Labour		
Total Panel/Mechanical	\$1,195.00	
Total Paintwork	\$520.00	
Total Visual Alignment work	\$50.00	
Total Labour		\$1,765.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,170.00	
Total of Additional Costs		\$1,170.00
Total Paint/Material Costs		\$247.61
Grand Total Excludes GST		\$18,032.56
GST @ 7 %		\$1,262.28
Grand Total Includes GST		\$19,294.84

Assessment Notes

簡福星嘢嘢工廠
KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2
SINGAPORE 068807

INVOICE NO : TEST
DATE : 31-08-2018

VEHICLE NO. : SDA8969A
ACCIDENT DATE : 23-07-2018 11:20
THIRD PARTY REF. : SLL6156P

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SDA8969A MERCEDES BENZ E200 SEDAN (R17)

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT WINDSCREEN GLASS	700.00
1	FRONT BONNET	1280.00
1	FRONT BONNET LOCK LOWER RH	38.00
1	FRONT BONNET STOPPER RH	18.50
1	FRONT HEADLAMP PANEL RH	150.00
1	FRONT HEADLAMP RH	1800.00
1	FRONT HEADLAMP CONTROL UNIT RH	480.00
1	FRONT GRILLE	560.00
1	FRONT FENDER RH	560.00
1	ENGINE LOWER COVER	130.00
10	FRONT FENDER SHIELD CLIP @\$3.00	30.00
1	FRONT FENDER CHROME RH	56.00
1	FRONT BUMPER	790.00
1	FRONT BUMPER SIDE CARRIER RH	38.00
1	FRONT BUMPER CENTRE CARRIER RH	70.00
1	FRONT BUMPER FOAM	78.00
1	FRONT BUMPER REINFORCEMENT	295.00
1	FRONT BUMPER REINFORCEMENT BRACKET RH	160.00
1	FRONT BUMPER REINFORCEMENT SIDE BRACKET RH	30.00
3	FRONT BUMPER SENSOR @\$120.00	360.00
2	FRONT BUMPER SENSOR RING @\$4.00	12.00
1	FRONT BUMPER SENSOR WIRE	115.00
1	FRONT BUMPER CENTRE GRILLE	54.00

簡福星摩多工廠
KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

VEHICLE NO. : SDA8969A
ACCIDENT DATE : 23-07-2018 11:20
THIRD PARTY REF. : SLL6156P

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT FENDER SHIELD RH	115.00
1	SPARE TANK	80.00
1	FRONT SHOCK ABSORBER RH	465.00
1	FRONT LOWER ARM RH	270.00
1	FRONT BALL JOINT RH	60.00
1	FRONT CONTROL ARM RH	270.00
1	FRONT KNUCKLE ARM RH	695.00
1	FRONT KNUCKLE BEARING RH	385.00
1	STEERING TIE ROD RH	70.00
1	STEERING TIE ROD END RH	105.00
1	FRONT GRILLE RADAR SENSOR	650.00
1	FRONT LOWER MOULDING	108.00
1	FRONT BUMPER FOGLAMP COVER RH	33.00
1	FRONT BUMPER FOGLAMP COVER SMALL RH	19.50
1	INTERCOOLER	680.00
1	HORN	105.00
1	FRONT BONNET LOCK SPRING	16.00
1	LOWER AIR DUCT	55.00
1	FRONT SUPPORT TOP GARNISH	25.00
1	FRONT SUPPORT ACCELERATION SENSOR	65.00
1	FRONT BUMPER SIDE BRACKET RH	24.00
1	RADIATOR	735.00
1	FAN SHROUD	78.00
		12,913.00
	ADD 15 %	
		1,936.95
	TOTAL (A)	
		14,849.95

SPECIAL NETT ITEMS

1	FRONT WINDSCREEN GUM	40.00
---	----------------------	-------

73

簡福星摩多工廠
 KAN FOOK SING MOTOR WORKSHOP
 81 DEFU LANE 12
 SINGAPORE 539147
 TEL: 67479560, 68582126, 68584361
 FAX: 67481006, 62818428

VEHICLE NO. : SDA8969A
 ACCIDENT DATE : 23-07-2018 11:20
 THIRD PARTY REF. : SLL6156P

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT WINDSCREEN SOLAR FILM	250.00
1	FRONT WINDSCREEN ERP STICKER	10.00
1	FRONT RIM RH	500.00
1	SPECIALIST CONFIGURATION OF HEADLAMP CONTROL UNIT	300.00
1	AIR CON GAS	50.00
1	ANTI-FREEZE	20.00
TOTAL (C)		1,170.00

LABOUR CHARGES

1	TOTAL PANEL/MECHANICAL LABOUR	1245.00
1	TOTAL PAINTWORK	520.00
1	TOTAL PAINT/MATERIAL	247.61

TOTAL (D)	2,012.61
TOTAL REPAIR COST :	18,032.56
G S T % :	1,262.27
INVOICE AMOUNT :	19,294.83

REPAIR DETAILS

SDA8969A

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Jul 2018)
 Parts: 143 MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SDA8969A/24/07/2018 16:44
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*PARTS	0.00	0.00	*19,110.70 F
Total Parts (S\$)						19,110.70

F=Franchise part.

Kan Fook Sing Motor Workshop/SDA8969A/24/07/2018 16:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Materials</u>			
1	1	PAINTWORK MATERIALS	247.24
<u>Miscellaneous Items</u>			
2	1	MISCELLANEOUS	375.00
Sub Total (S\$)			622.24

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	505.00
<u>Labour Items</u>			
2	LABOUR CHARGES	New	1,520.00
Gross Labour Cost (S\$)			2,025.00

Kan Fook Sing Motor Workshop/SDA8969A/24/07/2018 16:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

SDA 8969A

Supplementary

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 31 Aug 2018)
 Parts: 143 MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SDA8969A/31/08/2018 12:05
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*PARTS	0.00	0.00	*2,744.50 F
Total Parts (S\$)						2,744.50

F=Franchise part.

Kan Fook Sing Motor Workshop/SDA8969A/31/08/2018 12:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	MISCELLANEOUS	1,120.00
2	1	PAINTWORK MATERIALS	0.61
Sub Total (S\$)			1,120.61

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	SPRAY PAINTING CHARGES	New	15.00
Gross Labour Cost (S\$)			15.00

Kan Fook Sing Motor Workshop/SDA8969A/31/08/2018 12:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SURPASS AUTO PARTS SUPPLIES PTE LTD

12 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

02/08/2018 10:25:49

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

TAX INVOICE

Inv No. : 18080013

Date : 01/08/2018

Page : 1 of 2

SDA SPOA

S/N Item No.	Description	Qty	U/ Price	Amount
1	SDA8969A			
2 A2128800357	BONNET	1	1,280.00 -	1,280.00 ✓
3 A2128202039	HEADLAMP	1	1,800.00 -	1,800.00 ✓
4 A2126204700 1128	2126200600 HEADLAMP PANEL	1	150.00 -	150.00 ✓
5 A2128801483	GRILLE	1	560.00 -	560.00 ✓
6 A2128801218	FRONT FENDER	1	560.00 -	560.00 ✓
7 A21288025479999	FRT BUMPER	1	790.00 -	790.00 ✓
8 A2126201500 1001	SUPPORT, FRONT BUMPER, METL	1	295.00 -	295.00 ✓
9 A2126200895 1192	ABSORBER RH <i>sponge</i>	1	160.00 -	160.00 ✓
10 A2126200285 1150	STRUT	1	30.00 -	30.00 ✓
11 A00090593009999 766	0009055504 PTS SENSON	1	120.00 -	120.00 ✓
12 A0005421251 360	2215420051 SEAL	1	4.00 -	4.00 ✓
13 A2128850722 308	2128802547 LOWER GRILLE	1	54.00 -	54.00 ✓
14 A2045000749 7187	2045000549 RAD EXPANSION TANK	1	80.00 -	80.00 ✓
15 A2123225300 7088	2123221300 SHOCK-ABSORBER STRUT	1	465.00 -	465.00 ✓

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

02/08/2018 10:25:49

6348

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

TAX INVOICE

Inv No. : 18080013

Date : 01/08/2018

Page : 2 of 2

S/N Item No.	Description	Qty	U/ Price	Amount
16 A2123302811 7048	TOP ARM	1	270.00 -	270.00 ✓
17 A2123330014 7066	BUSH TOP ARM	1	60.00 -	60.00 ✓
18 A2123304000 7072	2123303011 LOWER ARM RH	1	270.00 -	270.00 ✓
19 A2123300025 7032	BER HUP FRT	1	385.00 -	385.00 ✓
20 A2123320800 7082	STEERING KNUCKLE FRT RH	1	695.00 -	695.00 ✓
21 A2123201289 7310	ROD	1	70.00 -	70.00 ✓
22 A2123302203* 7312	2183300400 TIE ROD RH	1	105.00 -	105.00 ✓

Sub Total 8,203.00 ✓

GST 7% 574.21

Total 8,777.21

Customer's Signature

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

06/08/2018 15:09:12

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

TAX INVOICE

Inv No. : 18080032

Date : 02/08/2018

Page : 1 of 2

SDA 8969A

S/N	Item No.	Description	Qty	U/ Price	Amount
1	A2128853865	FRT RH BASIC 2128803000	1	38.00	38.00
2	A2128854065	FRT LOW BASIC	1	70.00	70.00
3	A2125402700	ELECTRICAL WIRING HARNESS	1	115.00	115.00
4	A0009055103	RADAR SENSOR	1	650.00	650.00
5	A2128850314	BRACKET	1	18.50	18.50
6	A2128852474	LOW MOULDING	1	108.00	108.00
7	A2128852222	GRILL RING	1	33.00	33.00
8	A2128852822	GRILLE AREA	1	19.50	19.50
9	A2045000200	CHARGE AIR INTERCOOLING 651	1	680.00	680.00
10	A2045420120	HORN NEW PLUGS	1	105.00	105.00
11	A2128800135	FRT SPONGE	1	78.00	78.00
12	A2048800127	SPRING BONNET 207/212	1	16.00	16.00
13	A2125053230	LOE AIR DUCT	1	55.00	55.00
14	A2125052930	TOP AIR BAFFLE	1	25.00	25.00
15	AAAAAA5555555555	AAAAAA5555555555	1	120.00	120.00

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

KAN FOOK SING MOTOR WORKSHOP

61 DEFU LANE 12

SINGAPORE 539147

TAX INVOICE

Inv No. : 18080032

Date : 02/08/2018

Page : 2 of 2

Item No.	Description	Qty	U/ Price	Amount
16	A2125203923	COVER F ENGINE 212034	1	130.00
17	A0009905492 9051	RIVET 6MM	10	3.00
18	A1729056000	ACCELERATION SENSOR	1	65.00
19	A2045241440	BRACKET RH	1	24.00
20	A0995006203	RADIATOR 7G	1	735.00
21	A2128853021	SIDE MOULDING	1	56.00
22	A2125000455	TOP FAN SHROUD NEW	1	78.00

SDA8969A

Sub Total 3,249.00
 GST 7% 227.43
 Total 3,476.43

Customer's Signature

GST Registration No.: 200807224Z

Customer Name & Address:

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
**SDA8969A E200

INVOICE No.: A 11317

DATE: 1/8/2018

TERMS: 30 DAYS

S/No.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1	ECP HLAMP 1650	1	\$ 480.00	\$ 480.00
2	SEAL 352 58?	2	\$ 4.00	\$ 8.00
Singapore Dollars			TOTAL	\$ 488.00
			GST 7%	\$ 34.16
			DEPOSIT	\$ -
			BALANCE	\$ 522.16

Goods Sold are not exchangeable and returnable.

All cheques should be crossed "A/C PAYEE" and made payable to LION'S AUTO TRADING PTE LTD.

for LION'S AUTO TRADING PTE LTD

Customer's Signature and Stamp

Authorised Signature

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175

Tel: 67476018 Fax: 67449644 Email: surpasslim@gmail.com

Co & Gst Reg No: 199904808E

07/08/2018 14:02:53

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147**TAX INVOICE**Inv No. : 18080080
Date : 07/08/2018
Page : 1 of 1

S/N	Item No.	Description	Qty	U/ Price	Amount
1	A2126906230 840	NEW FRT COVER I RH	1	115.00	115.00
2	A2048800260 816	ENGINE HOOD CATCH LOW SDA8969A	1	38.00	38.00


Customer's Signature

Sub Total 153.00
GST 7% 10.71
Total 163.71

SG AUTO GLASS

SG Auto Glass Pte Ltd
3 Ang Mo Kio Street 62
#01-19 Link@AMK
Singapore 569139
Tel: 6253 0709 Fax: 6253 2278
Co. Reg & GST No.: 201530612W

TAX INVOICE

To:
Kan Fook Sing Motor Workshop
61 Defu Lane 12
Singapore 539147

Delivery To:

Tel : 6747 9560
Fax : 6748 1006

Tel :
Fax :

No. : I-18080020
Ref. No. :
Date : 03-08-2018
Vehicle No. : SDA8969A
Make : MERCEDES BENZ
Model : E CLASS W212
Terms : Net 30 days
Salesman : JERRY KHOO

Item	Description	Qty	UOM	U/Price	Total
1.	Front Windscreen Glass With Moulding (Sensor)	1	PCS	700.00	700.00

Notes :

- All cheques should be crossed and made payable to
SG Auto Glass Pte Ltd
- Goods sold are neither returnable nor refundable. Otherwise
a cancellation fee of 20% on purchase price will be imposed.

SubTotal : S\$ 700.00
GST 7% : S\$ 49.00
Total : S\$ 749.00

SG Auto Glass Pte Ltd

This is computer generated document.
No signature required

Sign & Company's Stamp
Goods Received in Good Order and
Condition

SURPASS AUTO PARTS SUPPLIES PTE LTD

10 KAKI BUKIT ROAD 1 #01-33 KB INDUSTRIAL BUILDING SINGAPORE 416175
Tel: 67476016 Fax: 67449644 Email: surpasslim@gmail.com
Co & Gst Reg No: 199904808E

06/08/2018 14:26:29

KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147

TAX INVOICE

Inv No. : 18080059
Date : 06/08/2018
Page : 1 of 1

S/N	Item No.	Description	Qty	U/ Price	Amount
1	A00090512029999	0009055604 PTS SENSOR SDA8969A	2	120.00	240.00

Sub Total 240.00
GST 7% 16.80
Total 256.80

Customer's Signature

12783

Claim Reference:
Assessment Number: KFS01510
Version: KFSMOTOR/8
Date Calculated: 02/01/2019 02:28

Full Report - V1
Registration: SDA8969A
Printed: 02/01/2019 10:29

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	D17MTPV01015819	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:	True	Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 200
Model Sheet Number:	3EE 46
Registration:	SDA8969A
Registration Month:	June
Registration Year:	2014
VIN Number:	WDD2120342A987860
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FR PRODUCTION START	MOD PACK 13/2
MODIFICAT PACK 13/3	MODEL 2014
FRT COLLISION ALARM	RADIATOR SHROUD
EL DRIVE POS SELECT	PARKTRONIC
LOAD COMPARTMENT BOX	AUDIO 20 CD CHANGER
MULTIMEDIA INTERFACE	LAMINATED GLASS
HEATED WASHER UNIT	LEATHER TRIM
SUNBLIND TWO-PIECE	TRIM ELEGANCE
MEMORY PACKAGE	DIPPING MIRROR
S-WDW ROLLER BLIND	WOOD TRIM ASH TREE
REM RELEASE FUEL CAP	KEYLESS GO
PELVIS BAG	RR SCREEN SUN BLIND
ECO START/STOP	STRG COLUMN SHIFT
EMISSION STD EURO 6	7 SPEED AUTOMATIC
DIRECT CONTROL SUSP	TYRES 245/45 WR 17
WHEELS 8J X 17 ALLOY	SPARE WHEEL
FUEL TANK 80 LTR	HD COOLING
TWO COAT METALLIC	COMPRESSOR VARIABLE
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	23/07/2018
Place of Inspection:	Repairer	
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	

Claim Reference:

Full Report - V1

Assessment Number: KFS01510


Registration: SDA8969A

Version: KFSMOTOR/8


Printed: 02/01/2019 10:29

Date Calculated: 02/01/2019 02:28

Damage Areas:



Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,765.00
Total Paint/Material	\$247.61
Total Parts	\$14,849.95
Total of Additional Costs	\$1,170.00
Excess:	TBA
Grand Total Exc GST:	\$18,032.56
7 % GST:	\$1,262.28
Grand Total Inc GST:	\$19,294.84

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	15.00
54-1010 ZAX	CHECK ELECTRIC-/ELECTRONIC SYSTEMS (AFTER SHORT TEST OR ACCORDING TO ERROR CODE)	3.0	15.00
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	10.00
61-1069 02	R + R COMPL LWR ENGINE COMPARTMENT COVER	3.0	15.00
NO NUMBER	ANCHOR VEHICLE ON STRAIGHTENING SYSTEM	9.0	45.00
88-2534 02	REPAIR OF R/FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	34.0	170.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	10.00
88-1357 ZAX	ADD TO DIS/ASS FRONT BUMPER CPL (LUXURY VERSION VEHICLE)	2.0	10.00
91-2147 01)	R + R R/F AIRBAG SENSOR	2.0	10.00
NO NUMBER	R + R R/F WHEEL COVER	1.0	5.00
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE	11.0	55.00

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/8

Printed: 02/01/2019 10:29

Date Calculated: 02/01/2019 02:28

	COMPARTMENT FOR RENEWAL OF THE FRONT MODULE		
	INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION		
62-1269 01	R + R OR RENEW FRONT CROSSMEMBER AND R/TRUSSING BETWEEN WHEELHOUSES	12.0	60.00
	INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY		
67-1700 02	RENEW WINDSCREEN	32.0	160.00
20-3865 01	R + R RADIATOR	19.0	95.00
	INCLUDES: R + R CENTRE STIFFENING, FAN UNIT AND CHARGE AIR COOLER		
20-5410 01	R + R OVERFLOW TANK	6.0	30.00
83-6543 ZAX	R + R AIR CONDITIONING CONDENSER	9.0	45.00
40-1580 01	R + R FRONT WHEEL	3.0	15.00
33-3570 03)	R + R R/F STEERING KNUCKLE	20.0	100.00
33-3630 03)	R + R FRONT STEERING KNUCKLE ASS WORK	3.0	15.00
33-1425 02)	DETACH + REFIT R/F TENSION ROD	2.0	10.00
33-1421 03)	R + R RIGHT FRONT TORSION BAR	9.0	45.00
32-1960 03)	R + R R/F STRUT	5.0	25.00
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	15.00
NO NUMBER	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	15.00
46-7005 01)	R + R RIGHT TIE ROD	5.0	25.00
40-1470 01	ADD TO R/F WHEEL REMOVE AND REFIT (ASSEMBLY ON WHEELS FROM 17 INCH	1.0	5.00
40-2410 01	R + R RIGHT FRONT TYRE	3.0	15.00
40-2702 ZAX	ADDITION TO R + R R/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	5.00
40-2055 01	R/F FRONT WHEEL BALANCE	2.0	10.00
83-1762 02	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	45.00
40-6500 01	ALIGN VEHICLE	7.0	35.00
	INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL		
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	5.00
40-4064 01	ADJUST FRONT WHEEL TOE (DURING ALIGNMENT)	2.0	10.00
1164	REPAIR R/UPP W-HOUSE S-MEMB	20.0*	100.00
LABOUR COST			
	Total Work Units	249.0	
	Panel / Mechanical Labour	23.9HRS	\$1,195.00
	Visual Alignment Labour	1.0HRS	\$50.00
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	24.9HRS	\$1,245.00
	Paint Labour	10.4HRS	\$520.00
	Total Labour	35.3HRS	\$1,765.00

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/8

Printed: 02/01/2019 10:29

Date Calculated: 02/01/2019 02:28

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- COMPRESSOR VARIABLE		
471	BONNET NEW PART PAINTING	30.0	
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER COVER NEW PART PAINT K1R	13.0	
362	R/F OUTER SENSOR NEW PART PAINT K1R	3.0	
361	L/F OUTER SENSOR SURFACE PAINT PLAST.	3.0	
363	L/F CTR PARKING SENS SURFACE PAINT PLAST.	3.0	
365	L/F INNER SENSOR SURFACE PAINT PLAST.	3.0	
741	L/F WING SURFACE PAINT	5.0	
1164	R/UPP W-HOUSE S-MEMBSURFACE PAINT	4.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
1730	R/DOOR MIRROR HSG SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	88.0	
	Preparation Main Work Metal	11.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	104.0	
	Total Paintwork Labour	10.4HRS	\$520.00
MATERIAL COST - PAINT			
	New Part Painting		Cost Price
	New Part Painting - Plastic K1R		\$120.74
	Surface-/Blend Paint		\$63.47
	Surface Paint Plastic		\$32.63
	Material-Const Main Work Metal		\$3.67
	Material-Const Comp. Work Plastic		\$18.10
	Total Excluding Pearlescent Uplift		\$9.00
	Pearlescent Uplift @ 0.0%		\$247.61
	Total Paint Material Cost		\$0.00
			\$247.61

PARTS

Guide No.		Qty	Description	Part Number	Supplier	Bet.	Price (\$)
7753	1		AIR GUIDE	212 505 2930		0%	25.00*
471	1		BONNET	212 880 0357		0%	1,280.00*
318	1		CTR LWR GRILLE MLDG	212 885 2474		0%	108.00*
4467	1		DRYER BOTTLE	204 835 0147		0%	0.00F
7787	1		EXPANSION TANK	204 500 0749		0%	80.00*
283	1		FRONT BUMPER COVER	212 880 2547 9999		0%	790.00*
305	1		FRONT BUMPER GRILLE	212 885 0722		0%	54.00*
8779	1		FRONT GRILLE PANEL	212 520 3923		0%	130.00*
540	1		FRONT RADAR SENSOR	000 905 5103		0%	650.00*
340	1		FRT CTR BUMPER REINF	212 885 3965		0%	70.00*
1001	1		FRT LWR CROSSMEMBER	212 620 1500		0%	295.00*
1413	4		FRT SCREEN SUPPORTS	210 671 0397		0%	0.00F
1000	1		FRT SENSOR WIRE	Renew		0%	115.00*
349	1		FRT/CTR IMPACT DAMP	212 880 0135		0%	78.00*
405	1		GRILLE	212 880 1483		0%	560.00*
9644	1		HIGH TONE HORN	007 542 6920		0%	105.00*

Price Valid: 01/06/2015

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/8

Printed: 02/01/2019 10:29

Date Calculated: 02/01/2019 02:28

8730	1	INTERCOOLER	204 500 0200	0%	680.00*
7752	1	LOWER AIR GUIDE	212 505 3230	0%	55.00*
496	1	R/F ACCELERAT SENSOR	172 905 6000	0%	65.00*
7066	1	R/F BALL JOINT	212 330 0135	0%	60.00*
1000	1	R/F BONNET STOPPER	Renew	0%	18.50*
1192	1	R/F BUMPER ABSORBER	212 620 0895	0%	160.00*
344	1	R/F BUMPER CARRIER	212 885 3865	0%	38.00*
836	1	R/F BUMPER COVER	212 885 2822	0%	19.50*
364	1	R/F CTR PARKING SENS	000 905 5504 9999	0%	120.00*
358	1	R/F CTR SPACER RING	000 542 1251	0%	4.00*
360	1	R/F INN SPACER RING	000 542 1251	0%	4.00*
366	1	R/F INNER SENSOR	000 905 5504 9999	0%	120.00*
7072	1	R/F LWR CONTROL ARM	212 330 3011	0%	270.00*
304	1	R/F OUT BUMP GRILLE	212 885 2222	0%	33.00*
356	1	R/F OUT SPACER RING	000 542 1251	0%	4.00*
362	1	R/F OUTER SENSOR	000 905 5604 9999	0%	120.00*
7088	1	R/F SHOCK ABSORBER	212 323 5300	0%	465.00*
7082	1	R/F STEERING KNUCKLE	212 332 0800	0%	695.00*
7048	1	R/F TENSION ROD	212 330 2811	0%	270.00*
1188	1	R/F UPP REINF	212 620 4700	0%	150.00*
7202	1	R/F WHEEL	212 401 5402	0%	0.00F
			7X45		
7208	1	R/F WHEEL COVER	171 400 0125 5337	0%	0.00F
7132	1	R/F WHEEL HUB	212 330 0025	0%	385.00*
840	1	R/F WHEELHOUSE COVER	212 690 6230	0%	115.00*
742	1	R/F WING	212 880 1218	0%	560.00*
784	1	R/F WING MOULDING	212 690 4482	0%	56.00*
9650	1	R/H-LAMP LVL C-UNIT	218 900 7206	0%	480.00*
516	1	R/LOWER LATCH	204 880 0260	0%	38.00*
796	2	R/NUT	414 990 0051	0%	30.00*
7312	1	R/OUTER TIE ROD BALL	212 330 8200	0%	105.00*
1180	1	R/REINFORCEMENT	212 620 0285	0%	30.00*
508	1	R/SPRING ELEMENT	204 880 0127	0%	16.00*
514	1	R/SUPPORT	212 620 0028	0%	24.00*
7056	1	R/TENSION ROD RUBBER	212 333 0014	0%	0.00F
7310	1	R/TIE ROD	212 330 2000	0%	70.00*
7761	1	RADIATOR	099 500 6203	0%	735.00*
562	1	RIGHT HEADLAMP ASSY	212 820 2039	0%	1,800.00*
7751	1	UPPER AIR GUIDE	212 500 0455	0%	78.00*
1401	1	WINDSCREEN	212 670 1200 28	0%	700.00F
1411	1	WINDSCREEN REP KIT	000 670 0100	0%	0.00F
f: OEM Parts			Saving		\$426.61
g: Original			Sub Total		\$12,913.00
h: Secondhand			Mark Up From Cost	(15 %)	\$1,936.95
p: Parallel			Sundry Parts	(Fixed)	\$0.00
x: Exchange			Total Parts		\$14,849.95

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT WINDSCREEN SPECIALIST	0%	\$40.00
GUM		

Claim Reference:

Full Report - V1

Assessment Number: KFS01510

Registration: SDA8969A

Version: KFSMOTOR/8

Printed: 02/01/2019 10:29

Date Calculated: 02/01/2019 02:28

ERP STICKER	SPECIALIST		\$10.00
F/W/S SOLAR FILM	SPECIALIST	0%	\$250.00
FRONT RIM RH	SPECIALIST		\$500.00
CONFIGURATION	SPECIALIST	0%	\$300.00
H/LAMP			
AIR CON GAS	SPECIALIST		\$50.00
ANTI-FREEZE	SPECIALIST	0%	\$20.00
Total Extras			\$1,170.00

Final Calculation

Total Parts	\$14,849.95
--------------------	--------------------

Labour

Total Panel/Mechanical	\$1,195.00
Total Paintwork	\$520.00
Total Visual Alignment work	\$50.00

Total Labour**\$1,765.00****Additional Costs**

Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$1,170.00

Total of Additional Costs**\$1,170.00****Total Paint/Material Costs****\$247.61****Grand Total Excludes GST****\$18,032.56**

GST @ 7 %

\$1,262.28**Grand Total Includes GST****\$19,294.84****Assessment Notes**

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jul 2018 16:22 Sendback Est	24 Jul 2018 16:44 S\$21,757.94	30 Jul 2018 09:40 Edit Adj Rpt	S\$18,032.56 Edit Estimates	S\$18,032.56 View Rpt		Pending for Survey Report Cancel Case
Supp #1	31 Aug 2018 12:01	31 Aug 2018 12:05 S\$3,880.11	31 Aug 2018 12:05			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	TAN SIANG HEE THOMSON, ID: S1691096A								
Vehicle Reg. No.:	SDA8969A	Date of Loss:	23/07/2018 11:00 - :59 [49 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 565505	Policy/Cover Note No.:	A29069766MKF (Comprehensive) Coverage: 01/02/2018 - 31/01/2019						
Vehicle Reg. No. (Insured):	SLL6156P	Policy No. (Claimant):							
		Excess:							
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, S39147 Defu Lane - Tel: 67479560								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/08/2018]								
Driver/Custodian (Insured):	YONG LEE LIN (), NRIC: S0125318B								
Adj Asg. Remarks:	ON WP. car is in. GRAB CASE. LIABILITY : 50/50.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SDA8969A (565505)
[SLL6156P]
TP
TAN SIANG HEE THOMSON
Jul 23 2018 11:00AM
[GRAB RENTALS PTE LTD]
Kan Fook Sing Motor Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/07/18 16:44	Repairer Estimates	Load HTM	☐
2	31/08/18 12:05	Repairer Estimates Suppl. #1	Load HTM	☐
MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print
1	26/07/18 10:57	Accident Statement Addm. #1 From: SC - Reg. No: SLL6156P, Claimant: GRAB RENTALS PTE LTD	Load HTM	☐
LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	31/07/18 12:51	Adjuster Immediate Advice	Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/18 20:27	Chassis Number	Load JPG	☒
2	30/07/18 20:27	Odometer Reading	Load JPG	☒
3	30/07/18 20:28	General View	Load JPG	☒
4	30/07/18 20:28	General View	Load JPG	☒
5	30/07/18 20:28	General View	Load JPG	☒
6	30/07/18 20:28	General View	Load JPG	☒
7	30/07/18 20:28	General View	Load JPG	☒
8	30/07/18 20:28	General View	Load JPG	☒
9	30/07/18 20:28	General View	Load JPG	☒
10	30/07/18 20:28	General View	Load JPG	☒
11	30/07/18 20:28	General View	Load JPG	☒
12	30/07/18 20:28	General View	Load JPG	☒
13	30/07/18 20:28	General View	Load JPG	☒
14	30/07/18 20:28	General View	Load JPG	☒
15	30/07/18 20:28	General View	Load JPG	☒
16	30/07/18 20:28	General View	Load JPG	☒
17	30/07/18 20:28	General View	Load JPG	☒
18	30/07/18 20:28	General View	Load JPG	☒
19	30/07/18 20:28	General View	Load JPG	☒
20	30/07/18 20:28	General View	Load JPG	☒
21	30/07/18 20:28	General View	Load JPG	☒
22	30/07/18 20:28	General View	Load JPG	☒
23	30/07/18 20:28	General View	Load JPG	☒
24	30/07/18 20:28	General View	Load JPG	☒
25	30/07/18 20:28	General View	Load JPG	☒
26	30/07/18 20:28	General View	Load JPG	☒
27	30/07/18 20:28	General View	Load JPG	☒
28	30/07/18 20:28	General View	Load JPG	☒
29	30/07/18 20:28	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
30	30/07/18 20:28	General View	 Load JPG	☒
31	30/07/18 20:28	General View	 Load JPG	☒
32	30/07/18 20:28	General View	 Load JPG	☒
33	30/07/18 20:28	General View	 Load JPG	☒
34	30/07/18 20:28	General View	 Load JPG	☒
35	30/07/18 20:28	General View	 Load JPG	☒
36	30/07/18 20:28	General View	 Load JPG	☒
37	30/07/18 20:28	General View	 Load JPG	☒
38	30/07/18 20:28	General View	 Load JPG	☒
39	30/07/18 20:28	General View	 Load JPG	☒
40	30/07/18 20:28	General View	 Load JPG	☒
41	30/07/18 20:28	General View	 Load JPG	☒
42	30/07/18 20:28	General View	 Load JPG	☒
43	30/07/18 20:28	General View	 Load JPG	☒
44	30/07/18 20:28	General View	 Load JPG	☒
45	30/07/18 20:28	General View	 Load JPG	☒
46	30/07/18 20:28	General View	 Load JPG	☒
47	30/07/18 20:28	General View	 Load JPG	☒
48	30/07/18 20:28	General View	 Load JPG	☒
49	30/07/18 20:28	General View	 Load JPG	☒
50	30/07/18 20:28	General View	 Load JPG	☒
51	30/07/18 20:28	General View	 Load JPG	☒
52	30/07/18 20:28	General View	 Load JPG	☒
53	30/07/18 20:28	General View	 Load JPG	☒
54	30/07/18 20:28	General View	 Load JPG	☒
55	30/07/18 20:28	General View	 Load JPG	☒
56	30/07/18 20:28	General View	 Load JPG	☒
57	30/07/18 20:28	General View	 Load JPG	☒
58	30/07/18 20:28	General View	 Load JPG	☒
59	30/07/18 20:28	General View	 Load JPG	☒
60	30/07/18 20:28	General View	 Load JPG	☒
61	30/07/18 20:28	General View	 Load JPG	☒
62	30/07/18 20:28	General View	 Load JPG	☒
63	30/07/18 20:28	General View	 Load JPG	☒
64	30/07/18 20:28	General View	 Load JPG	☒
65	30/07/18 20:28	General View	 Load JPG	☒
66	30/07/18 20:28	General View	 Load JPG	☒
67	30/07/18 20:28	General View	 Load JPG	☒
68	30/07/18 20:28	General View	 Load JPG	☒
69	30/07/18 20:28	General View	 Load JPG	☒
70	30/07/18 20:28	General View	 Load JPG	☒
71	30/07/18 20:28	General View	 Load JPG	☒
72	30/07/18 20:28	General View	 Load JPG	☒
73	30/07/18 20:28	General View	 Load JPG	☒
74	30/07/18 20:28	General View	 Load JPG	☒
75	30/07/18 20:28	General View	 Load JPG	☒
76	30/07/18 20:28	General View	 Load JPG	☒
77	30/07/18 20:28	General View	 Load JPG	☒
78	30/07/18 20:28	General View	 Load JPG	☒
79	30/07/18 20:28	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
80	30/07/18 20:28	General View	 Load JPG	☒
81	30/07/18 20:28	General View	 Load JPG	☒
82	30/07/18 20:28	General View	 Load JPG	☒
83	30/07/18 20:28	General View	 Load JPG	☒
84	30/07/18 20:28	General View	 Load JPG	☒
85	30/07/18 20:28	General View	 Load JPG	☒
86	30/07/18 20:28	General View	 Load JPG	☒
87	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
88	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
89	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
90	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
91	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
92	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
93	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
94	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
95	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
96	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
97	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
98	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
99	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
100	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
101	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
102	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
103	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
104	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
105	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
106	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
107	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
108	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
109	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
110	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
111	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
112	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
113	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
114	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
115	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
116	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
117	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
118	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
119	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
120	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
121	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
122	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
123	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
124	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
125	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
126	31/07/18 18:25	Reinspection Photo	Load JPG	☒
127	31/07/18 18:25	Reinspection Photo	Load JPG	☒
128	31/07/18 18:25	Reinspection Photo	Load JPG	☒
129	31/07/18 18:25	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
130	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
131	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
132	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
133	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
134	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
135	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
136	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
137	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
138	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
139	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
140	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
141	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
142	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
143	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
144	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
145	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
146	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
147	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
148	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
149	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
150	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
151	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
152	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
153	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
154	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
155	31/07/18 18:25	Reinspection Photo	 Load JPG	☒
156	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
157	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
158	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
159	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
160	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
161	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
162	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
163	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
164	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
165	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
166	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
167	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
168	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
169	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
170	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
171	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
172	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
173	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
174	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
175	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
176	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
177	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
178	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
179	05/08/18 10:02	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
180	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
181	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
182	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
183	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
184	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
185	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
186	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
187	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
188	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
189	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
190	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
191	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
192	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
193	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
194	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
195	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
196	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
197	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
198	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
199	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
200	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
201	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
202	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
203	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
204	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
205	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
206	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
207	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
208	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
209	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
210	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
211	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
212	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
213	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
214	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
215	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
216	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
217	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
218	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
219	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
220	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
221	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
222	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
223	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
224	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
225	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
226	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
227	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
228	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
229	05/08/18 10:02	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
230	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
231	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
232	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
233	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
234	05/08/18 10:02	Reinspection Photo	 Load JPG	☒
235	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
236	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
237	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
238	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
239	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
240	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
241	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
242	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
243	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
244	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
245	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
246	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
247	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
248	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
249	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
250	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
251	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
252	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
253	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
254	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
255	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
256	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
257	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
258	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
259	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
260	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
261	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
262	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
263	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
264	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
265	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
266	05/08/18 10:03	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	24/07/18 16:48	Audatex Report	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/18 11:00	SDA8969A e-file report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/01/19 12:16	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18013779/UVD3E2

Date: 03/01/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29069766MKF

Claimant Vehicle No: SDA8969A

Insured Vehicle No: SLL6156P

Date of Loss: 23/07/2018

Nature of Claim: TP

Claim No: 565505

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDA8969A

Make & Model: MERCEDES-BENZ E200, 2.0 (A)

Engine No: 27492030161115

Reg. Date: 02/06/2014 (Man. Year: 2014)

Chassis No: WDD2120342A987860

Colour: Grey

Odometer: 55406 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R17

Rear Tyre Size: 245/45 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,855.20	14,849.95	7,005.25	32.05
Miscellaneous Items	1,495.61	1,170.00	325.61	21.77
Paintwork Materials	247.24	247.61	-0.37	-0.15
Labour	1,535.00	1,260.00	275.00	17.92
Paintwork Labour	505.00	505.00	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,638.05	18,032.56	7,605.49	29.66
+ GST 7.00/7.00% (S\$)	1,794.67	1,262.28	532.39	29.67
Nett Amount (S\$)	27,432.72	19,294.84	8,137.88	29.66

INSPECTION

Date of Assignment: 30/07/2018 Present Location:

Kan Fook Sing Motor Workshop (Defu)

Date Inspected: 30/07/2018 Inspected At:

Kan Fook Sing Motor Workshop (Defu)

No. 61 Defu Lane 12

Singapore 539147

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts: 143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDA8969A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS (WCP)		19,110.70 F	*10,168.50 F
Supplementary #1						
2	1		*PARTS (WCP)		2,744.50 F	*2,744.50 F
F=Franchise part.						
Sub Total (S\$)					21,855.20	12,913.00
+ Margin on L,N Items 0.00/15.00% (S\$)					0.00	1,936.95
Total Parts (S\$)					21,855.20	14,849.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	PAINTWORK MATERIALS	247.24	247.61
<u>Miscellaneous Items</u>				
2	1	MISCELLANEOUS	375.00	50.00
<u>Supplementary #1</u>				
3	1	MISCELLANEOUS	1,120.00	1,120.00
4	1	PAINTWORK MATERIALS	0.61	0.00
Sub Total (S\$)			1,742.85	1,417.61

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAYPAINTING CHARGES	New	505.00	505.00
<u>Labour Items</u>				
2	LABOUR CHARGES	New	1,520.00	1,245.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	SPRAY PAINTING CHARGES	New	15.00	15.00
Gross Labour Cost (S\$)			2,040.00	1,765.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >