

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05824

Vehicle Insured : PC3304Z

Accident Date : 26-Jul-2018

Date : 27-Jul-2018

Our Ref : 218129 (III) / CHAN

PAGE : 1

Q & F LEASING
10 WOODLEIGH CLOSE
#01-05
Singapore 357905

*Not Authorised
Resurvey By pain
1.B.1
2 days*

ESTIMATED COST OF REPAIR FOR M/BENZ S400 HYBRID 3.0 SLE480D

=====

1 pc Front bumper fascia	<i>Br</i> 2,019.00	✓
1 pc Frt n/s bumper parking sensor	306.00	?
1 pc N/s headlamp	<i>cms</i> 6,280.00	✓
1 pc N/s headlamp lower bracket	300.00	?

8,905.00

Less 10% : 890.50

8,014.50

To rewire damaged parts and refocus
headlamp beam, programme & reset

380.00 *12cl*

To putty and spray replaced parts

450.00 *30cl*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500.00 *30cl*

Total : S\$ 9,344.50

=====

Singapore Dollars Nine Thousand Three Hundred
and Forty Four and Cents Fifty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: