

INSURANCE

INS. CASE OWNER

CC 6 / AIG1801 7809, 11/20/18 LKK: 11/20/18

Surveyor:

MARMS

DOE:

ASSIGNMENT

7/0/18

Date / Time:

20/7/18

Registered in Meritmen:

20/7/18

Pre-assign / CCU / FTE

SEQ 6775A

3755826866



Insured Vehicle No.:

Name of Insured:

DANLEE FLEET MANAGEMENT

Claim No.:

Policy No.:

999999580

Insured Tel No.:

HP:

D.O.A.:

16/7/18

Make / Model:

Bmw

Place of Accident:

9100000 RV

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

DELEEN EMMANUEL

(V/L: YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

STD 800P



INSRS:
WSP:
Tel:
Liability:
RMKS:

Tan
Lim



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time:

1/8/18
20/7/18

SHAWN OF AIG CALLED
& CLEARED OI

RECEIVED 1 SEP 2018

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

20/7/18

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

UTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

days (Reduction):

%

FINAL SETTLEMENT

Date/Time:

Confirm with:

JOHNSON

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

SS

3,317

Loss of Rental (LOR):

SS

60.4

days:

Loss of Use (LOU):

SS

240

days:

Loss of Income (LOI):

SS

7.49

days:

LOR only

LOU only

SS

LOR + LOU

LOR + LOI

[Tick only one]

GIA/TA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Travel Independent)

Legal Cost:

SS

3,564.49

Total:

SS

3,564.49

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS

3,564.49

Name 1:

TAN LIM MOTOR PRE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

H2K
01 BEH/2/18

ASSIGNMENT

From: Date: 30-07-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJD 8024P

at Workshop n/s Tan Lim

of 51 Defu lane 10

Insured: SKQ6335A

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8281

IDAC Accident Report: Consistent? : Yes or No

CA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

3608A

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJD 8024P Yr Regn: 4 of

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Honda civic cc 1595

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 199185 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMF0452085201188

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

L/Bal: 6 mm D.O.A: 16/7/18 D.O.I: 30/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 18465

31/3/2023

30/7/18 CONFIRMED R/S @ 3100 with Lerner

R (3,299.66/527.)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$

Survey Fee:

Transportation:

\$ - RS. \$

Photo:

Other:

Report Format :

Lump Sum / I.B.I: (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18013809/Ujb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 30-07-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 6335A	Veh. Inspected	SJD 8024P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/07/2018	Inspection Date	30/07/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Date of Accident : 16 July 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Yap Foong Yeng (Ye Fengying)

Date : 30 July 2018

Confirmed with
marcus 36.07.14

Estimate To Repair SJD8024P - Honda Civic 1.6L VTI 5MT

Chassis No : JHMFD45208S201188

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid <i>2/3 set</i>	\$ 596.00
02	1 pc	bootlid civic badge <i>neu</i>	\$ 35.80
03	1 pc	bootlid 1.6 VTec badge <i>neu</i>	\$ 45.80
04	2 pc	bootlid reflector @ \$199.20 <i>n/scre</i>	\$ 398.40
05	1 pc	bootlid centre emblem badge <i>neu</i>	\$ 27.80
06	1 pc	bootlid weatherstrip <i>neu</i>	\$ 121.00
07	1 pc	bootlid inner trim cover <i>11</i>	\$ 90.00
08	4 pc	bootlid inner trim cover clips @ \$3.50 <i>11</i>	\$ 14.00
09	2 pc	bootlid inner bracket/stopper @ \$16.20 <i>11</i>	\$ 32.40
10	1 pc	bootlid inner lock <i>neu</i>	\$ 70.80
11	1 pc	bootlid inner lock stricker <i>11</i>	\$ 19.70
12	1 pc	rear end panel <i>neu 306.00</i>	\$ 399.60
13	1 pc	rear end panel inner trim <i>neu</i>	\$ 99.70
14	2 pc	rear bumper side retainer @ \$22.20 <i>neu</i>	\$ 44.40
15	8 pc	rear bumper clips @ \$3.50 <i>neu</i>	\$ 28.00
16	1 pc	rear bumper screw spacer <i>neu</i>	\$ 12.50
17	2 pc	rear lamp @ \$297.80 <i>n/scre</i>	\$ 595.60
18	4 pc	rear lamp clip holder @ \$8.50 <i>11</i>	\$ 34.00
19	1 pc	rear luggage floor trimboard <i>11</i>	\$ 129.70
20	2 pc	rear license plate lamp @ \$28.20 <i>11</i>	\$ 56.40
21	1 pc	rear bumper <i>202</i>	\$ 638.00
			\$ 3,489.60
<u>SPECIAL NETT ITEMS</u>			
22	1 pc	rear bumper parking sensor <i>shock</i>	\$ 450.00
23	1 pc	rear license plate <i>11</i>	\$ 80.00
			\$ 530.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To check electrical lighting concerned.	\$ 60.00
05		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SKQ6335A

Date of Accident : 16 July 2018

Miss Yap Foong Yeng (Ye Fengying)

Date : 30 July 2018

Estimate To Repair SJD8024P - Honda Civic 1.6L VTI 5MT

Chassis No : JHMFD45208S201188

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion.	\$ 850.00 \$ 2,380.00
		Total	\$ 6,399.60

3878.24
3102.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

2516-30
2608.24

3878.24

3102.59.

Joy Irene (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, 30 July 2018 4:43 PM
To: 'Wui, Shawnkaijie'; Joy Irene (LKKAuto)
Cc: Admin A; assignments
Subject: RE: Case Assignment TP - SJD8024P - 16/07/2018 -

Dear Shawn,

Thank you for your email.

Dear Joy,

FYNA. Our Ref: CC6/AIG18013809/Ujb3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wui, Shawnkaijie [mailto:Shawnkaijie.Wui@aig.com]
Sent: Monday, 30 July, 2018 4:28 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: Case Assignment TP - SJD8024P - 16/07/2018 -

Dear Sirs,

We refer to aforementioned case.

Please be informed that OI ack accident liability as OID has involved in another similar accident on 16 July 2018.

Please don't clear OI again.

Thanks and Regards,
Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijie.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Do-Not-Reply [<mailto:do-not-reply@merimen.com>]
Sent: Monday, July 30, 2018 4:20 PM
To: Wui, Shawnkaijye
Subject: Case Assignment TP - SJD8024P - 16/07/2018 -

This mail is associated with :
***SJD8024P (3355822886SG)**
[SKQ6335A]
TP

-
Jul 16 2018 12:00AM

Tan Lim Motor Pte Ltd

Dear Wui, Shawn-KJ,

Please note that a claim has been assigned to you for handling in Merimen. For your action and follow up please.

This is an auto-generated email. Do not reply to this email.

Sent by : Wui, Shawn-KJ (AIG Asia Pacific Insurance Pte. Ltd.)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP022072018

Date 23/08/18

Your Ref SKQ6335A

WITHOUT PREJUDICE

Claims Department - Executive in charge _____

AIG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SJD8024P / SKQ6335A on 16.07.18

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- | | |
|-------------------------------------------------------------------------------------|---------------------------------------------------------------|
| <input type="checkbox"/> Original survey report / _____ copies of photographs _____ | <input type="checkbox"/> Original rental invoice number _____ |
| <input checked="" type="checkbox"/> Original Tax-invoice number <u>TP08181015</u> | <input type="checkbox"/> police result |
| <input type="checkbox"/> SAS / AS & IS / police report | <input checked="" type="checkbox"/> Vehicle search result |
| <input type="checkbox"/> Certificate Of Insurance _____ | <input type="checkbox"/> _____ |
| <input checked="" type="checkbox"/> Authorization to act | |

* Survey under insurance instruction / Independent surveyor / No survey.

<u>LKR</u>	
a) Cost of repair (inclusive GST)	\$ <u>3,317.00</u>
b) Survey fees / Photographs as per request	\$ <u>-</u>
c) Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
d) Loss of hire / use / rental / earnings / rental fees	\$ <u>320.00</u>
e) Scene photographs	\$ <u>-</u>
f) Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g) _____	\$ _____
Total	\$ <u>3,644.49</u>
	=====

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 31 August 2018 11:57 AM
To: 'faizal.mohamed@daimler.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING SKQ 6335A AND SJD 8024P ON 16/07/2018

OUR REF: LKK: CC6/AIG18013809/Ujb3

DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING SKQ 6335A AND SJD 8024P ON 16/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party. Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Yap Foong Yeng (Ye Feng Ying) ("the third party claimant")
of 21 Fernvale Lane #11-25 Singapore 797500 (address),
owner of SJD8024P (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJD8024P that was
damaged pursuant to the accident which occurred on 16.07.2018 (date) along
Taxi stand of Faragon Shopping Centre (location)
involving vehicle no/s 8KQ6335A ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 01 day of 08 (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,317.00 (Repair Cost), S\$240.00 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. SJD 8024P that was damaged pursuant to the accident which occurred on 16/07/2018 (date) along TAXI STAND OF PARAGON SHOPPING CENTRE (location) involving vehicle no/s SKQ 6335A. This is pursuant to the inspection conducted on 30/07/2018 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner YAP FOONG YENG (YE FENGYING) ("the third party claimant") of vehicle no. SJD 8024P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJD 8024P (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 31st (day) of August (month) 2018 (year)


Signed by appointed surveyor


Signed by "the workshop" (with chop)



"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0818/015

(Please quote our reference number TP022072018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Yap Foong Yeng (Ye Fengying)

Date: 13/08/2018

Vehicle No: SJD8024P
Model: HONDA CIVIC 1.6 L

Description	Amount
To lump sum repair as recommended by surveyor.	\$3,100.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$3,107.00
Add 7% GST	\$217.49
Total	\$3,324.49

Tan Lim Motor Pte Ltd

Enquire Vehicle & Owner Information (Vehicle No. SKQ6335A As At 16 Jul 2018 / 21:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: 5JD8024P

Current Owner Details

Owner ID Type: Company
Owner ID: 199803778Z
Owner Name: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 1
Registered Street Name: GATEWAY DRIVE
Registered Unit No.: # 15 - 08
Registered Building Name: WESTGATE TOWER
Registered Postal Code: 608531

Current Vehicle Details

Vehicle No.: SKQ6335A
Make Description/Model: B.M.W. / X3 SDRIVE 20i LED 5R NAV
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018 Edit Reg		30 Jul 2018 00:00 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD., Co. Reg. No.: 1998037782									
Main Claimant: YAP FOONG YENG (YE FENGYING), ID: 57243609A									
Vehicle Reg. No.: SJD8024P		Date of Loss: 16/07/2018 22:00 - :59 [123 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3355822886SG		Policy/Cover Note No.: 0999994749 (Comprehensive)							
Vehicle Reg. No. (Insured): SKQ6335A		Policy No. (Claimant): 2018-V0103871-VAW							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wul, Shawn-KJ] Shawnkaijie.Wul@aig.com									
Claimant's Insurer: Great American Insurance Company (HQ) - Tel: 6804 6047									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/08/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (31/07/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD8024P (3355822886SG)
[SKQ6335A]

TP

































YAP FOONG YENG (YE FENGYING)

Jul 16 2018 10:00PM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tan Lim Motor Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page 1 <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit	
Photos/Images						3 per page 3 <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
2	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
3	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
4	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
5	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
6	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
7	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
8	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
9	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
10	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
11	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
12	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
13	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
14	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
15	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
16	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
17	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
18	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
19	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
20	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
21	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
22	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
23	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
24	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
25	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
26	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
27	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
28	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
29	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
30	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
31	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
32	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
33	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	
34	10/08/18 08:04	General View				<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/08/18 08:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/08/18 08:04	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/07/18 18:52	TP ESTIMATE- MARKED	 Load PDF	
2	31/07/18 18:52	TP GIA REPORT	 Load PDF	
3	31/08/18 17:39	LETTER TO INSURED	 Load PDF	
4	19/09/18 10:56	WORKSHOP INVOICE	 Load PDF	
5	19/09/18 10:56	AUTHORISATION TO ACT FORM	 Load PDF	
6	19/09/18 10:56	Release Voucher	 Load PDF	
7	19/09/18 10:56	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/07/18 14:44	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKQ6335A (Insd veh)	Model:	HONDA CIVIC 1.6 VTI (A)
	SJD8024P (TP veh)		
Date of Accident:	16/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,847.57
Final Repair Cost	:	\$	3,317.00
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,564.49

4.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 3,564.49
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

19 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18013809/UJB3Q2

Date: 19/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994749

Claimant Vehicle No : SJD8024P

Insured Vehicle No : SKQ6335A

Date of Loss: 16/07/2018

Nature of Claim:

TP

Claim No: 3355822886SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD8024P**

Make & Model: HONDA CIVIC, 1.6 VTi (A)

Engine No: R16A13003606

Reg. Date: 03/04/2008 (Man. Year: 2008)

Chassis No: JHMF45208S201188

Colour: White

Odometer: 199185 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,019.60	2,208.24	1,811.36	45.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,670.00	710.00	29.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,399.60	3,878.24	2,521.36	39.40
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	6,399.60	3,100.00	3,299.60	51.56
+ GST 7.00/7.00% (S\$)	447.97	217.00	230.97	51.56
Nett Amount (S\$)	6,847.57	3,317.00	3,530.57	51.56
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,564.49		

INSPECTION

Date of Assignment: 30/07/2018

Date Inspected: 30/07/2018

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

51 Defu Lane 10

Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	596.00 F	*596.00 FL
2	1		*BOOTLID CIVIC BADGE	Necessary	35.80 F	*35.80 FL
3	1		*BOOTLID 1.6 VTEC BADGE	Necessary	45.80 F	*45.80 FL
4	1		*BOOTLID REFLECTOR	N/S Cracked	398.40 F	*199.20 FL
5	1		*BOOTLID CENTRE EMBLEM BADGE	Necessary	27.80 F	*27.80 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	121.00 F	*121.00 FL
7	1		*BOOTLID INNER TRIM COVER	Not Necessary	90.00 F	*- FL
8	4		*BOOTLID INNER TRIM COVER CLIPS	Not Necessary	14.00 F	*- FL
9	1		*BOOTLID INNER BRACKET /STOPPER	Not Necessary	32.40 F	*- FL
10	1		*BOOTLID INNER LOCK	Twisted	70.80 F	*70.80 FL
11	1		*BOOTLID INNER LOCK STRIKER	Not Necessary	19.70 F	*- FL
12	1		*REAR END PANEL	Dented	399.60 F	*306.00 FL
13	1		*REAR END PANEL INNER TRIM	Twisted	99.70 F	*99.70 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	44.40 F	*44.40 FL
15	8		*REAR BUMPER CLIPS	Necessary	28.00 F	*28.00 FL
16	1		*REAR BUMPER SCREW SPACER	Not Necessary	12.50 F	*- FL
17	1		*REAR LAMP	N/S Cracked	595.60 F	*297.80 FL
18	4		*REAR LAMP CLIP HOLDER	Not Necessary	34.00 F	*- FL
19	2		*REAR LICENSE PLATE LAMP	Not Necessary	56.40 F	*- FL
20	1		*REAR LUDDAGE FLOOR TRIMBOARD	Not Necessary	129.70 F	*- FL
21	1		*REAR BUMPER	Distorted	638.00 F	*638.00 FL
22	1		*REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
23	1		*REAR LICENSE PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	4,019.60	2,710.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	502.06
Total Parts (\$\$)	4,019.60	2,208.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	180.00	80.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	900.00	600.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	800.00
Gross Labour Cost (\$\$)			2,380.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >