



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SKQ6335A
Date of Accident : 16 July 2018

Miss Yap Foong Yeng (Ye Fengying)

Date : 30 July 2018

Estimate To Repair SJD8024P - Honda Civic 1.6L VTI 5MT
Chassis No : JHMFD45208S201188

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid <i>D/seat</i>	\$ 596.00
02	1 pc	bootlid civic badge <i>nu</i>	\$ 35.80
03	1 pc	bootlid 1.6 VTec badge <i>nu</i>	\$ 45.80
04	2 pc	bootlid reflector @ \$199.20 <i>n/scre</i>	\$ 398.40
05	1 pc	bootlid centre emblem badge <i>nu</i>	\$ 27.80
06	1 pc	bootlid weatherstrip <i>nu</i>	\$ 121.00
07	1 pc	bootlid inner trim cover <i>nu</i>	\$ 90.00
08	4 pc	bootlid inner trim cover clips @ \$3.50 <i>nu</i>	\$ 14.00
09	2 pc	bootlid inner bracket/stopper @ \$16.20 <i>nu</i>	\$ 32.40
10	1 pc	bootlid inner lock <i>nu</i>	\$ 70.80
11	1 pc	bootlid inner lock stricker <i>nu</i>	\$ 19.70
12	1 pc	rear end panel <i>306.00</i>	\$ 399.60
13	1 pc	rear end panel inner trim <i>nu</i>	\$ 99.70
14	2 pc	rear bumper side retainer @ \$22.20 <i>nu</i>	\$ 44.40
15	8 pc	rear bumper clips @ \$3.50 <i>nu</i>	\$ 28.00
16	1 pc	rear bumper screw spacer <i>nu</i>	\$ 12.50
17	2 pc	rear lamp @ \$297.80 <i>n/scre</i>	\$ 595.60
18	4 pc	rear lamp clip holder @ \$8.50 <i>nu</i>	\$ 34.00
19	1 pc	rear luddage floor trimboard <i>nu</i>	\$ 129.70
20	2 pc	rear license plate lamp @ \$28.20 <i>nu</i>	\$ 56.40
21	1 pc	rear bumper <i>D/S</i>	\$ 638.00
			\$ 3,489.60
<u>SPECIAL NETT ITEMS</u>			
22	1 pc	rear bumper parking sensor <i>shubh</i>	\$ 450.00
23	1 pc	rear license plate <i>nu</i>	\$ 80.00
			\$ 530.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To check electrical lighting concerned.	\$ 60.00
05		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 120.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00

*not Acknowled
able
L/S \$ 3102/-
L/S photo after repair
30/7/18
4dy.*

*confirmed with
marcus 30.7.18
f*

202

*25103
2008.24*

*200
X*

*50
80
60
20
60
600*

AlGAsia Insured's Veh No : SKQ6335A
Date of Accident : 16 July 2018



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Yap Foong Yeng (Ye Fengying)

Date : 30 July 2018

Estimate To Repair SJD8024P - Honda Civic 1.6L VTI 5MT
Chassis No : JHMFD45208S201188

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u> Putty and spray painting of the affected portion.	\$ 850.00
			\$ 2,380.00
		Total	\$ 6,399.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2516-30

2608.24

3878.24

3102.59.