

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5768G**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BOOT	BENT	1,680.00	1,680.00
1	REAR BOOT LOGO	NECESSARY	56.00	56.00
1	REAR BOOT LOGO (ELANTRA)	NECESSARY	74.00	74.00
1	REAR BOOT LOCK (NPA)	NOT NECESSARY	-	-
1	REAR BOOT CATCH (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER	DEFORMED	659.00	659.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR LIGHT RH	NOT NECESSARY	69.00	-
1	REAR BUMPER REFLECTOR LIGHT LH (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER LOWER GARNISH	CUT	351.00	351.00
1	REAR REINFORCEMENT	BENT	353.00	353.00
2	REAR BUMPER RETAINER L+R (NPA)	NOT NECESSARY	-	-
	LESS 20% DISCOUNT		-658.40	-644.60
			2,633.60	2,578.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR (SN)	NOT WORKING	250.00	200.00
			250.00	200.00
	<b><u>LABOUR</u></b>			
	TO REPAIR REAR END PANEL, REAR SPARE TYRE HOUSE AND REALIGN AFFECTED AREAS. TO REMOVE & REPLACE ALL ACCIDENT AFFECTED AREAS.		450.00	300.00
	TO SPRAY PAINT AFFECTED AREAS.		500.00	400.00
	TO RUST PROOF AFFECTED AREAS.		40.00	30.00
	TO INSPECT REAR TAILLAMP WATER LEAKAGE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR PARKING SENSOR & CHECK WIRING.		60.00	30.00
			1,130.00	760.00
	<b>GRAND TOTAL</b>		<b>4,013.60</b>	<b>3,538.40</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,800.00</b>

Report Ref No. CS/SMO18013813/T1vd3e2



Report Ref No. CS/SMO18013813/T1vd3e2

A handwritten signature in black ink, appearing to read 'Taufikh'.

**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

A handwritten signature in black ink, appearing to read 'A.L.P.'.

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.