

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1811P
 Ref. No : TAX/07/18/2126
 Reg. Date : 16/10/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : HO SENG HUAT
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 26/07/2018 05:40:00 PM
 Accident Reported Date / Time : 27/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097241
 Special Instruction to ARC, if any :
 SKS9082Z
 Prepared Date : 27/07/2018 09:32:53 AM



4 Days.
 part by part.
 After paint photos.
 Gene Ring - 888082
 27/7/18

LK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U005766223

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,052.00	0.00
Total Material Charges	: 5,853.44	5,853.44
Other Charges	: 1,185.00	0.00
TOTAL	: 10,104.44	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 27/07/2018 04:26:10 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/07/2018 04:24:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 50
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 X NN
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X NN
Total Spray Painting & Panel Beating	2,052.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X NN
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO TRANSFER DOOR MECHANISM	240.00	0.00 X
Total Other Costs	1,185.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67002-47070		6505529	DOOR FRT/LH <i>X repair</i>	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR) <i>/ MC</i>	1	60.00	0.00	60.00	Replace	Replace	No
87940-47310		6505599	MIRROR ASSY, LH <i>X NN</i>	1	1,224.90	25.00	918.67	Replace	Replace	No
87945-74010		6505597	COVER, OUTER MIRROR, LH <i>X repair</i>	1	107.40	25.00	80.55	Replace	Replace	No
75852-47900			MOULDING BODY, LH <i>X NN</i>	1	673.60	25.00	505.20	Replace	Replace	No
69210-74030			DOOR OUTER HANDLE FRT/LH <i>X</i>	1	370.80	25.00	278.10	Replace	Replace	No
69217-74010			COVER, FRONT DOOR OUTSIDE HANDLE <i>X</i>	1	14.10	25.00	10.57	Replace	Replace	No
67004-47080		6505487	DOOR RR/LH <i>X repair</i>	1	954.50	25.00	715.87	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH <i>X repair</i>	1	766.80	25.00	575.10	Replace	Replace	No
	COMMON		SMRT LOGO <i>/ MC</i>	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888 <i>/ MC</i>	1	21.60	0.00	21.60	Replace	Replace	No
		6503707	TYRE <i>X</i>	1	126.74	0.00	126.74	Replace	Replace	No
42611-47140		6505658	WHEEL, DISC <i>X NN</i>	1	1,490.20	25.00	1,117.65	Replace	Replace	No
52159-47905		6505548	BUMPER REAR <i>X repair</i>	1	458.60	25.00	343.95	Replace	Replace	No
52592-47021			BUMPER SEAL, RR LH <i>X NN</i>	1	88.90	25.00	66.67	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH <i>X NN</i>	1	94.80	25.00	71.10	Replace	Replace	No
			PIXEL STICKER <i>/ MC</i>	2	60.00	0.00	120.00	Replace	Replace	No
62720-47031			QUARTER GLASS RR/LH <i>X NN</i>	1	168.10	25.00	126.07	Replace	Replace	No
	COMMON		SEALANT W/SCREEN <i>X NN</i>	1	37.00	0.00	37.00	Replace	Replace	No
TOTAL MATERIALS								5,853.47	5,853.44	
TOTAL MATERIALS(Discounted)								5,853.44	5,853.44	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									