

COMFORTDELGRO ENGINEERING PTE LTD

AIG

REPAIR ESTIMATE*

VEHICLE NO : SH 8099X

DATE 27/7/2018 9:07

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>cut</i>			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips <i>✓</i>			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover <i>X</i>			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70 Nett
	Rear Bumper Rubber Mat <i>✓</i>			\$ 50.00 Nett
	Rear Bumper Advertisement Logo <i>✓</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH) <i>✓</i>		\$ 100.00	\$ 200.00 Nett
				\$ 435.70
	Labour Charge			<i>200</i>
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>30</i>
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,731.58

Kalari 16/8/18
27/7/18 1035h
2 hrs.
45
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.