

ASS. REC. BY:

REF:

CS/MSG18013831/711231

Word Instruction:

Surveyor

menmen

From (Person):

Jacelyn Ng

of

MSG

Date/Time:

30/7/18 @ 3:44pm

Estimated Cost:

Bill to:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV / ☐ CS

To Inspect Vehicle No.:

SLG 4112 E

Insured:

at Workshop m/z

Hitachi Capital

Tel:

6466 3022

of

No. 8 Fourth Lok Yang Road

Policy No.:

MSD 1VPCP/18-000756-00

Claim No.:

MSC/V/18-001020

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

(Client's Record)

D.O.A.

26/7/2018

CA / ☒ REV /

REP. / REV 24 HRS

31/7/18 @ Morning

H.O.D. Endorsement:

Date/Time:

4:09pm @ 30/7/18

Person Contacted:

Ms. Vann

Vehicle:

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 4112 E - X
01/8/18 @ 5:34pm	revert to Jacelyn Ng via menmen.
02/8/18 @ 9:23pm	Kong eng informed C/A via menmen.
03/8/18 @ 9:43pm	informed Vann C/A & ex: \$1500 by email.
16/8/18 @ 3:26pm	confirmed with Vann final Ag \$2237.46, 4 days by email. (Red \$1486.72, 40%)

Driver: Taylor

REF:

ms16

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$1500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$7500

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 4112E Yr Regn: 2016 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis cc 1598

Colour: Blue A/C: Insured / Std / NI / NA

Sp Reading: 123588 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053REH104557298

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Franken

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. _____ D.O.I. 1/8/18 4pm

Survey held at Hatchi Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/8

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$ _____

Photos

Others

TOTAL

Report Format : MBR-00

Lump Sum / I.B.I: (\$ 2237.46)

150
10
160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18013831/T1qd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 30-07-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLG 4112E
Policy No.	MSD/VPCP/18-000756-00	Coverage (\$)	0.00
Claim No.	MSC/V/18-001020	Excess (\$)	1,500.00
Assign From	MERIMEN (JOCELYN NG)	Assign Date	30/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/07/2018	Inspection Date	01/08/2018
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018 14:34 Sendback Est	30 Jul 2018 14:35 S\$3,724.38	30 Jul 2018 15:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N, Tel: +6597108392		
Vehicle Reg. No.:	SLG4112E	Date of Loss:	26/07/2018 18:00 - :59 [21 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	MSD/VPCP/18-000756-00 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019
		Excess:	S\$1,500.00
Repairer:	Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/07/2018]		
Driver/Custodian:	LAM TONG SIONG (53 / Male), NRIC: S2699042D, Tel: +6581802080		
Adj Asg. Remarks:	Car In, pls survey and revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Thursday, 16 August 2018 3:26 PM
To: Shiau Chan (LKKAUTO); 'sur@lkkauto.com'; Taufikh (LKKAUTO)
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: RE: SLG4112E DOA: 26/7/2018 FINALIZATION

Hi Shiau Chan,

Thank you for the attachment.

We accept the COR at \$2,237.46 before excess \$1,500.00 & GST and 4 repair days.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6274
e: vonnlm.siow@hcspl.com.sg
w: www.hitachi-capital.com.sg

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, August 16, 2018 3:09 PM
To: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>; 'sur@lkkauto.com'; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SLG4112E DOA: 26/7/2018 FINALIZATION

Dear Vonn,

As per your requested.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Thursday, 16 August 2018 3:02 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; 'sur@lkkauto.com'; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: RE: SLG4112E DOA: 26/7/2018 FINALIZATION

Dear Shiau Chan,

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 2 August 2018 9:43 AM
To: Vonn, LM Siow; 'sur@lkkauto.com'
Cc: Jamilah, Binte MohdKassim; JiongHow, Ng
Subject: RE: SLG4112E DOA:26/7/2018 MSIG OD Pending approval

Dear Vonn,

As instructed by our client MSIG Insurance, please proceed to repair the insured vehicle **SLG 4112E (excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vonn, LM Siow <vonnlm.siow@hcspl.com.sg>
Sent: Wednesday, 1 August 2018 5:30 PM
To: 'sur@lkkauto.com'
Cc: Jamilah, Binte MohdKassim <jamilahbegum@hcspl.com.sg>; JiongHow, Ng <jionghow.ng@hcspl.com.sg>
Subject: SLG4112E DOA:26/7/2018 MSIG OD Pending approval

Dear sirs,

The above mentioned vehicle has surveyed by Mr Taufikh at 4pm today.

Kindly follow up on the authorisation to repair for us.

Please do not hesitate to contact us if you need any more documents.

Thanks & Regards

Vonn Siow
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705
t: 6833 6274

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	30 Jul 2018 14:27	Clim Veh Model Changed	(204463) TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A).	[R] Vonn Siow Lie Mien
2	30 Jul 2018 14:27	Clim Created	Reg No: SLG4112E, Policy No: MSD/VPCP/18-000756-00, Acct Date: 2018/07/26, Claim Type: OD, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Hitachi Capital Asia Pacific Pte. Ltd (HQ). Created from SAS:MJT118097318	[R] Vonn Siow Lie Mien
3	30 Jul 2018 14:35	Clim Submitted	3724.38.	[R] Vonn Siow Lie Mien
4	30 Jul 2018 15:21	Clim Registration Modified	Excess: -> 1500.00.	[I] Jocelyn Ng Shin Bun
5	30 Jul 2018 15:22	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):A IF C	[I] Jocelyn Ng Shin Bun
6	30 Jul 2018 15:22	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/07/31	[I] Jocelyn Ng Shin Bun
7	30 Jul 2018 15:22	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
8	30 Jul 2018 15:22	Assignment 1st Accessed		[A] Crystal Lee
9	30 Jul 2018 15:44	Adj Assignment Cancelled	Car in, IHS unable to attend (KL, FT & ET - Appt Full, AL - Medical excused from survey).	[I] Pauline Soh Li Ping
10	30 Jul 2018 15:44	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Pauline Soh Li Ping
11	30 Jul 2018 15:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Car in, pls survey and revert	[I] Pauline Soh Li Ping
12	30 Jul 2018 15:44	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/07/31	[I] Pauline Soh Li Ping
13	30 Jul 2018 15:44	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Pauline Soh Li Ping
14	30 Jul 2018 15:55	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	30 Jul 2018 16:48	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
16	01 Aug 2018 17:25	Adj Rpt Initiated		[A] SHIAU CHAN
17	01 Aug 2018 17:33	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/08/29	[A] SHIAU CHAN
18	01 Aug 2018 17:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/29	[A] SHIAU CHAN
19	01 Aug 2018 17:34	Adj Mandate Request	Cur.Req:2778.96:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE N OT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	02 Aug 2018 09:23	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/29. Mandate Remarks: a if c	[I] Keny Ong Thiam Beng
21	02 Aug 2018 09:23	Adj Mandate Set	Approved:2778.96:a if c	[I] Keny Ong Thiam Beng

Date From



Date To



Audit Type

None

Go

ACTIVITY

[30/07/2018 15:43] Pauline Soh Li Ping:
Car in, IHS unable to attend (KL, FT & ET - Appt Full, AL - Medical excused from survey).
[30/07/2018 15:24] Crystal Lee:
Jlong How confirmed car in.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1873203	30/07/2018 14:27	Motor	Hitachi Capital Asia Pacific Pte. Ltd	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	SLG4112E		xx.xx
1877228	01/08/2018 17:25	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLG4112E		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 01 Aug 2018

Preliminary Advice

Vehicle No	: SLG4112E	Accident Date	: 26/07/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MSD/VPCP/18-000756-00
Assignment Date	: 30/07/2018	Excess	: S\$1,500.00
Date of Inspection	: 01/08/2018	Est. Duration of Repair	: 5.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,724.38
Revised Amount	:S\$	2,266.36
Check Items (Estimated)	:S\$	512.60
Total	:S\$	2,778.96

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	54,620.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,380.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0399N
Vehicle Details	
Vehicle No.:	SLG4112E
Vehicle to be Exported:	No
Intended De-registration Date:	01 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1ZRX591955
Chassis No.:	MR053REH104557298
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$16,800.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2026
PARF Rebate Amount:	\$12,600.00
Intended COE Rebate Details	
COE Expiry Date:	28 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$42,020.00
Total Rebate Amount:	\$54,620.00

The information contained herein is correct as at 01 Aug 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	0399N

Vehicle Details

Vehicle No.:	SLG4112E
Vehicle to be Exported:	No
Intended De-registration Date:	22 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	12RX591955
Chassis No.:	MR053REH104557298
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,800.00
Original Registration Date:	29 Sep 2016
First Registration Date:	29 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$16,800.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Sep 2026
PARF Rebate Amount:	\$12,600.00

Intended COE Rebate Details

COE Expiry Date:	28 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$41,719.00
Total Rebate Amount:	\$54,319.00

The information contained herein is correct as at 30 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2018 17:48
Date Of Accident	26/07/2018 18:00
Exact Location Of Accident	BLK 936 JURONG WEST ST 91 CAR APRK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4112E
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	JUNTAIYO@HCSPL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64663022

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MSD/VPCP/18-000756-00
Cover Note Number	

Driver

Name of Driver	LAM TONG SIONG
NRIC No	S2699042D
Date Of Birth	09/07/1965
Occupation	OUTDOOR
Date Of Driving Pass	30/01/2015
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81802080
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27/7/18 2:52pm




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Refer to police report T/20180726/2148.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Driver's Signature _____
(If driver is not the policyholder)

Date & Time: 3:05 pm
27/7/2018



Name: _____
NRIC/FIN No.: _____



SINGAPORE POLICE FORCE



T/20180726/2148

1 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180726/2148

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/07/2018 19:15	Vide Report No.:	Station Diary No.: 141
--	------------------	---------------------------

Informant's Particulars

Name of Informant: LAM TONG SIONG			Address: APT BLK 936 JURONG WEST STREET 91 #09-365 SINGAPORE 640936		
ID Type / ID No.: NRIC NO / S2699042D			Contact No.: Home/Office: Mobile: 81802080		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 53	Date of Birth: 09/07/1965	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 26/07/2018 18:30	Type of Location: Car Park
Location: Along Road 1 JURONG WEST STREET 91				
OSCP OF B/936 JURONG WEST STREET 91, LOT NUMBER 141				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLG4112E	Car	TOYOTA	ALTIS	Silver	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE
POLICE FORCE**



T/20180726/2148

2 of 3

Report No. T/20180726/2148

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

CONTINUATION OF REPORT

Vehicle Owner			
Name	LAM TONG SIONG	ID No.	S2699042D
Related Vehicle	NIL	Contact No.	81802080
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 26/7/2018 at about 5.30am, I last parked my car, Silver Toyota Altis, SLG4112E, at the open space carpark of B/936 Jurong West St 91 at lot 141. Everything was last intact then. At about 6.30pm, I went to retrieve my vehicle and discovered that the front right side of the car was damaged and dented. I have an in car vehicle camera however I am not sure if it was switched on.



**SINGAPORE
POLICE FORCE**



T/20180726/2148

3 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20180726/2148

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 NURAQILAH BINTE ABDUL HAMID

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
SSI GOH GEOK LYE
Contact No.: 65476148

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
26/07/2018 19:15

Classification Of Case:

**HITACHI CAPITAL
SINGAPORE PTE LTD
8 FOURTH LOK YANG ROAD
SINGAPORE
629705**

Claim Reference:
Assessment Number: HT000009
Version: HITACHIC/1
Date Calculated: 30/07/2018 07:24

Full Report - V1
Registration: SLG4112E
Printed: 30/07/2018 14:24

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Cheong Chia Liang	Date of Incident:	26/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	12 day(s)
Policy Number:	MSD/VPCP/18-000756-00	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	YCM 19
Registration:	SLG4112E
Registration Month:	September
Registration Year:	2016
VIN Number:	
Odometer:	123588
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

AIR CONDITIONING	FOG LAMPS
TWO COAT METALLIC	PREPARE OFF VEHICLE

Signature
6/8/18

Tanjil 17415749
Ex \$1500
Revert, Not Authorised
Resurvey before print
11/8/18 2:45 pm
Surge 11/8/18 auto. w.n
4-5 days

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
Steering:

Brakes Pedal Travel:
Place of Inspection:
Pre-Accident Damage:

Severity of Impact:
Vehicle Status on
Inspection:
Date of Inspection:

Fax: 62564
62564 315
31/07/2018

Tyres Condition:
Tread Depth LHF:
Tread Depth LHR:
Damage Areas:

Tread Depth RHF:
Tread Depth RHR:
Direction of Impact:

LKK Auto Consultants hence notify the Repairer of the following:



- Resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

HITACHI CAPITAL SINGAPORE PTE LTD

Claim Reference:
 Assessment Number: HT000009
 Version: HITACHIC/1
 Date Calculated: 30/07/2018 07:24

Full Report - V1
 Registration: SLG4112E
 Printed: 30/07/2018 14:24



Primary Impact
 Secondary Impact

Addresses

Cost Summary

Total Labour	\$1,110.00
Total Paint/Material	\$228.48
Total Parts	\$2,385.90
Excess:	TBA
Grand Total Exc GST:	\$3,724.38
7 % GST:	\$260.71
Grand Total Inc GST:	\$3,985.09

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	3.0	15.00
043233	ALIGN VEHICLE CPL	12.0	60.00
M030 ZAX	R + R RIGHT FRONT AXLE HALF	9.0	45.00
	INCLUDES: R + R WHEEL, CONTROL ARM, TRACK ROD, UPPER STRUT, STABILIZER AND DRIVE SHAFT		
B100	R + R LEFT WING	4.0	20.00
B100	R + R R/WING	4.0	20.00
B110)	RENEW L/F WING (REMOVED)	2.0	10.00
B110)	RENEW R/F WING (REMOVED)	2.0	10.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	10.00
B140	RENEW FRONT PANEL CPL	18.0	90.00
B150)	RENEW R/F WHEELHOUSE CPL (COMP WORK)	27.0	135.00
B010	R + R FRONT BUMPER	5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)	11.0	55.00
B040)	R + R LEFT HEADLAMP	1.0	5.00
B040)	R + R RIGHT HEADLAMP	1.0	5.00
B040)	RENEW HEADLAMP	1.0	5.00
B060	R + R BONNET	3.0	15.00
B070)	RENEW BONNET (REMOVED)	1.0	5.00
B080	R + R BONNET HINGES	1.0	5.00
851051)	R + R WASHER PUMP	2.0	10.00
B085	R + R FRONT SCREEN FRAME MOULDING	2.0	10.00
B085)	R + R WATER BOX CLOSING PANEL	1.0	5.00
M010)	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00
M020	R + R RADIATOR	6.0	30.00

HITACHI CAPITAL SINGAPORE PTE LTD

Claim Reference:
Assessment Number: HT000009
Version: HITACHIC/1
Date Calculated: 30/07/2018 07:24

Full Report - V1
Registration: SLG4112E
Printed: 30/07/2018 14:24

INCLUDES: BLEED COOLING SYSTEM

LABOUR COST

Total Work Units	128.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	12.8HRS	\$640.00
Paint Labour	9.4HRS	\$470.00
Total Labour	22.2HRS	\$1,110.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	21.0	
742	R/F WING NEW PART PAINTING	10.0	
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	4.0	

LABOUR COST - PAINT

TIME(PAINT)	64.0	
Preparation Main Work Plastic	5.0	
Preparation Main Work Metal	25.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	94.0	
Total Paintwork Labour	9.4HRS	\$470.00

MATERIAL COST - PAINT

	Cost Price
New Part Painting	\$86.69
New Part Painting - Plastic K1R	\$72.32
Material-Constant Main Work Metal	\$28.60
Surface-/Blend Paint	\$31.87
Material-Const Main Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$228.48
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$228.48

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
254	1	R/LOWER GRILLE	81481 02110		0%	0.00
281	1	FRONT BUMPER	52119 02850		0%	180.00*
318	1	R/F BUMPER BRACKET	52115 02140		0%	25.00*
340	1	BUMPER SUPPORT	52021 02101		0%	110.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	15.00*
410	1	GRILLE	53100 02310		0%	150.00*
431	1	GRILLE BADGE	75301 02050		0%	25.00*
471	1	BONNET	53301 02230		0%	280.00*
475	1	L/F HINGE	53420 02060		0%	28.00*
476	1	R/F HINGE	53410 02060		0%	28.00*
493	1	BONNET LOCK	53510 02380		0%	60.00*
562	1	RIGHT HEADLAMP ASSY	81130 02720		0%	285.00*

Price Valid: 01/06/2015

HITACHI CAPITAL SINGAPORE PTE LTD

Claim Reference:
 Assessment Number: HT000009
 Version: HITACHIC/1
 Date Calculated: 30/07/2018 07:24

Full Report - V1
 Registration: SLG4112E
 Printed: 30/07/2018 14:24

638	1	R/F FOG LAMP	81210 02121	0%	X M	110.00*	X
742	1	R/F WING	53811 02250	0%	bt	190.00*	X
790	9	R/F WING CLAMP KIT	90119 06137	0%	nd	15.00*	X
812	1	BADGE "VVT-I" R	75444 02161	0%	nd	20.00*	X
842	1	R/WHEELHOUSE SHELL	53875 02270	0%	2 de	55.00*	X
1009	1	INNER FRT PANEL CPL	53201 02270	0%	Ry	220.00*	X
1118	1	R/F WHEELHOUSE CPL	53701 02220	0%	Ry	180.00*	X
1436	1	WASHER CONTAINER	85315 02470	0%	de	65.00*	X
1000	1	BNTINSULATORCLIPX6	Renew	0%	nd	9.00*	X
1000	1	FRTBPRSPONGE	Renew	0%	X M	40.00*	X
1000	1	RADTOPGARNISH	Renew	0%	X M	35.00*	X
1000	1	RADTPGNHCLIPX6	Renew	0%	Mi S	9.00*	X
1000	1	FRTFOGLMPCVERRH	Renew	0%	X M	35.00*	X
Sub Total						\$2,169.00	
Mark Up From Cost (10 %)						\$216.90	
Total Parts						\$2,385.90	

f: OEM Parts
 g: Original
 h: Secondhand
 p: Parallel
 x: Exchange

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$2,385.90
Labour	
Total Panel/Mechanical	\$640.00
Total Paintwork	\$470.00
Total Labour	\$1,110.00
Total Paint/Material Costs	\$228.48
Grand Total Excludes GST	\$3,724.38
GST @ 7 %	\$260.71
Grand Total Includes GST	\$3,985.09

Assessment Notes

HITACHI CAPITAL SINGAPORE PTE LTD

Claim Reference:
 Assessment Number: HT000009
 Version: HITACHIC/1
 Date Calculated: 30/07/2018 07:24

Full Report - V1
 Registration: SLG4112E
 Printed: 30/07/2018 14:24

638	1	R/F FOG LAMP	81210 02121	0%	X	110.00*
742	1	R/F WING	53811 02250	0%	bt	190.00*
790	9	R/F WING CLAMP KIT	90119 06137	0%	nk	15.00*
812	1	BADGE "VVT-1" R	75444 02161	0%	nk	20.00*
842	1	R/WHEELHOUSE SHELL	53875 02270	0%	?	55.00*
1009	1	INNER FRT PANEL CPL	53201 02270	0%	Ry	220.00*
1118	1	R/F WHEELHOUSE CPL	53701 02220	0%	Ry	180.00*
1436	1	WASHER CONTAINER	85315 02470	0%	ll	65.00*
1000	1	BNTINSULATORCLIPX6	Renew	0%	nk	9.00*
1000	1	FRTBPRSPONGE	Renew	0%	X	40.00*
1000	1	RADTOPGARNISH	Renew	0%	?	35.00*
1000	1	RADTPGNSHCLIPX6	Renew	0%	nk	9.00*
1000	1	FRTFOGLMPCVERRH	Renew	0%	?	35.00*
f: OEM Parts						Sub Total
g: Original						Mark Up From Cost (10 %)
h: Secondhand						Total Parts
p: Parallel						
x: Exchange						

THIS ASSESSMENT CONTAINS UNPRICED PARTS
 NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts	\$2,385.90
Labour	
Total Panel/Mechanical	\$640.00
Total Paintwork	\$470.00
Total Labour	\$1,110.00
Total Paint/Material Costs	\$228.48
Grand Total Excludes GST	\$3,724.38
GST @ 7 %	\$260.71
Grand Total Includes GST	\$3,985.09

Assessment Notes

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: HT000009
Version: HITACHIC/2
Date Calculated: 01/08/2018 10:09

Full Report - V1
Registration: SLG4112E
Printed: 01/08/2018 17:09

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	26/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	12 day(s)
Policy Number:	MSD/VPCP/18-000756-00	Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	YCM 19
Registration:	SLG4112E
Registration Month:	September
Registration Year:	2016
VIN Number:	
Odometer:	123588
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

AIR CONDITIONING	FOG LAMPS
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	31/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: HT000009

Registration: SLG4112E

Version: HITACHIC/2

Printed: 01/08/2018 17:09

Date Calculated: 01/08/2018 10:09



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$855.00
Total Paint/Material	\$209.06
Total Parts	\$1,714.90
Excess:	TBA
Grand Total Exc GST:	\$2,778.96
7 % GST:	\$194.53
Grand Total Inc GST:	\$2,973.49

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	3.0	15.00
B100	R + R LEFT WING	4.0	20.00
B100	R + R R/WING	4.0	20.00
B110)	RENEW L/F WING (REMOVED)	2.0	10.00
B110)	RENEW R/F WING (REMOVED)	2.0	10.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	10.00
B135	RENEW FR/LWR CROSSMEMBER	11.0	55.00
B125	RENEW FRONT LOCK CARRIER	7.0	35.00
B010	R + R FRONT BUMPER	5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)	11.0	55.00
B040)	R + R LEFT HEADLAMP	1.0	5.00
B040)	R + R RIGHT HEADLAMP	1.0	5.00
B040)	RENEW HEADLAMP	1.0	5.00
B060	R + R BONNET	3.0	15.00
B070)	RENEW BONNET (REMOVED)	1.0	5.00
B080	R + R BONNET HINGES	1.0	5.00
851091)	R + R WASHER RESERVOIR	2.0	10.00
851051)	R + R WASHER PUMP	2.0	10.00
B085	R + R FRONT SCREEN FRAME MOULDING	2.0	10.00
M010)	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00
M020	R + R RADIATOR	6.0	30.00
INCLUDES: BLEED COOLING SYSTEM			

LABOUR COST

Total Work Units	81.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00

Claim Reference:

Full Report - V1

Assessment Number: HT000009

Registration: SLG4112E

Version: HITACHIC/2

Printed: 01/08/2018 17:09

Date Calculated: 01/08/2018 10:09

Sub Total	8.1HRS	\$405.00
Paint Labour	9.0HRS	\$450.00
Total Labour	17.1HRS	\$855.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
340	BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	21.0	
742	R/F WING NEW PART PAINTING	10.0	
1016	FRT LWR CROSSMEMBER SURFACE PAINT	4.0	
1017	FRT LOCK CARRIER SURFACE PAINT	4.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE NEW PART PAINT K1R	4.0	
LABOUR COST - PAINT			
TIME(PAINT)		60.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		90.0	
Total Paintwork Labour		9.0HRS	\$450.00
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$86.69
New Part Painting - Plastic K1R			\$72.32
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$12.45
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$209.06
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$209.06

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
281	1	FRONT BUMPER	52119 02850		0%	180.00*
318	1	R/F BUMPER BRACKET	52115 02140		0%	25.00*
340	1	BUMPER SUPPORT	52021 02101		0%	110.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	15.00*
410	1	GRILLE	53100 02310		0%	150.00*
431	1	GRILLE BADGE	75301 02050		0%	25.00*
471	1	BONNET	53301 02230		0%	280.00*
475	1	L/F HINGE	53420 02060		0%	28.00*
476	1	R/F HINGE	53410 02060		0%	28.00*
562	1	RIGHT HEADLAMP ASSY	81130 02720		0%	285.00*
742	1	R/F WING	53811 02250		0%	190.00*
790	9	R/F WING CLAMP KIT	90119 06137		0%	15.00*
812	1	BADGE "VVT-I" R	75444 02161		0%	20.00*
842	1	R/WHEELHOUSE SHELL	53875 02270		0%	55.00*
1016	1	FRT LWR CROSSMEMBER	57104 02170		0%	0.00
1017	1	FRT LOCK CARRIER	53205 02170		0%	0.00
1436	1	WASHER CONTAINER	85315 02470		0%	65.00*

Claim Reference:

Full Report - V1

Assessment Number: HT000009

Registration: SLG4112E

Version: HITACHIC/2

Printed: 01/08/2018 17:09

Date Calculated: 01/08/2018 10:09

1000	1	BNTINSULATORCLIPX6	Renew	0%	9.00*
1000	1	RADTOPGARNISH	Renew	0%	35.00*
1000	1	RADTPGNSHCLIPX6	Renew	0%	9.00*
1000	1	FRTFOGLMPCVERRH	Renew	0%	35.00*
f: OEM Parts			Sub Total		\$1,559.00
g: Original			Mark Up From Cost	(10 %)	\$155.90
h: Secondhand			Total Parts		\$1,714.90
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras **\$0.00**

Final Calculation

Total Parts **\$1,714.90**

Labour

Total Panel/Mechanical \$405.00
Total Paintwork \$450.00

Total Labour **\$855.00**

Total Paint/Material Costs **\$209.06**

Grand Total Excludes GST **\$2,778.96**

GST @ 7 % **\$194.53**

Grand Total Includes GST **\$2,973.49**

Assessment Notes



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HITACHI CAPITAL ASIA PACIFIC PTE LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629705

ALDIS

VONN

NO: DL19266177

PAGE: 1

DATE: 02/06/2018

A/C CODE: LDHC008

TERMS: CR

O/R = 113679

VEH NO: SLOH12E

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T53301-02310	BONNET	DB1KS	1	280.00	280.00
2 T90467-09050	CLIP INSULATOR	DDIAS3-6	6	1.50	9.00
3 T52119-02955	BUMPER FR	DB2G	1	180.00	180.00
4 T52161-16010	CLIP BUMPER	DUIAD11-3✓	10	1.50	15.00
5 T52161-16010	CLIP TOP GARNISH	DUIAD11-3✓	6	1.50	9.00
6 T52115-02270	BUMPER RETAINER FR RH	DUIAD28-4✓	1	25.00	25.00
7 T53801-02240	FENDER FR RH	DB1D-1	1	190.00	190.00
8 T90467-07215	CLIP COWLING	DDIAS3-5	10	1.50	15.00
9 T81110-02F30	HEADLAMP ASSY RH	DDS	1	285.00	285.00
10 T85315-02630	WASHER TANK	DUIAB8-3✓	1	65.00	65.00
11 T75444-02700	FENDER PLATE RH (DUAL VTH)	DULAS3-19✓	1	20.00	20.00

TOTAL QUANTITY: 39 TOTAL SIN 1,093.00

ADD GST @ 7% 76.51

GRAND TOTAL **SIN 1,169.51**

O/R: 113679

MR WENG

Print / LSK / 2/6/2018 9:29:37 AM

SALESMAN LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. R

GOODS RECEIVED BY



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: HATCH CAPITAL ASIA PACIFIC PTE LTD

8 FOURTH LOK YANG ROAD

SINGAPORE 629708

ALIB

MONN

NO: DL19206196

PAGE: 1

DATE: 02/08/2018

A/C CODE: LDR008

TERMS: CR

		VEHICLE		SCHEDULE	
Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T53875-02G30✓	FENDER LINER FR RH	DBE10	1	55.00	55.00
TOTAL QUANTITY			1	TOTAL	SIN 55.00
				ADD GST @ 7%	3.85
				GRAND TOTAL	SIN 58.85

O/R: 113679

MR WENG

Print / LSK / 2018/08/02 11:49:35 AM

SALESMAN: LSK

This document is computer generated. No signature required

GOODS SOLD ARE NOT RETURNABLE

R & O/E

GOODS RECEIVED BY

0000

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MSD/VPCP/18-000756-00	Date of Loss:	26/07/2018
Vehicle Reg. No.:	SLG4112E	Driveable?	
Driver Age/Info:	53 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD	Contact No:	+6597108392
Driver:	LAM TONG SIONG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	29/09/2016
Vehicle Colour:	SILVER		
Engine No:	1ZRX591955	Chassis No:	MR053REH104557298
Odometer:	123588 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO ATTACHED.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS	Amount
Parts	2,385.90
Miscellaneous Items	0.00
Labour	1,338.48
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,724.38
+ GST 7.00% (S\$)	260.71
Nett Amount (S\$)	3,985.09

This claim is handled by: VONN SIOW LIE MIEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 30 Jul 2018)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/SLG4112E/30/07/2018 14:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SPARE PARTS	0.00	0.00	1762.70 *2,385.90 F
Total Parts (S\$)						2,385.90

F=Franchise part.

Hitachi Capital Asia Pacific Pte. Ltd/SLG4112E/30/07/2018 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR	New	775 1,110.00
2	PAINT/MATERIAL	New	198.48 228.48
Gross Labour Cost (S\$)			1,338.48

Hitachi Capital Asia Pacific Pte. Ltd/SLG4112E/30/07/2018 14:35, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference:
Assessment Number: HT000009
Version: LKKAUTOC/2
Date Calculated: 16/08/2018 07:53

Full Report - V1
Registration: SLG4112E
Printed: 16/08/2018 14:54

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	26/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	12 day(s)
Policy Number:	MSD/VPCP/18-000756-00	Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS CLASSIC
Model Sheet Number:	YCM 19
Registration:	SLG4112E
Registration Month:	September
Registration Year:	2016
VIN Number:	
Odometer:	123588
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

AIR CONDITIONING	FOG LAMPS
TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	31/07/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

Claim Reference:

Full Report - V1



Assessment Number: HT000009

Registration: SLG4112E

Version: LKKAUTOC/2

Printed: 16/08/2018 14:54

Date Calculated: 16/08/2018 07:53



Primary Impact
Secondary Impact

Addresses

Cost Summary

Total Labour	\$775.00
Total Paint/Material	\$199.66
Total Parts	\$1,262.80
Repair Cost Exc GST:	\$2,237.46
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,500.00
After Deduction -	
Grand Total Exc GST:	\$737.46
7 % GST:	\$51.62
Grand Total Inc GST:	\$789.08

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	3.0	15.00
B100	R + R R/WING	4.0	20.00
B110)	RENEW R/F WING (REMOVED)	2.0	10.00
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	10.00
B135	RENEW FR/LWR CROSSMEMBER	11.0	55.00
B125	RENEW FRONT LOCK CARRIER	7.0	35.00
B010	R + R FRONT BUMPER	5.0	25.00
B020)	RENEW FRONT BUMPER (REMOVED)	11.0	55.00
B040)	R + R RIGHT HEADLAMP	1.0	5.00
B040)	RENEW HEADLAMP	1.0	5.00
B060	R + R BONNET	3.0	15.00
B070)	RENEW BONNET (REMOVED)	1.0	5.00
851091)	R + R WASHER RESERVOIR	2.0	10.00
851051)	R + R WASHER PUMP	2.0	10.00
B085	R + R FRONT SCREEN FRAME MOULDING	2.0	10.00
M010)	R + R AIR CONDITIONING CONDENSER	3.0	15.00
002889	DRAIN/REFILL AIR CONDITIONING	7.0	35.00
M020	R + R RADIATOR	6.0	30.00
INCLUDES: BLEED COOLING SYSTEM			

LABOUR COST

Total Work Units	73.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.3HRS	\$365.00
Paint Labour	8.2HRS	\$410.00

Claim Reference:

Full Report - V1

Assessment Number: HT000009

Registration: SLG4112E

Version: LKKAUTOC/2

Printed: 16/08/2018 14:54

Date Calculated: 16/08/2018 07:53

Total Labour	15.5HRS	\$775.00
---------------------	----------------	-----------------

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
471	BONNET NEW PART PAINTING	21.0	
742	R/F WING NEW PART PAINTING	10.0	
1016	FRT LWR CROSSMEMBER SURFACE PAINT	4.0	
1017	FRT LOCK CARRIER SURFACE PAINT	4.0	
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
LABOUR COST - PAINT			
TIME(PAINT)		52.0	
Preparation Main Work Plastic		5.0	
Preparation Main Work Metal		25.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		82.0	
Total Paintwork Labour		8.2HRS	\$410.00
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$86.69
New Part Painting - Plastic K1R			\$67.40
Material-Constant Main Work Metal			\$28.60
Surface-/Blend Paint			\$7.97
Material-Const Main Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$199.66
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$199.66

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
281	1	FRONT BUMPER	52119 02850		0% 180.00*
318	1	R/F BUMPER BRACKET	52115 02140		0% 25.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% 15.00*
471	1	BONNET	53301 02230		0% 280.00*
562	1	RIGHT HEADLAMP ASSY	81130 02720		0% 285.00*
742	1	R/F WING	53811 02250		0% 190.00*
790	9	R/F WING CLAMP KIT	90119 06137		0% 15.00*
812	1	BADGE "VVT-I" R	75444 02161		0% 20.00*
842	1	R/WHEELHOUSE SHELL	53875 02270		0% 55.00*
1016	1	FRT LWR CROSSMEMBER	57104 02170		0% 0.00
1017	1	FRT LOCK CARRIER	53205 02170		0% 0.00
1436	1	WASHER CONTAINER	85315 02470		0% 65.00*
1000	1	BNTINSULATORCLIPX6	Renew		0% 9.00*
1000	1	RADTPGNSHCLIPX6	Renew		0% 9.00*
f: OEM Parts			Sub Total		\$1,148.00
g: Original			Mark Up From Cost	(10 %)	\$114.80
h: Secondhand			Total Parts		\$1,262.80
p: Parallel					
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Claim Reference:

Full Report - V1

Assessment Number: HT000009

Registration: SLG4112E

Version: LKKAUTOC/2

Printed: 16/08/2018 14:54

Date Calculated: 16/08/2018 07:53

	Total Extras	\$0.00
Final Calculation		
Total Parts		\$1,262.80
Labour		
Total Panel/Mechanical	\$365.00	
Total Paintwork	\$410.00	
Total Labour		\$775.00
Total Paint/Material Costs		\$199.66
Repair Costs Excludes GST		\$2,237.46
Deductions		
Deduction for Excess (Fixed)	-\$1,500.00	
Total Deductions		-\$1,500.00
Grand Total Excludes GST (After Deduction)		\$737.46
GST @ 7 %		\$51.62
Grand Total Includes GST (After Deduction)		\$789.08

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jul 2018 Sendback Est	30 Jul 2018 14:35 S\$3,724.38	30 Jul 2018 15:44 Edit Adj Rpt	S\$2,237.46 Edit Estimates	S\$2,237.46 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: HITACHI CAPITAL ASIA PACIFIC PTE LTD , Co. Reg. No.: 199400399N, Tel: +6597108392									
Vehicle Reg. No.: SLG4112E		Date of Loss: 26/07/2018 18:00 - :59 [21 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / MSC/V/18-001020		Policy/Cover Note No.: MSD/VPCP/18-000756-00 (Comprehensive) Coverage: 01/06/2018 - 31/05/2019							
		Excess: S\$1,500.00							
Repairer: Hitachi Capital Asia Pacific Pte. Ltd (HQ) No 8 Fourth Lok Yang Road, 629705 Pioneer - Tel: 64663022									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 29/08/2018]									
Driver/Custodian: LAM TONG SIONG (53 / Male), NRIC: S2699042D, Tel: +6581802080									
Adj Asg. Remarks: Car in, pls survey and revert									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (02/08/2018): Alert - Adj Mandate Approved (S\$2778.96) - SLG4112E - Claim Handler: Jocelyn Ng ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLG4112E (MSC/V/18-001020)

OD

Jul 26 2018 6:00PM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Hitachi Capital Asia Pacific Pte. Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports

1 per page ☐

No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	27/07/18 17:54	Accident Statement	 Load HTM	☐
2	30/07/18 14:35	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 17:33	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ☐

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/08/18 15:45	Odometer Reading	 Load JPG	☒
2	16/08/18 15:45	Chassis Number	 Load JPG	☒
3	16/08/18 15:45	General View	 Load JPG	☒
4	16/08/18 15:45	General View	 Load JPG	☒
5	16/08/18 15:45	General View	 Load JPG	☒
6	16/08/18 15:45	General View	 Load JPG	☒
7	16/08/18 15:45	General View	 Load JPG	☒
8	16/08/18 15:45	General View	 Load JPG	☒
9	16/08/18 15:45	General View	 Load JPG	☒
10	16/08/18 15:45	General View	 Load JPG	☒
11	16/08/18 15:45	General View	 Load JPG	☒
12	16/08/18 15:45	General View	 Load JPG	☒
13	16/08/18 15:45	General View	 Load JPG	☒
14	16/08/18 15:45	General View	 Load JPG	☒
15	16/08/18 15:45	General View	 Load JPG	☒
16	16/08/18 15:45	General View	 Load JPG	☒
17	16/08/18 15:45	General View	 Load JPG	☒
18	16/08/18 15:45	General View	 Load JPG	☒
19	16/08/18 15:45	General View	 Load JPG	☒
20	16/08/18 15:45	General View	 Load JPG	☒
21	16/08/18 15:45	General View	 Load JPG	☒
22	16/08/18 15:45	General View	 Load JPG	☒
23	16/08/18 15:45	General View	 Load JPG	☒
24	16/08/18 15:45	General View	 Load JPG	☒
25	16/08/18 15:45	General View	 Load JPG	☒
26	16/08/18 15:45	General View	 Load JPG	☒
27	16/08/18 15:45	General View	 Load JPG	☒
28	16/08/18 15:45	General View	 Load JPG	☒
29	16/08/18 15:45	General View	 Load JPG	☒
30	16/08/18 15:45	General View	 Load JPG	☒
31	16/08/18 15:45	General View	 Load JPG	☒
32	16/08/18 15:45	General View	 Load JPG	☒
33	16/08/18 15:45	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
				☒
34	16/08/18 15:45	General View	 Load JPG	☒
35	16/08/18 15:45	General View	 Load JPG	☒
36	16/08/18 15:45	General View	 Load JPG	☒
37	16/08/18 15:45	General View	 Load JPG	☒
38	16/08/18 15:45	General View	 Load JPG	☒
39	16/08/18 15:45	General View	 Load JPG	☒
40	16/08/18 15:45	General View	 Load JPG	☒
41	16/08/18 15:45	General View	 Load JPG	☒
42	16/08/18 15:45	General View	 Load JPG	☒
43	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
44	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
45	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
46	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
47	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
48	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
49	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
50	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
51	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
52	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
53	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
54	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
55	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
56	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
57	16/08/18 15:45	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	30/07/18 14:36	Driver's Driving License	 Load PDF	
2	30/07/18 14:36	Singapore Accident Statement	 Load PDF	
3	30/07/18 14:36	AUDATEX REPORT	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/07/18 15:23	PARF COE	 Load PDF	
2	30/07/18 15:23	Transfer Fee Details	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/08/18 17:19	ESTIMATE	 Load PDF	
2	01/08/18 17:19	AUDATEX	 Load PDF	
3	16/08/18 15:45	REVISED AUDATEX	 Load PDF	
4	20/08/18 12:49	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	27/07/18 17:54	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	27/07/18 17:53	Accident Photo	 Load JPG	☒
2	27/07/18 17:53	Accident Photo	 Load JPG	☒
3	27/07/18 17:53	Accident Photo	 Load JPG	☒
4	27/07/18 17:53	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
5	27/07/18 17:53	Accident Photo	 Load JPG	☒
6	27/07/18 17:53	Accident Photo	 Load JPG	☒
7	27/07/18 17:53	Accident Photo	 Load JPG	☒
8	27/07/18 17:53	Accident Photo	 Load JPG	☒
9	27/07/18 17:53	Accident Photo	 Load JPG	☒
10	27/07/18 17:53	Accident Photo	 Load JPG	☒
11	27/07/18 17:53	Accident Photo	 Load JPG	☒
12	27/07/18 17:53	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Hitachi Capital Asia Pacific Pte. Ltd (HQ)	Thumbnail	Print
1	27/07/18 17:53	Sketch Plan	 Load TIF	
2	27/07/18 17:53	POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18013831/T1QD3E2

Date: 20/08/2018

REFERENCE

Insured/Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD	Policy No:	MSD/VPCP/18-000756-00	Claim No:	MSC/V/18-001020
Date of Loss:	26/07/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG4112E	Engine No:	1ZRX591955
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104557298
Reg. Date:	29/09/2016 (Man. Year: 2016)	Odometer:	123588 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,385.90	1,262.80	1,123.10	47.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,338.48	974.66	363.82	27.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,724.38	2,237.46	1,486.92	39.92
- Excess (S\$)	0.00	1,500.00	-1,500.00	
(S\$)	3,724.38	737.46	2,986.92	80.20
+ GST 7.00/7.00% (S\$)	260.71	51.62	209.09	80.20
Nett Amount (S\$)	3,985.09	789.08	3,196.01	80.20

INSPECTION

Date of Assignment:	30/07/2018	Present Location:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)
Date Inspected:	01/08/2018	Inspected At:	Hitachi Capital Asia Pacific Pte. Ltd (HQ)

No 8 Fourth Lok Yang Road
Singapore 629705

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG4112E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS (WCP)		2,385.90 F	*1,148.00 F
					Sub Total (\$\$)	2,385.90 1,148.00
					+ Margin on L,N Items 0.00/10.00% (\$\$)	0.00 114.80
					Total Parts (\$\$)	2,385.90 1,262.80

F=Franchise part

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	1,110.00	775.00
2	PAINT/MATERIAL	New	228.48	199.66
Gross Labour Cost (S\$)			1,338.48	974.66

Report was unsubmitted during this print-out.

< END OF ESTIMATES >