

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0298/2018
DATE : 23-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : ARUMUGAN SUNDARAM
ADDRESS : BLK 284 CHUA CHU KANG AVE 3
#04-324
S(680284)
TELEPHONE NO : 94594371

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBG2295S
VEHICLE NO : SJF6206J
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2594602A
CHASSIS NO : SJNFEAJ11U2233583
MILEAGE : 1 KM
DATE IN : 23/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 12/07/2018

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

23/07/18

OFFICE : 67038916 FAX : 64697472

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJP6206J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	ADJUST R/LAMP,VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	10.00	X
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED 2PANEL X \$120	120.00	/
4	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/ 55
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA 2PANEL X \$100	200.00	/ 100
6	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
7	ZZ/001	REPLACE REAR WINDSHIELD	240.00	/
8	ZZ/002	REPAIR REAR END PANEL,REAR FENDER RH & LH SIDE RENEW REAR BACK DOOR & REAR BUMPER COVER	1250.00	/ 700
9	ZZ/003	S/PAINT REAR FENDER RH & LH SIDE,REAR END PANEL, REAR BACK DOOR & REAR BUMPER COVER	1200.00	/ 1000
10	ZZ/004	TRANSFER BACK DOOR MECHANICAL PART	80.00	/
TOTAL LABOUR CHARGES			3408.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJF6206J

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			180.00 <i>me</i>
2 DRAFTER-AIR	76804-JD00A	62.30	?	
3 FENDER ARK	93829-4EA0A	483.00	<i>DE</i>	
4 LAMP COMB RR,LH	26555-HV55A	215.90	<i>CA</i>	
5 LAMP COMB RR,LH	26555-HV00A	323.70	<i>CA</i>	
6 ORNAMENT-BACK DOOR EMBLEM	90892-4EA0A	87.00	<i>de</i>	
7 EMBLEM-REAR	90890-4EA0A	59.70	<i>de</i>	
8 A FIN BACK DOOR HANDLE	90810-4ES0H	336.00	<i>DE</i>	
9 DOOR BACK	K0100-HV0MB	2936.80	<i>BA</i>	
10 WEATHER STRIP	90830-4EA0B	158.70	<i>act</i>	
11 SEALANT - REAR W/SCREEN GLASS	SEALANT - 2			80.00 <i>me</i>
12 GLASS-TAIL GATE	90300-HV00A	930.00	<i>me</i>	<i>photo</i>
13 STAY ASSY-REAR LH	H5211-4EAMA	126.00	?	
14 ENERGY ABSORBER	85090-HV00A	126.40	?	
15 REINF-BUMPER RR	H5030-4EAMA	619.20	-	
16 BRACKET-BUMPER LH	85221-4EA0A	35.90	<i>me</i>	
17 RETAINER-BUMPER LH	79185-4EA0A	23.80	<i>me</i>	
18 CLIP(10X1.2)	01553-05933	12.00	<i>me</i>	
19 CLIP(3X7.4)	85284-JD00A	22.20	<i>me</i>	
20 CANOE RIVET(2X6.5)	76882-0M000	13.00	<i>me</i>	
21 FASCIA-RR BUMP	85022-HV00H	717.00	<i>DE</i>	
SUB TOTAL		7288.60	0.00	260.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1457.72	0.00	0.00
GRAND TOTAL		5830.88	0.00	260.00
OVERALL TOTAL		6090.88		

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJF6206J

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJF6206J

TOTAL LABOUR CHARGES	3408.00
TOTAL SPARE PARTS CHARGES	6090.88
GRAND TOTAL	9498.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Ram - Hp 90010068
SURVEYED DATE	:	30/07/18 @ 1125
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 7 days
LIABILITY	:	0.00
REMARKS	:	

Resurvey 64 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: