

AXN
FZ

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8097B

DATE 30/7/2018 9:56

MAKE :

MODEL : HYUNDAI SONATA

| Qty | Parts Description/ Labour | Type | Unit Price | Amount | |
|-----|----------------------------------|------|------------|--------------------------|------|
| | Rear Bumper ✓ | | | \$ 578.40 | |
| | Rear Bumper Reinforcement ? | | | \$ 483.30 | |
| | Rear Bumper Clip ✓ | | | \$ 22.00 | |
| | Rear Bumper Sponge ? | | | \$ 137.40 | |
| | Rear Bumper Under Cover ✕ | | | \$ 185.80 | |
| | Rear Bumper Protector (LH/RH) ✕ | | \$ 38.00 | \$ 76.00 | |
| | SUB TOTAL | | | \$ 1,482.90 | |
| | LESS 20% | | | \$ 296.58 | |
| | DISCOUNTED TOTAL | | | \$ 1,186.32 | |
| | Rear Bumper Reverse Sensor ✕ | | | \$ 135.70 | Nett |
| | Rear Bumper Advertisement Logo ✕ | | | \$ 50.00 | Nett |
| | | | | \$ 185.70 | |
| | Labour Charge | | | | |
| | Panel Beating | | | \$ 350.00 200 | |
| | Spray Painting Charge | | | \$ 250.00 200 | |
| | Wiring Charge | | | \$ 50.00 ✕ | |
| | Remove/Refix Reverse Sensor | | | \$ 120.00 30 | |
| | TOTAL LABOUR | | | \$ 770.00 | |
| | ESTIMATE TOTAL | | | \$ 2,142.02 | |

Kahin 10000
30/7/18 1400h
2 Pp
4/3
After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.